




**Northeast Ohio
Regional Sewer District**

**Daily Precipitation Report
Saturday, August 1, 2020**

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report
Saturday, August 1, 2020

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.52	0.45	0.42	0.36	0.20
Brecksville	0.49	0.46	0.34	0.27	0.12
Brook Park	0.90	0.86	0.79	0.73	0.31
Cleveland Industrial Pkwy	0.88	0.84	0.73	0.66	0.30
Dille Ave PS	0.52	0.50	0.47	0.42	0.21
Division Ave PS	0.38	0.35	0.25	0.18	0.09
Easterly WWTP	0.36	0.35	0.28	0.23	0.10
Independence	0.86	0.81	0.80	0.66	0.29
James Rhodes HS	0.59	0.55	0.54	0.47	0.26
Jennings PS	0.66	0.63	0.60	0.50	0.22
Macedonia	0.41	0.32	0.19	0.15	0.14
Maple Heights	0.54	0.51	0.48	0.38	0.16
Mary Street PS	0.45	0.43	0.39	0.33	0.18
Mayfield Heights	0.38	0.27	0.24	0.18	0.10
Moreland Hills	0.21	0.14	0.14	0.12	0.05
North Olmsted	0.62	0.56	0.30	0.26	0.17
North Royalton	1.10	1.02	1.02	0.85	0.56
Oakwood	0.28	0.20	0.16	0.15	0.08
Olmsted Falls	0.84	0.77	0.47	0.46	0.24
Parma	0.87	0.80	0.78	0.67	0.30
Richfield	0.33	0.26	0.19	0.18	0.09
Shaker Heights	0.45	0.42	0.39	0.32	0.14
South Euclid	0.28	0.26	0.25	0.21	0.08
Southerly WWTC	0.47	0.42	0.41	0.31	0.13
Strongsville C WWTP	1.04	1.02	1.00	0.93	0.51
Strongsville Foltz	1.49	1.46	1.45	1.36	0.70
University Heights	0.34	0.30	0.30	0.25	0.11
Wade Park	0.37	0.35	0.28	0.24	0.09
Westlake	0.48	0.46	0.26	0.21	0.18

Work Order Detail Report

8/5/2020

SSO INSPECTION 8-1-2020 0.34 INCHES OF RAIN

9:18 AM

WO Number:	200803-0007	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	8/5/2020 9:17 am	Main Task:	Inspection
Asset: SSO 431			
Location: FAIRFAX AT NORTH PARK			
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	8/3/2020 8:00 AM
Lead Worker:	DelZoppo, Michael	End Date:	8/3/2020
Priority:	High		Override Notifications
Account #:			<input type="checkbox"/> Problem
Proj No - Acct:			<input type="checkbox"/> Overdue
Project:		Project ID:	<input type="checkbox"/> Lead Worker
Reason:		Project Name:	<input type="checkbox"/> Task
Received By:			<input type="checkbox"/> Supervisor
Inspected By:			<input type="checkbox"/> Hard Lock WO

Request Comments for Work Order

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer Collection

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Comments for Crew

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200803-0007

Work Order Detail Report

8/5/2020

SSO INSPECTION 8-1-2020 0.34 INCHES OF RAIN

9:18 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200803-0007

Work Order Detail Report

8/5/2020

SSO INSPECTION 8-1-2020 0.34 INCHES OF RAIN

9:18 AM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

8/5/2020

9:18 AM

SSO INSPECTION 8-1-2020 0.34 INCHES OF RAIN

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

8/5/2020

SSO INSPECTION 8-1-2020 0.34 INCHES OF RAIN

9:18 AM

Work Order Assets								
Object Type	System ID 1	System ID 2	Description 1	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve	SSO 431					FAIRFAX AT NORTH PARK		26
Sewer Control Valve	SSO 114					NORTH PARK AND COVENTRY		16
Sewer Control Valve	SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH		35
Sewer Structure	SA16AAWB0						3094	
Sewer Control Valve	SSO 112					FAIRMOUNT AT FAIRFAX		7
Sewer Control Valve	SSO 99					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		6
Sewer Control Valve	SSO 432					3012 NORTH WOODLAND		14
Sewer Control Valve	DB-03						55	
Sewer Control Valve	DB-01						56	
Sewer Control Valve	DB-02						57	
Sewer Control Valve	CH-04					FAIRMOUNT AT DARTMOOR		5
Sewer Control Valve	SSO 110					FAIRMOUNT AT WELLINGTON		44
Sewer Control Valve	SSO 87					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		33
Sewer Control Valve	SSO 116					FAIRMOUNT AT MARLBORO		4
Sewer Control Valve	SSO 111					FAIRMOUNT AT ARLINGTON		46
Sewer Control Valve	SSO 113					FAIRMOUNT & COVENTRY (SCARBOROUGH)		37
Sewer Control Valve	SSO 124					FAIRMOUNT AND COVENTRY		47
Sewer Control Valve	CH-50					SCARBOROUGH AT LAMBERTON		53
Sewer Control Valve	SSO 129					BRADFORD AND LEE		11
Sewer Control Valve	CH-52					EDDINGTON		2
Sewer Control Valve	SSO 88					HAMPSHIRE LANE AT MAYFIELD (18")		42
Sewer Control Valve	SSO 122					EAST OVERLOOK AT EDGEHILL		36
Sewer Control Valve	SSO 89					HAMPSHIRE LANE AT MAYFIELD (36")		34
Sewer Structure	SA16ADZB0						1536	
Sewer Control Valve	SSO 91					HAMPSHIRE AT EUCLID HTS. BLVD.		20
Sewer Structure	SA16ADPH0						4446	
Sewer Control Valve	SSO 120					CEDAR BTW. FAIRMOUNT/DEMINGTON		8
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200803-0007

Work Order Detail Report

8/5/2020

SSO INSPECTION 8-1-2020 0.34 INCHES OF RAIN

9:18 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	3402
SA16AGMG0	South Taylor between Antisdale Ave and Superior R
Sewer Control Valve	52
CH-30	LEE RD. & SUPERIOR AVE.
Sewer Control Valve	9
DV-11	EUCLID HEIGHTS BLVD AND LEE
Sewer Control Valve	22
SSO 108	EUCLID HEIGHTS BLVD/CUMBERLAND
Sewer Control Valve	43
SSO 106	1685 CUMBERLAND
Sewer Control Valve	18
SSO 95	4987
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	3745
SA16AQQD0	2225 NOBLE ROAD
Sewer Structure	3
SA16AQQC0	QUILLIAMS, N. OF RANDOLF
Sewer Control Valve	38
SSO 102	LANGTON AND AHERSTONE
Sewer Control Valve	54
SSO 107	1809
Sewer Control Valve	
CH-51	
Sewer Structure	
SA16APEF0	

Work Order Detail Report

8/5/2020

SSO INSPECTION 8-1-2020 0.34 INCHES OF RAIN

9:18 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	8/3/2020/ 8:05 am	8/3/2020
No overflow					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	8/3/2020/ 8:08 am	8/3/2020
No overflow					
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	8/3/2020/ 8:10 am	8/3/2020
No overflow					
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	8/3/2020/ 8:12 am	8/3/2020
No overflow					
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	8/3/2020/ 8:13 am	8/3/2020
No overflow					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	8/3/2020/ 8:16 am	8/3/2020
No overflow					
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	8/3/2020/ 8:18 am	8/3/2020
No overflow					
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	8/3/2020/ 8:21 am	8/3/2020
No overflow					
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	8/3/2020/ 8:22 am	8/3/2020
No overflow					
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	8/3/2020/ 8:24 am	8/3/2020
No overflow					
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	8/3/2020/ 8:26 am	8/3/2020
No overflow					
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/3/2020/ 8:28 am	8/3/2020
No overflow					
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	8/3/2020/ 8:31 am	8/3/2020
No overflow					
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/3/2020/ 8:34 am	8/3/2020
No overflow					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/3/2020/ 8:36 am	8/3/2020
No overflow					
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	8/3/2020/ 8:38 am	8/3/2020
No overflow					
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/3/2020/ 8:40 am	8/3/2020
Overflowed					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	8/3/2020/ 8:44 am	8/3/2020
No overflow					

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200803-0007

Work Order Detail Report

8/5/2020

SSO INSPECTION 8-1-2020 0.34 INCHES OF RAIN

9:18 AM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	8/3/2020/ 8:49 am	8/3/2020
	No overflow				
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	8/3/2020/ 8:51 am	8/3/2020
	No overflow				
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	8/3/2020/ 8:53 am	8/3/2020
	No overflow				
22	A-9 BRADFORD AT LEE SA16AFL00 (INTERSECTION)	<input type="checkbox"/>	Sound	8/3/2020/ 8:55 am	8/3/2020
	No overflow				
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	8/3/2020/ 9:02 am	8/3/2020
	No overflow				
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	8/3/2020/ 9:05 am	8/3/2020
	No overflow				
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	8/3/2020/ 9:06 am	8/3/2020
	No overflow				
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	8/3/2020/ 9:07 am	8/3/2020
	No overflow				
27	B-13 HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	8/3/2020/ 9:08 am	8/3/2020
	No overflow				
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Sound	8/3/2020/ 9:11 am	8/3/2020
	Overflowed				
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	8/3/2020/ 9:18 am	8/3/2020
	No overflow				
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	8/3/2020/ 9:21 am	8/3/2020
	No overflow				
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	8/3/2020/ 9:23 am	8/3/2020
	No overflow				
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	8/3/2020/ 9:26 am	8/3/2020
	No overflow				
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	8/3/2020/ 9:30 am	8/3/2020
	No overflow				
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	8/3/2020/ 9:38 am	8/3/2020
	Overflowed				
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	8/3/2020/ 9:42 am	8/3/2020
	No overflow				
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	8/3/2020/ 9:45 am	8/3/2020
	Overflowed				
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	8/3/2020/ 9:46 am	8/3/2020
	No overflow				
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>		8/3/2020/ 9:47 am	8/3/2020
	Block missing. Replaced block.				
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	8/3/2020/ 9:50 am	8/3/2020
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200803-0007

Work Order Detail Report

8/5/2020

SSO INSPECTION 8-1-2020 0.34 INCHES OF RAIN

9:18 AM

40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	8/3/2020/ 9:56 am	8/3/2020
No overflow					
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	8/3/2020/ 9:57 am	8/3/2020
No overflow					
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	8/3/2020/10:01 am	8/3/2020
No overflow					
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	8/3/2020/10:04 am	8/3/2020
No overflow					
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	8/3/2020/10:08 am	8/3/2020
No overflow					
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	8/3/2020/10:09 am	8/3/2020
No overflow					
46	B-14 DERBYSHIRE AT EUCLID HEIGHTS BLVD SA16ADPH0	<input type="checkbox"/>	Sound	8/3/2020/ 9:15 am	8/3/2020
Overflowed					

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC: \$6.21	*Task Cost: \$279.52	Start Dt:	
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32			
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20			
5						
Task Comment: EXCESSIVE RAINFALL 0.34 INCHES						

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	8.00	0.00	0.00
Subcontractor:		Labor Costs	\$172.32	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data				
Contact Name:		*Billing Amount:		Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:		Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:		Imported to Financials: <input type="checkbox"/>
		Payment Method:		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200803-0007

Work Order Detail Report

8/5/2020

SSO INSPECTION 8-1-2020 0.34 INCHES OF RAIN

9:18 AM

Associated PMs		Closed <input checked="" type="checkbox"/>		
Item	PM Code and Description	By	Date	Time
Work Order Creation	SSO-02 SSO INSPECTION	jjackson	8/3/2020	12:02 PM
Supervisor Notification	Email Queued Successfully!	jjackson	8/3/2020	12:02 PM
Email Successfully Sent	jjackson@clvhts.com Lucy City Work Order	BackgroundTaskUser	8/3/2020	12:02 PM
Status Change	Update - Supervisor	aferrone	8/5/2020	9:17 AM
Rates:	From New Work Order to Complete			
Received By:	Opened At:			Televised: <input type="checkbox"/>
Work From:	Pipe Footage Cleaned.			Power Rooter: <input type="checkbox"/>
Pipe Size:	Gallons Used:			Jet: <input type="checkbox"/>
Pipe Condition:	WO User 23:			Gap Vac: <input type="checkbox"/>
Could Not Open:	WO User 24:			Dye Test: <input type="checkbox"/>
Additional Repair:	WO User 9:			Gap Root Cut: <input type="checkbox"/>
Dye Test Reason:	User 10:			GIS Correction?: <input type="checkbox"/>
Test Performed Through:	Appointment Date DNL			WO User 30: <input type="checkbox"/>
Dye Test Results:	Appointment Date: 8/3/2020	7:00 AM		
WO User 51:				
Measurement:	E Mail:			
History:	WO User 22:			
Manhole Basin Repair:	Pipe Size:			
Material Used:	PVC Tees, Angles, Slat			
Pipe Repair:	WO User 44:			
Street Repair:	WO User 45:			
Grass Repair:	WO User 46:			
Curb Repair:				
Driveway- Sidewalk Re:				
Construction Crew:				
WO User 39:	OUPS #:			
WO User 40:	WO User 48:			
WO User 41:				
WO User 52:	WO User 62:			
WO User 53:	WO User 63:			
WO User 54:	WO User 64:			
WO User 55:	WO User 65:			
WO User 56:	WO User 66:			
WO User 57:	WO User 67:			
WO User 58:	WO User 68:			
WO User 59:	WO User 69:			
WO User 60:	WO User 70:			
WO User 61:	WO User 71:			
WO User 72:	WO User 82:			Televised: <input type="checkbox"/>
WO User 73:	Quantity:			Paid: <input type="checkbox"/>
WO User 74:	WO User 84:			WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:			WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:			WO User 106: <input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:			
WO User 93 Date:	WO User 98 Date:			
WO User 94 Date:	WO User 99 Date:			
WO User 95 Date:	WO User 100 Date:			
WO User 96 Date:	WO User 101 Date:			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200803-0007


Work Order Detail Report

8/5/2020

SSO INSPECTION 8-1-2020 0.34 INCHES OF RAIN

9:18 AM

WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 8/3/2020	PM Trigger:	Rec #: 5711



Northeast Ohio Regional Sewer District

Daily Precipitation Report
Sunday, August 16, 2020

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.28	0.28	0.28	0.24	0.11
Brecksville	0.39	0.39	0.39	0.32	0.18
Brook Park	0.77	0.77	0.77	0.47	0.21
Cleveland Industrial Pkwy	0.98	0.98	0.98	0.75	0.43
Dille Ave PS	0.64	0.64	0.64	0.57	0.40
Division Ave PS	0.82	0.82	0.82	0.71	0.51
Easterly WWTP	0.57	0.57	0.56	0.51	0.38
Independence	0.49	0.49	0.49	0.31	0.20
James Rhodes HS	0.87	0.87	0.87	0.65	0.42
Jennings PS	0.74	0.74	0.74	0.64	0.40
Macedonia	0.25	0.25	0.25	0.20	0.09
Maple Heights	0.32	0.32	0.32	0.28	0.16
Mary Street PS	0.69	0.69	0.69	0.60	0.43
Mayfield Heights	0.15	0.15	0.15	0.11	0.04
Moreland Hills	0.18	0.18	0.18	0.16	0.05
North Olmsted	1.33	1.33	1.33	0.98	0.55
North Royalton	0.40	0.40	0.40	0.31	0.15
Oakwood	n/a	n/a	n/a	n/a	n/a
Olmsted Falls	1.10	1.10	1.10	0.83	0.57
Parma	0.38	0.38	0.38	0.25	0.11
Richfield	0.42	0.42	0.42	0.37	0.22
Shaker Heights	0.41	0.41	0.41	0.39	0.23
South Euclid	0.48	0.48	0.48	0.41	0.26
Southerly WWTC	0.49	0.49	0.49	0.37	0.19
Strongsville C WWTP	0.57	0.57	0.57	0.51	0.30
Strongsville Foltz	0.71	0.71	0.71	0.58	0.27
University Heights	0.32	0.32	0.32	0.28	0.15
Wade Park	0.67	0.67	0.66	0.62	0.40
Westlake	1.34	1.34	1.34	1.10	0.70

Work Order Detail Report

8/26/2020

SSO INSPECTION 8-16-2020 0.32 INCHES OF RAIN

1:26 PM

WO Number: 200821-0001	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 8/26/2020 1:19 pm	Main Task:	Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	8/16/2020
Supervisor:	Jackson, Jeff	Start Date:	8/19/2020 8:00 AM
Lead Worker:	Eathridge, David	End Date:	8/19/2020
Priority:	High		<u>Override Notifications</u>
Account #:			Problem <input type="checkbox"/>
Proj No - Acct:		Project ID:	Overdue <input type="checkbox"/>
Project:		Project Name:	Lead Worker <input type="checkbox"/>
Reason:			Task <input type="checkbox"/>
Received By:			Supervisor <input type="checkbox"/>
Inspected By:			Hard Lock WO <input type="checkbox"/>

Request Comments for Work Order

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection

Comments for Crew

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

Work Order Detail Report

8/26/2020

SSO INSPECTION 8-16-2020 0.32 INCHES OF RAIN

1:26 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200821-0001

Work Order Detail Report

8/26/2020

SSO INSPECTION 8-16-2020 0.32 INCHES OF RAIN

1:26 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

8/26/2020

SSO INSPECTION 8-16-2020 0.32 INCHES OF RAIN

1:26 PM

Work Order Assets							
<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>		<u>Description 2</u>		<u>Completed</u>
			<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>	<u>Asset ID</u>
Sewer Control Valve	SSO 431					FAIRFAX AT NORTH PARK	26
Sewer Control Valve	SSO 114					NORTH PARK AND COVENTRY	16
Sewer Control Valve	SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH	35
Sewer Structure	SA16AAWB0						3094
Sewer Control Valve	SSO 112					FAIRMOUNT AT FAIRFAX	7
Sewer Control Valve	SSO 99					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6
Sewer Control Valve	SSO 432					3012 NORTH WOODLAND	14
Sewer Control Valve	DB-03						55
Sewer Control Valve	DB-01						56
Sewer Control Valve	DB-02						57
Sewer Control Valve	CH-04					FAIRMOUNT AT DARTMOOR	5
Sewer Control Valve	SSO 110					FAIRMOUNT AT WELLINGTON	44
Sewer Control Valve	SSO 87					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33
Sewer Control Valve	SSO 116					FAIRMOUNT AT MARLBORO	4
Sewer Control Valve	SSO 111					FAIRMOUNT AT ARLINGTON	46
Sewer Control Valve	SSO 113					FAIRMOUNT & COVENTRY (SCARBOROUGH)	37
Sewer Control Valve	SSO 124					FAIRMOUNT AND COVENTRY	47
Sewer Control Valve	CH-50					SCARBOROUGH AT LAMBERTON	53
Sewer Control Valve	SSO 129					BRADFORD AND LEE	11
Sewer Control Valve	CH-52					EDDINGTON	2
Sewer Control Valve	SSO 88					HAMPSHIRE LANE AT MAYFIELD (18")	42
Sewer Control Valve	SSO 122					EAST OVERLOOK AT EDGEHILL	36
Sewer Control Valve	SSO 89					HAMPSHIRE LANE AT MAYFIELD (36")	34
Sewer Structure	SA16ADZB0						1536
Sewer Control Valve	SSO 91					HAMPSHIRE AT EUCLID HTS. BLVD.	20
Sewer Structure	SA16ADPH0						4446
Sewer Control Valve	SSO 120					CEDAR BTW. FAIRMOUNT/DEMINGTON	8
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200821-0001

Work Order Detail Report

8/26/2020

SSO INSPECTION 8-16-2020 0.32 INCHES OF RAIN

1:26 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

8/26/2020

SSO INSPECTION 8-16-2020 0.32 INCHES OF RAIN

1:26 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	8/21/2020/ 7:41 am	
	Overflowed				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	8/21/2020/ 7:44 am	
	Overflowed				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	8/21/2020/ 7:47 am	
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	8/21/2020/ 7:50 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	8/21/2020/ 7:52 am	
	Overflowed				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	8/21/2020/ 7:56 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	8/21/2020/ 8:00 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	8/21/2020/ 8:05 am	
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	8/21/2020/ 8:05 am	
	No overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	8/21/2020/ 8:05 am	
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	8/21/2020/ 8:09 am	
	Block missing. Replaced block.				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/21/2020/ 8:12 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	8/21/2020/ 8:14 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/21/2020/ 8:15 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/21/2020/ 8:16 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	8/21/2020/ 8:17 am	
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/21/2020/ 8:19 am	
	Overflowed				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	8/21/2020/ 8:23 am	
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200821-0001

Work Order Detail Report

8/26/2020

SSO INSPECTION 8-16-2020 0.32 INCHES OF RAIN

1:26 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/> Sound	8/21/2020/ 8:25 am
No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/> Sound	8/21/2020/ 8:25 am
No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/> Sound	8/21/2020/ 8:30 am
No overflow			
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	<input type="checkbox"/> Sound	8/21/2020/ 8:32 am
Overflowed			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/> Sound	8/21/2020/ 8:40 am
No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/> Sound	8/21/2020/ 8:43 am
No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/> Sound	8/21/2020/ 8:43 am
No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/> Sound	8/21/2020/ 8:45 am
No overflow			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/> Sound	8/21/2020/ 8:46 am
No overflow			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/> Sound	8/21/2020/ 8:47 am
Overflowed			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/> Sound	8/21/2020/ 8:55 am
No overflow			
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/> Sound	8/21/2020/ 8:57 am
No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/> Sound	8/21/2020/ 9:00 am
No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/> Sound	8/21/2020/ 9:05 am
No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/> Sound	8/21/2020/ 9:11 am
No overflow			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/> Sound	8/21/2020/ 9:20 am
Overflowed			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/> Sound	8/21/2020/ 9:25 am
No overflow			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/> Sound	8/21/2020/ 9:28 am
No overflow			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/> Sound	8/21/2020/ 9:32 am
No overflow			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/> Sound	8/21/2020/ 9:35 am
Overflowed			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/> Sound	8/21/2020/ 9:37 am
No overflow			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200821-0001

Work Order Detail Report

8/26/2020

SSO INSPECTION 8-16-2020 0.32 INCHES OF RAIN

1:26 PM

40	C-59 3427 THORNE RD SA16AQJD0	<input type="checkbox"/>	Sound	8/21/2020/ 9:45 am
No overflow				
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	8/21/2020/ 9:45 am
Overflowed				
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	8/21/2020/ 9:50 am
No overflow				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	8/21/2020/ 9:55 am
No overflow				
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	8/21/2020/10:05 am
No overflow				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	8/21/2020/10:10 am
No overflow				

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC: \$10.99	*Task Cost: \$494.64	Start Dt:	
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	8.00	\$181.12			
9512 DelZoppo, Michael	Hours	8.00	\$172.32			
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB	Hours	8.00	\$141.20			
9						

Task Comment: SSO INSPECTION 0.32 INCHES OF RAIN.

		Lock: <input type="checkbox"/>		*Actual	*Estimated	*Difference
Projected Complete:			WO Duration	0.00	0.00	0.00
Repair Type:			Labor Hours	16.00	0.00	0.00
Subcontractor:			Labor Costs	\$353.44	\$0.00	\$0.00
Profit Center:			Material Costs	0.00	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each		Equipment Costs	141.20	0.00	0.00
*Unit Cost:	\$0.00		Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00		Misc. Costs	0.00	0.00	0.00
			Total Costs	\$494.64	\$0.00	\$0.00
			Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data		*Billing Amount:	Billing Required: <input type="checkbox"/>	
Contact Name:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>	
Invoice Number:		Payment Received:	Imported to Financials: <input type="checkbox"/>	
Incoming Account #:		Payment Method:		

Work Order Detail Report

8/26/2020

SSO INSPECTION 8-16-2020 0.32 INCHES OF RAIN

1:26 PM

Associated PMs		PM Code and Description	Closed	
Item	Tracking	Description	By	Date
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	aferrone	8/21/2020
Supervisor Notification		Email Queued Successfully!	aferrone	8/21/2020
Email Successfully Sent		jackson@clvhts.com Lucity Work Order Update - Supervisor	BackgroundTaskUser	8/21/2020
Status Change		From New Work Order to Complete	aferrone	8/26/2020
Rates:		Opened At:		Televised: <input type="checkbox"/>
Received By:		Pipe Footage Cleaned,		Power Rooter: <input type="checkbox"/>
Work From:		Gallons Used:		Jet: <input type="checkbox"/>
Pipe Size:		WO User 23:		Gap Vac: <input type="checkbox"/>
Pipe Condition:		WO User 24:		Dye Test: <input type="checkbox"/>
Could Not Open:		WO User 9:		Gap Root Cut: <input type="checkbox"/>
Additional Repair:		User 10:		GIS Correction?: <input type="checkbox"/>
Dye Test Reason:		Appointment Date DNL		WO User 30: <input type="checkbox"/>
Test Performed Through:		Appointment Date:		
Dye Test Results:		E Mail:		
WO User 51:		WO User 22:		
Measurement:		Pipe Size:		
History:		PVC Tees, Angles, Sles		
Manhole Basin Repair:		WO User 44:		
Material Used:		WO User 45:		
Pipe Repair:		WO User 46:		
Street Repair:				
Grass Repair:				
Curb Repair:				
Driveway- Sidewalk Re				
Construction Crew:				
WO User 39:		OUPS #:		
WO User 40:		WO User 48:		
WO User 41:				
WO User 52:		WO User 62:		
WO User 53:		WO User 63:		
WO User 54:		WO User 64:		
WO User 55:		WO User 65:		
WO User 56:		WO User 66:		
WO User 57:		WO User 67:		
WO User 58:		WO User 68:		
WO User 59:		WO User 69:		
WO User 60:		WO User 70:		
WO User 61:		WO User 71:		
WO User 72:		WO User 82:		Televised: <input type="checkbox"/>
WO User 73:		Quantity:		Paid: <input type="checkbox"/>
WO User 74:		WO User 84:		WO User 104: <input type="checkbox"/>
WO User 75:		WO User 85:		WO User 105: <input type="checkbox"/>
WO User 76:		WO User 86:		WO User 106: <input type="checkbox"/>
WO User 92 Date:		WO User 97 Date:		
WO User 93 Date:		WO User 98 Date:		
WO User 94 Date:		WO User 99 Date:		
WO User 95 Date:		WO User 100 Date:		
WO User 96 Date:		WO User 101 Date:		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200821-0001

Work Order Detail Report

8/26/2020

SSO INSPECTION 8-16-2020 0.32 INCHES OF RAIN

1:26 PM


WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: aferrone	WO Creation Date: 8/21/2020	PM Trigger:	Rec #: 5776



Daily Precipitation Report

Friday, August 28, 2020

Accumulation in Inches



Northeast Ohio Regional Sewer District
Daily Precipitation Report
Friday, August 28, 2020

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	5-Minute
Beachwood	1.70	1.17	0.96	0.64	0.38
Brecksville	2.66	1.75	1.74	1.07	0.63
Brook Park	4.39	2.93	2.92	2.20	0.97
Cleveland Industrial Pkwy	2.62	1.32	1.30	0.79	0.47
Dille Ave PS	1.93	1.17	1.17	0.93	0.62
Division Ave PS	1.73	0.99	0.99	0.51	0.37
Easterly WWTP	1.55	1.00	0.81	0.56	0.29
Independence	3.76	2.71	2.70	2.03	0.66
James Rhodes HS	2.59	1.55	1.54	1.08	0.73
Jennings PS	3.18	1.87	1.87	1.32	1.04
Macedonia	3.59	2.10	2.10	1.46	0.67
Maple Heights	3.17	2.30	2.22	1.58	0.59
Mary Street PS	1.72	1.01	1.01	0.74	0.46
Mayfield Heights	2.00	1.63	1.47	1.20	0.82
Moreland Hills	3.26	2.06	1.91	1.10	0.59
North Olmsted	2.66	1.83	1.61	1.30	0.70
North Royalton	2.07	1.46	1.05	0.78	0.66
Oakwood	3.68	2.67	2.64	2.06	0.79
Olmsted Falls	3.61	2.23	2.18	1.39	0.56
Parma	3.96	2.60	2.59	1.73	0.54
Richfield	1.09	0.83	0.58	0.26	0.24
Shaker Heights	2.16	1.13	1.12	0.83	0.65
South Euclid	2.10	1.61	1.36	1.04	0.80
Southerly WWTC	2.77	1.66	1.61	1.16	0.79
Strongsville C WWTP	2.88	1.77	1.73	1.01	0.40
Strongsville Foltz	n/a	n/a	n/a	n/a	n/a
University Heights	1.21	0.75	0.70	0.48	0.37
Wade Park	1.30	0.75	0.71	0.44	0.36
Westlake	3.25	2.09	1.93	1.65	1.12

Work Order Detail Report

8/31/2020

SSO INSPECTION 8-28-2020 1.21 INCHES OF RAIN

3:03 PM

WO Number:	200831-0001	Category:	SSOs		
Status:	Complete	Problem:	Storm Response		
Status Date:	8/31/2020 3:02 pm	Main Task:	Inspection		
Asset: SSO 431					
Location: FAIRFAX AT NORTH PARK					
Cause:	Weather				
Assigned Crew:					
Supervisor:	Jackson, Jeff	Assigned By:			
Lead Worker:	DelZoppo, Michael	Assigned Date:			
Priority:	High	Start Date:	8/31/2020 8:00 AM		
Account #:		End Date:	8/31/2020		
Proj No - Act:		Project ID:	<input checked="" type="checkbox"/> Override Notifications		
Project:		Project Name:	<input checked="" type="checkbox"/> Problem		
Reason:			<input checked="" type="checkbox"/> Overdue		
Received By:			<input checked="" type="checkbox"/> Lead Worker		
Inspected By:			<input checked="" type="checkbox"/> Task		
			<input checked="" type="checkbox"/> Supervisor		
			<input checked="" type="checkbox"/> Hard Lock WO		

Request Comments for Work Order

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department:	Sewer Collection
Division:	Sewer Collection
Sub-Division:	
Area:	
Sub-Area:	
Owner:	
Location:	
Classification:	

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook
	2,226,440.21168265	664,329.55524255	
	2,226,354.79813956	664,409.89202413	
	2,226,389.92077273	664,379.07548472	FAIRMOUNT AT DARTMOOR
	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
	2,223,969.26550905	664,532.08075613	FAIRMOUNT AT WELLINGTON
			DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

Work Order Detail Report

8/31/2020

SSO INSPECTION 8-28-2020 1.21 INCHES OF RAIN

3:03 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481	672,922.02624655	EAST OVERLOOK AT EDGEHILL
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	LEE RD. & SUPERIOR AVE.
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

8/31/2020

SSO INSPECTION 8-28-2020 1.21 INCHES OF RAIN

3:03 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

8/31/2020

SSO INSPECTION 8-28-2020 1.21 INCHES OF RAIN

3:03 PM

Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve						FAIRFAX AT NORTH PARK		
SSO 431							26	
Sewer Control Valve						NORTH PARK AND COVENTRY		
SSO 114							16	
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121							35	
Sewer Structure								
SA16AAW0							3094	
Sewer Control Valve						FAIRMOUNT AT FAIRFAX		
SSO 112							7	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99							6	
Sewer Control Valve						3012 NORTH WOODLAND		
SSO 432							14	
Sewer Control Valve								
DB-03							55	
Sewer Control Valve								
DB-01							56	
Sewer Control Valve								
DB-02							57	
Sewer Control Valve						FAIRMOUNT AT DARTMOOR		
CH-04							5	
Sewer Control Valve						FAIRMOUNT AT WELLINGTON		
SSO 110							44	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87							33	
Sewer Control Valve						FAIRMOUNT AT MARLBORO		
SSO 116							4	
Sewer Control Valve						FAIRMOUNT AT ARLINGTON		
SSO 111							46	
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113							37	
Sewer Control Valve						FAIRMOUNT AND COVENTRY		
SSO 124							47	
Sewer Control Valve						SCARBOROUGH AT LAMBERTON		
CH-50							53	
Sewer Control Valve						BRADFORD AND LEE		
SSO 129							11	
Sewer Control Valve						EDDINGTON		
CH-52							2	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88							42	
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL		
SSO 122							36	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89							34	
Sewer Structure								
SA16ADZ0							1536	
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91							20	
Sewer Structure								
SA16ADPH0							4446	
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120							8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200831-0001

Work Order Detail Report

8/31/2020

SSO INSPECTION 8-28-2020 1.21 INCHES OF RAIN

3:03 PM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQD0	4987
Sewer Structure SA16AQCO	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

8/31/2020

SSO INSPECTION 8-28-2020 1.21 INCHES OF RAIN

3:03 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	8/31/2020/ 7:27 am	
	Overflowed				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	8/31/2020/ 7:31 am	
	Overflowed				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	8/31/2020/ 7:33 am	
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	8/31/2020/ 7:35 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	8/31/2020/ 7:36 am	
	No overflow				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	8/31/2020/ 7:38 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	8/31/2020/ 7:40 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	8/31/2020/ 7:43 am	
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	8/31/2020/ 7:46 am	
	No overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	8/31/2020/ 7:49 am	
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	8/31/2020/ 7:50 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/31/2020/ 7:52 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	8/31/2020/ 7:53 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/31/2020/ 7:57 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/31/2020/ 7:58 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	8/31/2020/ 8:00 am	
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/31/2020/ 8:02 am	
	No overflow				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	8/31/2020/ 8:04 am	
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200831-0001

Work Order Detail Report

8/31/2020

SSO INSPECTION 8-28-2020 1.21 INCHES OF RAIN

3:03 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	8/31/2020/ 8:06 am
	No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	8/31/2020/ 8:09 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	8/31/2020/ 8:11 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/31/2020/ 8:13 am
	Overflowed			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	8/31/2020/ 8:24 am
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	8/31/2020/ 8:28 am
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	8/31/2020/ 8:29 am
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	8/31/2020/ 8:30 am
	No overflow			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	8/31/2020/ 8:31 am
	No overflow			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Sound	8/31/2020/ 8:33 am
	Overflowed			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	8/31/2020/ 8:41 am
	No overflow			
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	8/31/2020/ 8:44 am
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	8/31/2020/ 8:46 am
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	8/31/2020/ 8:49 am
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	8/31/2020/ 8:54 am
	No overflow			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	8/31/2020/ 8:58 pm
	Overflowed			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	8/31/2020/ 9:02 am
	No overflow			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	8/31/2020/ 9:03 am
	Overflowed			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	8/31/2020/ 9:05 am
	Overflowed			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	8/31/2020/ 9:08 am
	Overflowed			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	8/31/2020/ 9:09 am
	No overflow			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200831-0001

Work Order Detail Report

8/31/2020

SSO INSPECTION 8-28-2020 1.21 INCHES OF RAIN

3:03 PM

40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	8/31/2020/ 9:15 am
	No overflow			
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	8/31/2020/ 9:16 am
	No overflow			
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	8/31/2020/ 9:20 am
	No overflow			
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	8/31/2020/ 9:22 am
	No overflow			
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	8/31/2020/ 9:25 am
	No overflow			
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	8/31/2020/ 9:27 am
	Overflowed			

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC: \$6.21	*Task Cost: \$279.52	Start Dt: 8/31/2020	
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		8/31/2020	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD F250 PICK UP 0	Hours	8.00	\$107.20		8/31/2020	

Task Comment: SSO INSPECTION 1.21" OF RAIN

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	8.00	0.00	0.00
Subcontractor:		Labor Costs	\$172.32	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data				
Contact Name:		*Billing Amount:	Billing Required: <input type="checkbox"/>	
Invoice Number:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>	
Incoming Account #:		Payment Received:	Imported to Financials: <input type="checkbox"/>	
		Payment Method:		

Associated PMs	
PM Code and Description	Closed <input checked="" type="checkbox"/>

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200831-0001

Work Order Detail Report

8/31/2020

SSO INSPECTION 8-28-2020 1.21 INCHES OF RAIN

3:03 PM

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	8/31/2020	6:50 AM
Supervisor Notification	Email Queued Successfully!	jjackson	8/31/2020	6:50 AM
Email Successfully Sent	jjackson@clvhts.com Lucy City Work Order Update - Supervisor	BackgroundTaskUser	8/31/2020	7:01 AM
Status Change	From New Work Order to Missing Required Data	aferrone	8/31/2020	3:00 PM
Status Change	From Missing Required Data to Complete	aferrone	8/31/2020	3:02 PM

Rates:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	WO User 30:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 8/31/2020 7:30 AM		
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	WO User 22:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Slic		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		

Work Order Detail Report

8/31/2020

SSO INSPECTION 8-28-2020 1.21 INCHES OF RAIN

3:03 PM

WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 8/31/2020	PM Trigger:	Rec #: 5805