




Daily Precipitation Report Wednesday, September 2, 2020

Accumulation in Inches



Northeast Ohio Regional Sewer District**Daily Precipitation Report****Wednesday, September 2, 2020**

<u>Site Location</u>	<u>Peak Accumulation (inches)</u>					
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>	
					<u>5-Minute</u>	
Beachwood	0.82	0.70	0.52	0.35	0.19	0.10
Brecksville	0.29	0.27	0.23	0.16	0.11	0.06
Brook Park	0.39	0.36	0.34	0.27	0.20	0.13
Cleveland Industrial Pkwy	0.45	0.42	0.31	0.22	0.11	0.08
Dill Ave PS	0.45	0.42	0.35	0.33	0.17	0.07
Division Ave PS	0.27	0.23	0.21	0.20	0.12	0.06
Easterly WWTP	0.11	0.08	0.08	0.06	0.06	0.03
Independence	0.10	0.10	0.06	0.03	0.03	0.02
James Rhodes HS	0.49	0.48	0.38	0.30	0.13	0.08
Jennings PS	0.61	0.58	0.50	0.36	0.15	0.11
Macedonia	0.38	0.37	0.34	0.30	0.13	0.07
Maple Heights	0.22	0.19	0.11	0.09	0.08	0.05
Mary Street PS	0.43	0.39	0.32	0.31	0.16	0.08
Mayfield Heights	0.73	0.67	0.63	0.59	0.26	0.15
Moreland Hills	0.15	0.14	0.09	0.07	0.05	0.02
North Olmsted	0.42	0.39	0.34	0.32	0.18	0.12
North Royalton	0.23	0.21	0.19	0.13	0.10	0.04
Oakwood	0.22	0.19	0.16	0.13	0.07	0.04
Olmsted Falls	0.32	0.30	0.27	0.21	0.21	0.19
Parma	0.26	0.25	0.20	0.11	0.09	0.08
Richfield	1.16	1.16	1.09	0.98	0.46	0.21
Shaker Heights	0.57	0.44	0.31	0.22	0.10	0.06
South Euclid	0.38	0.32	0.27	0.26	0.14	0.08
Southerly WWTC	0.35	0.32	0.23	0.18	0.15	0.09
Strongsville C WWTP	0.20	0.19	0.18	0.09	0.09	0.08
Strongsville Foltz	0.16	0.14	0.08	0.05	0.04	0.03
University Heights	0.69	0.64	0.53	0.46	0.18	0.08
Wade Park	0.35	0.31	0.29	0.28	0.17	0.09
Westlake	0.20	0.18	0.18	0.11	0.10	0.06

Work Order Detail Report

9/9/2020

SSO INSPECTIONS 9-2-2020 0.69 INCHES OF RAIN

4:50 PM

WO Number:	200909-0006	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	9/9/2020 4:49 pm	Main Task:	Inspection
Asset: SSO 431			
Location: FAIRFAX AT NORTH PARK			
Cause:	Weather	Assigned By:	29960 Jackson, Jeff
Assigned Crew:		Assigned Date:	9/2/2020
Supervisor:	Jackson, Jeff	Start Date:	9/4/2020 7:57 AM
Lead Worker:	Eathridge, David	End Date:	9/4/2020 2:57 PM
Priority:	High		<u>Override Notifications</u>
Account #:			Problem <input type="checkbox"/>
Proj No + Acct:		Project ID:	Overdue <input type="checkbox"/>
Project:		Project Name:	Lead Worker <input type="checkbox"/>
Reason:			Task <input type="checkbox"/>
Received By:			Supervisor <input type="checkbox"/>
Inspected By:			Hard Lock WO <input type="checkbox"/>

Request Comments for Work Order

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department:	Sewer Collection
Division:	Sewer Collection
Sub-Division:	
Area:	
Sub-Area:	
Owner:	
Location:	
Classification:	

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK			
2,220,655,65435414	665,517,24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873,16674590	666,048,82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364,86097248	666,446,72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920,81917815	666,080,57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053,81655256	664,693,25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845,06631389	664,689,08536339		Doan Brook
2,226,440,21168265	664,329,55524255		
2,226,354,79813956	664,409,89202413		
2,226,389,92077273	664,379,07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149,97508989	664,453,31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969,26550905	664,532,08075613		DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200909-0006

Work Order Detail Report

9/9/2020

SSO INSPECTIONS 9-2-2020 0.69 INCHES OF RAIN

4:50 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

9/9/2020

SSO INSPECTIONS 9-2-2020 0.69 INCHES OF RAIN

4:50 PM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

9/9/2020

SSO INSPECTIONS 9-2-2020 0.69 INCHES OF RAIN

4:50 PM

Work Order Assets							
<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>PM Description</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve				FAIRFAX AT NORTH PARK			
SSO 431						26	
Sewer Control Valve				NORTH PARK AND COVENTRY			
SSO 114						16	
Sewer Control Valve				FAIRMOUNT SOUTH OF SCARBOROUGH			
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve				FAIRMOUNT AT FAIRFAX			
SSO 112						7	
Sewer Control Valve				FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
SSO 99						6	
Sewer Control Valve				3012 NORTH WOODLAND			
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve				FAIRMOUNT AT DARTMOOR			
CH-04						5	
Sewer Control Valve				FAIRMOUNT AT WELLINGTON			
SSO 110						44	
Sewer Control Valve				FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
SSO 87						33	
Sewer Control Valve				FAIRMOUNT AT MARLBORO			
SSO 116						4	
Sewer Control Valve				FAIRMOUNT AT ARLINGTON			
SSO 111						46	
Sewer Control Valve				FAIRMOUNT & COVENTRY (SCARBOROUGH)			
SSO 113						37	
Sewer Control Valve				FAIRMOUNT AND COVENTRY			
SSO 124						47	
Sewer Control Valve				SCARBOROUGH AT LAMBERTON			
CH-50						53	
Sewer Control Valve				BRADFORD AND LEE			
SSO 129						11	
Sewer Control Valve				EDDINGTON			
CH-52						2	
Sewer Control Valve				HAMPSHIRE LANE AT MAYFIELD (18")			
SSO 88						42	
Sewer Control Valve				EAST OVERLOOK AT EDGEHILL			
SSO 122						36	
Sewer Control Valve				HAMPSHIRE LANE AT MAYFIELD (36")			
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve				HAMPSHIRE AT EUCLID HTS. BLVD.			
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve				CEDAR BTW. FAIRMOUNT/DEMINGTON			
SSO 120						8	
Sewer Control Valve				2828 BERKSHIRE, EAST OF COVENTRY			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200909-0006

Work Order Detail Report

9/9/2020

SSO INSPECTIONS 9-2-2020 0.69 INCHES OF RAIN

4:50 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQCO	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

9/9/2020

SSO INSPECTIONS 9-2-2020 0.69 INCHES OF RAIN

4:50 PM

Check List		<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	9/4/2020/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	9/4/2020/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	9/4/2020/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	9/4/2020/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/4/2020/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	9/4/2020/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	9/4/2020/	
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	9/4/2020/	
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/4/2020/	
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	9/4/2020/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	9/4/2020/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/4/2020/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	9/4/2020/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/4/2020/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/4/2020/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	9/4/2020/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/4/2020/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/4/2020/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/4/2020/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	9/4/2020/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	9/4/2020/	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/4/2020/	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	9/4/2020/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	9/4/2020/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	9/4/2020/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	9/4/2020/	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	9/4/2020/	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200909-0006

Work Order Detail Report

9/9/2020

SSO INSPECTIONS 9-2-2020 0.69 INCHES OF RAIN

4:50 PM

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	9/4/2020/
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	9/4/2020/
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	9/4/2020/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	9/4/2020/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	9/4/2020/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	9/4/2020/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	9/4/2020/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Not Sound	9/4/2020/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	9/4/2020/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	9/4/2020/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	9/4/2020/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	9/4/2020/
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	9/4/2020/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	9/4/2020/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	9/4/2020/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	9/4/2020/
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	9/4/2020/
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	9/4/2020/

Tasks/Resources						
SWCT26 Inspection						
Crew: Supervisor: Jackson, Jeff	Status: Complete	UOM: Each	*Cal'c UC: \$10.73 # of Units: 45.00	*Task Cost: \$482.80 *Unit Cost: \$0.00	Start Dt: 9/4/2020	End Dt: 9/4/2020
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	8.00	\$181.12		9/4/2020	9/4/2020
27146 Corbo, Joe	Hours	8.00	\$160.48		9/4/2020	9/4/2020
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CAB AND 8 CHASSIS	Hours	8.00	\$141.20		9/4/2020	9/4/2020
Task Comment: SSO INSPECTION 0.69 INCHES OF RAIN						

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	7.00	0.00	0.00
Subcontractor:		Labor Costs	16.00	0.00	0.00
Profit Center:		Material Costs	\$341.60	\$0.00	\$0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$482.80	\$0.00	\$0.00
		Use Task Info:	True	True	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200909-0006

Work Order Detail Report

9/9/2020

SSO INSPECTIONS 9-2-2020 0.69 INCHES OF RAIN

4:50 PM

Billing				
Billed Party				
Customer ID:	Customer Number:			
Customer Name:	Last Name:			
Address:	Phone:			
City:	Cell #:			
State:	Fax #:			
Zip:	E-mail:			
Billing Data				
Contact Name:	*Billing Amount:	Billing Required: <input type="checkbox"/>		
Invoice Number:	Date Bill Sent:	Billing Processed: <input type="checkbox"/>		
Incoming Account #:	Payment Received:	Imported to Financials: <input type="checkbox"/>		
Payment Method:				
Associated PMs				
PM Code and Description		Closed		
SSO-02 SSO INSPECTION		<input checked="" type="checkbox"/>		
Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aferrone	9/9/2020	4:37 PM
Supervisor Notification	Email Queued Successfully!	aferrone	9/9/2020	4:37 PM
Email Successfully Sent	jackson@clvhts.com Lucy Work Order Update - Supervisor	BackgroundTaskUser	9/9/2020	4:38 PM
Status Change	From New Work Order to Complete	aferrone	9/9/2020	4:49 PM
Rates:	Opened At:	Televised: <input type="checkbox"/>		
Received By:	Pipe Footage Cleaned.	Power Rooter: <input type="checkbox"/>		
Work From:	Gallons Used:	Jet: <input type="checkbox"/>		
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>		
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>		
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>		
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>		
Dye Test Reason:	Appointment Date DNL	WO User 30: <input type="checkbox"/>		
Test Performed Through:	Appointment Date:			
Dye Test Results:				
WO User 51:				
Measurement:	E Mail:			
History:	WO User 22:			
Manhole Basin Repair:	Pipe Size:			
Material Used:	PVC Tees, Angles, Sles			
Pipe Repair:	WO User 44:			
Street Repair:	WO User 45:			
Grass Repair:	WO User 46:			
Curb Repair:				
Driveway- Sidewalk Re:				
Construction Crew:				
WO User 39:	OUPS #:			
WO User 40:	WO User 48:			
WO User 41:				

Work Order Detail Report

9/9/2020

SSO INSPECTIONS 9-2-2020 0.69 INCHES OF RAIN

4:50 PM

WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	Quantity:	Paid: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>

WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>


WO Creator: aferrone WO Creation Date: 9/9/2020 PM Trigger: Rec #: 5836



Daily Precipitation Report

Monday, September 7, 2020

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report
Monday, September 7, 2020

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	3.80	3.78	2.82	1.47	0.58
Brecksville	4.39	4.17	2.30	1.69	0.67
Brook Park	3.95	3.60	2.10	1.51	0.78
Cleveland Industrial Pkwy	3.95	3.53	2.25	1.34	0.48
Dillie Ave PS	3.81	3.70	2.51	1.46	0.81
Division Ave PS	3.47	3.36	2.34	1.50	0.79
Easterly WWTP	2.02	2.02	1.50	0.76	0.45
Independence	3.63	3.33	2.04	1.24	0.50
Janes Rhodes HS	3.67	3.35	2.24	1.18	0.50
Jennings PS	4.55	4.38	3.01	1.32	0.54
Macedonia	3.05	2.92	1.75	1.23	0.45
Maple Heights	3.74	3.55	2.65	1.36	0.65
Mary Street PS	3.72	3.61	2.50	1.46	0.80
Mayfield Heights	2.61	2.58	1.86	0.86	0.39
Moreland Hills	3.60	3.53	2.87	1.32	0.53
North Olmsted	3.52	3.21	1.73	1.14	0.54
North Royalton	4.46	4.16	2.16	1.53	0.56
Oakwood	4.34	4.09	2.63	1.40	0.64
Olmsted Falls	3.40	2.97	1.72	1.12	0.64
Parma	3.19	2.93	1.78	1.09	0.41
Richfield	3.60	3.46	2.04	1.13	0.45
Shaker Heights	4.02	3.91	2.95	1.48	0.52
South Euclid	2.55	2.53	1.70	0.81	0.34
Southerly WWTP	3.46	3.25	2.28	1.12	0.50
Strongsville C WWTP	4.07	3.67	2.12	1.42	0.48
Strongsville Foltz	n/a	n/a	n/a	n/a	n/a
University Heights	3.59	3.56	2.52	1.22	0.63
Wade Park	3.25	3.21	2.25	0.95	0.47
Westlake	3.45	3.08	1.75	0.94	0.52

Work Order Detail Report

SSO INSPECTION 9-7-2020 3.59 INCHES OF RAIN

9/9/2020

4:35 PM

WO Number:	200909-0003	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	9/9/2020 4:34 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	9/9/2020 8:00 AM
Lead Worker:	DelZoppo, Michael	End Date:	9/9/2020
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No + Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection

Comments for Crew
Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

Work Order Detail Report

9/9/2020

SSO INSPECTION 9-7-2020 3.59 INCHES OF RAIN

4:35 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

9/9/2020

SSO INSPECTION 9-7-2020 3.59 INCHES OF RAIN

4:35 PM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

SSO INSPECTION 9-7-2020 3.59 INCHES OF RAIN

9/9/2020

4:35 PM

Work Order Assets								
Object Type	System ID 1	System ID 2	Description 1	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve	SSO 431					FAIRFAX AT NORTH PARK		
Sewer Control Valve	SSO 114					NORTH PARK AND COVENTRY	26	
Sewer Control Valve	SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH	35	
Sewer Structure	SA16AAWBO						3094	
Sewer Control Valve	SSO 112					FAIRMOUNT AT FAIRFAX	7	
Sewer Control Valve	SSO 99					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6	
Sewer Control Valve	SSO 432					3012 NORTH WOODLAND	14	
Sewer Control Valve	DB-03						55	
Sewer Control Valve	DB-01						56	
Sewer Control Valve	DB-02						57	
Sewer Control Valve	CH-04					FAIRMOUNT AT DARTMOOR	5	
Sewer Control Valve	SSO 110					FAIRMOUNT AT WELLINGTON	44	
Sewer Control Valve	SSO 87					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33	
Sewer Control Valve	SSO 116					FAIRMOUNT AT MARLBORO	4	
Sewer Control Valve	SSO 111					FAIRMOUNT AT ARLINGTON	46	
Sewer Control Valve	SSO 113					FAIRMOUNT & COVENTRY (SCARBOROUGH)	37	
Sewer Control Valve	SSO 124					FAIRMOUNT AND COVENTRY	47	
Sewer Control Valve	CH-50					SCARBOROUGH AT LAMBERTON	53	
Sewer Control Valve	SSO 129					BRADFORD AND LEE	11	
Sewer Control Valve	CH-52					EDDINGTON	2	
Sewer Control Valve	SSO 88					HAMPSHIRE LANE AT MAYFIELD (18")	42	
Sewer Control Valve	SSO 122					EAST OVERLOOK AT EDGEHILL	36	
Sewer Control Valve	SSO 89					HAMPSHIRE LANE AT MAYFIELD (36")	34	
Sewer Structure	SA16ADZB0						1536	
Sewer Control Valve	SSO 91					HAMPSHIRE AT EUCLID HTS. BLVD.	20	
Sewer Structure	SA16ADPH0						4446	
Sewer Control Valve	SSO 120					CEDAR BTW. FAIRMOUNT/DEMINGTON	8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200909-0003

Work Order Detail Report

9/9/2020

SSO INSPECTION 9-7-2020 3.59 INCHES OF RAIN

4:35 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

9/9/2020

SSO INSPECTION 9-7-2020 3.59 INCHES OF RAIN

4:35 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
	<u>Item</u>				
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	9/9/2020/ 8:05 am	
	Overflowed				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	9/9/2020/ 8:08 am	
	Overflowed				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	9/9/2020/ 8:10 am	
	Overflowed				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	9/9/2020/ 8:14 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/9/2020/ 8:16 am	
	Overflowed				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	9/9/2020/ 8:19 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	9/9/2020/ 8:22 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	9/9/2020/ 8:26 am	
	Overflowed				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/9/2020/ 8:30 am	
	No overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	9/9/2020/ 8:32 am	
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	9/9/2020/ 8:34 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/9/2020/ 8:36 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	9/9/2020/ 8:38 am	
	Overflowed				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/9/2020/ 8:41 am	
	Overflowed				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/9/2020/ 8:43 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	9/9/2020/ 8:45 am	
	Overflowed				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/9/2020/ 8:48 am	
	Overflowed				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/9/2020/ 8:50 am	
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200909-0003

Work Order Detail Report

9/9/2020

SSO INSPECTION 9-7-2020 3.59 INCHES OF RAIN

4:35 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/9/2020/ 8:53 am
	Overflowed			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	9/9/2020/ 8:57 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	9/9/2020/ 8:59 am
	No			
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	<input type="checkbox"/>	Sound	9/9/2020/ 9:01 am
	Overflowed			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	9/9/2020/ 9:13 am
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	9/9/2020/ 9:16 am
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	9/9/2020/ 9:17 am
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	9/9/2020/ 9:19 am
	Overflowed			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	9/9/2020/ 9:20 am
	No overflow			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	9/9/2020/ 9:23 am
	Overflowed			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	9/9/2020/ 9:30 am
	Overflowed			
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	9/9/2020/ 9:34 am
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	9/9/2020/ 9:36 am
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	9/9/2020/ 9:39 am
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	9/9/2020/ 9:44 am
	No overflow			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	9/9/2020/ 9:49 am
	Overflowed. Block stuck in pipe. Can't reset. Needs jetted.			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	9/9/2020/ 9:52 am
	Overflowed			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	9/9/2020/ 9:55 am
	Overflowed			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	9/9/2020/ 9:57 am
	Overflowed			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	9/9/2020/ 9:59 am
	Overflowed			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	9/9/2020/10:00 am
	Overflowed			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200909-0003

Work Order Detail Report

9/9/2020

SSO INSPECTION 9-7-2020 3.59 INCHES OF RAIN

4:35 PM

40	C-59 3427 THORNE RD SA16AQJD0	<input type="checkbox"/>	Sound	9/9/2020/10:05 am
	No overflow			
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	9/9/2020/10:07 am
	No overflow			
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	9/9/2020/10:11 am
	No overflow			
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	9/9/2020/10:15 am
	Rope and block missing. Replaced both.			
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	9/9/2020/10:17 am
	Overflowed			
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	9/9/2020/10:20 am
	No overflow			

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC: \$6.21	*Task Cost: \$279.52	Start Dt:	9/9/2020
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		9/9/2020	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT93 FORD F250 4 X 4 PICK UP	Hours	8.00	\$107.20		9/9/2020	
1						
Task Comment: SSO INSPECTION 3.59" OF RAIN						

Projected Complete:	Lock: <input type="checkbox"/>	*Actual	*Estimated	*Difference
Repair Type:		WO Duration	0.00	0.00
Subcontractor:		Labor Hours	8.00	0.00
Profit Center:		Labor Costs	\$172.32	\$0.00
Quantity:	0.00	Material Costs	0.00	0.00
Unit of Measure:	Each	Fluids Costs	0.00	0.00
*Unit Cost:	\$0.00	Equipment Costs	107.20	0.00
WO Hours:	0.00	Contractor Costs	0.00	0.00
		Misc. Costs	0.00	0.00
		Total Costs	\$279.52	\$0.00
		Use Task Info:	True	True

Billing			
Billed Party			
Customer ID:	Customer Number:		
Customer Name:	Last Name:		
Address:	Phone:	Cell #:	
City:	Fax #:		
State:	E-mail:		
Zip:			
Billing Data			
Contact Name:	*Billing Amount:	Billing Required: <input type="checkbox"/>	
Invoice Number:	Date Bill Sent:	Billing Processed: <input type="checkbox"/>	
Incoming Account #:	Payment Received:	Imported to Financials: <input type="checkbox"/>	
	Payment Method:		

Associated PMs	
PM Code and Description	Closed <input checked="" type="checkbox"/>
SSO-02 SSO INSPECTION	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200909-0003

Work Order Detail Report

9/9/2020

SSO INSPECTION 9-7-2020 3.59 INCHES OF RAIN

4:35 PM

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	9/9/2020	7:32 AM
Supervisor Notification	Email Queued Successfully!	jjackson	9/9/2020	7:32 AM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order Update - Supervisor	BackgroundTaskUser	9/9/2020	7:33 AM
Status Change	From New Work Order to Complete	aferrone	9/9/2020	4:34 PM

Rates:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned,	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	WO User 30:	<input type="checkbox"/>
Test Performed Through:	Appointment Date:		
Dye Test Results:			
WO User 51:	E Mail:		
Measurement:	WO User 22:		
History:			
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sled		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Repair:			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		

Work Order Detail Report

9/9/2020

SSO INSPECTION 9-7-2020 3.59 INCHES OF RAIN

4:35 PM

WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 9/9/2020	PM Trigger:	Rec #: 5833



Daily Precipitation Report

Sunday, September 13, 2020

Accumulation in Inches

L a k e E r i e

L a k e C o u n t y

Easterly
WWTP

0.21

South
Euclid

0.52

Mayfield
Heights

0.45

University
Heights

0.45

Wade
Park

0.41

Division PS

0.34

Dille PS

0.34

Mary
Street PS

0.44

0.49

Westlake

0.29

Jennings PS

0.33

James
Rhodes HS

0.31

Cleveland
Industrial Pkwy

0.22

North
Olmsted

0.30

Brook Park

0.23

Parma

0.14

Independence

0.27

Maple
Heights

0.32

Moreland
Hills

0.47

Beachwood

0.52

Shaker
Heights

0.49

University
Heights

0.45

South
Euclid

0.52

Mayfield
Heights

0.45

Wade
Park

0.41

Division PS

0.34

Dille PS

0.34

Mary
Street PS

0.44

Jennings PS

0.33

James
Rhodes HS

0.31

Cleveland
Industrial Pkwy

0.22

Brook Park

0.23

Parma

0.14

Independence

0.27

Strongsville
"C" WWTP

0.17

Olmsted
Falls

0.24

Strongsville
Foltz

0.21

Brook Park

0.23

Parma

0.14

Independence

0.27

Maple
Heights

0.32

Moreland
Hills

0.47

Beachwood

0.52

Shaker
Heights

0.49

University
Heights

0.45

South
Euclid

0.52

Mayfield
Heights

0.45

Wade
Park

0.41

Division PS

0.34

Dille PS

0.34

Mary
Street PS

0.44

Jennings PS

0.33

James
Rhodes HS

0.31

Strongsville
Foltz

0.21

Olmsted
Falls

0.24

Strongsville
"C" WWTP

0.17

Brook Park

0.23

Parma

0.14

Independence

0.27

Maple
Heights

0.32

Moreland
Hills

0.47

Beachwood

0.52

Shaker
Heights

0.49

University
Heights

0.45

South
Euclid

0.52

Mayfield
Heights

0.45

Wade
Park

0.41

Division PS

0.34

Dille PS

0.34

Mary
Street PS

0.44

Jennings PS

0.33

James
Rhodes HS

0.31

Cuyahoga
County

0.37

Macdonia

0.12

Brecksville

0.32

North
Royalton

0.28

Strongsville
Foltz

0.21

Olmsted
Falls

0.24

Strongsville
"C" WWTP

0.17

Brook Park

0.23

Parma

0.14

Independence

0.27

Maple
Heights

0.32

Moreland
Hills

0.47

Beachwood

0.52

Shaker
Heights

0.49

University
Heights

0.45

South
Euclid

0.52

Mayfield
Heights

0.45

Wade
Park

0.41

Division PS

0.34

Dille PS

0.34

Mary
Street PS

0.44

Jennings PS

0.33

James
Rhodes HS

0.31

Cuyahoga
County

0.37

Macdonia

0.12

Brecksville

0.32

North
Royalton

0.28

Strongsville
Foltz

0.21

Olmsted
Falls

0.24

Strongsville
"C" WWTP

0.17

Brook Park

0.23

Parma

0.14

Independence

0.27

Maple
Heights

0.32

Moreland
Hills

0.47

Beachwood

0.52

Shaker
Heights

0.49

University
Heights

0.45

South
Euclid

0.52

Mayfield
Heights

0.45

Wade
Park

0.41

Division PS

0.34

Dille PS

0.34

Mary
Street PS

0.44

Jennings PS

0.33

James
Rhodes HS

0.31

Cuyahoga
County

0.37

Macdonia

0.12

Brecksville

0.32

North
Royalton

0.28

Strongsville
Foltz

0.21

Olmsted
Falls

0.24

Strongsville
"C" WWTP

0.17

Brook Park

0.23

Parma

0.14

Independence

0.27

Maple
Heights

0.32

Moreland
Hills

0.47

Beachwood

0.52

Shaker
Heights

0.49

University
Heights

0.45

South
Euclid

0.52

Mayfield
Heights

0.45

Wade
Park

0.41

Division PS

0.34

Dille PS

0.34

Mary
Street PS

0.44

Jennings PS

0.33

James
Rhodes HS

0.31

Cuyahoga
County

0.37

Macdonia

0.12

Brecksville

0.32

North
Royalton

0.28

Strongsville
Foltz

0.21

Olmsted
Falls

0.24

Strongsville
"C" WWTP

</div

Northeast Ohio Regional Sewer District

Daily Precipitation Report
Sunday, September 13, 2020

<u>Site Location</u>	<u>Peak Accumulation (Inches)</u>				
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>
Beachwood	0.52	0.52	0.52	0.52	0.26
Brecksville	0.32	0.32	0.32	0.30	0.18
Brook Park	0.23	0.23	0.23	0.21	0.10
Cleveland Industrial Pkwy	0.22	0.22	0.22	0.21	0.12
Dillie Ave PS	0.34	0.34	0.34	0.33	0.18
Division Ave PS	0.34	0.34	0.34	0.33	0.17
Easterly WWTP	0.21	0.21	0.21	0.21	0.19
Independence	0.27	0.27	0.27	0.24	0.15
James Rhodes HS	0.31	0.31	0.30	0.30	0.15
Jennings PS	0.33	0.33	0.33	0.33	0.17
Macedonia	0.12	0.12	0.12	0.11	0.07
Maple Heights	0.32	0.32	0.32	0.32	0.17
May Street PS	0.41	0.43	0.43	0.36	0.17
Mayfield Heights	0.45	0.45	0.45	0.45	0.23
Moreland Hills	0.47	0.47	0.47	0.45	0.25
North Olmsted	0.30	0.30	0.30	0.27	0.22
North Royalton	0.28	0.28	0.28	0.24	0.12
Oakwood	0.37	0.37	0.37	0.34	0.22
Olmsted Falls	0.24	0.24	0.24	0.20	0.08
Parma	0.14	0.14	0.14	0.14	0.08
Richfield	0.09	0.09	0.09	0.09	0.05
Shaker Heights	0.49	0.49	0.49	0.49	0.24
South Euclid	0.52	0.52	0.52	0.47	0.26
Southerly WWTC	0.50	0.50	0.50	0.49	0.26
Strongsville C WWTP	0.17	0.17	0.17	0.16	0.09
Strongsville Foltz	0.21	0.21	0.21	0.19	0.10
University Heights	0.45	0.45	0.45	0.44	0.21
Wade Park	0.41	0.41	0.41	0.37	0.17
Westlake	0.29	0.29	0.29	0.28	0.23

Work Order Detail Report

9/16/2020

SSO INSPECTION 9-13-2020 0.48 INCHES OF RAIN

3:38 PM

WO Number:	200915-0003	Category:	SSOs			
Status:	Complete	Problem:	Storm Response			
Status Date:	9/16/2020 3:36 pm	Main Task:	Inspection			
Asset:	SSO 431					
Location:	FAIRFAX AT NORTH PARK					
Cause:	Weather					
Assigned Crew:						
Supervisor:	Jackson, Jeff	Start Date:	9/15/2020 8:00 AM			
Lead Worker:	DelZoppo, Michael	End Date:	9/15/2020			
Priority:	High	Assigned By:				
Account #:						
Proj No - Acct:						
Project:						
Reason:						
Received By:						
Inspected By:						
Request Comments for Work Order Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.						
Location Department: Sewer Collection Division: Sewer Collection Sub-Division: Area: Sub-Area: Owner: Location: Classification:						
Comments for Crew Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.						

Maintenance Zone: Alternate Zone:

Work Order Locations			Address 2
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200915-0003

Work Order Detail Report

9/16/2020

SSO INSPECTION 9-13-2020 0.48 INCHES OF RAIN

3:38 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

9/16/2020

SSO INSPECTION 9-13-2020 0.48 INCHES OF RAIN

3:38 PM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

9/16/2020

SSO INSPECTION 9-13-2020 0.48 INCHES OF RAIN

3:38 PM

Work Order Assets							
Object Type	System ID 1	System ID 2	Description 1	PM Description	Description 2	Asset ID	Completed
			Odometer	Hourmeter	Othermeter		
Sewer Control Valve						FAIRFAX AT NORTH PARK	
SSO 431						26	
Sewer Control Valve						NORTH PARK AND COVENTRY	
SSO 114						16	
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH	
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve						FAIRMOUNT AT FAIRFAX	
SSO 112						7	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
SSO 99						6	
Sewer Control Valve						3012 NORTH WOODLAND	
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve						FAIRMOUNT AT DARTMOOR	
CH-04						5	
Sewer Control Valve						FAIRMOUNT AT WELLINGTON	
SSO 110						44	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
SSO 87						33	
Sewer Control Valve						FAIRMOUNT AT MARLBORO	
SSO 116						4	
Sewer Control Valve						FAIRMOUNT AT ARLINGTON	
SSO 111						46	
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)	
SSO 113						37	
Sewer Control Valve						FAIRMOUNT AND COVENTRY	
SSO 124						47	
Sewer Control Valve						SCARBOROUGH AT LAMBERTON	
CH-50						53	
Sewer Control Valve						BRADFORD AND LEE	
SSO 129						11	
Sewer Control Valve						EDDINGTON	
CH-52						2	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")	
SSO 88						42	
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL	
SSO 122						36	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")	
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.	
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON	
SSO 120						8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200915-0003

Work Order Detail Report

9/16/2020

SSO INSPECTION 9-13-2020 0.48 INCHES OF RAIN

3:38 PM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

9/16/2020

SSO INSPECTION 9-13-2020 0.48 INCHES OF RAIN

3:38 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	9/15/2020/ 7:49 am	
No overflow					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	9/15/2020/ 7:52 am	
No overflow					
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	9/15/2020/ 7:54 am	
No overflow					
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	9/15/2020/ 7:56 am	
No overflow					
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/15/2020/ 7:57 am	
No overflow					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	9/15/2020/ 7:59 am	
Overflowed					
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	9/15/2020/ 8:02 am	
No overflow					
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	9/15/2020/ 8:05 am	
No overflow					
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/15/2020/ 8:07 am	
No overflow					
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	9/15/2020/ 8:08 am	
No overflow					
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	9/15/2020/ 8:10 am	
No overflow					
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/15/2020/ 8:12 am	
No overflow					
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	9/15/2020/ 8:14 am	
No overflow					
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/15/2020/ 8:17 am	
No overflow					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/15/2020/ 8:18 am	
No overflow					
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	9/15/2020/ 8:20 am	
No overflow					
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/15/2020/ 8:22 am	
Overflowed					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/15/2020/ 8:24 am	
No overflow					

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200915-0003

Work Order Detail Report

9/16/2020

SSO INSPECTION 9-13-2020 0.48 INCHES OF RAIN

3:38 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/15/2020/ 8:26 am
	No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	9/15/2020/ 8:28 am
	No no			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	9/15/2020/ 8:29 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/15/2020/ 8:31 am
	Overflowed			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	9/15/2020/ 8:42 am
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	9/15/2020/ 8:45 am
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	9/15/2020/ 8:46 am
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	9/15/2020/ 8:47 am
	No overflow			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	9/15/2020/ 8:48 am
	Overflowed			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Sound	9/15/2020/ 8:51 am
	No overflow			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	9/15/2020/ 8:56 am
	Overflowed			
30	B-15 COVENTRY AND CEDAR SA16ADB0	<input type="checkbox"/>	Sound	9/15/2020/ 8:57 am
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	9/15/2020/ 8:59 am
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	9/15/2020/ 9:02 am
	Overflowed			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	9/15/2020/ 9:10 am
	Overflowed. Block missing. Replaced.			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	9/15/2020/ 9:07 am
	Overflowed			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	9/15/2020/ 9:05 am
	Overflowed			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	9/15/2020/ 9:28 am
	No overflow			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	9/15/2020/ 9:29 am
	No overflow			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	9/15/2020/ 9:30 am
	No overflow			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	9/15/2020/ 9:31 am
	No overflow			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200915-0003

Work Order Detail Report

9/16/2020

SSO INSPECTION 9-13-2020 0.48 INCHES OF RAIN

3:38 PM

40	C-59 3427 THORNE RD SA16AQD0	<input type="checkbox"/>	Sound	9/15/2020/ 9:36 am
No overflow				
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	9/15/2020/ 9:37 am
No overflow				
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	9/15/2020/ 9:41 am
No overflow				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	9/15/2020/ 9:44 am
No overflow				
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	9/15/2020/ 9:47 am
Overflowed. Block missing. Replaced.				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	9/15/2020/ 9:55 am
No overflow				

Tasks/Resources						
SWCT26 Inspection						
Crew:		Status:		*Cal'c UC: \$6.21	*Task Cost: \$279.52	Start Dt: 9/15/2020
Supervisor:		UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:
Employee						
Resource		UOM	Units	*Total Cost	Alt Description	Start Dt
9512 DelZoppo, Michael		Hours	8.00	\$172.32		9/15/2020
Equipment						
Resource		UOM	Units	*Total Cost	Alt Description	Start Dt
CHFLT50 FORD F250 CREW CAB		Hours	8.00	\$107.20		9/15/2020
5						
Task Comment: SSO INSPECTIONS 0.45 INCHES OF RAIN						

Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:			Labor Hours	0.00	0.00	0.00
Subcontractor:			Labor Costs	\$172.32	\$0.00	\$0.00
Profit Center:			Material Costs	0.00	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each		Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00		Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00		Misc. Costs	0.00	0.00	0.00
			Total Costs	\$279.52	\$0.00	\$0.00
			Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data		*Billing Amount:	Billing Required: <input type="checkbox"/>	
Contact Name:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>	
Invoice Number:		Payment Received:	Imported to Financials: <input type="checkbox"/>	
Incoming Account #:		Payment Method:		

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200915-0003

Work Order Detail Report

9/16/2020

SSO INSPECTION 9-13-2020 0.48 INCHES OF RAIN

3:38 PM

Tracking			Date	Time
Item	Description	By		
Work Order Creation	From Routine Work SSO-02 - SSO	jjackson	9/15/2020	11:04 AM
INSPECTION				
Supervisor Notification	Email Queued Successfully!	jjackson	9/15/2020	11:04 AM
Email Successfully Sent	jjackson@clvhts.com Lucyity Work Order	BackgroundTaskUser	9/15/2020	11:05 AM
Update - Supervisor				
Status Change	From New Work Order to Complete	aferrone	9/16/2020	3:36 PM

Rates:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned,	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	WO User 30:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 9/15/2020	8:00 AM	
Dye Test Results:			
WO User 51:	E Mail:		
Measurement:	WO User 22:		
History:			
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sled		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		

Work Order Detail Report

9/16/2020

SSO INSPECTION 9-13-2020 0.48 INCHES OF RAIN


3:38 PM

WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 9/15/2020	PM Trigger:	Rec #: 5863



**Daily Precipitation Report
Monday, September 28, 2020**

Accumulation in Inches



Northeast Ohio Regional Sewer District
Daily Precipitation Report
Monday, September 28, 2020

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	1.73	1.73	1.43	0.88	0.34
Brecksville	1.55	1.55	1.32	0.86	0.40
Brook Park	1.65	1.62	1.44	0.83	0.33
Cleveland Industrial Pkwy	1.57	1.54	1.35	0.72	0.35
Dille Ave PS	1.65	1.64	1.30	0.68	0.35
Division Ave PS	1.52	1.52	1.29	0.63	0.27
Easterly WWTP	1.68	1.67	1.41	0.62	0.30
Independence	1.67	1.66	1.41	0.94	0.41
James Rhodes HS	1.73	1.72	1.41	0.73	0.36
Jennings PS	1.93	1.92	1.62	0.91	0.56
Macedonia	1.38	1.37	1.13	0.57	0.26
Maple Heights	1.67	1.67	1.37	0.92	0.42
Mary Street PS	1.51	1.51	1.17	0.58	0.31
Mayfield Heights	1.73	1.73	1.47	0.89	0.42
Moreland Hills	1.53	1.53	1.24	0.65	0.32
North Olmsted	1.27	1.27	1.10	0.77	0.25
North Royalton	1.95	1.93	1.65	1.05	0.41
Oakwood	1.50	1.49	1.22	0.63	0.34
Olmsted Falls	1.35	1.34	1.14	0.71	0.26
Parma	1.78	1.77	1.49	0.82	0.38
Richfield	1.13	1.13	0.84	0.44	0.16
Shaker Heights	1.79	1.78	1.42	0.88	0.39
South Euclid	1.48	1.45	1.14	0.56	0.29
Southerly WWTC	1.66	1.63	1.29	0.80	0.36
Strongsville C WWTP	n/a	n/a	n/a	n/a	n/a
Strongsville Foltz	1.89	1.88	1.61	0.86	0.36
University Heights	1.82	1.80	1.48	0.91	0.39
Wade Park	1.91	1.89	1.54	0.84	0.44
Westlake	1.24	1.23	1.10	0.73	0.24

Northeast Ohio Regional Sewer District

Daily Precipitation Report
Monday, September 28, 2020

<u>Site Location</u>	<u>Peak Accumulation (inches)</u>				
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>
Beachwood	1.73	1.73	1.43	0.88	0.34
Brecksville	1.55	1.55	1.32	0.86	0.40
Brook Park	1.65	1.62	1.24	0.83	0.33
Cleveland Industrial Pkwy	1.57	1.54	1.35	0.72	0.35
Dixie Ave PS	1.65	1.64	1.30	0.68	0.35
Division Ave PS	1.52	1.52	1.29	0.63	0.27
Easterly WWTP	1.68	1.67	1.21	0.62	0.30
Independence	1.67	1.66	1.41	0.94	0.41
James Rhodes HS	1.73	1.72	1.21	0.73	0.36
Jennings PS	1.93	1.92	1.62	0.91	0.56
Macedonia	1.38	1.37	1.33	0.57	0.26
Maple Heights	1.67	1.67	1.37	0.92	0.42
Map Street PS	1.51	1.51	1.17	0.58	0.31
Mayfield Heights	1.73	1.73	1.47	0.89	0.42
Moreland Hills	1.53	1.53	1.24	0.65	0.32
North Olmsted	1.27	1.27	1.10	0.77	0.25
North Royalton	1.95	1.93	1.65	1.05	0.41
Oakwood	1.50	1.49	1.22	0.63	0.34
Olmsted Falls	1.35	1.34	1.14	0.71	0.26
Parma	1.78	1.77	1.49	0.82	0.38
Richfield	1.13	1.13	0.84	0.44	0.16
Shaker Heights	1.79	1.78	1.42	0.88	0.39
South Euclid	1.43	1.45	1.14	0.56	0.29
Southerly WWTC	1.66	1.63	1.28	0.80	0.36
Strongsville C. WWTP	na	na	na	na	na
Strongsville Foltz	1.89	1.88	1.61	0.86	0.36
University Heights	1.82	1.80	1.48	0.91	0.39
Wade Park	1.91	1.89	1.54	0.84	0.44
Westlake	2.24	2.23	1.10	0.73	0.24

Work Order Detail Report

9/30/2020

SSO INSPECTION 9-21-2020 1.87 INCHES OF RAIN

4:07 PM

WO Number:	200930-0002	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	9/30/2020 4:06 pm	Main Task:	Inspection

Asset:	SSO 431	Location:	FAIRFAX AT NORTH PARK	
Cause:	Weather	Assigned By:		
Assigned Crew:		Assigned Date:		
Supervisor:	Jackson, Jeff	Start Date:	9/30/2020 8:00 AM	Override
Lead Worker:	DelZoppo, Michael	End Date:	9/30/2020	Notifications
Priority:	High			
Account #:				Problem <input type="checkbox"/>
Proj No - Act:		Project ID:		Overdue <input type="checkbox"/>
Project:		Project Name:		Lead Worker <input type="checkbox"/>
Reason:				Task <input type="checkbox"/>
Received By:				Supervisor <input type="checkbox"/>
Inspected By:				Hard Lock WO <input type="checkbox"/>

Request Comments for Work Order

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection

Comments for Crew
Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook
	2,226,440.21168265	664,329.55524255	
	2,226,354.79813956	664,409.89202413	
	2,226,389.92077273	664,379.07548472	FAIRMOUNT AT DARTMOOR
	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
	2,223,969.26550905	664,532.08075613	FAIRMOUNT AT WELLINGTON
			DOAN BROOK - MAIN BRANCH

Work Order Detail Report

9/30/2020

SSO INSPECTION 9-21-2020 1.87 INCHES OF RAIN

4:07 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

9/30/2020

SSO INSPECTION 9-21-2020 1.87 INCHES OF RAIN

4:07 PM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

9/30/2020

SSO INSPECTION 9-21-2020 1.87 INCHES OF RAIN

4:07 PM

Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>Asset ID</u>	<u>Completed</u>
			<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>
Sewer Control Valve	SSO 431					FAIRFAX AT NORTH PARK 26
Sewer Control Valve	SSO 114					NORTH PARK AND COVENTRY 16
Sewer Control Valve	SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH 35
Sewer Structure	SA16AAWB0					
Sewer Control Valve	SSO 112					FAIRMOUNT AT FAIRFAX 7
Sewer Control Valve	SSO 99					FAIRMOUNT AT NORTH WOODLAND (S. SIDE) 6
Sewer Control Valve	SSO 432					3012 NORTH WOODLAND 14
Sewer Control Valve	DB-03					
Sewer Control Valve	DB-01					55 56
Sewer Control Valve	DB-02					
Sewer Control Valve	CH-04					FAIRMOUNT AT DARTMOOR 5
Sewer Control Valve	SSO 110					FAIRMOUNT AT WELLINGTON 44
Sewer Control Valve	SSO 87					FAIRMOUNT AT NORTH WOODLAND (N. SIDE) 33
Sewer Control Valve	SSO 116					FAIRMOUNT AT MARLBORO 4
Sewer Control Valve	SSO 111					FAIRMOUNT AT ARLINGTON 46
Sewer Control Valve	SSO 113					FAIRMOUNT & COVENTRY (SCARBOROUGH) 37
Sewer Control Valve	SSO 124					FAIRMOUNT AND COVENTRY 47
Sewer Control Valve	CH-50					SCARBOROUGH AT LAMBERTON 53
Sewer Control Valve	SSO 129					BRADFORD AND LEE 11
Sewer Control Valve	CH-52					EDDINGTON 2
Sewer Control Valve	SSO 88					HAMPSHIRE LANE AT MAYFIELD (18") 42
Sewer Control Valve	SSO 122					EAST OVERLOOK AT EDGEHILL 36
Sewer Control Valve	SSO 89					HAMPSHIRE LANE AT MAYFIELD (36") 34
Sewer Structure	SA16ADZB0					
Sewer Control Valve	SSO 91					1536
Sewer Structure	SA16ADPH0					HAMPSHIRE AT EUCLID HTS. BLVD. 20
Sewer Control Valve	SSO 120					4446
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON 8
						2828 BERKSHIRE, EAST OF COVENTRY

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200930-0002

Work Order Detail Report

9/30/2020

SSO INSPECTION 9-21-2020 1.87 INCHES OF RAIN

4:07 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

9/30/2020

SSO INSPECTION 9-21-2020 1.87 INCHES OF RAIN

4:07 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	9/30/2020/ 8:13 am	
	Overflowed				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	9/30/2020/ 8:17 am	
	No overflow				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	9/30/2020/ 8:18 am	
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	9/30/2020/ 8:20 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/30/2020/ 8:21 am	
	No overflow				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	9/30/2020/ 8:24 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	9/30/2020/ 8:26 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	9/30/2020/ 8:28 am	
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/30/2020/ 8:30 am	
	No overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	9/30/2020/ 8:32 am	
	Overflowed				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	9/30/2020/ 8:36 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/30/2020/ 8:38 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	9/30/2020/ 8:39 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/30/2020/ 8:41 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/30/2020/ 8:42 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	9/30/2020/ 8:44 am	
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/30/2020/ 8:45 am	
	Overflowed				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/30/2020/ 8:48 am	
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200930-0002

Work Order Detail Report

9/30/2020

SSO INSPECTION 9-21-2020 1.87 INCHES OF RAIN

4:07 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/30/2020/ 8:50 am
	No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	9/30/2020/ 8:52 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	9/30/2020/ 8:53 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFL00 (INTERSECTION)	<input type="checkbox"/>	Sound	9/30/2020/ 8:55 am
	Overflowed			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	9/30/2020/ 9:04 am
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	9/30/2020/ 9:07 am
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	9/30/2020/ 9:08 am
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	9/30/2020/ 9:09 am
	Overflowed			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	9/30/2020/ 9:10 am
	No overflow			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Sound	9/30/2020/ 9:17 am
	Overflowed			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	9/30/2020/ 9:24 am
	No overflow			
30	B-15 COVENTRY AND CEDAR SA16ADB0	<input type="checkbox"/>	Sound	9/30/2020/ 9:26 am
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	9/30/2020/ 9:30 am
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	9/30/2020/ 9:30 am
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	9/30/2020/ 9:49 am
	Overflowed			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	9/30/2020/ 9:43 am
	Overflowed			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	9/30/2020/ 9:35 am
	Overflowed			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	9/30/2020/ 9:59 am
	No overflow			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	9/30/2020/10:00 am
	No overflow			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	9/30/2020/10:04 am
	Can't inspect. Contractor covered manhole with top soil.			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	9/30/2020/10:06 am
	Overflowed			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200930-0002

Work Order Detail Report

9/30/2020

SSO INSPECTION 9-21-2020 1.87 INCHES OF RAIN

4:07 PM

40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	9/30/2020/10:13 am
No overflow				
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	9/30/2020/10:14 am
No overflow				
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	9/30/2020/10:19 am
No overflow				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	9/30/2020/10:22 am
Overflowed				
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	9/30/2020/10:24 am
No overflow				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	9/30/2020/10:28 am
No overflow				

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC: \$6.21	*Task Cost: \$279.52	Start Dt: 9/30/2020	
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		9/30/2020	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		9/30/2020	
5						
Task Comment: SSO INSPECTION 1.82 INCHES OF RAIN						

Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:			Labor Hours	8.00	0.00	0.00
Subcontractor:			Labor Costs	\$172.32	\$0.00	\$0.00
Profit Center:			Material Costs	0.00	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each		Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00		Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00		Misc. Costs	0.00	0.00	0.00
			Total Costs	\$279.52	\$0.00	\$0.00
			Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data				
Contact Name:		*Billing Amount:		Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:		Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:		Imported to Financials: <input type="checkbox"/>
		Payment Method:		

Associated PMs		Closed
PM Code and Description	SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200930-0002

Work Order Detail Report

9/30/2020

SSO INSPECTION 9-21-2020 1.87 INCHES OF RAIN

4:07 PM

Tracking			Date	Time
Item	Description	By		
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	9/30/2020	11:51 AM
Supervisor Notification	Email Queued Successfully!	jjackson	9/30/2020	11:51 AM
Email Successfully Sent	jjackson@clvhts.com LucyCity Work Order Update - Supervisor	BackgroundTaskUser	9/30/2020	11:52 AM
Status Change	From New Work Order to Complete	aferrone	9/30/2020	4:06 PM

Rates:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned,	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	WO User 30: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 9/30/2020	7:30 AM
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	WO User 22:	
History:		
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Sled	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Re		
Construction Crew:		
WO User 39:	OUPS #:	
WO User 40:	WO User 48:	
WO User 41:		
WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	Quantity:	Paid: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	

Work Order Detail Report

9/30/2020

SSO INSPECTION 9-21-2020 1.87 INCHES OF RAIN

4:07 PM

WO User 77:

WO User 87:

WO User 107:

WO User 78:

WO User 88:

WO User 108:

WO User 79:

WO User 89:

WO User 109:

WO User 80:

WO User 90:

WO User 110:

WO User 81:

WO User 91:

WO User 111:

WO Creator: jjackson

WO Creation Date: 9/30/2020

PM Trigger:

Rec #: 5943