




Northeast Ohio Regional Sewer District

Daily Precipitation Report Saturday, April 10, 2021

Accumulation in Inches



Work Order Detail Report

4/14/2021

SSO INSPECTION 4-13-2021 0.44 INCHES OF RAIN

9:01 AM

WO Number: 210413-0002	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 4/14/2021 9:00 am	Main Task:	Inspection

Asset: SSO 431	Location: FAIRFAX AT NORTH PARK	Assigned By:
Cause: Weather	Assigned Crew:	Assigned Date:
Supervisor: Jackson, Jeff	Lead Worker: DelZoppo, Michael	Start Date: 4/13/2021 8:00 AM
Priority: High		End Date: 4/13/2021
Account #:		Override Notifications
Proj No - Act:		Problem <input type="checkbox"/>
Project:		Overdue <input type="checkbox"/>
Reason:		Lead Worker <input type="checkbox"/>
Received By:		Task <input type="checkbox"/>
Inspected By:		Supervisor <input type="checkbox"/>
		Hard Lock WO <input type="checkbox"/>

Request Comments for Work Order
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Maintenance Zone: Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

Work Order Detail Report

4/14/2021

SSO INSPECTION 4-13-2021 0.44 INCHES OF RAIN

9:01 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

4/14/2021

SSO INSPECTION 4-13-2021 0.44 INCHES OF RAIN

9:01 AM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

4/14/2021

SSO INSPECTION 4-13-2021 0.44 INCHES OF RAIN

9:01 AM

Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>PM Description</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve				FAIRFAX AT NORTH PARK			
SSO 431						26	
Sewer Control Valve				NORTH PARK AND COVENTRY			
SSO 114						16	
Sewer Control Valve				FAIRMOUNT SOUTH OF SCARBOROUGH			
SSO 121						35	
Sewer Structure						3094	
SA16AAWB0							
Sewer Control Valve				FAIRMOUNT AT FAIRFAX			
SSO 112						7	
Sewer Control Valve				FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
SSO 99						6	
Sewer Control Valve				3012 NORTH WOODLAND			
SSO 432						14	
Sewer Control Valve						55	
DB-03							
Sewer Control Valve						56	
DB-01							
Sewer Control Valve						57	
DB-02							
Sewer Control Valve				FAIRMOUNT AT DARTMOOR			
CH-04						5	
Sewer Control Valve				FAIRMOUNT AT WELLINGTON			
SSO 110						44	
Sewer Control Valve				FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
SSO 87						33	
Sewer Control Valve				FAIRMOUNT AT MARLBORO			
SSO 116						4	
Sewer Control Valve				FAIRMOUNT AT ARLINGTON			
SSO 111						46	
Sewer Control Valve				FAIRMOUNT & COVENTRY (SCARBOROUGH)			
SSO 113						37	
Sewer Control Valve				FAIRMOUNT AND COVENTRY			
SSO 124						47	
Sewer Control Valve				SCARBOROUGH AT LAMBERTON			
CH-50						53	
Sewer Control Valve				BRADFORD AND LEE			
SSO 129						11	
Sewer Control Valve				EDDINGTON			
CH-52						2	
Sewer Control Valve				HAMPSHIRE LANE AT MAYFIELD (18")			
SSO 88						42	
Sewer Control Valve				EAST OVERLOOK AT EDGEHILL			
SSO 122						36	
Sewer Control Valve				HAMPSHIRE LANE AT MAYFIELD (36")			
SSO 89						34	
Sewer Structure						1536	
SA16ADZB0							
Sewer Control Valve				HAMPSHIRE AT EUCLID HTS. BLVD.			
SSO 91						20	
Sewer Structure						4446	
SA16ADPH0							
Sewer Control Valve				CEDAR BTW. FAIRMOUNT/DEMINGTON			
SSO 120						8	
Sewer Control Valve				2828 BERKSHIRE, EAST OF COVENTRY			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210413-0002

Work Order Detail Report

4/14/2021

SSO INSPECTION 4-13-2021 0.44 INCHES OF RAIN

9:01 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

4/14/2021

SSO INSPECTION 4-13-2021 0.44 INCHES OF RAIN

9:01 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	4/13/2021/ 7:45 am	
	No overflow				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	4/13/2021/ 7:56 am	
	Overflowed				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	4/13/2021/ 7:59 am	
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	4/13/2021/ 8:01 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	4/13/2021/ 8:05 am	
	No overflow				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	4/13/2021/ 8:07 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	4/13/2021/ 8:09 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	4/13/2021/ 8:15 am	
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	4/13/2021/ 8:16 am	
	No overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	4/13/2021/ 8:17 am	
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	4/13/2021/ 8:19 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/13/2021/ 8:22 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	4/13/2021/ 8:24 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/13/2021/ 8:27 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/13/2021/ 8:29 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	4/13/2021/ 8:32 am	
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/13/2021/ 8:37 am	
	No overflow				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/13/2021/ 8:39 am	
	Overflowed				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210413-0002

Work Order Detail Report

4/14/2021

SSO INSPECTION 4-13-2021 0.44 INCHES OF RAIN

9:01 AM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/13/2021/ 8:43 am
	No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	4/13/2021/ 8:46 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	4/13/2021/ 8:48 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/13/2021/ 8:51 am
	Overflowed			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	4/13/2021/ 9:22 am
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	4/13/2021/ 9:26 am
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	4/13/2021/ 9:27 am
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	4/13/2021/ 9:29 am
	No overflow			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	4/13/2021/ 9:30 am
	Overflowed			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Sound	4/13/2021/ 9:46 am
	No overflow			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	4/13/2021/ 9:39 am
	No overflow			
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	4/13/2021/ 9:41 am
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	4/13/2021/ 9:45 am
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	4/13/2021/ 9:48 am
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	4/13/2021/ 9:54 am
	Overflowed			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	4/13/2021/12:16 pm
	Overflowed			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	4/13/2021/12:25 pm
	No overflow			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	4/13/2021/12:27 pm
	No overflow			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	4/13/2021/12:29 pm
	Overflowed			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	4/13/2021/12:30 pm
	No overflow			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	4/13/2021/12:33 pm
	No overflow			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210413-0002

Work Order Detail Report

4/14/2021

SSO INSPECTION 4-13-2021 0.44 INCHES OF RAIN

9:01 AM

40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	4/13/2021/12:38 pm
	No overflow			
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	4/13/2021/12:39 pm
	No overflow			
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	4/13/2021/12:43 pm
	No overflow			
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	4/13/2021/12:47 pm
	Overflowed			
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	/	
	Tangled. Cannot inspect.			
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	4/13/2021/12:50 pm
	No overflow			

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC: \$9.78	*Task Cost: \$440.00	Start Dt:	
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32			
27146 Corbo, Joe	Hours	8.00	\$160.48			
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20			
5						
Task Comment: SSO INSPECTIONS 0.44" OF RAIN						

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	0.00	0.00	0.00
Subcontractor:		Labor Costs	16.00	0.00	0.00
Profit Center:		Material Costs	\$332.80	\$0.00	\$0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$440.00	\$0.00	\$0.00
		Use Task Info:	True	True	

Billing			
Billed Party			
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:			
City:		Phone:	
State:		Fax #:	
Zip:		Cell #:	
E-mail:			
Billing Data			
Contact Name:		*Billing Amount:	
Invoice Number:		Billing Required: <input type="checkbox"/>	
Incoming Account #:		Date Bill Sent:	
		Payment Received:	
		Imported to Financials: <input type="checkbox"/>	
		Payment Method:	

Work Order Detail Report

4/14/2021

SSO INSPECTION 4-13-2021 0.44 INCHES OF RAIN

9:01 AM

Associated PMs	PM Code and Description	Closed
	SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

Item	Tracking	Description	By	Date	Time
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	jjackson	4/13/2021	2:35 PM
Supervisor Notification		Email Queued Successfully!	jjackson	4/13/2021	2:36 PM
Status Change		From New Work Order to Complete	aferrone	4/14/2021	9:00 AM

Rates:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned,	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 4/13/2021	7:30 AM	

Dye Test Results:	
WO User 51:	
Measurement:	E Mail:
History:	WO User 22:

Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Sled
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:

Curb Repair:	
Driveway- Sidewalk Repair:	
Construction Crew:	
WO User 39:	
WO User 40:	OUPS #:
WO User 41:	WO User 48:

WO User 52:	WO User 62:	Televised:	<input type="checkbox"/>
WO User 53:	WO User 63:	Paid:	<input type="checkbox"/>
WO User 54:	WO User 64:	WO User 104:	<input type="checkbox"/>
WO User 55:	WO User 65:	WO User 105:	<input type="checkbox"/>
WO User 56:	WO User 66:	WO User 106:	<input type="checkbox"/>
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:		
WO User 73:	Quantity:		
WO User 74:	WO User 84:		
WO User 75:	WO User 85:		
WO User 76:	WO User 86:		

WO User 92 Date:	WO User 97 Date:
WO User 93 Date:	WO User 98 Date:
WO User 94 Date:	WO User 99 Date:
WO User 95 Date:	WO User 100 Date:
WO User 96 Date:	WO User 101 Date:

Work Order Detail Report

4/14/2021

SSO INSPECTION 4-13-2021 0.44 INCHES OF RAIN


9:01 AM

WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 4/13/2021	PM Trigger:	Rec #: 7544



**Daily Precipitation Report
Wednesday, April 21, 2021**

Accumulation in Inches



Work Order Detail Report

4/29/2021

SSO INSPECTION 4-21-2021 0.45 INCHES OF RAIN

3:05 PM

WO Number:	210428-0005	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	4/29/2021 3:04 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	4/28/2021 8:00 AM
Lead Worker:	DelZoppo, Michael	End Date:	4/28/2021
Priority:	High	Override Notifications	
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer Collection

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations

Address 2

X Coord	Y Coord	General Location	Address 2
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339	Doan Brook	
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210428-0005

Work Order Detail Report

4/29/2021

SSO INSPECTION 4-21-2021 0.45 INCHES OF RAIN

3:05 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210428-0005

Work Order Detail Report

4/29/2021

SSO INSPECTION 4-21-2021 0.45 INCHES OF RAIN

3:05 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

4/29/2021

SSO INSPECTION 4-21-2021 0.45 INCHES OF RAIN

3:05 PM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve							FAIRFAX AT NORTH PARK		
SSO 431								26	
Sewer Control Valve							NORTH PARK AND COVENTRY		
SSO 114								16	
Sewer Control Valve							FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121								35	
Sewer Structure									
SA16AAW0								3094	
Sewer Control Valve							FAIRMOUNT AT FAIRFAX		
SSO 112								7	
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99								6	
Sewer Control Valve							3012 NORTH WOODLAND		
SSO 432								14	
Sewer Control Valve									
DB-03								55	
Sewer Control Valve									
DB-01								56	
Sewer Control Valve									
DB-02								57	
Sewer Control Valve							FAIRMOUNT AT DARTMOOR		
CH-04								5	
Sewer Control Valve							FAIRMOUNT AT WELLINGTON		
SSO 110								44	
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87								33	
Sewer Control Valve							FAIRMOUNT AT MARLBORO		
SSO 116								4	
Sewer Control Valve							FAIRMOUNT AT ARLINGTON		
SSO 111								46	
Sewer Control Valve							FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113								37	
Sewer Control Valve							FAIRMOUNT AND COVENTRY		
SSO 124								47	
Sewer Control Valve							SCARBOROUGH AT LAMBERTON		
CH-50								53	
Sewer Control Valve							BRADFORD AND LEE		
SSO 129								11	
Sewer Control Valve							EDDINGTON		
CH-52								2	
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88								42	
Sewer Control Valve							EAST OVERLOOK AT EDGEHILL		
SSO 122								36	
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89								34	
Sewer Structure									
SA16ADZB0								1536	
Sewer Control Valve							HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91								20	
Sewer Structure									
SA16ADPH0								4446	
Sewer Control Valve							CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120								8	
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210428-0005

Work Order Detail Report

4/29/2021

SSO INSPECTION 4-21-2021 0.45 INCHES OF RAIN

3:05 PM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND ATERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

4/29/2021

SSO INSPECTION 4-21-2021 0.45 INCHES OF RAIN

3:05 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	4/28/2021 8:33 am	
	No overflow				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	4/28/2021 8:36 am	
	No overflow				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	4/28/2021 8:41 am	
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	4/28/2021 8:44 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	4/28/2021 8:47 am	
	No overflow				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	4/28/2021 8:50 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	4/28/2021 8:54 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	4/28/2021 8:52 am	
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	4/28/2021 9:00 am	
	Overflowed				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	4/28/2021 9:02 am	
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	4/28/2021 9:05 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/28/2021 9:08 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	4/28/2021 9:11 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/28/2021 9:14 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/28/2021 9:16 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	4/28/2021 9:20 am	
	Overflowed				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/28/2021 9:24 am	
	No overflow				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/28/2021 9:29 am	
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210428-0005

Work Order Detail Report

4/29/2021

SSO INSPECTION 4-21-2021 0.45 INCHES OF RAIN

3:05 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/28/2021/ 9:32 am
	No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	4/28/2021/ 9:36 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	4/28/2021/ 9:38 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/28/2021/ 9:42 am
	Overflowed			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	4/28/2021/ 9:52 am
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	4/28/2021/ 9:56 am
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	4/28/2021/ 9:56 am
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	4/28/2021/ 9:58 am
	No overflow			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	4/28/2021/10:01 am
	No overflow			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Sound	4/28/2021/10:04 am
	No overflow			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	4/28/2021/10:13 am
	No overflow			
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	4/28/2021/10:16 am
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	4/28/2021/10:22 am
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	4/28/2021/12:21 pm
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	4/28/2021/12:28 pm
	Overflowed			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	4/28/2021/12:35 pm
	No overflow			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	4/28/2021/12:39 pm
	No overflow			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	4/28/2021/12:42 pm
	No overflow			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	4/28/2021/12:44 pm
	Overflowed			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	4/28/2021/12:47 pm
	No overflow			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	4/28/2021/12:51 pm
	No overflow			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210428-0005

Work Order Detail Report

4/29/2021

SSO INSPECTION 4-21-2021 0.45 INCHES OF RAIN

3:05 PM

40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	4/28/2021/ 1:01 pm
	No overflow			
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	4/28/2021/ 1:04 pm
	No overflow			
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	4/28/2021/ 1:09 pm
	No overflow			
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	4/28/2021/ 1:13 pm
	No overflow			
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	4/28/2021/ 1:19 pm
	Tangled. Can't determine overflow.			
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	4/28/2021/ 1:18 pm
	No overflow			

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'd UC: \$6.21	*Task Cost: \$279.52	Start Dt: 4/28/2021	
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		4/28/2021	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20		4/28/2021	
Task Comment: SSO INSPECTION 0.45 INCHES OF RAIN						

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	0.00	0.00	0.00
Subcontractor:		Labor Costs	8.00	0.00	0.00
Profit Center:		Material Costs	\$172.32	\$0.00	\$0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data				
Contact Name:		*Billing Amount:		Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:		Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:		Imported to Financials: <input type="checkbox"/>
		Payment Method:		

Associated PMs	
PM Code and Description	Closed <input checked="" type="checkbox"/>
SSO-02 SSO INSPECTION	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210428-0005

Work Order Detail Report

4/29/2021

SSO INSPECTION 4-21-2021 0.45 INCHES OF RAIN

3:05 PM

Tracking		Item	Description	By	Date	Time
		Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	4/28/2021	7:56 AM
		Supervisor Notification	Email Queued Successfully!	jjackson	4/28/2021	7:56 AM
		Status Change	From New Work Order to Complete	aferrone	4/29/2021	3:04 PM
Rates:			Opened At:			Televised: <input type="checkbox"/>
Received By:			Pipe Footage Cleaned:			Power Rooter: <input type="checkbox"/>
Work From:			Gallons Used:			Jet: <input type="checkbox"/>
Pipe Size:			WO User 23:			Gap Vac: <input type="checkbox"/>
Pipe Condition:			WO User 24:			Dye Test: <input type="checkbox"/>
Could Not Open:			WO User 9:			Gap Root Cut: <input type="checkbox"/>
Additional Repair:			User 10:			GIS Correction?: <input type="checkbox"/>
Dye Test Reason:			Appointment Date DNL			Test Tee Correction: <input type="checkbox"/>
Test Performed Through:			Appointment Date:	4/28/2021	7:30 AM	
Dye Test Results:						
WO User 51:			E Mail:			
Measurement:			WO User 22:			
History:						
Manhole Basin Repair:			Pipe Size:			
Material Used:			PVC Tees, Angles, Slat			
Pipe Repair:			WO User 44:			
Street Repair:			WO User 45:			
Grass Repair:			WO User 46:			
Curb Repair:						
Driveway- Sidewalk Re						
Construction Crew:						
WO User 39:			OUPS #:			
WO User 40:			WO User 48:			
WO User 41:						
WO User 52:			WO User 62:			
WO User 53:			WO User 63:			
WO User 54:			WO User 64:			
WO User 55:			WO User 65:			
WO User 56:			WO User 66:			
WO User 57:			WO User 67:			
WO User 58:			WO User 68:			
WO User 59:			WO User 69:			
WO User 60:			WO User 70:			
WO User 61:			WO User 71:			
WO User 72:			WO User 82:			Televised: <input type="checkbox"/>
WO User 73:			Quantity:			Paid: <input type="checkbox"/>
WO User 74:			WO User 84:			WO User 104: <input type="checkbox"/>
WO User 75:			WO User 85:			WO User 105: <input type="checkbox"/>
WO User 76:			WO User 86:			WO User 106: <input type="checkbox"/>
WO User 92 Date:			WO User 97 Date:			
WO User 93 Date:			WO User 98 Date:			
WO User 94 Date:			WO User 99 Date:			
WO User 95 Date:			WO User 100 Date:			
WO User 96 Date:			WO User 101 Date:			
WO User 77:			WO User 87:			WO User 107: <input type="checkbox"/>
WO User 78:			WO User 88:			WO User 108: <input type="checkbox"/>
WO User 79:			WO User 89:			WO User 109: <input type="checkbox"/>
WO User 80:			WO User 90:			WO User 110: <input type="checkbox"/>
WO User 81:			WO User 91:			WO User 111: <input type="checkbox"/>

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210428-0005

Work Order Detail Report

4/29/2021

SSO INSPECTION 4-21-2021 0.45 INCHES OF RAIN

3:05 PM

WO Creator: jjackson

WO Creation Date: 4/28/2021

PM Trigger:


Rec #: 7590



Northeast Ohio Regional Sewer District

Daily Precipitation Report Thursday, April 29, 2021

Accumulation in Inches



Work Order Detail Report

4/30/2021

SSO INSPECTION 4-29-2021 1.57

3:44 PM

WO Number:	210430-0006	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	4/30/2021 3:40 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	4/30/2021 8:00 AM
Lead Worker:	DelZoppo, Michael	End Date:	4/30/2021
Priority:	High	Override Notifications	
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook
	2,226,440.21168265	664,329.55524255	
	2,226,354.79813956	664,409.89202413	
	2,226,389.92077273	664,379.07548472	FAIRMOUNT AT DARTMOOR
	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
	2,223,969.26550905	664,532.08075613	FAIRMOUNT AT WELLINGTON
			DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210430-0006

Work Order Detail Report

4/30/2021

SSO INSPECTION 4-29-2021 1.57

3:44 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

4/30/2021

SSO INSPECTION 4-29-2021 1.57

3:44 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

SSO INSPECTION 4-29-2021 1.57

4/30/2021

3:44 PM

Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>Description 2</u>	<u>PM Description</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve							FAIRFAX AT NORTH PARK			26
SSO 431										
Sewer Control Valve							NORTH PARK AND COVENTRY			16
SSO 114										
Sewer Control Valve							FAIRMOUNT SOUTH OF SCARBOROUGH			35
SSO 121										
Sewer Structure										3094
SA16AAWB0										
Sewer Control Valve							FAIRMOUNT AT FAIRFAX			7
SSO 112										
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			6
SSO 99										
Sewer Control Valve							3012 NORTH WOODLAND			14
SSO 432										
Sewer Control Valve										55
DB-03										
Sewer Control Valve										56
DB-01										
Sewer Control Valve										57
DB-02										
Sewer Control Valve							FAIRMOUNT AT DARTMOOR			5
CH-04										
Sewer Control Valve							FAIRMOUNT AT WELLINGTON			44
SSO 110										
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			33
SSO 87										
Sewer Control Valve							FAIRMOUNT AT MARLBORO			4
SSO 116										
Sewer Control Valve							FAIRMOUNT AT ARLINGTON			46
SSO 111										
Sewer Control Valve							FAIRMOUNT & COVENTRY (SCARBOROUGH)			37
SSO 113										
Sewer Control Valve							FAIRMOUNT AND COVENTRY			47
SSO 124										
Sewer Control Valve							SCARBOROUGH AT LAMBERTON			53
CH-50										
Sewer Control Valve							BRADFORD AND LEE			11
SSO 129										
Sewer Control Valve							EDDINGTON			2
CH-52										
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (18")			42
SSO 88										
Sewer Control Valve							EAST OVERLOOK AT EDGEHILL			36
SSO 122										
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (36")			34
SSO 89										
Sewer Structure										1536
SA16ADZB0										
Sewer Control Valve							HAMPSHIRE AT EUCLID HTS. BLVD.			20
SSO 91										
Sewer Structure										4446
SA16ADPH0										
Sewer Control Valve							CEDAR BTW. FAIRMOUNT/DEMINGTON			8
SSO 120										
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210430-0006

Work Order Detail Report

4/30/2021

SSO INSPECTION 4-29-2021 1.57

3:44 PM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQD0	4987
Sewer Structure SA16AQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

4/30/2021

SSO INSPECTION 4-29-2021 1.57

3:44 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	4/30/2021/ 8:10 am	
	No overflow				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	4/30/2021/ 8:13 am	
	No overflow				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	4/30/2021/ 8:18 am	
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	4/30/2021/ 8:21 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	4/30/2021/ 8:24 am	
	Overflow				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	4/30/2021/ 8:28 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	4/30/2021/ 8:31 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	4/30/2021/ 8:37 am	
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	4/30/2021/ 8:40 am	
	Overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	4/30/2021/ 8:45 am	
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	4/30/2021/ 8:49 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/30/2021/ 8:52 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	4/30/2021/ 8:56 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/30/2021/ 9:00 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/30/2021/ 9:03 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	4/30/2021/ 9:07 am	
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/30/2021/ 9:11 am	
	Overflow				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/30/2021/ 9:16 am	
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210430-0006

Work Order Detail Report

4/30/2021

SSO INSPECTION 4-29-2021 1.57

3:44 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/30/2021/ 9:21 am
	No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	4/30/2021/ 9:26 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	4/30/2021/ 9:29 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/30/2021/ 9:34 am
	Overflow			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	4/30/2021/ 9:48 am
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	4/30/2021/ 9:54 am
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	4/30/2021/ 9:54 am
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	4/30/2021/ 9:58 am
	No overflow			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	4/30/2021/10:02 am
	No overflow			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	4/30/2021/10:04 am
	No overflow			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	4/30/2021/10:08 am
	No overflow			
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	4/30/2021/10:11 am
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	4/30/2021/10:17 am
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	4/30/2021/10:23 am
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	4/30/2021/10:32 am
	Overflow			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	4/30/2021/12:10 pm
	Overflow			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	4/30/2021/12:19 pm
	No overflow			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	4/30/2021/12:14 pm
	No overflow			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	4/30/2021/12:21 pm
	No overflow			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	4/30/2021/12:24 pm
	No overflow			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	4/30/2021/12:27 pm
	No overflow			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210430-0006

Work Order Detail Report

4/30/2021

SSO INSPECTION 4-29-2021 1.57

3:44 PM

40	C-59 3427 THORNE RD SA16AQJD0	<input type="checkbox"/>	Sound	4/30/2021/12:33 pm
No overflow				
41	C-60 3415 THORNE RD SA16AQJC0	<input type="checkbox"/>	Sound	4/30/2021/12:35 pm
No overflow				
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	4/30/2021/12:40 pm
No overflow				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	4/30/2021/12:45 pm
No overflow				
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	4/30/2021/12:49 pm
Line tangled.				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	4/30/2021/12:49 pm
No overflow				

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'd UC: \$6.21	*Task Cost: \$279.52	Start Dt: 4/30/2021	
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		4/30/2021	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		4/30/2021	
5						
Task Comment: SSO INSPECTIONS 1.57" OF RAIN						

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	0.00	0.00	0.00
Subcontractor:		Labor Costs	8.00	0.00	0.00
Profit Center:		Material Costs	\$172.32	\$0.00	\$0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Lock: <input type="checkbox"/>	Equipment Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data				
Contact Name:		*Billing Amount:		Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:		Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:		Imported to Financials: <input type="checkbox"/>
		Payment Method:		

Associated PMs		
PM Code	and Description	Closed <input checked="" type="checkbox"/>
SSO-02 SSO INSPECTION		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210430-0006

Work Order Detail Report

4/30/2021

SSO INSPECTION 4-29-2021 1.57

3:44 PM

Tracking		Item	Description	By	Date	Time
		Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	4/30/2021	7:45 AM
		Supervisor Notification	Email Queued Successfully!	jjackson	4/30/2021	7:45 AM
		Status Change	From New Work Order to Complete	aferrone	4/30/2021	3:40 PM
Rates:		Opened At:		Televised: <input type="checkbox"/>		
Recieved By:		Pipe Footage Cleaned:		Power Rooter: <input type="checkbox"/>		
Work From:		Gallons Used:		Jet: <input type="checkbox"/>		
Pipe Size:		WO User 23:		Gap Vac: <input type="checkbox"/>		
Pipe Condition:		WO User 24:		Dye Test: <input type="checkbox"/>		
Could Not Open:		WO User 9:		Gap Root Cut: <input type="checkbox"/>		
Additional Repair:		User 10:		GIS Correction?: <input type="checkbox"/>		
Dye Test Reason:		Appointment Date DNL		Test Tee Correction: <input type="checkbox"/>		
Test Performed Through:		Appointment Date: 4/30/2021		7:30 AM		
Dye Test Results:		E Mail:				
WO User 51:		WO User 22:				
Measurement:		Pipe Size:				
History:		PVC Tees, Angles, Sles				
Manhole Basin Repair:		WO User 44:				
Material Used:		WO User 45:				
Pipe Repair:		WO User 46:				
Street Repair:						
Grass Repair:						
Curb Repair:						
Driveway- Sidewalk Repair:						
Construction Crew:						
WO User 39:		OUPS #:				
WO User 40:		WO User 48:				
WO User 41:						
WO User 52:		WO User 62:				
WO User 53:		WO User 63:				
WO User 54:		WO User 64:				
WO User 55:		WO User 65:				
WO User 56:		WO User 66:				
WO User 57:		WO User 67:				
WO User 58:		WO User 68:				
WO User 59:		WO User 69:				
WO User 60:		WO User 70:				
WO User 61:		WO User 71:				
WO User 72:		WO User 82:		Televised: <input type="checkbox"/>		
WO User 73:		Quantity:		Paid: <input type="checkbox"/>		
WO User 74:		WO User 84:		WO User 104: <input type="checkbox"/>		
WO User 75:		WO User 85:		WO User 105: <input type="checkbox"/>		
WO User 76:		WO User 86:		WO User 106: <input type="checkbox"/>		
WO User 92 Date:		WO User 97 Date:				
WO User 93 Date:		WO User 98 Date:				
WO User 94 Date:		WO User 99 Date:				
WO User 95 Date:		WO User 100 Date:				
WO User 96 Date:		WO User 101 Date:				
WO User 77:		WO User 87:		WO User 107: <input type="checkbox"/>		
WO User 78:		WO User 88:		WO User 108: <input type="checkbox"/>		
WO User 79:		WO User 89:		WO User 109: <input type="checkbox"/>		
WO User 80:		WO User 90:		WO User 110: <input type="checkbox"/>		
WO User 81:		WO User 91:		WO User 111: <input type="checkbox"/>		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210430-0006

Work Order Detail Report

4/30/2021

SSO INSPECTION 4-29-2021 1.57

3:44 PM

WO Creator: jjackson

WO Creation Date: 4/30/2021

PM Trigger:

Rec #: 7608