


**Daily Precipitation Report**  
Monday, March 7, 2022  
Accumulation in Inches



# Northeast Ohio Regional Sewer District

## Daily Precipitation Report

Monday, March 7, 2022

| Site Location             | Peak Accumulation (inches) |        |        |        |           |
|---------------------------|----------------------------|--------|--------|--------|-----------|
|                           | 24-Hour                    | 6-Hour | 3-Hour | 1-Hour | 15-Minute |
| Beachwood                 | 0.93                       | 0.77   | 0.66   | 0.38   | 0.13      |
| Brecksville               | 1.16                       | 1.04   | 0.86   | 0.43   | 0.13      |
| Brook Park                | 0.96                       | 0.89   | 0.77   | 0.41   | 0.14      |
| Cleveland Industrial Pkwy | 0.95                       | 0.87   | 0.76   | 0.40   | 0.14      |
| Dille Ave PS              | n/a                        | n/a    | n/a    | n/a    | n/a       |
| Division Ave PS           | 0.83                       | 0.78   | 0.69   | 0.36   | 0.13      |
| Easterly WWTP             | 0.83                       | 0.75   | 0.64   | 0.35   | 0.13      |
| Independence              | 1.03                       | 0.93   | 0.78   | 0.40   | 0.12      |
| James Rhodes HS           | 0.94                       | 0.86   | 0.74   | 0.41   | 0.15      |
| Jennings PS               | 0.91                       | 0.83   | 0.73   | 0.41   | 0.15      |
| Macedonia                 | 1.32                       | 1.20   | 0.98   | 0.49   | 0.14      |
| Maple Heights             | 1.04                       | 0.94   | 0.80   | 0.43   | 0.14      |
| Mary Street PS            | 0.75                       | 0.72   | 0.63   | 0.34   | 0.12      |
| Mayfield Heights          | 0.83                       | 0.71   | 0.63   | 0.38   | 0.13      |
| Moreland Hills            | 0.97                       | 0.86   | 0.74   | 0.43   | 0.14      |
| North Olmsted             | 0.78                       | 0.73   | 0.63   | 0.33   | 0.12      |
| North Royalton            | 1.27                       | 1.14   | 0.94   | 0.47   | 0.14      |
| Oakwood                   | 0.99                       | 0.90   | 0.77   | 0.40   | 0.12      |
| Olmsted Falls             | n/a                        | n/a    | n/a    | n/a    | n/a       |
| Parma                     | 1.09                       | 0.97   | 0.83   | 0.44   | 0.14      |
| Richfield                 | n/a                        | n/a    | n/a    | n/a    | n/a       |
| Shaker Heights            | 0.99                       | 0.84   | 0.72   | 0.41   | 0.14      |
| South Euclid              | 0.70                       | 0.65   | 0.58   | 0.32   | 0.12      |
| Southerly WWTC            | 1.08                       | 0.94   | 0.80   | 0.44   | 0.14      |
| Strongsville C WWTP       | 1.20                       | 1.08   | 0.93   | 0.49   | 0.14      |
| Strongsville Foltz        | 1.20                       | 1.11   | 0.92   | 0.48   | 0.14      |
| University Heights        | 0.89                       | 0.79   | 0.69   | 0.38   | 0.14      |
| Wade Park                 | 0.71                       | 0.69   | 0.61   | 0.34   | 0.12      |
| Westerly WWTP             | 0.72                       | 0.68   | 0.59   | 0.31   | 0.10      |
| Westlake                  | n/a                        | n/a    | n/a    | n/a    | n/a       |

## Work Order Detail Report

3/14/2022

SSO INSPECTIONS 3-7-2022 0.84" OF RAIN

11:20 AM

WO Number: 220314-0007  
Status: Complete  
Status Date: 3/14/2022 11:19 am  
Category: SSOs  
Problem: Storm Response  
Main Task: Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause: Weather

Assigned Crew:

Supervisor: Jackson, Jeff

Lead Worker: Corbo, Joe

Priority: High

Account #:

Proj No - Acct:

Project:

Reason:

Received By:

Inspected By:

Assigned By:

Assigned Date: 3/7/2022

Start Date: 3/11/2022 7:16 AM

End Date: 3/11/2022 3:16 PM

OverrideNotificationsProblem ☐Overdue ☐Lead Worker ☐Task ☐Supervisor ☐Hard Lock WO ☐

Project ID:

Project Name:

### Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

### Location

Department: Sewer Collection

Division: Sewer Collection

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

### Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

### Work Order Locations

| Address                               |                  | Address 2                |
|---------------------------------------|------------------|--------------------------|
| X Coord                               | Y Coord          | General Location         |
| FAIRFAX AT NORTH PARK                 |                  |                          |
| 2,220,655.65435414                    | 665,517.24643672 | Doan Brook               |
| NORTH PARK AND COVENTRY               |                  |                          |
| 2,219,873.16674590                    | 666,048.82312946 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT SOUTH OF SCARBOROUGH        |                  |                          |
| 2,220,364.86097248                    | 666,446.72325230 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT FAIRFAX                  |                  |                          |
| 2,220,920.81917815                    | 666,080.57995571 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT NORTH WOODLAND (S. SIDE) |                  |                          |
| 2,223,053.81655256                    | 664,693.25202172 | DOAN BROOK - MAIN BRANCH |
| 3012 NORTH WOODLAND                   |                  |                          |
| 2,222,845.06631389                    | 664,689.08536339 | Doan Brook               |
| 2,226,440.21168265                    | 664,329.55524255 |                          |
| 2,226,354.79813956                    | 664,409.89202413 |                          |
| 2,226,389.92077273                    | 664,379.07548472 |                          |
| FAIRMOUNT AT DARTMOOR                 |                  |                          |
| 2,225,149.97508989                    | 664,453.31024438 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT WELLINGTON               |                  |                          |
| 2,223,969.26550905                    | 664,532.08075613 | DOAN BROOK - MAIN BRANCH |

## Work Order Detail Report

3/14/2022

SSO INSPECTIONS 3-7-2022 0.84" OF RAIN

11:20 AM

|                                                    |                  |                                      |
|----------------------------------------------------|------------------|--------------------------------------|
| FAIRMOUNT AT NORTH WOODLAND (N. SIDE)              |                  |                                      |
| 2,223,111.44143730                                 | 664,794.46048072 | DOAN BROOK - MAIN BRANCH             |
| FAIRMOUNT AT MARLBORO                              |                  |                                      |
| 2,221,638.88762389                                 | 665,726.15513962 | DOAN BROOK - MAIN BRANCH             |
| FAIRMOUNT AT ARLINGTON                             |                  |                                      |
| 2,222,127.85875881                                 | 665,393.74077822 | DOAN BROOK - MAIN BRANCH             |
| FAIRMOUNT & COVENTRY (SCARBOROUGH)                 |                  |                                      |
| 2,220,278.63411081                                 | 667,231.62916280 | DOAN BROOK - MAIN BRANCH             |
| FAIRMOUNT AND COVENTRY                             |                  |                                      |
| 2,220,419.37169023                                 | 666,567.10752596 | DOAN BROOK - MAIN BRANCH             |
| SCARBOROUGH AT LAMBERTON                           |                  |                                      |
| 2,221,598.28993607                                 | 666,996.61322863 |                                      |
| MONMOUTH, EAST OF DARTMOOR                         |                  |                                      |
| 2,225,152.08663423                                 | 665,499.19660404 | DOAN BROOK                           |
| BRADFORD AND LEE                                   |                  |                                      |
| 2,224,643.84191582                                 | 665,970.39907372 | DOAN BROOK - MAIN BRANCH             |
| EDDINGTON                                          |                  |                                      |
| 2,221,299.08384156                                 | 674,932.84604380 |                                      |
| HAMPSHIRE LANE AT MAYFIELD (18")                   |                  |                                      |
| 2,219,348.17140481                                 | 672,922.02624655 | DUGWAY CREEK - MAIN BRANCH           |
| EAST OVERLOOK AT EDGEHILL                          |                  |                                      |
| 2,218,479.60588473                                 | 671,538.70289771 | DOAN BROOK - MAIN BRANCH             |
| HAMPSHIRE LANE AT MAYFIELD (36")                   |                  |                                      |
| 2,219,354.97683740                                 | 672,902.85961822 | DUGWAY CREEK - MAIN BRANCH           |
| 2600 HAMPSHIRE RD                                  |                  |                                      |
| HAMPSHIRE AT EUCLID HTS. BLVD.                     |                  |                                      |
| 2,218,465.44876081                                 | 671,703.91811846 | DOAN BROOK - MAIN BRANCH             |
| CEDAR BTW. FAIRMOUNT/DEMINGTON                     |                  |                                      |
| 2,218,036.25112839                                 | 669,668.09115338 | DOAN BROOK - MAIN BRANCH             |
| 2828 BERKSHIRE, EAST OF COVENTRY                   |                  |                                      |
| 2,220,768.48319674                                 | 670,614.63814481 | DUGWAY CREEK - MAIN BRANCH           |
| 3003 EUCLID HEIGHTS BLVD                           |                  |                                      |
| 2,222,538.05642922                                 | 672,458.71614955 | DUGWAY CREEK - MAIN BRANCH           |
| South Taylor between Antisdale Ave and Superior Rd |                  |                                      |
| 2,227,113.30810548                                 | 671,276.67684697 |                                      |
| LEE RD. & SUPERIOR AVE.                            |                  |                                      |
| 2,224,449.07983814                                 | 672,366.92072946 | HEIGHT = NA, WIDTH = NA, LENGTH = NA |
| EUCLID HEIGHTS BLVD AND LEE                        |                  |                                      |
| 2,224,196.49208874                                 | 673,102.72798488 | DUGWAY CREEK - MAIN BRANCH           |
| EUCLID HEIGHTS BLVD/CUMBERLAND                     |                  |                                      |
| 2,223,890.24106081                                 | 672,984.80925746 | DUGWAY CREEK - MAIN BRANCH           |
| 1685 CUMBERLAND                                    |                  |                                      |
| 2,223,414.40769489                                 | 674,158.55920655 | DUGWAY CREEK - MAIN BRANCH           |
| CUMBERLAND/SOMERTON                                |                  |                                      |
| 2,223,678.60992239                                 | 673,517.13791722 | DUGWAY CREEK - MAIN BRANCH           |
| 2225 NOBLE RD                                      |                  |                                      |
| 2225 NOBLE ROAD                                    |                  |                                      |
| 2,227,020.20068015                                 | 682,910.03907888 | NINE MILE CREEK - MAIN BRANCH        |
| QUILLIAMS, N. OF RANDOLF                           |                  |                                      |
| 2,229,594.65878581                                 | 682,393.53289405 | NINE MILE CREEK - MAIN BRANCH        |
| LANGTON AND ATHERSTONE                             |                  |                                      |
| 2,228,126.76638040                                 | 684,188.23206055 |                                      |
| 2,220,777.89623564                                 | 666,181.72575080 |                                      |
| 2,218,501.67473823                                 | 671,997.54581206 |                                      |
| 2,216,759.55453481                                 | 670,474.59347738 |                                      |

## Work Order Detail Report

3/14/2022

SSO INSPECTIONS 3-7-2022 0.84" OF RAIN

11:20 AM

|                    |                  |
|--------------------|------------------|
| 2,224,536.21778722 | 668,887.44048372 |
| 2,226,741.35609348 | 679,432.95121680 |
| 2,226,591.76420106 | 679,420.92761880 |
| 2,227,825.14395215 | 684,881.15948047 |

# Work Order Detail Report

3/14/2022

SSO INSPECTIONS 3-7-2022 0.84" OF RAIN

11:20 AM

| Work Order Assets   |               |          |               |            |                                       |          |           |
|---------------------|---------------|----------|---------------|------------|---------------------------------------|----------|-----------|
| Object Type         | Description 1 |          | Description 2 |            |                                       |          |           |
| System ID 1         | System ID 2   | Odometer | Hourmeter     | Othermeter | PM Description                        | Asset ID | Completed |
| Sewer Control Valve |               |          |               |            | FAIRFAX AT NORTH PARK                 |          |           |
| SSO 431             |               |          |               |            |                                       | 26       |           |
| Sewer Control Valve |               |          |               |            | NORTH PARK AND COVENTRY               |          |           |
| SSO 114             |               |          |               |            |                                       | 16       |           |
| Sewer Control Valve |               |          |               |            | FAIRMOUNT SOUTH OF SCARBOROUGH        |          |           |
| SSO 121             |               |          |               |            |                                       | 35       |           |
| Sewer Structure     |               |          |               |            |                                       |          |           |
| SA16AAWB0           |               |          |               |            |                                       | 3094     |           |
| Sewer Control Valve |               |          |               |            | FAIRMOUNT AT FAIRFAX                  |          |           |
| SSO 112             |               |          |               |            |                                       | 7        |           |
| Sewer Control Valve |               |          |               |            | FAIRMOUNT AT NORTH WOODLAND (S. SIDE) |          |           |
| SSO 99              |               |          |               |            |                                       | 6        |           |
| Sewer Control Valve |               |          |               |            | 3012 NORTH WOODLAND                   |          |           |
| SSO 432             |               |          |               |            |                                       | 14       |           |
| Sewer Control Valve |               |          |               |            |                                       |          |           |
| DB-03               |               |          |               |            |                                       | 55       |           |
| Sewer Control Valve |               |          |               |            |                                       |          |           |
| DB-01               |               |          |               |            |                                       | 56       |           |
| Sewer Control Valve |               |          |               |            |                                       |          |           |
| DB-02               |               |          |               |            |                                       | 57       |           |
| Sewer Control Valve |               |          |               |            | FAIRMOUNT AT DARTMOOR                 |          |           |
| CH-04               |               |          |               |            |                                       | 5        |           |
| Sewer Control Valve |               |          |               |            | FAIRMOUNT AT WELLINGTON               |          |           |
| SSO 110             |               |          |               |            |                                       | 44       |           |
| Sewer Control Valve |               |          |               |            | FAIRMOUNT AT NORTH WOODLAND (N. SIDE) |          |           |
| SSO 87              |               |          |               |            |                                       | 33       |           |
| Sewer Control Valve |               |          |               |            | FAIRMOUNT AT MARLBORO                 |          |           |
| SSO 116             |               |          |               |            |                                       | 4        |           |
| Sewer Control Valve |               |          |               |            | FAIRMOUNT AT ARLINGTON                |          |           |
| SSO 111             |               |          |               |            |                                       | 46       |           |
| Sewer Control Valve |               |          |               |            | FAIRMOUNT & COVENTRY (SCARBOROUGH)    |          |           |
| SSO 113             |               |          |               |            |                                       | 37       |           |
| Sewer Control Valve |               |          |               |            | FAIRMOUNT AND COVENTRY                |          |           |
| SSO 124             |               |          |               |            |                                       | 47       |           |
| Sewer Control Valve |               |          |               |            | SCARBOROUGH AT LAMBERTON              |          |           |
| CH-50               |               |          |               |            |                                       | 53       |           |
| Sewer Control Valve |               |          |               |            | BRADFORD AND LEE                      |          |           |
| SSO 129             |               |          |               |            |                                       | 11       |           |
| Sewer Control Valve |               |          |               |            | EDDINGTON                             |          |           |
| CH-52               |               |          |               |            |                                       | 2        |           |
| Sewer Control Valve |               |          |               |            | HAMPSHIRE LANE AT MAYFIELD (18")      |          |           |
| SSO 88              |               |          |               |            |                                       | 42       |           |
| Sewer Control Valve |               |          |               |            | EAST OVERLOOK AT EDGEHILL             |          |           |
| SSO 122             |               |          |               |            |                                       | 36       |           |
| Sewer Control Valve |               |          |               |            | HAMPSHIRE LANE AT MAYFIELD (36")      |          |           |
| SSO 89              |               |          |               |            |                                       | 34       |           |
| Sewer Structure     |               |          |               |            |                                       |          |           |
| SA16ADZB0           |               |          |               |            |                                       | 1536     |           |
| Sewer Control Valve |               |          |               |            | HAMPSHIRE AT EUCLID HTS. BLVD.        |          |           |
| SSO 91              |               |          |               |            |                                       | 20       |           |
| Sewer Structure     |               |          |               |            |                                       |          |           |
| SA16ADPH0           |               |          |               |            |                                       | 4446     |           |
| Sewer Control Valve |               |          |               |            | CEDAR BTW. FAIRMOUNT/DEMINGTON        |          |           |
| SSO 120             |               |          |               |            |                                       | 8        |           |
| Sewer Control Valve |               |          |               |            | 2828 BERKSHIRE, EAST OF COVENTRY      |          |           |

**Work Order Detail Report**

3/14/2022

SSO INSPECTIONS 3-7-2022 0.84" OF RAIN

11:20 AM

|                     |                                                   |
|---------------------|---------------------------------------------------|
| SSO 103             | 19                                                |
| Sewer Control Valve | 3003 EUCLID HEIGHTS BLVD                          |
| SSO 104             | 15                                                |
| Sewer Structure     |                                                   |
| SA16AGMG0           | 3402                                              |
| Sewer Control Valve | South Taylor between Antisdale Ave and Superior F |
| CH-30               | 52                                                |
| Sewer Control Valve | LEE RD. & SUPERIOR AVE.                           |
| DV-11               | 9                                                 |
| Sewer Control Valve | EUCLID HEIGHTS BLVD AND LEE                       |
| SSO 108             | 22                                                |
| Sewer Control Valve | EUCLID HEIGHTS BLVD/CUMBERLAND                    |
| SSO 106             | 43                                                |
| Sewer Control Valve | 1685 CUMBERLAND                                   |
| SSO 95              | 18                                                |
| Sewer Control Valve | CUMBERLAND/SOMERTON                               |
| SSO 105             | 30                                                |
| Sewer Structure     |                                                   |
| SA16AQD0            | 4987                                              |
| Sewer Structure     |                                                   |
| SA16AQQC0           | 3745                                              |
| Sewer Control Valve | 2225 NOBLE ROAD                                   |
| SSO 102             | 3                                                 |
| Sewer Control Valve | QUILLIAMS, N. OF RANDOLF                          |
| SSO 107             | 38                                                |
| Sewer Control Valve | LANGTON AND ATHERSTONE                            |
| CH-51               | 54                                                |
| Sewer Structure     |                                                   |
| SA16APEF0           | 1809                                              |

## Work Order Detail Report

3/14/2022

SSO INSPECTIONS 3-7-2022 0.84" OF RAIN

11:20 AM

| Check List |                                                                                |                          |           |                      |                     |
|------------|--------------------------------------------------------------------------------|--------------------------|-----------|----------------------|---------------------|
|            | Item                                                                           | Completed                | Condition | Completion Date/Time | Est Completion Date |
| 1          | A-37-FAIRFAX AT NORTH PARK<br>SA16ACPG0                                        | <input type="checkbox"/> | Not Sound | 3/11/2022/           |                     |
| 2          | A-36-NORTH PARK AT COVENTRY<br>SA16ACNB0 (IN MEDIAN-CEMENT)                    | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 3          | A-45-FAIRMOUNT ( IN THE ISLAND<br>EAST OF COVENTRY) SA16ACNE0                  | <input type="checkbox"/> | Not Sound | 3/11/2022/           |                     |
| 4          | A-54-2806 FAIRMOUNT SA16AAWB0<br>(TREE LAWN BY SIDEWALK)                       | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 5          | A-33-FAIRMOUNT AT FAIRFAX<br>SA16AAWC0 (SW CORNER IN THE<br>SIDEWALK)          | <input type="checkbox"/> | Not Sound | 3/11/2022/           |                     |
| 6          | A-39-3012 NORTH WOODLAND<br>SA16AAWM5 (TREE LAWN)                              | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 7          | A-2 FAIRMOUNT AT NORTH<br>WOODLAND SA16AAWK0(MIDDLE<br>OF THE ROAD)            | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 8          | A-6 FAIRMOUNT AT SHELBURNE<br>ST16ZBJK0 (WEST BOUND LANE)                      | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 9          | A-5 FAIRMOUNT AT SHELBURNE<br>SA16AAXB0(ON THE SE CORNER IN<br>THE SIDEWALK)   | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 10         | A-7 FAIRMOUNT AT SHELBURNE<br>SA16AAVH0 (EAST BOUND)                           | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 11         | A-4 FAIRMOUNT AT DARTMOOR<br>SA16AAVB0(NW CORNER IN THE<br>GRASS BY STOP SIGN) | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 12         | A-3 FAIRMOUNT AT WELLINGTON<br>SA16AAUW0 (INTERSECTION)                        | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 13         | A-1 3041 FAIRMOUNT SA16AAUT0<br>(TREE LAWN NEAR SIDEWALK)                      | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 14         | A-32 FAIRMOUNT AT ARLINGTON<br>SA16AAUP0 (INTERSECTION)                        | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 15         | A-38 FAIRMOUNT AT MARLBORO<br>SA16AAUM0 (INTERSECTION)                         | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 16         | A-49 2757 FAIRMOUNT SA16AAUC0<br>(EAST OF CHURCH IN TREE LAWN)                 | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 17         | A-35 2393 COVENTRY SA16AASK0<br>(INTERSECTION)                                 | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 18         | A-50 SCARBOROUGH AND<br>LAMBERTON SA16AANE5<br>(INTERSECTION)                  | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 19         | A-47 2528 STRATFORD SA16ACDB5<br>(INTERSECTION)                                | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 20         | A-57 E MONMOUTH SA16AFWA5<br>WEST OF (DARTMOOR NEAR LEE)                       | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 21         | A-58 E MONMOUTH AT EXETER<br>(INTERSECTION)                                    | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 22         | A-9 BRADFORD AT LEE SA16AFLL0<br>(INTERSECTION)                                | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 23         | B-52 EDDINGTON NORTH OF<br>AVONDALE SA16AHVE0                                  | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 24         | B-10 HAMPSHIRE LANE AT MAYFIELD<br>SA16BACB0                                   | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 25         | B-11 HAMPSHIRE LANE AT MAYFIELD<br>SA16AEEA0                                   | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 26         | B-61 2600 HAMPSHIRE SA16ADZB0                                                  | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |
| 27         | HAMPSHIRE AT EUCLID HTS. BLVD.<br>SA16ADPR0                                    | <input type="checkbox"/> | Sound     | 3/11/2022/           |                     |

\* A "Hidden" field indicates permission to view the secured field is turned off.

WO#: 220314-0007

# Work Order Detail Report

3/14/2022

SSO INSPECTIONS 3-7-2022 0.84" OF RAIN

11:20 AM

|                   |                                                  |                          |           |            |
|-------------------|--------------------------------------------------|--------------------------|-----------|------------|
| 28                | B-46 EDGEHILL AT E OVERLOOK<br>SA16AEPF0         | <input type="checkbox"/> | Not Sound | 3/11/2022/ |
| string is missing |                                                  |                          |           |            |
| 29                | B-42 12537 CEDAR SA16ACZA0                       | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 30                | B-15 COVENTRY AND CEDAR<br>SA16ADBHO             | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 31                | B-23 2828 BERKSHIRE SA16AETA0                    | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 32                | B-24 3003 EUCLID HTS. BLVD.<br>ST16AALB0         | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 33                | B-56 LEE AND MEADOWBROOK<br>SA16AGMG0            | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 34                | C-30 S TAYLOR NORTH OF<br>SUPERIOR SA16AIVF0     | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 35                | C-12 LEE AND SUPERIOR<br>SA16AGTJ0               | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 36                | C-28 EUCLID HTS. BLVD AND LEE RD<br>SA16AGTE0    | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 37                | C-26 EUCLID HTS BLVD AND<br>CUMBERLAND SA16AIRL0 | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 38                | C-25 CUMBERLAND AND SOMERTON<br>SA16AISA0        | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 39                | C-17 1685 CUMBERLAND RD<br>SA16AQIB0             | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 40                | C-59 3427 THORNE RD SA16AQD0                     | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 41                | C-60 3415 THORNE RD SA16AQQC0                    | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 42                | C-22 2225 NOBLE RD ST16ZLHB0                     | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 43                | C-27 QUILLIAMS NORTH OF<br>RANDOLPH SA16AOUQ0    | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 44                | C-51 ATHERSTONE AND LANGTON<br>SA16AOKA0         | <input type="checkbox"/> | Sound     | 3/11/2022/ |
| 45                | C-50 3593 FENLEY SA16APEH0                       | <input type="checkbox"/> | Sound     | 3/11/2022/ |

## Tasks/Resources

### SWCT26 Inspection

**Crew:** **Status:** Complete **\*Cal'c UC:** \$29.64 **\*Task Cost:** \$1,333.68 **Start Dt:** 3/11/2022  
**Supervisor:** Jackson, Jeff **UOM:** Each **# of Units:** 45.00 **\*Unit Cost:** \$0.00 **End Dt:** 3/11/2022

### Employee

| Resource                 | UOM   | Units | *Total Cost | Alt Description | Start Dt  | End Dt    |
|--------------------------|-------|-------|-------------|-----------------|-----------|-----------|
| 27146 Corbo, Joe         | Hours | 16.00 | \$320.96    |                 | 3/11/2022 | 3/11/2022 |
| 39986 OBrien, Dominick   | Hours | 16.00 | \$330.56    |                 | 3/11/2022 | 3/11/2022 |
| 28056 Palmisano, Anthony | Hours | 16.00 | \$320.96    |                 | 3/11/2022 | 3/11/2022 |

### Equipment

| Resource                          | UOM   | Units | *Total Cost | Alt Description | Start Dt  | End Dt    |
|-----------------------------------|-------|-------|-------------|-----------------|-----------|-----------|
| CHFLT50 FORD F250 CREW CAB<br>5   | Hours | 8.00  | \$107.20    |                 | 3/11/2022 | 3/11/2022 |
| CHFLT55 FORD F250 PICK UP<br>0    | Hours | 8.00  | \$107.20    |                 | 3/11/2022 | 3/11/2022 |
| CHFLT55 GMC SAVANA SEWER<br>7 VAN | Hours | 8.00  | \$146.80    |                 | 3/11/2022 | 3/11/2022 |

**Task Comment:** SSO INSPECTION 0.89" OF RAIN

## Work Order Detail Report

3/14/2022

SSO INSPECTIONS 3-7-2022 0.84" OF RAIN

11:20 AM

|                       |                                |                  | <u>*Actual</u> | <u>*Estimated</u> | <u>*Difference</u> |
|-----------------------|--------------------------------|------------------|----------------|-------------------|--------------------|
| Projected Complete:   | Lock: <input type="checkbox"/> | WO Duration      | 8.00           | 0.00              | 0.00               |
| Repair Type:          |                                | Labor Hours      | 48.00          | 0.00              | 0.00               |
| Subcontractor:        |                                | Labor Costs      | \$972.48       | \$0.00            | \$0.00             |
| Profit Center:        |                                | Material Costs   | 0.00           | 0.00              | 0.00               |
|                       |                                | Fluids Costs     | 0.00           | 0.00              | 0.00               |
| Quantity: 0.00        | Lock: <input type="checkbox"/> | Equipment Costs  | 361.20         | 0.00              | 0.00               |
| Unit of Measure: Each |                                | Contractor Costs | 0.00           | 0.00              | 0.00               |
| *Unit Cost: \$0.00    |                                | Misc. Costs      | 0.00           | 0.00              | 0.00               |
| WO Hours: 0.00        |                                | Total Costs      | \$1,333.68     | \$0.00            | \$0.00             |
| Use Task Info:        |                                |                  | True           | True              |                    |

|                     |                   |                                                  |  |
|---------------------|-------------------|--------------------------------------------------|--|
| <b>Billed Party</b> |                   | <b>Billing</b>                                   |  |
| Customer ID:        | Customer Number:  |                                                  |  |
| Customer Name:      | Last Name:        |                                                  |  |
| Address:            | Phone:            | Cell #:                                          |  |
| City:               | Fax #:            |                                                  |  |
| State:              | E-mail:           |                                                  |  |
| Zip:                |                   |                                                  |  |
| <b>Billing Data</b> |                   |                                                  |  |
| Contact Name:       | *Billing Amount:  | Billing Required: <input type="checkbox"/>       |  |
| Invoice Number:     | Date Bill Sent:   | Billing Processed: <input type="checkbox"/>      |  |
| Incoming Account #: | Payment Received: | Imported to Financials: <input type="checkbox"/> |  |
|                     | Payment Method:   |                                                  |  |

|                                |                                     |
|--------------------------------|-------------------------------------|
| <b>Associated PMs</b>          |                                     |
| <u>PM Code and Description</u> | <u>Closed</u>                       |
| SSO-02 SSO INSPECTION          | <input checked="" type="checkbox"/> |

| <b>Tracking</b>         |                                           |           |             |             |
|-------------------------|-------------------------------------------|-----------|-------------|-------------|
| <u>Item</u>             | <u>Description</u>                        | <u>By</u> | <u>Date</u> | <u>Time</u> |
| Work Order Creation     | From Routine Work SSO-02 - SSO INSPECTION | aferrone  | 3/14/2022   | 11:08 AM    |
| Supervisor Notification | Email Queued Successfully!                | aferrone  | 3/14/2022   | 11:08 AM    |
| Status Change           | From New Work Order to Complete           | aferrone  | 3/14/2022   | 11:19 AM    |

|                       |                        |                                               |
|-----------------------|------------------------|-----------------------------------------------|
| Rate:                 | Opened At:             | Televised: <input type="checkbox"/>           |
| Recieved By:          | Pipe Footage Cleaned : | Power Rooter: <input type="checkbox"/>        |
| Work From:            | Gallons Used:          | Jet: <input type="checkbox"/>                 |
| Pipe Size:            | WO User 23:            | Gap Vac: <input type="checkbox"/>             |
| Pipe Condition:       | WO User 24:            | Dye Test: <input type="checkbox"/>            |
| Could Not Open:       | WO User 9:             | Gap Root Cut: <input type="checkbox"/>        |
| Additional Repair:    | User 10:               | GIS Correction?: <input type="checkbox"/>     |
| Dye Test Reason:      | Appointment Date DNL   | Test Tee Correction: <input type="checkbox"/> |
| Test Performed Throug | Appointment Date:      |                                               |
| Dye Test Results:     |                        |                                               |
| WO User 51:           |                        |                                               |
| Measurement:          | E Mail:                |                                               |
| History:              | Measurement Line 2:    |                                               |

## Work Order Detail Report

3/14/2022

SSO INSPECTIONS 3-7-2022 0.84" OF RAIN


11:20 AM

|                       |                             |                                       |
|-----------------------|-----------------------------|---------------------------------------|
| Manhole Basin Repair: | Pipe Size:                  |                                       |
| Material Used:        | PVC Tees, Angles, Slet      |                                       |
| Pipe Repair:          | WO User 44:                 |                                       |
| Street Repair:        | WO User 45:                 |                                       |
| Grass Repair:         | WO User 46:                 |                                       |
| Curb Repair:          |                             |                                       |
| Driveway- Sidewalk Re |                             |                                       |
| Construction Crew:    |                             |                                       |
| WO User 39:           |                             |                                       |
| WO User 40:           | OUPS #:                     |                                       |
| WO User 41:           | WO User 48:                 |                                       |
| WO User 52:           | WO User 62:                 |                                       |
| WO User 53:           | WO User 63:                 |                                       |
| WO User 54:           | WO User 64:                 |                                       |
| WO User 55:           | WO User 65:                 |                                       |
| WO User 56:           | WO User 66:                 |                                       |
| WO User 57:           | WO User 67:                 |                                       |
| WO User 58:           | WO User 68:                 |                                       |
| WO User 59:           | WO User 69:                 |                                       |
| WO User 60:           | WO User 70:                 |                                       |
| WO User 61:           | WO User 71:                 |                                       |
| WO User 72:           | WO User 82:                 | Televised: <input type="checkbox"/>   |
| WO User 73:           | Quantity:                   | Paid: <input type="checkbox"/>        |
| WO User 74:           | WO User 84:                 | WO User 104: <input type="checkbox"/> |
| WO User 75:           | WO User 85:                 | WO User 105: <input type="checkbox"/> |
| WO User 76:           | WO User 86:                 | WO User 106: <input type="checkbox"/> |
| WO User 92 Date:      | WO User 97 Date:            |                                       |
| WO User 93 Date:      | WO User 98 Date:            |                                       |
| WO User 94 Date:      | WO User 99 Date:            |                                       |
| WO User 95 Date:      | WO User 100 Date:           |                                       |
| WO User 96 Date:      | WO User 101 Date:           |                                       |
| WO User 77:           | WO User 87:                 | WO User 107: <input type="checkbox"/> |
| WO User 78:           | WO User 88:                 | WO User 108: <input type="checkbox"/> |
| WO User 79:           | WO User 89:                 | WO User 109: <input type="checkbox"/> |
| WO User 80:           | WO User 90:                 | WO User 110: <input type="checkbox"/> |
| WO User 81:           | WO User 91:                 | WO User 111: <input type="checkbox"/> |
| WO Creator: aferrone  | WO Creation Date: 3/14/2022 | PM Trigger: Rec #: 12479              |



Wednesday, March 23, 2022

### Accumulation in Inches



# Northeast Ohio Regional Sewer District

## Daily Precipitation Report

Wednesday, March 23, 2022

| Site Location             | Peak Accumulation (inches) |        |        |        |           |
|---------------------------|----------------------------|--------|--------|--------|-----------|
|                           | 24-Hour                    | 6-Hour | 3-Hour | 1-Hour | 15-Minute |
| Beachwood                 | 0.92                       | 0.78   | 0.66   | 0.57   | 0.28      |
| Brecksville               | 0.62                       | 0.50   | 0.37   | 0.29   | 0.14      |
| Brook Park                | 0.62                       | 0.53   | 0.35   | 0.29   | 0.23      |
| Cleveland Industrial Pkwy | 0.45                       | 0.36   | 0.32   | 0.28   | 0.22      |
| Dille Ave PS              | n/a                        | n/a    | n/a    | n/a    | n/a       |
| Division Ave PS           | 0.64                       | 0.54   | 0.29   | 0.20   | 0.17      |
| Easterly WWTP             | 0.56                       | 0.46   | 0.24   | 0.18   | 0.15      |
| Independence              | 0.78                       | 0.67   | 0.53   | 0.33   | 0.21      |
| James Rhodes HS           | 0.62                       | 0.54   | 0.39   | 0.24   | 0.22      |
| Jennings PS               | 0.50                       | 0.41   | 0.24   | 0.15   | 0.12      |
| Macedonia                 | 0.65                       | 0.48   | 0.44   | 0.26   | 0.12      |
| Maple Heights             | 0.88                       | 0.76   | 0.63   | 0.56   | 0.25      |
| Mary Street PS            | 0.71                       | 0.61   | 0.40   | 0.30   | 0.28      |
| Mayfield Heights          | 0.94                       | 0.78   | 0.69   | 0.52   | 0.26      |
| Moreland Hills            | 0.64                       | 0.49   | 0.40   | 0.25   | 0.10      |
| North Olmsted             | 0.41                       | 0.29   | 0.22   | 0.21   | 0.19      |
| North Royalton            | 0.98                       | 0.86   | 0.70   | 0.41   | 0.32      |
| Oakwood                   | 0.71                       | 0.59   | 0.51   | 0.37   | 0.27      |
| Olmsted Falls             | 0.46                       | 0.37   | 0.31   | 0.28   | 0.24      |
| Parma                     | 0.53                       | 0.43   | 0.26   | 0.15   | 0.08      |
| Richfield                 | 0.78                       | 0.63   | 0.51   | 0.31   | 0.15      |
| Shaker Heights            | 0.77                       | 0.64   | 0.50   | 0.31   | 0.16      |
| South Euclid              | 0.76                       | 0.62   | 0.40   | 0.21   | 0.14      |
| Southerly WWTC            | 0.73                       | 0.62   | 0.46   | 0.30   | 0.23      |
| Strongsville CWWTP        | 0.79                       | 0.69   | 0.51   | 0.44   | 0.40      |
| Strongsville Foltz        | 0.91                       | 0.82   | 0.64   | 0.53   | 0.51      |
| University Heights        | 0.73                       | 0.61   | 0.47   | 0.28   | 0.10      |
| Wade Park                 | 0.76                       | 0.64   | 0.40   | 0.32   | 0.24      |
| Westerly WWTP             | 0.54                       | 0.46   | 0.28   | 0.21   | 0.14      |
| Westlake                  | 0.35                       | 0.21   | 0.15   | 0.14   | 0.13      |




**Northeast Ohio  
Regional Sewer District**

### Daily Precipitation Report

Saturday, March 19, 2022

Accumulation in Inches



# Northeast Ohio Regional Sewer District

## Daily Precipitation Report

Saturday, March 19, 2022

| Site Location             | Peak Accumulation (inches) |        |        |        |           |
|---------------------------|----------------------------|--------|--------|--------|-----------|
|                           | 24-Hour                    | 6-Hour | 3-Hour | 1-Hour | 15-Minute |
| Beachwood                 | 0.33                       | 0.18   | 0.17   | 0.11   | 0.05      |
| Brecksville               | 0.44                       | 0.22   | 0.20   | 0.15   | 0.07      |
| Brook Park                | 0.50                       | 0.24   | 0.24   | 0.23   | 0.13      |
| Cleveland Industrial Pkwy | 0.34                       | 0.18   | 0.18   | 0.16   | 0.08      |
| Dille Ave PS              | n/a                        | n/a    | n/a    | n/a    | n/a       |
| Division Ave PS           | 0.38                       | 0.19   | 0.19   | 0.16   | 0.08      |
| Easterly WWTP             | 0.43                       | 0.24   | 0.23   | 0.19   | 0.08      |
| Independence              | 0.27                       | 0.16   | 0.16   | 0.13   | 0.05      |
| James Rhodes HS           | 0.34                       | 0.16   | 0.16   | 0.15   | 0.11      |
| Jennings PS               | 0.35                       | 0.17   | 0.17   | 0.16   | 0.12      |
| Macedonia                 | 0.52                       | 0.28   | 0.26   | 0.24   | 0.11      |
| Maple Heights             | 0.25                       | 0.13   | 0.13   | 0.09   | 0.04      |
| Mary Street PS            | 0.35                       | 0.17   | 0.17   | 0.16   | 0.12      |
| Mayfield Heights          | 0.36                       | 0.19   | 0.19   | 0.10   | 0.04      |
| Moreland Hills            | 0.62                       | 0.29   | 0.27   | 0.23   | 0.15      |
| North Olmsted             | 0.39                       | 0.18   | 0.18   | 0.15   | 0.08      |
| North Royalton            | 0.31                       | 0.20   | 0.20   | 0.17   | 0.06      |
| Oakwood                   | 0.52                       | 0.27   | 0.27   | 0.20   | 0.16      |
| Olmsted Falls             | 0.46                       | 0.28   | 0.28   | 0.16   | 0.08      |
| Parma                     | 0.32                       | 0.17   | 0.17   | 0.15   | 0.07      |
| Richfield                 | 0.74                       | 0.43   | 0.43   | 0.30   | 0.26      |
| Shaker Heights            | 0.24                       | 0.14   | 0.14   | 0.12   | 0.04      |
| South Euclid              | 0.40                       | 0.18   | 0.18   | 0.15   | 0.07      |
| Southerly WWTC            | 0.28                       | 0.18   | 0.17   | 0.16   | 0.06      |
| Strongsville CWWTP        | 0.45                       | 0.24   | 0.24   | 0.21   | 0.09      |
| Strongsville Foltz        | 0.32                       | 0.23   | 0.23   | 0.20   | 0.08      |
| University Heights        | 0.30                       | 0.16   | 0.16   | 0.13   | 0.05      |
| Wade Park                 | 0.33                       | 0.15   | 0.15   | 0.14   | 0.08      |
| Westerly WWTP             | 0.41                       | 0.20   | 0.20   | 0.16   | 0.09      |
| Westlake                  | 0.39                       | 0.20   | 0.18   | 0.14   | 0.07      |

3/25/2022

12:57 PM

**Work Order Detail Report**

SSO INSPECTIONS 3-24-2022 0.73 INCHES OF RAIN

WO Number: 220325-0006      Category: SSOs  
 Status: Complete      Problem: Storm Response  
 Status Date: 3/25/2022 12:56 pm      Main Task: Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause: Weather

Assigned Crew:

Supervisor: Jackson, Jeff

Lead Worker: Eathridge, David

Priority: High

Account #:

Proj No - Acct:

Project:

Reason:

Received By:

Inspected By:

Assigned By:

Assigned Date: 3/23/2022

Start Date: 3/24/2022 7:45 AM

End Date: 3/24/2022 2:45 PM

OverrideNotificationsProblem ☐Overdue ☐Lead Worker ☐Task ☐Supervisor ☐Hard Lock WO ☐

Project ID:

Project Name:

**Request Comments for Work Order**

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer Collection

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

**Comments for Crew**

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

**Work Order Locations**

| <u>Address</u>                        |                  | <u>Address 2</u>         |
|---------------------------------------|------------------|--------------------------|
| <u>X Coord</u>                        | <u>Y Coord</u>   | <u>General Location</u>  |
| FAIRFAX AT NORTH PARK                 |                  |                          |
| 2,220,655.65435414                    | 665,517.24643672 | Doan Brook               |
| NORTH PARK AND COVENTRY               |                  |                          |
| 2,219,873.16674590                    | 666,048.82312946 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT SOUTH OF SCARBOROUGH        |                  |                          |
| 2,220,364.86097248                    | 666,446.72325230 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT FAIRFAX                  |                  |                          |
| 2,220,920.81917815                    | 666,080.57995571 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT NORTH WOODLAND (S. SIDE) |                  |                          |
| 2,223,053.81655256                    | 664,693.25202172 | DOAN BROOK - MAIN BRANCH |
| 3012 NORTH WOODLAND                   |                  |                          |
| 2,222,845.06631389                    | 664,689.08536339 | Doan Brook               |
| 2,226,440.21168285                    | 664,329.55524255 |                          |
| 2,226,354.79813956                    | 664,409.89202413 |                          |
| 2,226,389.92077273                    | 664,379.07548472 |                          |
| FAIRMOUNT AT DARTMOOR                 |                  |                          |
| 2,225,149.97508989                    | 664,453.31024438 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT WELLINGTON               |                  |                          |
| 2,223,969.26550905                    | 664,532.08075613 | DOAN BROOK - MAIN BRANCH |

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220325-0006

**Work Order Detail Report**

SSO INSPECTIONS 3-24-2022 0.73 INCHES OF RAIN

|                                                    |                  |                                      |
|----------------------------------------------------|------------------|--------------------------------------|
| FAIRMOUNT AT NORTH WOODLAND (N. SIDE)              |                  |                                      |
| 2,223,111.44143730                                 | 664,794.46048072 | DOAN BROOK - MAIN BRANCH             |
| FAIRMOUNT AT MARLBORO                              |                  |                                      |
| 2,221,638.88762389                                 | 665,726.15513962 | DOAN BROOK - MAIN BRANCH             |
| FAIRMOUNT AT ARLINGTON                             |                  |                                      |
| 2,222,127.85875881                                 | 665,393.74077822 | DOAN BROOK - MAIN BRANCH             |
| FAIRMOUNT & COVENTRY (SCARBOROUGH)                 |                  |                                      |
| 2,220,278.63411081                                 | 667,231.62916280 | DOAN BROOK - MAIN BRANCH             |
| FAIRMOUNT AND COVENTRY                             |                  |                                      |
| 2,220,419.37169023                                 | 666,567.10752596 | DOAN BROOK - MAIN BRANCH             |
| SCARBOROUGH AT LAMBERTON                           |                  |                                      |
| 2,221,598.28993607                                 | 666,996.61322863 |                                      |
| MONMOUTH, EAST OF DARTMOOR                         |                  |                                      |
| 2,225,152.08663423                                 | 665,499.19660404 | DOAN BROOK                           |
| BRADFORD AND LEE                                   |                  |                                      |
| 2,224,643.84191582                                 | 665,970.39907372 | DOAN BROOK - MAIN BRANCH             |
| EDDINGTON                                          |                  |                                      |
| 2,221,299.08384156                                 | 674,932.84604380 |                                      |
| HAMPSHIRE LANE AT MAYFIELD (18")                   |                  |                                      |
| 2,219,348.17140481                                 | 672,922.02624655 | DUGWAY CREEK - MAIN BRANCH           |
| EAST OVERLOOK AT EDGEHILL                          |                  |                                      |
| 2,218,479.60588473                                 | 671,538.70289771 | DOAN BROOK - MAIN BRANCH             |
| HAMPSHIRE LANE AT MAYFIELD (36")                   |                  |                                      |
| 2,219,354.97683740                                 | 672,902.85961822 | DUGWAY CREEK - MAIN BRANCH           |
| 2600 HAMPSHIRE RD                                  |                  |                                      |
|                                                    |                  |                                      |
| HAMPSHIRE AT EUCLID HTS. BLVD.                     |                  |                                      |
| 2,218,465.44876081                                 | 671,703.91811846 | DOAN BROOK - MAIN BRANCH             |
| CEDAR BTW. FAIRMOUNT/DEMINGTON                     |                  |                                      |
| 2,218,036.25112839                                 | 669,668.09115338 | DOAN BROOK - MAIN BRANCH             |
| 2828 BERKSHIRE, EAST OF COVENTRY                   |                  |                                      |
| 2,220,768.48319674                                 | 670,614.63814481 | DUGWAY CREEK - MAIN BRANCH           |
| 3003 EUCLID HEIGHTS BLVD                           |                  |                                      |
| 2,222,538.05642922                                 | 672,458.71614955 | DUGWAY CREEK - MAIN BRANCH           |
| South Taylor between Antisdale Ave and Superior Rd |                  |                                      |
| 2,227,113.30810548                                 | 671,276.67684697 |                                      |
| LEE RD. & SUPERIOR AVE.                            |                  |                                      |
| 2,224,449.07983814                                 | 672,366.92072946 | HEIGHT = NA, WIDTH = NA, LENGTH = NA |
| EUCLID HEIGHTS BLVD AND LEE                        |                  |                                      |
| 2,224,196.49208874                                 | 673,102.72798488 | DUGWAY CREEK - MAIN BRANCH           |
| EUCLID HEIGHTS BLVD/CUMBERLAND                     |                  |                                      |
| 2,223,890.24106081                                 | 672,984.80925746 | DUGWAY CREEK - MAIN BRANCH           |
| 1685 CUMBERLAND                                    |                  |                                      |
| 2,223,414.40769489                                 | 674,158.55920655 | DUGWAY CREEK - MAIN BRANCH           |
| CUMBERLAND/SOMERTON                                |                  |                                      |
| 2,223,678.60992239                                 | 673,517.13791722 | DUGWAY CREEK - MAIN BRANCH           |
| 2225 NOBLE RD                                      |                  |                                      |
|                                                    |                  |                                      |
| 2225 NOBLE ROAD                                    |                  |                                      |
| 2,227,020.20068015                                 | 682,910.03907888 | NINE MILE CREEK - MAIN BRANCH        |
| QUILLIAMS, N. OF RANDOLF                           |                  |                                      |
| 2,229,594.65878581                                 | 682,393.53289405 | NINE MILE CREEK - MAIN BRANCH        |
| LANGTON AND ATHERSTONE                             |                  |                                      |
| 2,228,126.76638040                                 | 684,188.23206055 |                                      |
|                                                    |                  |                                      |
| 2,220,777.89623564                                 | 666,181.72575080 |                                      |
|                                                    |                  |                                      |
| 2,218,501.67473823                                 | 671,997.54581206 |                                      |
|                                                    |                  |                                      |
| 2,216,759.55453481                                 | 670,474.59347738 |                                      |

\* A 'Hidden' field indicates permission to view the secured field is turned off.

3/25/2022

## Work Order Detail Report

12:57 PM

SSO INSPECTIONS 3-24-2022 0.73 INCHES OF RAIN

|                    |                  |
|--------------------|------------------|
| 2,224,536.21778722 | 668,887.44048372 |
| 2,226,741.35609348 | 679,432.95121680 |
| 2,226,591.76420106 | 679,420.92761880 |
| 2,227,825.14395215 | 684,881.15948047 |

**Work Order Detail Report**

SSO INSPECTIONS 3-24-2022 0.73 INCHES OF RAIN

| Work Order Assets   |             | Description 1 |          |           | Description 2 | Asset ID                              | Completed |
|---------------------|-------------|---------------|----------|-----------|---------------|---------------------------------------|-----------|
| Object Type         | System ID 1 | System ID 2   | Odometer | Hourmeter | Othermeter    | PM Description                        |           |
| Sewer Control Valve | SSO 431     |               |          |           |               | FAIRFAX AT NORTH PARK                 | 26        |
| Sewer Control Valve | SSO 114     |               |          |           |               | NORTH PARK AND COVENTRY               | 16        |
| Sewer Control Valve | SSO 121     |               |          |           |               | FAIRMOUNT SOUTH OF SCARBOROUGH        | 35        |
| Sewer Structure     | SA16AAWB0   |               |          |           |               |                                       | 3094      |
| Sewer Control Valve | SSO 112     |               |          |           |               | FAIRMOUNT AT FAIRFAX                  | 7         |
| Sewer Control Valve | SSO 99      |               |          |           |               | FAIRMOUNT AT NORTH WOODLAND (S. SIDE) | 6         |
| Sewer Control Valve | SSO 432     |               |          |           |               | 3012 NORTH WOODLAND                   | 14        |
| Sewer Control Valve | DB-03       |               |          |           |               |                                       | 55        |
| Sewer Control Valve | DB-01       |               |          |           |               |                                       | 56        |
| Sewer Control Valve | DB-02       |               |          |           |               |                                       | 57        |
| Sewer Control Valve | CH-04       |               |          |           |               | FAIRMOUNT AT DARTMOOR                 | 5         |
| Sewer Control Valve | SSO 110     |               |          |           |               | FAIRMOUNT AT WELLINGTON               | 44        |
| Sewer Control Valve | SSO 87      |               |          |           |               | FAIRMOUNT AT NORTH WOODLAND (N. SIDE) | 33        |
| Sewer Control Valve | SSO 116     |               |          |           |               | FAIRMOUNT AT MARLBORO                 | 4         |
| Sewer Control Valve | SSO 111     |               |          |           |               | FAIRMOUNT AT ARLINGTON                | 46        |
| Sewer Control Valve | SSO 113     |               |          |           |               | FAIRMOUNT & COVENTRY (SCARBOROUGH)    | 37        |
| Sewer Control Valve | SSO 124     |               |          |           |               | FAIRMOUNT AND COVENTRY                | 47        |
| Sewer Control Valve | CH-50       |               |          |           |               | SCARBOROUGH AT LAMBERTON              | 53        |
| Sewer Control Valve | SSO 129     |               |          |           |               | BRADFORD AND LEE                      | 11        |
| Sewer Control Valve | CH-52       |               |          |           |               | EDDINGTON                             | 2         |
| Sewer Control Valve | SSO 88      |               |          |           |               | HAMPSHIRE LANE AT MAYFIELD (18")      | 42        |
| Sewer Control Valve | SSO 122     |               |          |           |               | EAST OVERLOOK AT EDGEHILL             | 36        |
| Sewer Control Valve | SSO 89      |               |          |           |               | HAMPSHIRE LANE AT MAYFIELD (36")      | 34        |
| Sewer Structure     | SA16ADZB0   |               |          |           |               |                                       | 1536      |
| Sewer Control Valve | SSO 91      |               |          |           |               | HAMPSHIRE AT EUCLID HTS. BLVD.        | 20        |
| Sewer Structure     | SA16ADPH0   |               |          |           |               |                                       | 4446      |
| Sewer Control Valve | SSO 120     |               |          |           |               | CEDAR BTW. FAIRMOUNT/DEMINGTON        | 8         |
| Sewer Control Valve |             |               |          |           |               | 2828 BERKSHIRE, EAST OF COVENTRY      |           |

\* A 'Hidden' field indicates permission to view the secured field is turned off.

**Work Order Detail Report**

SSO INSPECTIONS 3-24-2022 0.73 INCHES OF RAIN

|                     |                                                   |
|---------------------|---------------------------------------------------|
| SSO 103             | 19                                                |
| Sewer Control Valve | 3003 EUCLID HEIGHTS BLVD                          |
| SSO 104             | 15                                                |
| Sewer Structure     | 3402                                              |
| SA16AGMG0           | South Taylor between Antisdale Ave and Superior F |
| Sewer Control Valve | 52                                                |
| CH-30               | LEE RD. & SUPERIOR AVE.                           |
| Sewer Control Valve | 9                                                 |
| DV-11               | EUCLID HEIGHTS BLVD AND LEE                       |
| Sewer Control Valve | 22                                                |
| SSO 108             | EUCLID HEIGHTS BLVD/CUMBERLAND                    |
| Sewer Control Valve | 43                                                |
| SSO 106             | 1685 CUMBERLAND                                   |
| Sewer Control Valve | 18                                                |
| SSO 95              | CUMBERLAND/SOMERTON                               |
| Sewer Control Valve | 30                                                |
| SSO 105             |                                                   |
| Sewer Structure     | 4987                                              |
| SA16AQD0            |                                                   |
| Sewer Structure     | 3745                                              |
| SA16AQQC0           | 2225 NOBLE ROAD                                   |
| Sewer Control Valve | 3                                                 |
| SSO 102             | QUILLIAMS, N. OF RANDOLF                          |
| Sewer Control Valve | 38                                                |
| SSO 107             | LANGTON AND ATHERSTONE                            |
| Sewer Control Valve | 54                                                |
| CH-51               |                                                   |
| Sewer Structure     | 1809                                              |
| SA16APEF0           |                                                   |

**Work Order Detail Report**

SSO INSPECTIONS 3-24-2022 0.73 INCHES OF RAIN

| Check List |                                                                                | Completed                | Condition | Completion Date/Time | Est Completion Date |
|------------|--------------------------------------------------------------------------------|--------------------------|-----------|----------------------|---------------------|
| Item       |                                                                                |                          |           |                      |                     |
| 1          | A-37-FAIRFAX AT NORTH PARK<br>SA16ACPG0                                        | <input type="checkbox"/> | Not Sound | 3/24/2022/           |                     |
| 2          | A-36-NORTH PARK AT COVENTRY<br>SA16ACNB0 (IN MEDIAN-CEMENT)                    | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 3          | A-45-FAIRMOUNT ( IN THE ISLAND<br>EAST OF COVENTRY) SA16ACNE0                  | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 4          | A-54-2806 FAIRMOUNT SA16AAWB0<br>(TREE LAWN BY SIDEWALK)                       | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 5          | A-33-FAIRMOUNT AT FAIRFAX<br>SA16AAWC0 (SW CORNER IN THE<br>SIDEWALK)          | <input type="checkbox"/> | Not Sound | 3/24/2022/           |                     |
| 6          | A-39-3012 NORTH WOODLAND<br>SA16AAWM5 (TREE LAWN)                              | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 7          | A-2 FAIRMOUNT AT NORTH<br>WOODLAND SA16AAWK0(MIDDLE<br>OF THE ROAD)            | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 8          | A-6 FAIRMOUNT AT SHELBURNE<br>ST16ZBJK0 (WEST BOUND LANE)                      | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 9          | A-5 FAIRMOUNT AT SHELBURNE<br>SA16AAXB0(ON THE SE CORNER IN<br>THE SIDEWALK)   | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 10         | A-7 FAIRMOUNT AT SHELBURNE<br>SA16AAVH0 (EAST BOUND)                           | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 11         | A-4 FAIRMOUNT AT DARTMOOR<br>SA16AAVB0(NW CORNER IN THE<br>GRASS BY STOP SIGN) | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 12         | A-3 FAIRMOUNT AT WELLINGTON<br>SA16AAUW0 (INTERSECTION)                        | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 13         | A-1 3041 FAIRMOUNT SA16AAUT0<br>(TREE LAWN NEAR SIDEWALK)                      | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 14         | A-32 FAIRMOUNT AT ARLINGTON<br>SA16AAUP0 (INTERSECTION)                        | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 15         | A-38 FAIRMOUNT AT MARLBORO<br>SA16AAUM0 (INTERSECTION)                         | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 16         | A-49 2757 FAIRMOUNT SA16AAUC0<br>(EAST OF CHURCH IN TREE LAWN)                 | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 17         | A-35 2393 COVENTRY SA16AASK0<br>(INTERSECTION)                                 | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 18         | A-50 SCARBOROUGH AND<br>LAMBERTON SA16AANE5<br>(INTERSECTION)                  | <input type="checkbox"/> | Not Sound | 3/24/2022/           |                     |
| 19         | A-47 2528 STRATFORD SA16ACDB5<br>(INTERSECTION)                                | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 20         | A-57 E MONMOUTH SA16AFWA5<br>WEST OF (DARTMOOR NEAR LEE)                       | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 21         | A-58 E MONMOUTH AT EXETER<br>(INTERSECTION)                                    | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 22         | A-9 BRADFORD AT LEE SA16AFLLO<br>(INTERSECTION)                                | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 23         | B-52 EDDINGTON NORTH OF<br>AVONDALE SA16AHVE0                                  | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 24         | B-10 HAMPSHIRE LANE AT MAYFIELD<br>SA16BACB0                                   | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 25         | B-11 HAMPSHIRE LANE AT MAYFIELD<br>SA16AEEA0                                   | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 26         | B-61 2600 HAMPSHIRE SA16ADZB0                                                  | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |
| 27         | HAMPSHIRE AT EUCLID HTS. BLVD.<br>SA16ADPR0                                    | <input type="checkbox"/> | Sound     | 3/24/2022/           |                     |

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220325-0006

**Work Order Detail Report**

SSO INSPECTIONS 3-24-2022 0.73 INCHES OF RAIN

|                  |                                                  |                          |           |            |
|------------------|--------------------------------------------------|--------------------------|-----------|------------|
| 28               | B-46 EDGEHILL AT E OVERLOOK<br>SA16AEPF0         | <input type="checkbox"/> | Not Sound | 3/24/2022/ |
| needs block      |                                                  |                          |           |            |
| 29               | B-42 12537 CEDAR SA16ACZA0                       | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 30               | B-15 COVENTRY AND CEDAR<br>SA16ADBH0             | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 31               | B-23 2828 BERKSHIRE SA16AETA0                    | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 32               | B-24 3003 EUCLID HTS. BLVD.<br>ST16AALB0         | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 33               | B-56 LEE AND MEADOWBROOK<br>SA16AGMG0            | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 34               | C-30 S TAYLOR NORTH OF<br>SUPERIOR SA16AIVF0     | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 35               | C-12 LEE AND SUPERIOR<br>SA16AGTJ0               | <input type="checkbox"/> |           | 3/24/2022/ |
| water main break |                                                  |                          |           |            |
| 36               | C-28 EUCLID HTS. BLVD AND LEE RD<br>SA16AGTE0    | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 37               | C-26 EUCLID HTS BLVD AND<br>CUMBERLAND SA16AIRL0 | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 38               | C-25 CUMBERLAND AND SOMERTON<br>SA16AISA0        | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 39               | C-17 1685 CUMBERLAND RD<br>SA16AQIQB0            | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 40               | C-59 3427 THORNE RD SA16AQD0                     | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 41               | C-60 3415 THORNE RD SA16AQD0                     | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 42               | C-22 2225 NOBLE RD ST16ZLHB0                     | <input type="checkbox"/> | Not Sound | 3/24/2022/ |
| could not locate |                                                  |                          |           |            |
| 43               | C-27 QUILLIAMS NORTH OF<br>RANDOLPH SA16AOUQ0    | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 44               | C-51 ATHERSTONE AND LANGTON<br>SA16AOKA0         | <input type="checkbox"/> | Sound     | 3/24/2022/ |
| 45               | C-50 3593 FENLEY SA16APEH0                       | <input type="checkbox"/> | Sound     | 3/24/2022/ |

**Tasks/Resources****SWCT26 Inspection**

Crew:

Supervisor: Jackson, Jeff

Status: Complete

UOM: Each

\*Cal'c UC: \$11.56

# of Units: 45.00

\*Task Cost: \$520.00

\*Unit Cost: \$0.00

Start Dt: 3/24/2022

End Dt: 3/24/2022

| Employee                   |  | UOM   | Units | *Total Cost | Alt Description | Start Dt  | End Dt    |
|----------------------------|--|-------|-------|-------------|-----------------|-----------|-----------|
| Resource                   |  |       |       |             |                 |           |           |
| 12459 Eathridge, David     |  | Hours | 4.00  | \$90.56     |                 | 3/24/2022 | 3/24/2022 |
| 28056 Palmisano, Anthony   |  | Hours | 4.00  | \$80.24     |                 | 3/24/2022 | 3/24/2022 |
| 39986 OBrien, Dominick     |  | Hours | 4.00  | \$82.64     |                 | 3/24/2022 | 3/24/2022 |
| 13859 Moten, Robert        |  | Hours | 4.00  | \$88.76     |                 | 3/24/2022 | 3/24/2022 |
| Equipment                  |  | UOM   | Units | *Total Cost | Alt Description | Start Dt  | End Dt    |
| Resource                   |  |       |       |             |                 |           |           |
| CHFLT50 FORD F250 CREW CAB |  | Hours | 4.00  | \$53.60     |                 | 3/24/2022 | 3/24/2022 |
| 5                          |  |       |       |             |                 |           |           |
| CHFLT55 FORD F250 PICK UP  |  | Hours | 4.00  | \$53.60     |                 | 3/24/2022 | 3/24/2022 |
| 0                          |  |       |       |             |                 |           |           |
| CHFLT55 FORD 350 CREW CAB  |  | Hours | 4.00  | \$70.60     |                 | 3/24/2022 | 3/24/2022 |
| 9                          |  |       |       |             |                 |           |           |

Task Comment: SSO INSPECTION 0.73 INCHES OF RAIN

**Work Order Detail Report**

SSO INSPECTIONS 3-24-2022 0.73 INCHES OF RAIN

|                       |                                |                  | <u>*Actual</u> | <u>*Estimated</u> | <u>*Difference</u> |
|-----------------------|--------------------------------|------------------|----------------|-------------------|--------------------|
| Projected Complete:   | Lock: <input type="checkbox"/> | WO Duration      | 7.00           | 0.00              | 0.00               |
| Repair Type:          |                                | Labor Hours      | 16.00          | 0.00              | 0.00               |
| Subcontractor:        |                                | Labor Costs      | \$342.20       | \$0.00            | \$0.00             |
| Profit Center:        |                                | Material Costs   | 0.00           | 0.00              | 0.00               |
|                       |                                | Fluids Costs     | 0.00           | 0.00              | 0.00               |
| Quantity: 0.00        | Lock: <input type="checkbox"/> | Equipment Costs  | 177.80         | 0.00              | 0.00               |
| Unit of Measure: Each |                                | Contractor Costs | 0.00           | 0.00              | 0.00               |
| *Unit Cost: \$0.00    |                                | Misc. Costs      | 0.00           | 0.00              | 0.00               |
| WO Hours: 0.00        |                                | Total Costs      | \$520.00       | \$0.00            | \$0.00             |
|                       |                                | Use Task Info:   | True           | True              |                    |

| Billing             |                                                  |
|---------------------|--------------------------------------------------|
| <b>Billed Party</b> | <b>Customer Number:</b>                          |
| Customer ID:        | Last Name:                                       |
| Customer Name:      | Phone:                                           |
| Address:            | Cell #:                                          |
| City:               | Fax #:                                           |
| State:              | E-mail:                                          |
| Zip:                |                                                  |
| <b>Billing Data</b> |                                                  |
| Contact Name:       | *Billing Amount:                                 |
| Invoice Number:     | Date Bill Sent:                                  |
| Incoming Account #: | Payment Received:                                |
|                     | Payment Method:                                  |
|                     | Billing Required: <input type="checkbox"/>       |
|                     | Billing Processed: <input type="checkbox"/>      |
|                     | Imported to Financials: <input type="checkbox"/> |

| Associated PMs                 |                                     |
|--------------------------------|-------------------------------------|
| <u>PM Code and Description</u> | <u>Closed</u>                       |
| SSO-02 SSO INSPECTION          | <input checked="" type="checkbox"/> |

| Item                    | Description                               | By       | Date      | Time     |
|-------------------------|-------------------------------------------|----------|-----------|----------|
| Work Order Creation     | From Routine Work SSO-02 - SSO INSPECTION | aferrone | 3/25/2022 | 12:33 PM |
| Supervisor Notification | Email Queued Successfully!                | aferrone | 3/25/2022 | 12:33 PM |
| Status Change           | From New Work Order to Complete           | aferrone | 3/25/2022 | 12:56 PM |

|                       |                        |                                               |
|-----------------------|------------------------|-----------------------------------------------|
| Rate:                 | Opened At:             | Televised: <input type="checkbox"/>           |
| Recieved By:          | Pipe Footage Cleaned : | Power Rooter: <input type="checkbox"/>        |
| Work From:            | Gallons Used:          | Jet: <input type="checkbox"/>                 |
| Pipe Size:            | WO User 23:            | Gap Vac: <input type="checkbox"/>             |
| Pipe Condition:       | WO User 24:            | Dye Test: <input type="checkbox"/>            |
| Could Not Open:       | WO User 9:             | Gap Root Cut: <input type="checkbox"/>        |
| Additional Repair:    | User 10:               | GIS Correction?: <input type="checkbox"/>     |
| Dye Test Reason:      | Appointment Date DNL   | Test Tee Correction: <input type="checkbox"/> |
| Test Performed Throug | Appointment Date:      |                                               |
| Dye Test Results:     |                        |                                               |
| WO User 51:           | E Mail:                |                                               |
| Measurement:          | Measurement Line 2:    |                                               |
| History:              |                        |                                               |

## Work Order Detail Report

3/25/2022

12:57 PM

SSO INSPECTIONS 3-24-2022 0.73 INCHES OF RAIN

Manhole Basin Repair:

Material Used:

Pipe Repair:

Street Repair:

Grass Repair:

Curb Repair:

Driveway- Sidewalk Re

Construction Crew:

WO User 39:

WO User 40:

WO User 41:

Pipe Size:

PVC Tees, Angles, Slec

WO User 44:

WO User 45:

WO User 46:

OUPS #:

WO User 48:

WO User 52:

WO User 53:

WO User 54:

WO User 55:

WO User 56:

WO User 57:

WO User 58:

WO User 59:

WO User 60:

WO User 61:

WO User 72:

WO User 73:

WO User 74:

WO User 75:

WO User 76:

WO User 62:

WO User 63:

WO User 64:

WO User 65:

WO User 66:

WO User 67:

WO User 68:

WO User 69:

WO User 70:

WO User 71:

WO User 82:

Quantity:

WO User 84:

WO User 85:

WO User 86:

Televised:

Paid:

WO User 104:

WO User 105:

WO User 106:

☐☐☐☐☐

WO User 92 Date:

WO User 93 Date:

WO User 94 Date:

WO User 95 Date:

WO User 96 Date:

WO User 97 Date:

WO User 98 Date:

WO User 99 Date:

WO User 100 Date:

WO User 101 Date:

WO User 77:

WO User 78:

WO User 79:

WO User 80:

WO User 81:

WO User 87:

WO User 88:

WO User 89:

WO User 90:

WO User 91:

WO User 107:

WO User 108:

WO User 109:

WO User 110:

WO User 111:

☐☐☐☐☐

WO Creator: aferrone

WO Creation Date:

3/25/2022

PM Trigger:

Rec #: 12514