



Daily Precipitation Report

Tuesday, June 7, 2022

Accumulation in Inches

Lake
County

Mayfield
Heights
0.22

South
Euclid
0.52

University
Heights
0.74

Beachwood
1.10

Easterly
WWTP
0.30

Wade
Park
0.37

Shaker
Heights
0.98

Moreland
Hills
0.68

Oakwood
1.08

Summit
County

Westerly
WWTP
0.31

Division PS
0.34

Dille PS
0.37

Mary
Street PS
0.38

Jennings PS
0.74

Southerly
WWTC
0.49

Maple
Heights
0.51

Independence
0.53

Macedonia
0.80

Brecksville
0.72

Richfield
0.75

Lake Erie

James
Rhodes HS
0.44

Cleveland
Industrial Pkwy
0.49

Parma
0.55

Strongsville
"C" WWTP
0.57

Cuyahoga
County

North
Royalton
1.03

Medina
County
1.15

Westlake
0.69

North
Olmsted
0.50

Olmsted
Falls
0.91

Strongsville
Foltz
0.80

Lorain
County

Northeast Ohio Regional Sewer District

Daily Precipitation Report

Tuesday, June 7, 2022

| Site Location | Peak Accumulation (inches) | | | | |
|---------------------------|----------------------------|--------|--------|--------|-----------|
| | 24-Hour | 6-Hour | 3-Hour | 1-Hour | 15-Minute |
| Beachwood | 1.10 | 0.66 | 0.43 | 0.39 | 0.36 |
| Brecksville | 0.72 | 0.53 | 0.48 | 0.25 | 0.10 |
| Brook Park | 0.57 | 0.32 | 0.32 | 0.19 | 0.07 |
| Cleveland Industrial Pkwy | 0.49 | 0.33 | 0.25 | 0.14 | 0.10 |
| Dille Ave PS | 0.37 | 0.28 | 0.19 | 0.10 | 0.06 |
| Division Ave PS | 0.34 | 0.29 | 0.17 | 0.08 | 0.05 |
| Easterly WWTP | 0.30 | 0.29 | 0.20 | 0.10 | 0.05 |
| Independence | 0.53 | 0.38 | 0.35 | 0.18 | 0.07 |
| James Rhodes HS | 0.44 | 0.27 | 0.22 | 0.15 | 0.09 |
| Jennings PS | 0.74 | 0.45 | 0.45 | 0.38 | 0.32 |
| Macedonia | 0.80 | 0.51 | 0.47 | 0.23 | 0.09 |
| Maple Heights | 0.51 | 0.40 | 0.38 | 0.22 | 0.08 |
| Mary Street PS | 0.38 | 0.31 | 0.19 | 0.09 | 0.05 |
| Mayfield Heights | 0.22 | 0.13 | 0.07 | 0.03 | 0.01 |
| Moreland Hills | 0.68 | 0.59 | 0.53 | 0.23 | 0.10 |
| North Olmsted | 0.50 | 0.28 | 0.21 | 0.18 | 0.10 |
| North Royalton | 1.03 | 0.52 | 0.47 | 0.24 | 0.12 |
| Oakwood | 1.08 | 0.65 | 0.63 | 0.51 | 0.31 |
| Olmsted Falls | 0.91 | 0.70 | 0.70 | 0.42 | 0.22 |
| Parma | 0.55 | 0.39 | 0.36 | 0.19 | 0.07 |
| Richfield | 0.75 | 0.62 | 0.56 | 0.26 | 0.10 |
| Shaker Heights | 0.98 | 0.54 | 0.52 | 0.46 | 0.32 |
| South Euclid | 0.52 | 0.50 | 0.34 | 0.17 | 0.06 |
| Southerly WWTC | 0.49 | 0.33 | 0.31 | 0.17 | 0.07 |
| Strongsville C WWTP | 0.64 | 0.33 | 0.31 | 0.18 | 0.12 |
| Strongsville Foltz | 0.80 | 0.42 | 0.36 | 0.24 | 0.20 |
| University Heights | 0.74 | 0.62 | 0.45 | 0.24 | 0.08 |
| Wade Park | 0.37 | 0.34 | 0.23 | 0.11 | 0.04 |
| Westerly WWTP | 0.31 | 0.27 | 0.16 | 0.07 | 0.05 |
| Westlake | 0.69 | 0.68 | 0.46 | 0.29 | 0.11 |

Work Order Detail Report

6/13/2022

SSO INSPECTION 6-7-2022 0.74 INCHES OF RAIN

12:34 PM

| | | | |
|--|--------------------|-----------------------|--|
| WO Number: | 220613-0001 | Category: | SSOs |
| Status: | Complete | Problem: | Storm Response |
| Status Date: | 6/13/2022 12:33 pm | Main Task: | Inspection |
| Asset: SSO 431 | | | |
| Location: FAIRFAX AT NORTH PARK | | | |
| Cause: | Weather | Assigned By: | 29960 Jackson, Jeff |
| Assigned Crew: | | Assigned Date: | 6/7/2022 |
| Supervisor: | Jackson, Jeff | Start Date: | 6/9/2022 7:29 AM |
| Lead Worker: | Mc Coy, Sam | End Date: | 6/9/2022 3:29 PM |
| Priority: | High | | Override Notifications |
| Account #: | | | Problem <input type="checkbox"/> |
| Proj No - Acct: | | | Overdue <input type="checkbox"/> |
| Project: | | Project ID: | Lead Worker <input type="checkbox"/> |
| Reason: | | Project Name: | Task <input type="checkbox"/> |
| Received By: | | | Supervisor <input type="checkbox"/> |
| Inspected By: | | | Hard Lock WO <input type="checkbox"/> |

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

| Work Order Locations | | | Address 2 |
|---------------------------------------|--------------------|------------------|--------------------------|
| <u>Address</u> | <u>X Coord</u> | <u>Y Coord</u> | <u>General Location</u> |
| FAIRFAX AT NORTH PARK | 2,220,655.65435414 | 665,517.24643672 | Doan Brook |
| NORTH PARK AND COVENTRY | 2,219,873.16674590 | 666,048.82312946 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT SOUTH OF SCARBOROUGH | 2,220,364.86097248 | 666,446.72325230 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT FAIRFAX | 2,220,920.81917815 | 666,080.57995571 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT NORTH WOODLAND (S. SIDE) | 2,223,053.81655256 | 664,693.25202172 | DOAN BROOK - MAIN BRANCH |
| 3012 NORTH WOODLAND | 2,222,845.06631389 | 664,689.08536339 | Doan Brook |
| | 2,226,440.21168265 | 664,329.55524255 | |
| | 2,226,354.79813956 | 664,409.89202413 | |
| | 2,226,389.92077273 | 664,379.07548472 | |
| FAIRMOUNT AT DARTMOOR | 2,225,149.97508989 | 664,453.31024438 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT WELLINGTON | 2,223,969.26550905 | 664,532.08075613 | DOAN BROOK - MAIN BRANCH |

* A 'Hidden' field indicates permission to view the secured field is turned off.



Work Order Detail Report

6/13/2022

SSO INSPECTION 6-7-2022 0.74 INCHES OF RAIN

12:34 PM

| | | |
|--|------------------|--------------------------------------|
| FAIRMOUNT AT NORTH WOODLAND (N. SIDE) | | |
| 2,223,111.44143730 | 664,794.46048072 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT MARLBORO | | |
| 2,221,638.88762389 | 665,726.15513962 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT ARLINGTON | | |
| 2,222,127.85875881 | 665,393.74077822 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT & COVENTRY (SCARBOROUGH) | | |
| 2,220,278.63411081 | 667,231.62916280 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AND COVENTRY | | |
| 2,220,419.37169023 | 666,567.10752596 | DOAN BROOK - MAIN BRANCH |
| SCARBOROUGH AT LAMBERTON | | |
| 2,221,598.28993607 | 666,996.61322863 | MONMOUTH, EAST OF DARTMOOR |
| 2,225,152.08663423 | 665,499.19660404 | DOAN BROOK |
| BRADFORD AND LEE | | |
| 2,224,643.84191582 | 665,970.39907372 | DOAN BROOK - MAIN BRANCH |
| EDDINGTON | | |
| 2,221,299.08384156 | 674,932.84604380 | HAMPSHIRE LANE AT MAYFIELD (18") |
| 2,219,348.17140481 | 672,922.02624655 | EAST OVERLOOK AT EDGEHILL |
| 2,218,479.60588473 | 671,538.70289771 | DOAN BROOK - MAIN BRANCH |
| HAMPSHIRE LANE AT MAYFIELD (36") | | |
| 2,219,354.97683740 | 672,902.85961822 | DUGWAY CREEK - MAIN BRANCH |
| 2600 HAMPSHIRE RD | | |
| HAMPSHIRE AT EUCLID HTS. BLVD. | | |
| 2,218,465.44876081 | 671,703.91811846 | DOAN BROOK - MAIN BRANCH |
| CEDAR BTW. FAIRMOUNT/DEMINGTON | | |
| 2,218,036.25112839 | 669,668.09115338 | DOAN BROOK - MAIN BRANCH |
| 2828 BERKSHIRE, EAST OF COVENTRY | | |
| 2,220,768.48319674 | 670,614.63814481 | DUGWAY CREEK - MAIN BRANCH |
| 3003 EUCLID HEIGHTS BLVD | | |
| 2,222,538.05642922 | 672,458.71614955 | DUGWAY CREEK - MAIN BRANCH |
| South Taylor between Antisdale Ave and Superior Rd | | |
| 2,227,113.30810548 | 671,276.67684697 | LEE RD. & SUPERIOR AVE. |
| 2,224,449.07983814 | 672,366.92072946 | HEIGHT = NA, WIDTH = NA, LENGTH = NA |
| EUCLID HEIGHTS BLVD AND LEE | | |
| 2,224,196.49208874 | 673,102.72798488 | DUGWAY CREEK - MAIN BRANCH |
| EUCLID HEIGHTS BLVD/CUMBERLAND | | |
| 2,223,890.24106081 | 672,984.80925746 | DUGWAY CREEK - MAIN BRANCH |
| 1685 CUMBERLAND | | |
| 2,223,414.40769489 | 674,158.55920655 | DUGWAY CREEK - MAIN BRANCH |
| CUMBERLAND/SOMERTON | | |
| 2,223,678.60992239 | 673,517.13791722 | DUGWAY CREEK - MAIN BRANCH |
| 2225 NOBLE RD | | |
| 2225 NOBLE ROAD | | |
| 2,227,020.20068015 | 682,910.03907888 | NINE MILE CREEK - MAIN BRANCH |
| QUILLIAMS, N. OF RANDOLF | | |
| 2,229,594.65878581 | 682,393.53289405 | NINE MILE CREEK - MAIN BRANCH |
| LANGTON AND AHERSTONE | | |
| 2,228,126.76638040 | 684,188.23206055 | |
| 2,220,777.89623564 | 666,181.72575080 | |
| 2,218,501.67473823 | 671,997.54581206 | |
| 2,216,759.55453481 | 670,474.59347738 | |

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220613-0001



Work Order Detail Report

6/13/2022

SSO INSPECTION 6-7-2022 0.74 INCHES OF RAIN

12:34 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047



Work Order Detail Report

6/13/2022

SSO INSPECTION 6-7-2022 0.74 INCHES OF RAIN

12:34 PM

| Work Order Assets | | | | | | | |
|---------------------|--------------------|--------------------|----------------------|-----------------|------------------|-------------------|---------------------------------------|
| <u>Object Type</u> | <u>System ID 1</u> | <u>System ID 2</u> | <u>Description 1</u> | <u>Odometer</u> | <u>Hourmeter</u> | <u>Othermeter</u> | <u>Description 2</u> |
| | | | | | | | <u>PM Description</u> |
| Sewer Control Valve | SSO 431 | | | | | | FAIRFAX AT NORTH PARK |
| Sewer Control Valve | SSO 114 | | | | | | NORTH PARK AND COVENTRY |
| Sewer Control Valve | SSO 121 | | | | | | FAIRMOUNT SOUTH OF SCARBOROUGH |
| Sewer Structure | SA16AAWB0 | | | | | | 3094 |
| Sewer Control Valve | SSO 112 | | | | | | FAIRMOUNT AT FAIRFAX |
| Sewer Control Valve | SSO 99 | | | | | | 7 |
| Sewer Control Valve | SSO 432 | | | | | | FAIRMOUNT AT NORTH WOODLAND (S. SIDE) |
| Sewer Control Valve | DB-03 | | | | | | 6 |
| Sewer Control Valve | DB-01 | | | | | | 14 |
| Sewer Control Valve | DB-02 | | | | | | 55 |
| Sewer Control Valve | CH-04 | | | | | | 56 |
| Sewer Control Valve | SSO 110 | | | | | | FAIRMOUNT AT DARTMOOR |
| Sewer Control Valve | SSO 87 | | | | | | 5 |
| Sewer Control Valve | SSO 116 | | | | | | FAIRMOUNT AT WELLINGTON |
| Sewer Control Valve | SSO 111 | | | | | | 44 |
| Sewer Control Valve | SSO 113 | | | | | | FAIRMOUNT AT MARLBORO |
| Sewer Control Valve | SSO 124 | | | | | | 33 |
| Sewer Control Valve | CH-50 | | | | | | FAIRMOUNT AT ARLINGTON |
| Sewer Control Valve | SSO 129 | | | | | | 46 |
| Sewer Control Valve | CH-52 | | | | | | FAIRMOUNT & COVENTRY (SCARBOROUGH) |
| Sewer Control Valve | SSO 88 | | | | | | 37 |
| Sewer Control Valve | SSO 122 | | | | | | FAIRMOUNT AND COVENTRY |
| Sewer Control Valve | SSO 89 | | | | | | 47 |
| Sewer Structure | SA16ADZB0 | | | | | | SCARBOROUGH AT LAMBERTON |
| Sewer Control Valve | SSO 91 | | | | | | 53 |
| Sewer Structure | SA16ADPH0 | | | | | | BRADFORD AND LEE |
| Sewer Control Valve | SSO 120 | | | | | | 11 |
| Sewer Control Valve | SSO 128 | | | | | | EDDINGTON |
| Sewer Control Valve | SSO 90 | | | | | | 2 |
| Sewer Control Valve | SSO 126 | | | | | | HAMPSHIRE LANE AT MAYFIELD (18") |
| Sewer Control Valve | SSO 92 | | | | | | 42 |
| Sewer Control Valve | SSO 125 | | | | | | EAST OVERLOOK AT EDGEHILL |
| Sewer Control Valve | SSO 87 | | | | | | 36 |
| Sewer Control Valve | SSO 93 | | | | | | HAMPSHIRE LANE AT MAYFIELD (36") |
| Sewer Control Valve | SSO 94 | | | | | | 34 |
| Sewer Control Valve | SSO 95 | | | | | | 1536 |
| Sewer Control Valve | SSO 96 | | | | | | HAMPSHIRE AT EUCLID HTS. BLVD. |
| Sewer Control Valve | SSO 97 | | | | | | 20 |
| Sewer Control Valve | SSO 98 | | | | | | 4446 |
| Sewer Control Valve | SSO 99 | | | | | | CEDAR BTW. FAIRMOUNT/DEMINGTON |
| Sewer Control Valve | SSO 100 | | | | | | 8 |
| Sewer Control Valve | SSO 101 | | | | | | 2828 BERKSHIRE, EAST OF COVENTRY |

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220613-0001



Work Order Detail Report

6/13/2022

SSO INSPECTION 6-7-2022 0.74 INCHES OF RAIN

12:34 PM

| | |
|--------------------------------|---|
| SSO 103 | 19 |
| Sewer Control Valve SSO 104 | 3003 EUCLID HEIGHTS BLVD 15 |
| Sewer Structure SA16AGMG0 | 3402 |
| Sewer Control Valve CH-30 | South Taylor between Antisdale Ave and Superior R 52 |
| Sewer Control Valve DV-11 | LEE RD. & SUPERIOR AVE. 9 |
| Sewer Control Valve SSO 108 | EUCLID HEIGHTS BLVD AND LEE 22 |
| Sewer Control Valve SSO 106 | EUCLID HEIGHTS BLVD/CUMBERLAND 43 |
| Sewer Control Valve SSO 95 | 1685 CUMBERLAND 18 |
| Sewer Control Valve SSO 105 | CUMBERLAND/SOMERTON 30 |
| Sewer Structure SA16AQQD0 | 4987 |
| Sewer Structure SA16AQQC0 | 3745 |
| Sewer Control Valve SSO 102 | 2225 NOBLE ROAD 3 |
| Sewer Control Valve SSO 107 | QUILLIAMS, N. OF RANDOLF 38 |
| Sewer Control Valve CH-51 | LANGTON AND AHERSTONE 54 |
| Sewer Structure SA16APEF0 | 1809 |



Work Order Detail Report

6/13/2022

SSO INSPECTION 6-7-2022 0.74 INCHES OF RAIN

12:34 PM

| Check List | | <u>Completed</u> | <u>Condition</u> | <u>Completion Date/Time</u> | <u>Est Completion Date</u> |
|------------|--|--------------------------|------------------|-----------------------------|----------------------------|
| 1 | A-37-FAIRFAX AT NORTH PARK SA16ACPG0 | <input type="checkbox"/> | Not Sound | 6/9/2022/ | |
| 2 | A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 3 | A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0 | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 4 | A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 5 | A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 6 | A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 7 | A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 8 | A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE) | <input type="checkbox"/> | Not Sound | 6/9/2022/ | |
| 9 | A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 10 | A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 11 | A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 12 | A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 13 | A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 14 | A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 15 | A-38 FAIRMOUNT AT MARLBORO SA16AAUJ0 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 16 | A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 17 | A-35 2393 COVENTRY SA16AASK0 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 18 | A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION) | <input type="checkbox"/> | Not Sound | 6/9/2022/ | |
| 19 | A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 20 | A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 21 | A-58 E MONMOUTH AT EXETER (INTERSECTION) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 22 | A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 23 | B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0 | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 24 | B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0 | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 25 | B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0 | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 26 | B-61 2600 HAMPSHIRE SA16ADZB0 | <input type="checkbox"/> | Sound | 6/9/2022/ | |
| 27 | HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0 | <input type="checkbox"/> | Sound | 6/9/2022/ | |

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220613-0001



Work Order Detail Report

6/13/2022

SSO INSPECTION 6-7-2022 0.74 INCHES OF RAIN

12:34 PM

| | | | | |
|----|--|--------------------------|-----------|-----------|
| 28 | B-46 EDGEHILL AT E OVERLOOK SA16AEPF0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 29 | B-42 12537 CEDAR SA16ACZA0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 30 | B-15 COVENTRY AND CEDAR SA16ADBH0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 31 | B-23 2828 BERKSHIRE SA16AETA0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 32 | B-24 3003 EUCLID HTS. BLVD. ST16AALB0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 33 | B-56 LEE AND MEADOWBROOK SA16AGMG0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 34 | C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 35 | C-12 LEE AND SUPERIOR SA16AGTJ0 | <input type="checkbox"/> | Not Sound | 6/9/2022/ |
| 36 | C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 37 | C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0 | <input type="checkbox"/> | Not Sound | 6/9/2022/ |
| 38 | C-25 CUMBERLAND AND SOMERTON SA16AISA0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 39 | C-17 1685 CUMBERLAND RD SA16AQIQB0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 40 | C-59 3427 THORNE RD SA16AQKD0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 41 | C-60 3415 THORNE RD SA16AQQC0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 42 | C-22 2225 NOBLE RD ST16ZLHB0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 43 | C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 44 | C-51 ATHERSTONE AND LANGTON SA16AOKA0 | <input type="checkbox"/> | Sound | 6/9/2022/ |
| 45 | C-50 3593 FENLEY SA16APEH0 | <input type="checkbox"/> | Sound | 6/9/2022/ |

| Tasks/Resources | | | | | | |
|---|-------------------------|------------------|--------------------------|-----------------------------|---------------------------|-------------------------|
| SWCT26 Inspection | | | | | | |
| Crew: Supervisor: Jackson, Jeff | Status: Complete | UOM: Each | *Cal'd UC: \$5.39 | *Task Cost: \$242.72 | Start Dt: 6/9/2022 | End Dt: 6/9/2022 |
| Employee | | | | | | |
| Resource | UOM | Units | *Total Cost | Alt Description | Start Dt | End Dt |
| 40151 Mc Coy, Sam | Hours | 8.00 | \$135.52 | | 6/9/2022 | 6/9/2022 |
| 29960 Jackson, Jeff | Hours | 4.00 | \$0.00 | | 6/9/2022 | 6/9/2022 |
| Equipment | | | | | | |
| Resource | UOM | Units | *Total Cost | Alt Description | Start Dt | End Dt |
| CHFLT55 FORD F250 PICK UP 0 | Hours | 8.00 | \$107.20 | | 6/9/2022 | 6/9/2022 |
| CHFT-500 FORD F250 PICK UP TRUCK | Each | 4.00 | \$0.00 | | 6/9/2022 | 6/9/2022 |

Task Comment: SSO INSPECTION 6-9-2022 0.74.

Work Order Detail Report

6/13/2022

SSO INSPECTION 6-7-2022 0.74 INCHES OF RAIN

12:34 PM

| | | | *Actual | *Estimated | *Difference |
|---------------------|--------|--------------------------------|------------------|------------|-------------|
| Projected Complete: | | Lock: <input type="checkbox"/> | WO Duration | 8.00 | 0.00 |
| Repair Type: | | | Labor Hours | 12.00 | 0.00 |
| Subcontractor: | | | Labor Costs | \$135.52 | \$0.00 |
| Profit Center: | | | Material Costs | 0.00 | 0.00 |
| | | | Fluids Costs | 0.00 | 0.00 |
| Quantity: | 0.00 | Lock: <input type="checkbox"/> | Equipment Costs | 107.20 | 0.00 |
| Unit of Measure: | Each | | Contractor Costs | 0.00 | 0.00 |
| *Unit Cost: | \$0.00 | | Misc. Costs | 0.00 | 0.00 |
| WO Hours: | 0.00 | | Total Costs | \$242.72 | \$0.00 |
| | | | Use Task Info: | True | True |

| Billed Party | | Billing | |
|---------------------|--|--|--|
| Customer ID: | | Customer Number: | |
| Customer Name: | | Last Name: | |
| Address: | | Phone: | |
| City: | | Fax #: | |
| State: | | E-mail: | |
| Billing Data | | Billing Required: <input type="checkbox"/> | |
| Contact Name: | | *Billing Amount: | |
| Invoice Number: | | Date Bill Sent: | |
| Incoming Account #: | | Payment Received: | |
| | | Payment Method: | |
| | | Billing Processed: <input type="checkbox"/> | |
| | | Imported to Financials: <input type="checkbox"/> | |

| Associated PMs | | PM Code and Description | | Closed <input checked="" type="checkbox"/> | |
|----------------|--|-------------------------|--|--|--|
| | | SSO-02 SSO INSPECTION | | | |

| Tracking | | | |
|-------------------------|---|---|-----------|
| Item | Description | By | Date |
| Work Order Creation | From Routine Work SSO-02 - SSO INSPECTION | aferrone | 6/13/2022 |
| Supervisor Notification | Email Queued Successfully! | aferrone | 6/13/2022 |
| Status Change | From New Work Order to Complete | aferrone | 6/13/2022 |
| Rate: | Opened At: | Televised: <input type="checkbox"/> | |
| Received By: | Pipe Footage Cleaned | Power Rooter: <input type="checkbox"/> | |
| Work From: | Gallons Used: | Jet: <input type="checkbox"/> | |
| Pipe Size: | WO User 23: | Gap Vac: <input type="checkbox"/> | |
| Pipe Condition: | WO User 24: | Dye Test: <input type="checkbox"/> | |
| Could Not Open: | WO User 9: | Gap Root Cut: <input type="checkbox"/> | |
| Additional Repair: | User 10: | GIS Correction?: <input type="checkbox"/> | |
| Dye Test Reason: | Appointment Date DNL | Test Tee Correction: <input type="checkbox"/> | |
| Test Performed Through: | Appointment Date: | | |
| Dye Test Results: | | | |
| WO User 51: | | | |
| Measurement: | E Mail: | | |
| History: | Measurement Line 2: | | |

Work Order Detail Report

6/13/2022

SSO INSPECTION 6-7-2022 0.74 INCHES OF RAIN


12:34 PM

| | | | |
|-----------------------|-----------------------------|--------------|--------------------------|
| Manhole Basin Repair: | Pipe Size: | | |
| Material Used: | PVC Tees, Angles, Sier | | |
| Pipe Repair: | WO User 44: | | |
| Street Repair: | WO User 45: | | |
| Grass Repair: | WO User 46: | | |
| Curb Repair: | | | |
| Driveway- Sidewalk Re | | | |
| Construction Crew: | | | |
| WO User 39: | | | |
| WO User 40: | OUPS #: | | |
| WO User 41: | WO User 48: | | |
| WO User 52: | WO User 62: | | |
| WO User 53: | WO User 63: | | |
| WO User 54: | WO User 64: | | |
| WO User 55: | WO User 65: | | |
| WO User 56: | WO User 66: | | |
| WO User 57: | WO User 67: | | |
| WO User 58: | WO User 68: | | |
| WO User 59: | WO User 69: | | |
| WO User 60: | WO User 70: | | |
| WO User 61: | WO User 71: | | |
| WO User 72: | WO User 82: | Televised: | <input type="checkbox"/> |
| WO User 73: | Quantity: | Paid: | <input type="checkbox"/> |
| WO User 74: | WO User 84: | WO User 104: | <input type="checkbox"/> |
| WO User 75: | WO User 85: | WO User 105: | <input type="checkbox"/> |
| WO User 76: | WO User 86: | WO User 106: | <input type="checkbox"/> |
| WO User 92 Date: | WO User 97 Date: | | |
| WO User 93 Date: | WO User 98 Date: | | |
| WO User 94 Date: | WO User 99 Date: | | |
| WO User 95 Date: | WO User 100 Date: | | |
| WO User 96 Date: | WO User 101 Date: | | |
| WO User 77: | WO User 87: | WO User 107: | <input type="checkbox"/> |
| WO User 78: | WO User 88: | WO User 108: | <input type="checkbox"/> |
| WO User 79: | WO User 89: | WO User 109: | <input type="checkbox"/> |
| WO User 80: | WO User 90: | WO User 110: | <input type="checkbox"/> |
| WO User 81: | WO User 91: | WO User 111: | <input type="checkbox"/> |
| WO Creator: aferrone | WO Creation Date: 6/13/2022 | PM Trigger: | Rec #: 12829 |



**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Sunday, June 12, 2005
Accumulated in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, June 12, 2022

| Site Location | Peak Accumulation (inches) | | | | |
|---------------------------|----------------------------|--------|--------|--------|-----------|
| | 24-Hour | 6-Hour | 3-Hour | 1-Hour | 15-Minute |
| Beachwood | 0.30 | 0.30 | 0.30 | 0.25 | 0.21 |
| Brecksville | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 |
| Brock Park | 0.17 | 0.17 | 0.17 | 0.17 | 0.15 |
| Cleveland Industrial Pkwy | 0.19 | 0.19 | 0.19 | 0.19 | 0.16 |
| Dille Ave PS | 0.37 | 0.37 | 0.37 | 0.36 | 0.24 |
| Division Ave PS | 0.19 | 0.19 | 0.19 | 0.18 | 0.11 |
| Eastern WWTP | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Independence | 0.04 | 0.04 | 0.04 | 0.04 | 0.03 |
| James Rhodes HS | 0.11 | 0.11 | 0.11 | 0.10 | 0.05 |
| Jennings PS | 0.24 | 0.24 | 0.24 | 0.23 | 0.11 |
| Macedonia | 0.02 | 0.02 | 0.02 | 0.02 | 0.01 |
| Maple Heights | 0.35 | 0.35 | 0.35 | 0.32 | 0.22 |
| Mary Street PS | 0.41 | 0.41 | 0.41 | 0.40 | 0.23 |
| Mayfield Heights | 0.02 | 0.01 | 0.01 | 0.01 | 0.01 |
| Moreland Hills | 0.14 | 0.14 | 0.14 | 0.13 | 0.09 |
| North Olmsted | 0.40 | 0.40 | 0.40 | 0.40 | 0.38 |
| North Royalton | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Oakwood | 0.52 | 0.52 | 0.52 | 0.51 | 0.48 |
| Olmsted Falls | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Parma | 0.09 | 0.09 | 0.09 | 0.09 | 0.09 |
| Richfield | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Shaker Heights | 0.30 | 0.30 | 0.30 | 0.29 | 0.22 |
| South Euclid | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Southerly WWTP | 0.27 | 0.27 | 0.27 | 0.26 | 0.15 |
| Strongsville CVWTP | 0.01 | 0.01 | 0.01 | 0.01 | 0.01 |
| Strongsville Foltz | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| University Heights | 0.31 | 0.31 | 0.31 | 0.30 | 0.26 |
| Wade Park | 0.53 | 0.53 | 0.53 | 0.53 | 0.51 |
| Westerly WWTP | 0.25 | 0.25 | 0.25 | 0.24 | 0.20 |
| Westlake | 0.33 | 0.33 | 0.33 | 0.33 | 0.32 |
| | | | | | 0.18 |

Work Order Detail Report

6/21/2022

SSO INSPECTION 6-12-2022 0.31 INCHES OF RAIN

10:17 AM

| | | | |
|------------------------|-----------------------|-----------------------|--|
| WO Number: | 220616-0005 | Category: | SSOs |
| Status: | Complete | Problem: | Storm Response |
| Status Date: | 6/21/2022 10:16 am | Main Task: | Inspection |
| Asset: SSO 431 | | | |
| Location: | FAIRFAX AT NORTH PARK | | |
| Cause: | Weather | Assigned By: | |
| Assigned Crew: | | Assigned Date: | |
| Supervisor: | Jackson, Jeff | Start Date: | 6/16/2022 7:13 AM |
| Lead Worker: | Cardarella, Joe | End Date: | 6/16/2022 3:14 PM |
| Priority: | High | | Override Notifications |
| Account #: | | | Problem <input type="checkbox"/> |
| Proj No - Acct: | | Project ID: | Overdue <input type="checkbox"/> |
| Project: | | Project Name: | Lead Worker <input type="checkbox"/> |
| Reason: | | | Task <input type="checkbox"/> |
| Received By: | | | Supervisor <input type="checkbox"/> |
| Inspected By: | | | Hard Lock WO <input type="checkbox"/> |

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection

Sub-Division:

Area:
Sub-Area:
Owner:
Location:
Classification:

Maintenance Zone:

Alternate Zone:

| Work Order Locations | | |
|---------------------------------------|------------------|--------------------------|
| <u>Address</u> | | <u>Address 2</u> |
| <u>X Coord</u> | <u>Y Coord</u> | <u>General Location</u> |
| FAIRFAX AT NORTH PARK | | |
| 2,220,655.65435414 | 665,517.24643672 | Doan Brook |
| NORTH PARK AND COVENTRY | | |
| 2,219,873.16674590 | 666,048.82312946 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT SOUTH OF SCARBOROUGH | | |
| 2,220,364.86097248 | 666,446.72325230 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT FAIRFAX | | |
| 2,220,920.81917815 | 666,080.57995571 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT NORTH WOODLAND (S. SIDE) | | |
| 2,223,053.81655256 | 664,693.25202172 | DOAN BROOK - MAIN BRANCH |
| 3012 NORTH WOODLAND | | |
| 2,222,845.06631389 | 664,689.08536339 | Doan Brook |
| 2,226,440.21168265 | 664,329.55524255 | |
| 2,226,354.79813956 | 664,409.89202413 | |
| 2,226,389.92077273 | 664,379.07548472 | |
| FAIRMOUNT AT DARTMOOR | | |
| 2,225,149.97508989 | 664,453.31024438 | DOAN BROOK - MAIN BRANCH |
| FAIRMOUNT AT WELLINGTON | | |
| 2,223,969.26550905 | 664,532.08075613 | DOAN BROOK - MAIN BRANCH |

* A 'Hidden' field indicates permission to view the secured field is turned off.

Work Order Detail Report

6/21/2022

SSO INSPECTION 6-12-2022 0.31 INCHES OF RAIN

10:17 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
2,223,111.44143730 664,794.46048072 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO
2,221,638.88762389 665,726.15513962 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
2,221,598.28993607 666,996.61322863
MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON
2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD

2225 NOBLE ROAD
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE
2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

Work Order Detail Report

6/21/2022

SSO INSPECTION 6-12-2022 0.31 INCHES OF RAIN

10:17 AM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

6/21/2022

SSO INSPECTION 6-12-2022 0.31 INCHES OF RAIN

10:17 AM

| Work Order Assets | | | | | | | | | |
|---------------------|-------------|-------------|---------------|----------|-----------|------------|---------------------------------------|----------|-----------|
| Object Type | System ID 1 | System ID 2 | Description 1 | Odometer | Hourmeter | Othermeter | PM Description | Asset ID | Completed |
| Sewer Control Valve | SSO 431 | | | | | | FAIRFAX AT NORTH PARK | | 26 |
| Sewer Control Valve | SSO 114 | | | | | | NORTH PARK AND COVENTRY | | 16 |
| Sewer Control Valve | SSO 121 | | | | | | FAIRMOUNT SOUTH OF SCARBOROUGH | | 35 |
| Sewer Structure | SA16AAWB0 | | | | | | | | 3094 |
| Sewer Control Valve | SSO 112 | | | | | | FAIRMOUNT AT FAIRFAX | | 7 |
| Sewer Control Valve | SSO 99 | | | | | | FAIRMOUNT AT NORTH WOODLAND (S. SIDE) | | 6 |
| Sewer Control Valve | SSO 432 | | | | | | 3012 NORTH WOODLAND | | 14 |
| Sewer Control Valve | DB-03 | | | | | | | | 55 |
| Sewer Control Valve | DB-01 | | | | | | | | 56 |
| Sewer Control Valve | DB-02 | | | | | | | | 57 |
| Sewer Control Valve | CH-04 | | | | | | FAIRMOUNT AT DARTMOOR | | 5 |
| Sewer Control Valve | SSO 110 | | | | | | FAIRMOUNT AT WELLINGTON | | 44 |
| Sewer Control Valve | SSO 87 | | | | | | FAIRMOUNT AT NORTH WOODLAND (N. SIDE) | | 33 |
| Sewer Control Valve | SSO 116 | | | | | | FAIRMOUNT AT MARLBORO | | 4 |
| Sewer Control Valve | SSO 111 | | | | | | FAIRMOUNT AT ARLINGTON | | 46 |
| Sewer Control Valve | SSO 113 | | | | | | FAIRMOUNT & COVENTRY (SCARBOROUGH) | | 37 |
| Sewer Control Valve | SSO 124 | | | | | | FAIRMOUNT AND COVENTRY | | 47 |
| Sewer Control Valve | CH-50 | | | | | | SCARBOROUGH AT LAMBERTON | | 53 |
| Sewer Control Valve | SSO 129 | | | | | | BRADFORD AND LEE | | 11 |
| Sewer Control Valve | CH-52 | | | | | | EDDINGTON | | 2 |
| Sewer Control Valve | SSO 88 | | | | | | HAMPSHIRE LANE AT MAYFIELD (18") | | 42 |
| Sewer Control Valve | SSO 122 | | | | | | EAST OVERLOOK AT EDGEHILL | | 36 |
| Sewer Control Valve | SSO 89 | | | | | | HAMPSHIRE LANE AT MAYFIELD (36") | | 34 |
| Sewer Structure | SA16ADZB0 | | | | | | | | 1536 |
| Sewer Control Valve | SSO 91 | | | | | | HAMPSHIRE AT EUCLID HTS. BLVD. | | 20 |
| Sewer Structure | SA16ADPH0 | | | | | | | | 4446 |
| Sewer Control Valve | SSO 120 | | | | | | CEDAR BTW. FAIRMOUNT/DEMINGTON | | 8 |
| Sewer Control Valve | | | | | | | 2828 BERKSHIRE, EAST OF COVENTRY | | |

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220616-0005

Work Order Detail Report

6/21/2022

SSO INSPECTION 6-12-2022 0.31 INCHES OF RAIN

10:17 AM

| | | |
|---------------------|---|----|
| SSO 103 | | 19 |
| Sewer Control Valve | 3003 EUCLID HEIGHTS BLVD | |
| SSO 104 | | 15 |
| Sewer Structure | | |
| SA16AGMG0 | 3402 | |
| Sewer Control Valve | South Taylor between Antisdale Ave and Superior R | |
| CH-30 | | 52 |
| Sewer Control Valve | LEE RD. & SUPERIOR AVE. | |
| DV-11 | | 9 |
| Sewer Control Valve | EUCLID HEIGHTS BLVD AND LEE | |
| SSO 108 | | 22 |
| Sewer Control Valve | EUCLID HEIGHTS BLVD/CUMBERLAND | |
| SSO 106 | | 43 |
| Sewer Control Valve | 1685 CUMBERLAND | |
| SSO 95 | | 18 |
| Sewer Control Valve | CUMBERLAND/SOMERTON | |
| SSO 105 | | 30 |
| Sewer Structure | | |
| SA16AQD0 | 4987 | |
| Sewer Structure | | |
| SA16AQC0 | 3745 | |
| Sewer Control Valve | 2225 NOBLE ROAD | |
| SSO 102 | | 3 |
| Sewer Control Valve | QUILLIAMS, N. OF RANDOLF | |
| SSO 107 | | 38 |
| Sewer Control Valve | LANGTON AND AHERSTONE | |
| CH-51 | | 54 |
| Sewer Structure | | |
| SA16APEF0 | 1809 | |

Work Order Detail Report

6/21/2022

SSO INSPECTION 6-12-2022 0.31 INCHES OF RAIN

10:17 AM

| Check List | | | | | |
|--------------------------|--|--------------------------|------------------|-----------------------------|----------------------------|
| | <u>Item</u> | <u>Completed</u> | <u>Condition</u> | <u>Completion Date/Time</u> | <u>Est Completion Date</u> |
| 1 | A-37-FAIRFAX AT NORTH PARK SA16ACPG0 | <input type="checkbox"/> | Sound | 6/16/2022/11:56 am | 6/16/2022 |
| 2 | A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT) | <input type="checkbox"/> | Sound | 6/16/2022/11:56 am | 6/16/2022 |
| 3 | A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0 | <input type="checkbox"/> | Sound | 6/16/2022/11:56 am | 6/16/2022 |
| 4 | A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK) | <input type="checkbox"/> | Sound | 6/16/2022/11:57 am | 6/16/2022 |
| 5 | A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK) | <input type="checkbox"/> | Sound | 6/16/2022/11:57 am | 6/16/2022 |
| 6 | A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN) | <input type="checkbox"/> | Sound | 6/16/2022/11:58 am | 6/16/2022 |
| 7 | A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD) | <input type="checkbox"/> | Sound | 6/16/2022/11:58 am | |
| Overflow meter installed | | | | | |
| 8 | A-6 FAIRMOUNT AT SHELBYNE ST16ZBjk0 (WEST BOUND LANE) | <input type="checkbox"/> | Sound | 6/16/2022/11:59 am | 6/16/2022 |
| 9 | A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK) | <input type="checkbox"/> | Sound | 6/16/2022/11:59 am | 6/16/2022 |
| 10 | A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND) | <input type="checkbox"/> | Sound | 6/16/2022/11:59 am | 6/16/2022 |
| 11 | A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN) | <input type="checkbox"/> | Sound | 6/16/2022/ 1:54 pm | 6/16/2022 |
| 12 | A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/16/2022/ 1:55 pm | 6/16/2022 |
| 13 | A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK) | <input type="checkbox"/> | Sound | 6/16/2022/12:03 pm | 6/16/2022 |
| 14 | A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/16/2022/ 1:55 pm | 6/16/2022 |
| Overflow meter installed | | | | | |
| 15 | A-38 FAIRMOUNT AT MARLBORO SA16AAU0 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/16/2022/ 1:56 pm | 6/16/2022 |
| 16 | A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN) | <input type="checkbox"/> | Sound | 6/16/2022/ 1:54 pm | 6/16/2022 |
| 17 | A-35 2393 COVENTRY SA16AASK0 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/16/2022/12:01 pm | 6/16/2022 |
| 18 | A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/16/2022/12:01 pm | 6/16/2022 |
| 19 | A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/16/2022/12:01 pm | |
| 20 | A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE) | <input type="checkbox"/> | Sound | 6/16/2022/ 1:54 pm | 6/16/2022 |
| 21 | A-58 E MONMOUTH AT EXETER (INTERSECTION) | <input type="checkbox"/> | Sound | 6/16/2022/ 1:53 pm | 6/16/2022 |
| 22 | A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION) | <input type="checkbox"/> | Sound | 6/16/2022/12:02 pm | |
| Overflow meter installed | | | | | |
| 23 | B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0 | <input type="checkbox"/> | Sound | 6/16/2022/ | |
| 24 | B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0 | <input type="checkbox"/> | Sound | 6/16/2022/ | |
| 25 | B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0 | <input type="checkbox"/> | Sound | 6/16/2022/ | |
| 26 | B-61 2600 HAMPSHIRE SA16ADZB0 | <input type="checkbox"/> | Sound | 6/16/2022/ | |

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220616-0005

Work Order Detail Report

6/21/2022

SSO INSPECTION 6-12-2022 0.31 INCHES OF RAIN

10:17 AM

| | | | | |
|----|--|--------------------------|-----------|------------|
| 27 | HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 28 | B-46 EDGEHILL AT E OVERLOOK SA16AEPF0 | <input type="checkbox"/> | Not Sound | 6/16/2022/ |
| 29 | B-42 12537 CEDAR SA16ACZA0 | <input type="checkbox"/> | Not Sound | 6/16/2022/ |
| 30 | B-15 COVENTRY AND CEDAR SA16ADBH0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 31 | B-23 2828 BERKSHIRE SA16AETA0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 32 | B-24 3003 EUCLID HTS. BLVD. ST16AALB0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 33 | B-56 LEE AND MEADOWBROOK SA16AGMG0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 34 | C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0 | <input type="checkbox"/> | Not Sound | 6/16/2022/ |
| 35 | C-12 LEE AND SUPERIOR SA16AGTJ0 | <input type="checkbox"/> | Not Sound | 6/16/2022/ |
| 36 | C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0 | <input type="checkbox"/> | Not Sound | 6/16/2022/ |
| 37 | C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 38 | C-25 CUMBERLAND AND SOMERTON SA16AISA0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 39 | C-17 1685 CUMBERLAND RD SA16AQIQB0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 40 | C-59 3427 THORNE RD SA16AQQD0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 41 | C-60 3415 THORNE RD SA16AQQC0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 42 | C-22 2225 NOBLE RD ST16ZLHB0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 43 | C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 44 | C-51 AATHERSTONE AND LANGTON SA16AOKA0 | <input type="checkbox"/> | Sound | 6/16/2022/ |
| 45 | C-50 3593 FENLEY SA16APEH0 | <input type="checkbox"/> | Sound | 6/16/2022/ |

| Tasks/Resources | | | | | | |
|--|-----------|-------------------|----------------------|-----------------|-----------|-----------|
| SWCT26 Inspection | | | | | | |
| Crew: | Status: | *Cal'c UC: \$9.45 | *Task Cost: \$425.08 | Start Dt: | 6/16/2022 | |
| Supervisor: | UOM: Each | # of Units: 45.00 | *Unit Cost: \$0.00 | End Dt: | 6/16/2022 | |
| Employee | | | | | | |
| Resource | UOM | Units | *Total Cost | Alt Description | Start Dt | End Dt |
| 29967 Claggett, Dwane | Hours | 4.00 | \$90.56 | | 6/16/2022 | 6/16/2022 |
| 40151 Mc Coy, Sam | Hours | 4.00 | \$67.76 | | 6/16/2022 | 6/16/2022 |
| 22394 Cardarella, Joe | Hours | 4.00 | \$86.16 | | 6/16/2022 | 6/16/2022 |
| Equipment | | | | | | |
| Resource | UOM | Units | *Total Cost | Alt Description | Start Dt | End Dt |
| CHFLT50 FORD F250 CREW CAB 5 | Hours | 4.00 | \$53.60 | | 6/16/2022 | 6/16/2022 |
| CHFLT55 FORD F250 PICK UP 0 | Hours | 4.00 | \$53.60 | | 6/16/2022 | 6/16/2022 |
| CHFLT-56 FORD TRANSIT SEWER 0 VAN | Hours | 4.00 | \$73.40 | | 6/16/2022 | 6/16/2022 |
| Task Comment: SSO INSPECTIONS 0.31 INCHES OF RAIN | | | | | | |

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220616-0005

Work Order Detail Report

6/21/2022

SSO INSPECTION 6-12-2022 0.31 INCHES OF RAIN

10:17 AM

| | | | *Actual | *Estimated | *Difference |
|---------------------|--------|--------------------------------|------------------|------------|-------------|
| Projected Complete: | | Lock: <input type="checkbox"/> | WO Duration | 8.02 | 0.00 |
| Repair Type: | | | Labor Hours | 12.00 | 0.00 |
| Subcontractor: | | | Labor Costs | \$244.48 | \$0.00 |
| Profit Center: | | | Material Costs | 0.00 | 0.00 |
| Quantity: | 0.00 | Lock: <input type="checkbox"/> | Fluids Costs | 0.00 | 0.00 |
| Unit of Measure: | Each | | Equipment Costs | 180.60 | 0.00 |
| *Unit Cost: | \$0.00 | | Contractor Costs | 0.00 | 0.00 |
| WO Hours: | 0.00 | | Misc. Costs | 0.00 | 0.00 |
| | | | Total Costs | \$425.08 | \$0.00 |
| | | | Use Task Info: | True | True |

| Billed Party | | Billing | |
|--|--|-------------------|--------------------------|
| Customer ID: | | Customer Number: | |
| Customer Name: | | Last Name: | |
| Address: | | Phone: | |
| City: | | Fax #: | |
| State: | | E-mail: | |
| Zip: | | | |
| Billing Data | | | |
| Contact Name: | | *Billing Amount: | <input type="checkbox"/> |
| Invoice Number: | | Date Bill Sent: | <input type="checkbox"/> |
| Incoming Account #: | | Payment Received: | <input type="checkbox"/> |
| | | Payment Method: | <input type="checkbox"/> |
| Imported to Financials: <input type="checkbox"/> | | | |

| Associated PMs | | PM Code and Description | Closed |
|----------------|--|-------------------------|-------------------------------------|
| | | SSO-02 SSO INSPECTION | <input checked="" type="checkbox"/> |

| Tracking | | | | | |
|-------------------------|---|-----------|-------------|-------------|--|
| <u>Item</u> | <u>Description</u> | <u>By</u> | <u>Date</u> | <u>Time</u> | |
| Work Order Creation | From Routine Work SSO-02 - SSO INSPECTION | jackson | 6/16/2022 | 7:06 AM | |
| Supervisor Notification | Email Queued Successfully! | jackson | 6/16/2022 | 7:06 AM | |
| Status Change | From New Work Order to Complete | aferrone | 6/21/2022 | 10:16 AM | |

| | | |
|-------------------------|-----------------------------|---|
| Rate: | Opened At: | Televised: <input type="checkbox"/> |
| Received By: Email | Pipe Footage Cleaned , | Power Rooter: <input type="checkbox"/> |
| Work From: | Gallons Used: | Jet: <input type="checkbox"/> |
| Pipe Size: | WO User 23: | Gap Vac: <input type="checkbox"/> |
| Pipe Condition: | WO User 24: | Dye Test: <input type="checkbox"/> |
| Could Not Open: | WO User 9: | Gap Root Cut: <input type="checkbox"/> |
| Additional Repair: | User 10: | GIS Correction?: <input type="checkbox"/> |
| Dye Test Reason: | Appointment Date DNL | Test Tee Correction: <input type="checkbox"/> |
| Test Performed Through: | Appointment Date: 6/16/2022 | 8:00 AM |
| Dye Test Results: | | |
| WO User 51: | | |
| Measurement: | E Mail: | |
| History: | Measurement Line 2: | |

Work Order Detail Report

6/21/2022

SSO INSPECTION 6-12-2022 0.31 INCHES OF RAIN

10:17 AM

| | | | |
|-----------------------|-----------------------------|--------------|--------------------------|
| Manhole Basin Repair: | Pipe Size: | | |
| Material Used: | PVC Tees, Angles, Slat | | |
| Pipe Repair: | WO User 44: | | |
| Street Repair: | WO User 45: | | |
| Grass Repair: | WO User 46: | | |
| Curb Repair: | | | |
| Driveway- Sidewalk Re | | | |
| Construction Crew: | | | |
| WO User 39: | | | |
| WO User 40: | OUPS #: | | |
| WO User 41: | WO User 48: | | |
| WO User 52: | WO User 62: | | |
| WO User 53: | WO User 63: | | |
| WO User 54: | WO User 64: | | |
| WO User 55: | WO User 65: | | |
| WO User 56: | WO User 66: | | |
| WO User 57: | WO User 67: | | |
| WO User 58: | WO User 68: | | |
| WO User 59: | WO User 69: | | |
| WO User 60: | WO User 70: | | |
| WO User 61: | WO User 71: | | |
| WO User 72: | WO User 82: | Televised: | <input type="checkbox"/> |
| WO User 73: | Quantity: | Paid: | <input type="checkbox"/> |
| WO User 74: | WO User 84: | WO User 104: | <input type="checkbox"/> |
| WO User 75: | WO User 85: | WO User 105: | <input type="checkbox"/> |
| WO User 76: | WO User 86: | WO User 106: | <input type="checkbox"/> |
| WO User 92 Date: | WO User 97 Date: | | |
| WO User 93 Date: | WO User 98 Date: | | |
| WO User 94 Date: | WO User 99 Date: | | |
| WO User 95 Date: | WO User 100 Date: | | |
| WO User 96 Date: | WO User 101 Date: | | |
| WO User 77: | WO User 87: | WO User 107: | <input type="checkbox"/> |
| WO User 78: | WO User 88: | WO User 108: | <input type="checkbox"/> |
| WO User 79: | WO User 89: | WO User 109: | <input type="checkbox"/> |
| WO User 80: | WO User 90: | WO User 110: | <input type="checkbox"/> |
| WO User 81: | WO User 91: | WO User 111: | <input type="checkbox"/> |
| WO Creator: jjackson | WO Creation Date: 6/16/2022 | PM Trigger: | Rec #: 12848 |