



Law Department

November 15, 2022

Via U.S. Mail and E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604

Re: October 2022 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through October 31, 2022, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,

A handwritten signature in black ink, appearing to read "William R. Hanna".


William R. Hanna
Director of Law

Enclosures

cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Wednesday, October 19, 2022
 Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Wednesday, October 19, 2022

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	1.55	0.71	0.44	0.24	0.10	0.05
Brecksville	0.63	0.27	0.20	0.12	0.04	0.02
Brook Park	0.77	0.38	0.29	0.15	0.05	0.02
Cleveland Industrial Pkwy	0.63	0.32	0.20	0.10	0.04	0.02
Dille Ave PS	n/a	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.74	0.34	0.22	0.14	0.06	0.03
Easterly WWTP	0.38	0.21	0.20	0.13	0.07	0.03
Independence	0.75	0.34	0.21	0.11	0.05	0.02
James Rhodes HS	0.75	0.32	0.20	0.11	0.05	0.02
Jennings PS	1.16	0.57	0.39	0.26	0.08	0.05
Macedonia	0.38	0.17	0.13	0.08	0.04	0.02
Maple Heights	1.18	0.59	0.30	0.20	0.07	0.03
Mary Street PS	0.97	0.43	0.28	0.13	0.07	0.04
Mayfield Heights	1.50	0.61	0.44	0.22	0.09	0.05
Moreland Hills	1.56	0.73	0.43	0.23	0.09	0.04
North Olmsted	0.96	0.44	0.38	0.22	0.10	0.04
North Royalton	0.59	0.28	0.16	0.09	0.03	0.02
Oakwood	0.75	0.37	0.26	0.13	0.06	0.03
Olmsted Falls	1.18	0.67	0.36	0.15	0.10	0.05
Parma	0.80	0.38	0.25	0.12	0.05	0.02
Richfield	0.56	0.34	0.19	0.09	0.04	0.03
Shaker Heights	1.07	0.50	0.29	0.16	0.06	0.03
South Euclid	0.70	0.28	0.26	0.12	0.05	0.02
Southerly WWTC	1.15	0.56	0.37	0.24	0.08	0.03
Strongsville C WWTP	0.82	0.39	0.25	0.12	0.04	0.02
Strongsville Foltz	0.88	0.55	0.33	0.14	0.05	0.02
University Heights	1.44	0.64	0.48	0.26	0.12	0.06
Wade Park	0.96	0.47	0.33	0.25	0.11	0.07
Westerly WWTP	0.51	0.24	0.20	0.15	0.06	0.03
Westlake	0.68	0.38	0.33	0.22	0.09	0.04

Work Order Detail Report

10/21/2022

SSO INSPECTION 0-19-2022 1.44 INCHES OF RAIN

3:17 PM

WO Number: 221019-0004	Category: SSOs
Status: Complete	Problem: Storm Response
Status Date: 10/21/2022 3:10 pm	Main Task: Inspection
Asset: SSO 431	
Location: FAIRFAX AT NORTH PARK	
Cause: Weather	Assigned By:
Assigned Crew:	Assigned Date:
Supervisor: Jackson, Jeff	Start Date: 10/19/2022 7:05 AM
Lead Worker: Cardarella, Joe	End Date: 10/19/2022 3:04 PM
Priority: High	Override
Account #:	Notifications
Proj No - Acct:	Problem ☐
Project:	Overdue ☐
Reason:	Lead Worker ☐
Received By:	Task ☐
Inspected By:	Supervisor ☐
	Hard Lock WO ☐

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:
Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

10/21/2022

SSO INSPECTION 0-19-2022 1.44 INCHES OF RAIN

3:17 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

10/21/2022

SSO INSPECTION 0-19-2022 1.44 INCHES OF RAIN

3:17 PM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

10/21/2022

SSO INSPECTION 0-19-2022 1.44 INCHES OF RAIN

3:17 PM

Work Order Assets							
Object Type	Description 1		Description 2				
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 221019-0004

Work Order Detail Report

10/21/2022

SSO INSPECTION 0-19-2022 1.44 INCHES OF RAIN

3:17 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

10/21/2022

SSO INSPECTION 0-19-2022 1.44 INCHES OF RAIN

3:17 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	10/19/2022/ 2:20 pm	10/19/2022
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	10/19/2022/ 2:21 pm	10/19/2022
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	10/19/2022/ 2:21 pm	10/19/2022
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Not Sound	10/19/2022/ 2:22 pm	10/19/2022
Reset					
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Not Sound	10/19/2022/ 2:22 pm	10/19/2022
Reset					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Not Sound	10/19/2022/ 2:22 pm	10/19/2022
Reset					
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	10/19/2022/ 2:23 pm	10/19/2022
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Not Sound	10/19/2022/ 2:23 pm	10/19/2022
Reset					
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Not Sound	10/19/2022/ 2:23 pm	10/19/2022
Reset					
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Not Sound	10/19/2022/ 2:24 pm	10/19/2022
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	10/19/2022/ 2:24 pm	10/19/2022
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	10/19/2022/ 2:25 pm	10/19/2022
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	10/19/2022/ 2:25 pm	10/19/2022
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	10/19/2022/ 2:26 pm	10/19/2022
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	10/19/2022/ 2:26 pm	10/19/2022
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	10/19/2022/ 2:27 pm	10/19/2022
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	10/19/2022/ 2:27 pm	10/19/2022
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Not Sound	/ 2:28 pm	10/19/2022
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	10/19/2022/ 2:28 pm	10/19/2022
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	10/19/2022/ 2:29 pm	10/19/2022
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	10/19/2022/ 2:29 pm	10/19/2022
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	10/19/2022/ 2:29 pm	10/19/2022
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	10/19/2022/ 2:30 pm	10/19/2022
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	10/19/2022/ 2:30 pm	10/19/2022

Work Order Detail Report

10/21/2022

SSO INSPECTION 0-19-2022 1.44 INCHES OF RAIN

3:17 PM

25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	10/19/2022/ 2:30 pm	10/19/2022
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Not Sound	10/19/2022/ 2:31 pm	10/19/2022
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	10/19/2022/ 2:31 pm	10/19/2022
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	10/19/2022/ 2:32 pm	
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	10/19/2022/ 2:33 pm	10/19/2022
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	10/19/2022/ 2:32 pm	10/19/2022
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	10/19/2022/ 2:34 pm	10/19/2022
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	10/19/2022/ 2:34 pm	10/19/2022
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	10/19/2022/ 2:35 pm	10/19/2022
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Not Sound	10/19/2022/ 2:35 pm	10/19/2022
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Sound	10/19/2022/ 2:35 pm	10/19/2022
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Not Sound	/ 2:36 pm	10/19/2022
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	10/19/2022/ 2:36 pm	10/19/2022
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	10/19/2022/ 2:36 pm	10/19/2022
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	10/19/2022/ 2:37 pm	10/19/2022
40	C-59 3427 THORNE RD SA16AQD0	☐	Sound	10/19/2022/ 2:37 pm	10/19/2022
41	C-60 3415 THORNE RD SA16AQCC0	☐	Sound	10/19/2022/ 2:37 pm	10/19/2022
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	10/19/2022/ 2:38 pm	10/19/2022
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Not Sound	10/19/2022/ 2:38 pm	10/19/2022
Reset					
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Not Sound	10/19/2022/ 2:38 pm	10/19/2022
Reset					
45	C-50 3593 FENLEY SA16APEH0	☐	Not Sound	10/19/2022/ 2:39 pm	10/19/2022
Reset					

Tasks/Resources

SWCT26 Inspection

Crew:

Status:

*Cal'c UC: \$6.21

*Task Cost: \$279.52

Start Dt: 10/19/2022

Supervisor:

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 10/19/2022

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	8.00	\$172.32		10/19/2022	10/19/2022

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20		10/19/2022	10/19/2022

Task Comment: SSO INSPECTION 1.44 INCHES OF RAIN

Work Order Detail Report

10/21/2022

SSO INSPECTION 0-19-2022 1.44 INCHES OF RAIN

3:17 PM

			<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
Projected Complete:		Lock: ☐	WO Duration	7.98	0.00
Repair Type:			Labor Hours	8.00	0.00
Subcontractor:			Labor Costs	\$172.32	\$0.00
Profit Center:			Material Costs	0.00	0.00
			Fluids Costs	0.00	0.00
Quantity:	0.00	Lock: ☐	Equipment Costs	107.20	0.00
Unit of Measure:	Each		Contractor Costs	0.00	0.00
*Unit Cost:	\$0.00		Misc. Costs	0.00	0.00
WO Hours:	0.00		Total Costs	\$279.52	\$0.00
			Use Task Info:	True	True

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data		*Billing Amount:	Billing Required: ☐
Contact Name:		Date Bill Sent:	Billing Processed: ☐
Invoice Number:		Payment Received:	Imported to Financials: ☐
Incoming Account #:		Payment Method:	

Associated PMs	
PM Code and Description	Closed ☒
SSO-02 SSO INSPECTION	

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	10/19/2022	1:54 PM
Supervisor Notification	Email Queued Successfully!	jjackson	10/19/2022	1:54 PM
Status Change	From New Work Order to Complete	aferrone	10/21/2022	3:10 PM

Rate:	Opened At:	Televised: ☐
Recieved By:	Pipe Footage Cleaned:	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Throug	Appointment Date:	
Dye Test Results:		
WO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	

Work Order Detail Report

10/21/2022


SSO INSPECTION 0-19-2022 1.44 INCHES OF RAIN

3:17 PM

Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sler		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:			
WO User 40:	OUPS #:		
WO User 41:	WO User 48:		
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	☐
WO User 73:	Quantity:	Paid:	☐
WO User 74:	WO User 84:	WO User 104:	☐
WO User 75:	WO User 85:	WO User 105:	☐
WO User 76:	WO User 86:	WO User 106:	☐
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	☐
WO User 78:	WO User 88:	WO User 108:	☐
WO User 79:	WO User 89:	WO User 109:	☐
WO User 80:	WO User 90:	WO User 110:	☐
WO User 81:	WO User 91:	WO User 111:	☐
WO Creator: jjackson	WO Creation Date: 10/19/2022	PM Trigger:	Rec #: 13165



Daily Precipitation Report
Wednesday, October 26, 2022
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Wednesday, October 26, 2022

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.86	0.48	0.27	0.21	0.11
Brecksville	0.49	0.37	0.30	0.16	0.05
Brook Park	0.30	0.23	0.20	0.10	0.04
Cleveland Industrial Pkwy	0.31	0.24	0.22	0.11	0.04
Dille Ave PS	0.30	0.26	0.22	0.10	0.04
Division Ave PS	0.22	0.19	0.16	0.09	0.03
Easterly WWTP	0.41	0.36	0.33	0.17	0.06
Independence	0.44	0.33	0.26	0.12	0.05
James Rhodes HS	0.35	0.20	0.17	0.09	0.03
Jennings PS	0.35	0.22	0.17	0.08	0.04
Macedonia	0.57	0.42	0.33	0.21	0.07
Maple Heights	0.56	0.36	0.30	0.17	0.06
Mary Street PS	0.28	0.23	0.18	0.09	0.04
Mayfield Heights	0.64	0.37	0.21	0.16	0.07
Moreland Hills	0.84	0.48	0.31	0.20	0.10
North Olmsted	0.32	0.26	0.24	0.13	0.05
North Royalton	0.47	0.29	0.23	0.12	0.04
Oakwood	0.64	0.43	0.34	0.22	0.08
Olmsted Falls	0.40	0.30	0.27	0.14	0.05
Parma	0.36	0.24	0.20	0.12	0.04
Richfield	0.51	0.39	0.32	0.17	0.05
Shaker Heights	0.69	0.47	0.32	0.17	0.10
South Euclid	0.42	0.27	0.22	0.13	0.05
Southerly WWTC	0.52	0.32	0.24	0.12	0.06
Strongsville C WWTP	0.34	0.25	0.21	0.10	0.04
Strongsville Foltz	0.30	0.22	0.21	0.11	0.04
University Heights	0.70	0.42	0.27	0.16	0.14
Wade Park	0.45	0.38	0.32	0.17	0.06
Westerly WWTP	0.19	0.19	0.17	0.10	0.04
Westlake	0.32	0.27	0.25	0.15	0.06

Work Order Detail Report

11/2/2022

SSO INSPECTION 10-26-2022 0.70 INCHES OF RAIN

1:18 PM

WO Number: 221102-0006	Category: SSOs
Status: Complete	Problem: Storm Response
Status Date: 11/2/2022 1:17 pm	Main Task: Inspection
Asset: SSO 431	
Location: FAIRFAX AT NORTH PARK	
Cause: Weather	Assigned By:
Assigned Crew:	Assigned Date: 10/26/2022
Supervisor: Jackson, Jeff	Start Date: 10/28/2022 8:00 AM
Lead Worker: Eathridge, David	End Date: 10/28/2022
Priority: High	Override
Account #:	Notifications
Proj No - Acct:	Problem ☐
Project:	Overdue ☐
Reason:	Lead Worker ☐
Received By:	Task ☐
Inspected By:	Supervisor ☐
	Hard Lock WO ☐

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:
Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

<u>Address</u>	<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>
<u>General Location</u>	
FAIRFAX AT NORTH PARK	
2,220,655.65435414	665,517.24643672
NORTH PARK AND COVENTRY	Doan Brook
2,219,873.16674590	666,048.82312946
FAIRMOUNT SOUTH OF SCARBOROUGH	DOAN BROOK - MAIN BRANCH
2,220,364.86097248	666,446.72325230
FAIRMOUNT AT FAIRFAX	DOAN BROOK - MAIN BRANCH
2,220,920.81917815	666,080.57995571
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	DOAN BROOK - MAIN BRANCH
2,223,053.81655256	664,693.25202172
3012 NORTH WOODLAND	DOAN BROOK - MAIN BRANCH
2,222,845.06631389	664,689.08536339
	Doan Brook
2,226,440.21168265	664,329.55524255
2,226,354.79813956	664,409.89202413
2,226,389.92077273	664,379.07548472
FAIRMOUNT AT DARTMOOR	
2,225,149.97508989	664,453.31024438
FAIRMOUNT AT WELLINGTON	DOAN BROOK - MAIN BRANCH
2,223,969.26550905	664,532.08075613
	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

11/2/2022

SSO INSPECTION 10-26-2022 0.70 INCHES OF RAIN

1:18 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

11/2/2022

SSO INSPECTION 10-26-2022 0.70 INCHES OF RAIN

1:18 PM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

11/2/2022

SSO INSPECTION 10-26-2022 0.70 INCHES OF RAIN

1:18 PM

Work Order Assets							
Object Type	Description 1			Description 2			
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		

Work Order Detail Report

11/2/2022

SSO INSPECTION 10-26-2022 0.70 INCHES OF RAIN

1:18 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

11/2/2022

SSO INSPECTION 10-26-2022 0.70 INCHES OF RAIN

1:18 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Not Sound	10/28/2022/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Not Sound	10/28/2022/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	10/28/2022/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	10/28/2022/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Sound	10/28/2022/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	10/28/2022/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	10/28/2022/	
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	10/28/2022/	
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	10/28/2022/	
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	10/28/2022/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	10/28/2022/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	10/28/2022/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	10/28/2022/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	10/28/2022/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	10/28/2022/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	10/28/2022/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Not Sound	10/28/2022/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	10/28/2022/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	10/28/2022/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	10/28/2022/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Not Sound	10/28/2022/	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Not Sound	10/28/2022/	
needs block					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	10/28/2022/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	10/28/2022/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	10/28/2022/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	10/28/2022/	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	10/28/2022/	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 221102-0006

Work Order Detail Report

11/2/2022

SSO INSPECTION 10-26-2022 0.70 INCHES OF RAIN

1:18 PM

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	10/28/2022/
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	10/28/2022/
30	B-15 COVENTRY AND CEDAR SA16ADBHO	☐	Sound	10/28/2022/
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Not Sound	10/28/2022/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	10/28/2022/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	10/28/2022/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	10/28/2022/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Sound	10/28/2022/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Sound	10/28/2022/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	10/28/2022/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	10/28/2022/
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	10/28/2022/
40	C-59 3427 THORNE RD SA16AQD0	☐	Sound	10/28/2022/
41	C-60 3415 THORNE RD SA16AQCC0	☐	Sound	10/28/2022/
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	10/28/2022/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	10/28/2022/
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	10/28/2022/
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	10/28/2022/

Tasks/Resources**SWCT26 Inspection****Crew:**

Status: Complete

*Cal'c UC: \$8.76

*Task Cost: \$394.08

Start Dt:

Supervisor: Jackson, Jeff

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt:

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	4.00	\$90.56			
13859 Moten, Robert	Hours	4.00	\$88.76			
11213 Owens, Will	Hours	4.00	\$90.56			
29960 Jackson, Jeff	Hours	4.00	\$0.00			

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	4.00	\$53.60			
CHFLT55 FORD 350 CREW CAB 9	Hours	4.00	\$70.60			
CHFT-500 FORD F250 PICK UP TRUCK	Each	4.00	\$0.00			

Task Comment: SSO INSPECTION 0.70"

Work Order Detail Report

11/2/2022

SSO INSPECTION 10-26-2022 0.70 INCHES OF RAIN

1:18 PM

			<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
Projected Complete:	Lock: ☐	WO Duration	0.00	0.00	0.00
Repair Type:		Labor Hours	16.00	0.00	0.00
Subcontractor:		Labor Costs	\$269.88	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	124.20	0.00	0.00
Unit of Measure:	Each	Contractor Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
WO Hours:	0.00	Total Costs	\$394.08	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: ☐
Invoice Number:		Date Bill Sent:	Billing Processed: ☐
Incoming Account #:		Payment Received:	Imported to Financials: ☐
		Payment Method:	

Associated PMs	
<u>PM Code and Description</u>	<u>Closed</u>
SSO-02 SSO INSPECTION	☒

Tracking				
<u>Item</u>	<u>Description</u>	<u>By</u>	<u>Date</u>	<u>Time</u>
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aferrone	11/2/2022	1:02 PM
Supervisor Notification	Email Queued Successfully!	aferrone	11/2/2022	1:02 PM
Status Change	From New Work Order to Complete	aferrone	11/2/2022	1:17 PM

Rate:	Opened At:	Televised: ☐
Recieved By:	Pipe Footage Cleaned	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Throug	Appointment Date:	
Dye Test Results:		
WO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	

Work Order Detail Report

11/2/2022

SSO INSPECTION 10-26-2022 0.70 INCHES OF RAIN

1:18 PM

Manhole Basin Repair:

Material Used:

Pipe Repair:

Street Repair:

Grass Repair:

Curb Repair:

Driveway- Sidewalk Re

Construction Crew:

WO User 39:

WO User 40:

WO User 41:

Pipe Size:

PVC Tees, Angles, Sles

WO User 44:

WO User 45:

WO User 46:

OUPS #:

WO User 48:

WO User 52:

WO User 53:

WO User 54:

WO User 55:

WO User 56:

WO User 57:

WO User 58:

WO User 59:

WO User 60:

WO User 61:

WO User 72:

WO User 73:

WO User 74:

WO User 75:

WO User 76:

WO User 62:

WO User 63:

WO User 64:

WO User 65:

WO User 66:

WO User 67:

WO User 68:

WO User 69:

WO User 70:

WO User 71:

WO User 82:

Quantity:

WO User 84:

WO User 85:

WO User 86:

Televised:

☐

Paid:

☐

WO User 104:

☐

WO User 105:

☐

WO User 106:

☐

WO User 92 Date:

WO User 93 Date:

WO User 94 Date:

WO User 95 Date:

WO User 96 Date:

WO User 97 Date:

WO User 98 Date:

WO User 99 Date:

WO User 100 Date:

WO User 101 Date:

WO User 77:

WO User 78:

WO User 79:

WO User 80:

WO User 81:

WO User 87:

WO User 88:

WO User 89:

WO User 90:

WO User 91:

WO User 107:

☐

WO User 108:

☐

WO User 109:

☐

WO User 110:

☐

WO User 111:

☐

WO Creator: aferrone

WO Creation Date: 11/2/2022

PM Trigger:

Rec #: 13211

