

Law Department

February 16, 2023

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604

Re: January 2023 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through January 31, 2023, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,


A handwritten signature in black ink that reads "William R. Hanna". The signature is fluid and cursive, with "William" on the top line and "R. Hanna" on the bottom line.
William R. Hanna
Director of Law

Enclosures

cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Tuesday, January 3, 2023
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Tuesday, January 3, 2023

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	n/a	n/a	n/a	n/a	n/a
Brecksville	0.77	0.56	0.40	0.24	0.07
Brook Park	0.60	0.40	0.26	0.16	0.05
Cleveland Industrial Pkwy	0.62	0.40	0.27	0.16	0.06
Dille Ave PS	0.66	0.44	0.28	0.18	0.06
Division Ave PS	0.77	0.46	0.31	0.18	0.07
Easterly WWTP	0.77	0.46	0.33	0.18	0.07
Independence	0.79	0.55	0.40	0.22	0.09
James Rhodes HS	0.63	0.42	0.28	0.18	0.07
Jennings PS	0.65	0.43	0.29	0.18	0.06
Macdonnia	0.84	0.60	0.44	0.27	0.09
Maple Heights	0.74	0.55	0.38	0.21	0.08
Mary Street PS	0.74	0.46	0.29	0.18	0.06
Mayfield Heights	0.77	0.49	0.33	0.18	0.07
Moreland Hills	1.02	0.68	0.45	0.28	0.13
North Olmsted	0.68	0.41	0.28	0.16	0.06
North Royalton	0.78	0.55	0.38	0.21	0.07
Oakwood	0.81	0.59	0.41	0.25	0.07
Olmsted Falls	0.69	0.46	0.31	0.18	0.06
Parma	0.66	0.48	0.33	0.20	0.07
Richfield	1.03	0.70	0.51	0.29	0.11
Shaker Heights	0.75	0.50	0.34	0.19	0.07
South Euclid	0.82	0.48	0.32	0.17	0.06
Southerly WWTC	0.63	0.43	0.29	0.17	0.06
Strongsville C WWTP	0.65	0.47	0.32	0.18	0.06
Strongsville Foltz	0.64	0.45	0.32	0.17	0.06
University Heights	0.81	0.51	0.34	0.18	0.07
Wade Park	0.80	0.49	0.31	0.19	0.07
Westerly WWTP	0.72	0.40	0.30	0.17	0.06
Westlake	0.76	0.43	0.34	0.19	0.04

Work Order Detail Report

1/6/2023

SSO INSPECTIONS 0.80 INCHES OF RAIN

11:13 AM

WO Number: 230104-0005 Category: SSOs
Status: Complete Problem: Storm Response
Status Date: 1/6/2023 10:41 am Main Task: Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause:	Weather	Assigned By:			
Assigned Crew:		Assigned Date:			
Supervisor:	Jackson, Jeff	Start Date:	1/4/2023	7:33 AM	Override
Lead Worker:	Cardarella, Joe	End Date:	1/4/2023	3:33 PM	Notifications
Priority:	High	Problem	<input type="checkbox"/>		
Account #:		Overdue	<input type="checkbox"/>		
Proj No - Acct:		Lead Worker	<input type="checkbox"/>		
Project:		Task	<input type="checkbox"/>		
Reason:		Supervisor	<input type="checkbox"/>		
Received By:		Hard Lock WO	<input type="checkbox"/>		
Inspected By:					

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations		
<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

1/6/2023

SSO INSPECTIONS 0.80 INCHES OF RAIN

11:13 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail ReportSSO INSPECTIONS 0.80 INCHES OF RAIN

1/6/2023

11:13 AM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

1/6/2023

SSO INSPECTIONS 0.80 INCHES OF RAIN

11:13 AM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1	Odometer	Hourmeter	Othermeter	Description 2	PM Description	Asset ID	Completed
Sewer Control Valve	SSO 431						FAIRFAX AT NORTH PARK		26	
Sewer Control Valve	SSO 114						NORTH PARK AND COVENTRY		16	
Sewer Control Valve	SSO 121						FAIRMOUNT SOUTH OF SCARBOROUGH		35	
Sewer Structure	SA16AAWB0						3094			
Sewer Control Valve	SSO 112						FAIRMOUNT AT FAIRFAX		7	
Sewer Control Valve	SSO 99						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		6	
Sewer Control Valve	SSO 432						3012 NORTH WOODLAND		14	
Sewer Control Valve	DB-03								55	
Sewer Control Valve	DB-01								56	
Sewer Control Valve	DB-02								57	
Sewer Control Valve	CH-04						FAIRMOUNT AT DARTMOOR		5	
Sewer Control Valve	SSO 110						FAIRMOUNT AT WELLINGTON		44	
Sewer Control Valve	SSO 87						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		33	
Sewer Control Valve	SSO 116						FAIRMOUNT AT MARLBORO		4	
Sewer Control Valve	SSO 111						FAIRMOUNT AT ARLINGTON		46	
Sewer Control Valve	SSO 113						FAIRMOUNT & COVENTRY (SCARBOROUGH)		37	
Sewer Control Valve	SSO 124						FAIRMOUNT AND COVENTRY		47	
Sewer Control Valve	CH-50						SCARBOROUGH AT LAMBERTON		53	
Sewer Control Valve	SSO 129						BRADFORD AND LEE		11	
Sewer Control Valve	CH-52						EDDINGTON		2	
Sewer Control Valve	SSO 88						HAMPSHIRE LANE AT MAYFIELD (18")		42	
Sewer Control Valve	SSO 122						EAST OVERLOOK AT EDGEHILL		36	
Sewer Control Valve	SSO 89						HAMPSHIRE LANE AT MAYFIELD (36")		34	
Sewer Structure	SA16ADZB0						1536			
Sewer Control Valve	SSO 91						HAMPSHIRE AT EUCLID HTS. BLVD.		20	
Sewer Structure	SA16ADPH0						4446			
Sewer Control Valve	SSO 120						CEDAR BTW. FAIRMOUNT/DEMINGTON		8	
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230104-0005

Work Order Detail Report

1/6/2023

SSO INSPECTIONS 0.80 INCHES OF RAIN

11:13 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	/	1/4/2023
Still surcharging					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	/	1/4/2023
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Not Sound	/	1/4/2023
Reset					
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	/	1/4/2023
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	/	
Still surcharging					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	/	1/4/2023
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	/	1/4/2023
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	/	1/4/2023
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	/	1/4/2023
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	/	1/4/2023
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	/	1/4/2023
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	1/4/2023
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	/	1/4/2023
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	/	1/4/2023
Still surcharging					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	/	1/4/2023
Still surcharging					
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	/	1/4/2023
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	/	1/4/2023
Reset					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	/	1/4/2023
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	/	1/4/2023
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	/	1/4/2023
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	/	1/4/2023
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	/	1/4/2023
Meter					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	/	1/4/2023

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230104-0005

Work Order Detail Report

1/6/2023

SSO INSPECTIONS 0.80 INCHES OF RAIN

11:13 AM

24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	/	1/4/2023
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	/	1/4/2023
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	/	1/4/2023
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	/	1/4/2023
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	/	1/4/2023
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	/	
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	/	1/4/2023
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	/	1/4/2023
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	/	1/4/2023
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	/	1/4/2023
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	/	1/4/2023
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	/	1/4/2023
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	/	1/4/2023
Reset					
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	/	1/4/2023
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	/	1/4/2023
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Not Sound	/	1/4/2023
Reset					
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	/	1/4/2023
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	/	1/4/2023
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	/	1/4/2023
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	/	1/4/2023
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	/	1/4/2023
Still surcharging					
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	/	1/4/2023

Tasks/Resources

SWCT26 Inspection

Crew:	Status:	*Cal'c UC: \$10.12	*Task Cost: \$455.44	Start Dt: 1/4/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 1/4/2023

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	8.00	\$197.52		1/4/2023	1/4/2023
40404 Don Johnson		8.00	\$150.72		1/4/2023	1/4/2023

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		1/4/2023	1/4/2023

5

Task Comment: SSO INSPECTION 0.81 INCHES OF RAIN

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230104-0005

Work Order Detail Report

1/6/2023

SSO INSPECTIONS 0.80 INCHES OF RAIN

11:13 AM

			<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	8.00	0.00
Repair Type:			Labor Hours	16.00	0.00
Subcontractor:			Labor Costs	\$348.24	\$0.00
Profit Center:			Material Costs	0.00	0.00
			Fluids Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Equipment Costs	107.20	0.00
Unit of Measure:	Each		Contractor Costs	0.00	0.00
*Unit Cost:	\$0.00		Misc. Costs	0.00	0.00
WO Hours:	0.00		Total Costs	\$455.44	\$0.00
			Use Task Info:	True	True

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Cell #:	
State:		Fax #:	
Zip:		E-mail:	
Billing Data			
Contact Name:		*Billing Amount:	<input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/>
		Payment Method:	<input type="checkbox"/>
Imported to Financials: <input type="checkbox"/>			

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

Tracking					
<u>Item</u>	<u>Description</u>	<u>By</u>	<u>Date</u>	<u>Time</u>	
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jackson	1/4/2023	12:54 PM	
Supervisor Notification	Email Queued Successfully!	jackson	1/4/2023	12:54 PM	
Status Change	From New Work Order to Complete	aferrone	1/6/2023	10:41 AM	
Rate:	Opened At:			Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned			Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:			Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:			Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:			Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:			Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:			GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL			Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date:	1/4/2023	8:00 AM		
Dye Test Results:					
WO User 51:	E Mail:				
Measurement:	Measurement Line 2:				
History:					

Work Order Detail Report

SSO INSPECTIONS 0.80 INCHES OF RAIN


1/6/2023

11:13 AM

Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Slic
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:
Curb Repair:	
Driveway- Sidewalk Re	
Construction Crew:	
WO User 39:	OUPS #:
WO User 40:	WO User 48:
WO User 41:	
WO User 52:	WO User 62:
WO User 53:	WO User 63:
WO User 54:	WO User 64:
WO User 55:	WO User 65:
WO User 56:	WO User 66:
WO User 57:	WO User 67:
WO User 58:	WO User 68:
WO User 59:	WO User 69:
WO User 60:	WO User 70:
WO User 61:	WO User 71:
WO User 72:	WO User 82:
WO User 73:	Quantity:
WO User 74:	WO User 84:
WO User 75:	WO User 85:
WO User 76:	WO User 86:
WO User 92 Date:	WO User 97 Date:
WO User 93 Date:	WO User 98 Date:
WO User 94 Date:	WO User 99 Date:
WO User 95 Date:	WO User 100 Date:
WO User 96 Date:	WO User 101 Date:
WO User 77:	WO User 87:
WO User 78:	WO User 88:
WO User 79:	WO User 89:
WO User 80:	WO User 90:
WO User 81:	WO User 91:
WO Creator: jjackson	WO Creation Date: 1/4/2023 PM Trigger: Rec #: 13296

 **Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Thursday, January 12, 2023
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Thursday, January 12, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	n/a	n/a	n/a	n/a	n/a	n/a
Brecksville	1.06	0.73	0.56	0.30	0.11	0.04
Brook Park	0.93	0.50	0.40	0.20	0.06	0.03
Cleveland Industrial Pkwy	1.11	0.68	0.53	0.25	0.08	0.03
Dille Ave PS	1.08	0.66	0.52	0.28	0.09	0.04
Division Ave PS	1.01	0.71	0.56	0.28	0.09	0.04
Easterly WWTP	0.90	0.64	0.52	0.27	0.09	0.03
Independence	1.02	0.67	0.54	0.29	0.10	0.04
James Rhodes HS	1.17	0.72	0.57	0.29	0.10	0.04
Jennings PS	1.23	0.72	0.58	0.29	0.10	0.04
Macedonia	0.92	0.70	0.50	0.31	0.13	0.05
Maple Heights	0.89	0.64	0.55	0.30	0.10	0.04
Mary Street PS	1.08	0.68	0.57	0.30	0.10	0.05
Mayfield Heights	1.04	0.68	0.56	0.29	0.09	0.03
Moreland Hills	1.12	0.86	0.72	0.40	0.15	0.06
North Olmsted	1.26	0.74	0.56	0.26	0.07	0.03
North Royalton	1.02	0.66	0.53	0.30	0.10	0.04
Oakwood	0.95	0.73	0.54	0.31	0.12	0.04
Olmsted Falls	1.17	0.73	0.57	0.27	0.08	0.03
Parma	1.11	0.69	0.56	0.29	0.09	0.04
Richfield	0.94	0.74	0.56	0.37	0.15	0.06
Shaker Heights	1.12	0.66	0.56	0.30	0.10	0.04
South Euclid	1.10	0.67	0.54	0.28	0.11	0.04
Southerly WWTC	0.99	0.65	0.54	0.29	0.10	0.04
Strongsville C WWTP	1.08	0.67	0.53	0.30	0.10	0.04
Strongsville Foltz	1.02	0.66	0.54	0.31	0.13	0.06
University Heights	1.21	0.73	0.60	0.31	0.10	0.04
Wade Park	1.06	0.67	0.54	0.28	0.10	0.04
Westerly WWTP	0.99	0.74	0.58	0.28	0.10	0.04
Westlake	1.10	0.80	0.59	0.28	0.09	0.04

Work Order Detail Report

1/17/2023

SSO INSPECTION 1-12-2023 1.21" OF RAIN

4:28 PM

WO Number:	230113-0001	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	1/17/2023 4:27 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather		
Assigned Crew:			
Supervisor:	Jackson, Jeff	Assigned By:	
Lead Worker:	Cardarella, Joe	Assigned Date:	
Priority:	High	Start Date:	1/13/2023 7:25 AM
Account #:		End Date:	1/17/2023 12:25 PM
Proj No - Acct:		Project ID:	<input type="checkbox"/>
Project:		Project Name:	<input type="checkbox"/>
Reason:			Lead Worker <input type="checkbox"/>
Received By:			Task <input type="checkbox"/>
Inspected By:			Supervisor <input type="checkbox"/>
			Hard Lock WO <input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook
	2,226,440.21168265	664,329.55524255	
	2,226,354.79813956	664,409.89202413	
	2,226,389.92077273	664,379.07548472	FAIRMOUNT AT DARTMOOR
	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
	2,223,969.26550905	664,532.08075613	FAIRMOUNT AT WELLINGTON
			DOAN BROOK - MAIN BRANCH

Work Order Detail Report

1/17/2023

SSO INSPECTION 1-12-2023 1.21" OF RAIN

4:28 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
2,223,111.44143730 664,794.46048072 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO
2,221,638.88762389 665,726.15513962 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
2,221,598.28993607 666,996.61322863
MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON
2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD

2225 NOBLE ROAD
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE
2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

Work Order Detail Report
SSO INSPECTION 1-12-2023 1.21" OF RAIN

1/17/2023
4:28 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

1/17/2023

SSO INSPECTION 1-12-2023 1.21" OF RAIN

4:28 PM

Work Order Assets										
Object Type	System ID 1	System ID 2	Description 1	Odometer	Hourmeter	Othermeter	Description 2	PM Description	Asset ID	Completed
Sewer Control Valve	SSO 431						FAIRFAX AT NORTH PARK		26	
Sewer Control Valve	SSO 114						NORTH PARK AND COVENTRY		16	
Sewer Control Valve	SSO 121						FAIRMOUNT SOUTH OF SCARBOROUGH		35	
Sewer Structure	SA16AAWB0						3094			
Sewer Control Valve	SSO 112						FAIRMOUNT AT FAIRFAX		7	
Sewer Control Valve	SSO 99						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		6	
Sewer Control Valve	SSO 432						3012 NORTH WOODLAND		14	
Sewer Control Valve	DB-03								55	
Sewer Control Valve	DB-01								56	
Sewer Control Valve	DB-02								57	
Sewer Control Valve	CH-04						FAIRMOUNT AT DARTMOOR		5	
Sewer Control Valve	SSO 110						FAIRMOUNT AT WELLINGTON		44	
Sewer Control Valve	SSO 87						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		33	
Sewer Control Valve	SSO 116						FAIRMOUNT AT MARLBORO		4	
Sewer Control Valve	SSO 111						FAIRMOUNT AT ARLINGTON		46	
Sewer Control Valve	SSO 113						FAIRMOUNT & COVENTRY (SCARBOROUGH)		37	
Sewer Control Valve	SSO 124						FAIRMOUNT AND COVENTRY		47	
Sewer Control Valve	CH-50						SCARBOROUGH AT LAMBERTON		53	
Sewer Control Valve	SSO 129						BRADFORD AND LEE		11	
Sewer Control Valve	CH-52						EDDINGTON		2	
Sewer Control Valve	SSO 88						HAMPSHIRE LANE AT MAYFIELD (18")		42	
Sewer Control Valve	SSO 122						EAST OVERLOOK AT EDGEHILL		36	
Sewer Control Valve	SSO 89						HAMPSHIRE LANE AT MAYFIELD (36")		34	
Sewer Structure	SA16ADZB0						1536			
Sewer Control Valve	SSO 91						HAMPSHIRE AT EUCLID HTS. BLVD.		20	
Sewer Structure	SA16ADPH0						4446			
Sewer Control Valve	SSO 120						CEDAR BTW. FAIRMOUNT/DEMINGTON		8	
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230113-0001

Work Order Detail Report

1/17/2023

SSO INSPECTION 1-12-2023 1.21" OF RAIN

4:28 PM

SSO 103	19	
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD	
SSO 104	15	
Sewer Structure		
SA16AGMG0	3402	
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R	
CH-30	52	
Sewer Control Valve	LEE RD. & SUPERIOR AVE.	
DV-11	9	
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE	
SSO 106	22	
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND	
SSO 108	43	
Sewer Control Valve	1685 CUMBERLAND	
SSO 95	18	
Sewer Control Valve	CUMBERLAND/SOMERTON	
SSO 105	30	
Sewer Structure		
SA16AQD0	4987	
Sewer Structure		
SA16AQC0	3745	
Sewer Control Valve	2225 NOBLE ROAD	
SSO 102	3	
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF	
SSO 107	38	
Sewer Control Valve	LANGTON AND AHERSTONE	
CH-51	54	
Sewer Structure		
SA16APEF0	1809	

Work Order Detail Report

1/17/2023

SSO INSPECTION 1-12-2023 1.21" OF RAIN

4:28 PM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	1/17/2023/ 8:49 am	1/17/2023
Still surcharging couldn't reset					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	1/17/2023/ 8:52 am	1/17/2023
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	1/17/2023/ 8:26 am	1/17/2023
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	1/17/2023/ 8:35 am	1/17/2023
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	1/17/2023/ 8:44 am	1/17/2023
Still surcharging couldn't reset					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	1/17/2023/ 9:04 am	1/17/2023
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	1/17/2023/ 9:01 am	1/17/2023
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	1/17/2023/ 9:14 am	1/17/2023
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	1/17/2023/ 9:18 am	1/17/2023
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	1/17/2023/ 9:20 am	1/17/2023
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	1/17/2023/ 9:43 am	1/17/2023
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	1/17/2023/ 9:50 am	1/17/2023
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	1/17/2023/10:11 am	1/17/2023
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	1/17/2023/10:15 am	1/17/2023
Still surcharging can't reset					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAU0 (INTERSECTION)	<input type="checkbox"/>	Sound	1/17/2023/10:21 am	1/17/2023
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	1/17/2023/10:26 am	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	1/17/2023/ 8:21 am	1/17/2023
Reset					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	1/17/2023/10:03 am	1/17/2023
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	1/17/2023/ 9:57 am	1/17/2023
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	1/17/2023/ 9:34 am	1/17/2023
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	1/17/2023/ 9:39 am	1/17/2023
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	1/13/2023/12:40 pm	1/13/2023
Meter in manhole					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	1/13/2023/ 9:09 am	1/13/2023
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	1/13/2023/ 9:21 am	1/13/2023

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230113-0001

Work Order Detail Report

1/17/2023

SSO INSPECTION 1-12-2023 1.21" OF RAIN

4:28 PM

25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	1/13/2023/ 9:22 am	1/13/2023
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	1/13/2023/ 9:29 am	1/13/2023
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Not Sound	1/13/2023/ 9:35 am	1/13/2023
Reset					
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Not Sound	1/13/2023/ 9:40 am	1/13/2023
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	1/13/2023/12:17 pm	1/13/2023
30	B-15 COVENTRY AND CEDAR SA16ADBHQ0	<input type="checkbox"/>	Sound	1/13/2023/12:23 pm	1/13/2023
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	1/13/2023/ 9:51 am	1/13/2023
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	1/13/2023/ 9:56 am	1/13/2023
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	1/13/2023/12:28 pm	1/13/2023
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	1/13/2023/10:35 am	1/13/2023
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	1/13/2023/10:31 am	1/13/2023
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	1/13/2023/10:27 am	1/13/2023
Reset					
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	1/13/2023/10:04 am	1/13/2023
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	1/13/2023/10:08 am	1/13/2023
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Not Sound	1/13/2023/10:17 am	1/13/2023
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	1/13/2023/ 8:55 am	1/13/2023
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	1/13/2023/ 8:50 am	1/13/2023
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	1/13/2023/ 8:43 am	1/13/2023
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	1/13/2023/ 8:16 am	1/13/2023
44	C-51 AATHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	1/13/2023/ 8:25 am	1/13/2023
Still surcharging					
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	1/13/2023/ 8:34 am	1/13/2023

Tasks/Resources

SWCT26 Inspection

Crew:

Status:

*Cal'c UC: \$10.16

*Task Cost: \$457.08

Start Dt: 1/13/2023

Supervisor:

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 1/17/2023

Employee

Resource

UOM

Units

*Total Cost

Alt Description

Start Dt

End Dt

22394 Cardarella, Joe

Hours

12.00

\$296.28

1/13/2023

1/17/2023

Equipment

Resource

UOM

Units

*Total Cost

Alt Description

Start Dt

End Dt

CHFLT50 FORD F250 CREW CAB

Hours

12.00

\$160.80

1/13/2023

1/17/2023

5

Task Comment: SSO INSPECTION 1.21" OF RAIN

Work Order Detail Report

1/17/2023

SSO INSPECTION 1-12-2023 1.21" OF RAIN

4:28 PM

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	37.00	0.00
Repair Type:			Labor Hours	12.00	0.00
Subcontractor:			Labor Costs	\$296.28	\$0.00
Profit Center:			Material Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00
Unit of Measure:	Each		Equipment Costs	160.80	0.00
*Unit Cost:	\$0.00		Contractor Costs	0.00	0.00
WO Hours:	0.00		Misc. Costs	0.00	0.00
			Total Costs	\$457.08	\$0.00
			Use Task Info:	True	True

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	<input type="checkbox"/> Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/> Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/> Imported to Financials: <input type="checkbox"/>
		Payment Method:	

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

Tracking	Description	By	Date	Time	
Item					
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jackson	1/13/2023	7:23 AM	
Supervisor Notification	Email Queued Successfully!	jackson	1/13/2023	7:23 AM	
Status Change	From New Work Order to Complete	aferrone	1/17/2023	4:27 PM	
Rate:					Televised: <input type="checkbox"/>
Received By:					Power Rooter: <input type="checkbox"/>
Work From:					Jet: <input type="checkbox"/>
Pipe Size:					Gap Vac: <input type="checkbox"/>
Pipe Condition:					Dye Test: <input type="checkbox"/>
Could Not Open:					Gap Root Cut: <input type="checkbox"/>
Additional Repair:					GIS Correction?: <input type="checkbox"/>
Dye Test Reason:					Test Tee Correction: <input type="checkbox"/>
Test Performed Through:					
Dye Test Results:					
WO User 51:					
Measurement:					
History:					

Work Order Detail Report
SSO INSPECTION 1-12-2023 1.21" OF RAIN

1/17/2023

4:28 PM

Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Slee		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 1/13/2023	PM Trigger:	Rec #: 13342

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Thursday, January 19, 2023

Accumulation in Inches

Easterly
WWTP
1.33

Mayfield
Heights
1.12

South
Euclid
1.19

University
Heights
1.02

Beachwood
1.06

Wade
Park
1.19

Division PS
1.17

Dille PS
0.98

Mary
Street PS
1.06

Westerly
WWTP
1.03

James
Rhodes HS
0.97

Cleveland
Industrial Pkwy
1.03

Westlake
1.15

North
Olmsted
1.08

Brook Park
0.93

Parma
0.99

Strongsville
"C" WWTP
1.01

Olmsted
Falls
1.13

Cuyahoga
County
1.02

North
Royalton
0.90

Brecksville
1.02

Macedonia
0.90

Oakwood
1.06

Moreland
Hills
1.11

Summit
County
1.12

Shaker
Heights
0.90

Maple
Heights
0.95

Jennings PS
1.06

Southly
WWTP
0.89

Independence
1.02

Lorain
County
1.00

Strongsville
Foltz
1.00

Richfield
0.88

Medina
County
1.00

Lake Erie

Accumulation in Inches

Northeast Ohio Regional Sewer District

Daily Precipitation Report

Thursday, January 19, 2023

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	1.06	0.72	0.47	0.23	0.12
Brecksville	1.02	0.66	0.49	0.20	0.13
Brook Park	0.93	0.56	0.41	0.26	0.12
Cleveland Industrial Pkwy	1.03	0.69	0.48	0.23	0.12
Dille Ave PS	0.98	0.58	0.40	0.30	0.17
Division Ave PS	1.17	0.80	0.54	0.28	0.14
Easterly WWTP	1.33	0.96	0.64	0.29	0.15
Independence	1.02	0.65	0.47	0.22	0.14
James Rhodes HS	0.97	0.56	0.39	0.28	0.15
Jennings PS	1.06	0.61	0.41	0.33	0.17
Macedonia	0.90	0.64	0.50	0.20	0.08
Maple Heights	0.95	0.62	0.44	0.21	0.11
Mary Street PS	1.06	0.64	0.43	0.31	0.17
Mayfield Heights	1.12	0.66	0.42	0.30	0.17
Moreland Hills	1.11	0.76	0.55	0.24	0.11
North Olmsted	1.08	0.68	0.46	0.28	0.17
North Royalton	0.90	0.57	0.42	0.19	0.11
Oakwood	1.06	0.75	0.58	0.23	0.09
Olmsted Falls	1.13	0.64	0.47	0.36	0.18
Parma	0.99	0.61	0.45	0.23	0.13
Richfield	0.88	0.58	0.44	0.16	0.09
Shaker Heights	0.90	0.60	0.41	0.21	0.10
South Euclid	1.19	0.73	0.46	0.31	0.13
Southerly WWTC	0.89	0.55	0.39	0.22	0.12
Strongsville C WWTP	1.01	0.64	0.47	0.22	0.12
Strongsville Foltz	1.00	0.66	0.50	0.22	0.10
University Heights	1.02	0.67	0.44	0.26	0.12
Wade Park	1.19	0.73	0.48	0.33	0.16
Westerly WWTP	1.03	0.72	0.47	0.23	0.12
Westlake	1.15	0.82	0.57	0.26	0.14

Work Order Detail Report

1/24/2023

SSO INSPECTION 1-19-2023 1.02 INCHES OF RAIN

4:48 PM

WO Number:	230120-0001	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	1/24/2023 4:45 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather		
Assigned Crew:			
Supervisor:	Jackson, Jeff	Assigned By:	
Lead Worker:	Cardarella, Joe	Assigned Date:	
Priority:	High	Start Date:	1/20/2023 7:43 AM
Account #:		End Date:	1/23/2023 12:43 PM
Proj No - Acct:		Project ID:	<input type="checkbox"/> Override Notifications
Project:		Project Name:	<input type="checkbox"/> Problem
Reason:			<input type="checkbox"/> Overdue
Received By:			<input type="checkbox"/> Lead Worker
Inspected By:			<input type="checkbox"/> Task
			<input type="checkbox"/> Supervisor
			<input type="checkbox"/> Hard Lock WO

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
X Coord	Y Coord	General Location	
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339	Doan Brook	
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

1/24/2023

SSO INSPECTION 1-19-2023 1.02 INCHES OF RAIN

4:48 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481	672,922.02624655	EAST OVERLOOK AT EDGEHILL
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

1/24/2023

SSO INSPECTION 1-19-2023 1.02 INCHES OF RAIN

4:48 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

1/24/2023

SSO INSPECTION 1-19-2023 1.02 INCHES OF RAIN

4:48 PM

Work Order Assets						
Object Type	System ID 1	Description 1		Description 2		Completed
		System ID 2	Odometer	Hourmeter	Othermeter	
Sewer Control Valve	SSO 431					FAIRFAX AT NORTH PARK 26
Sewer Control Valve	SSO 114					NORTH PARK AND COVENTRY 16
Sewer Control Valve	SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH 35
Sewer Structure	SA16AAWB0					3094
Sewer Control Valve	SSO 112					FAIRMOUNT AT FAIRFAX 7
Sewer Control Valve	SSO 99					FAIRMOUNT AT NORTH WOODLAND (S. SIDE) 6
Sewer Control Valve	SSO 432					3012 NORTH WOODLAND 14
Sewer Control Valve	DB-03					55
Sewer Control Valve	DB-01					56
Sewer Control Valve	DB-02					57
Sewer Control Valve	CH-04					FAIRMOUNT AT DARTMOOR 5
Sewer Control Valve	SSO 110					FAIRMOUNT AT WELLINGTON 44
Sewer Control Valve	SSO 87					FAIRMOUNT AT NORTH WOODLAND (N. SIDE) 33
Sewer Control Valve	SSO 116					FAIRMOUNT AT MARLBORO 4
Sewer Control Valve	SSO 111					FAIRMOUNT AT ARLINGTON 46
Sewer Control Valve	SSO 113					FAIRMOUNT & COVENTRY (SCARBOROUGH) 37
Sewer Control Valve	SSO 124					FAIRMOUNT AND COVENTRY 47
Sewer Control Valve	CH-50					SCARBOROUGH AT LAMBERTON 53
Sewer Control Valve	SSO 129					BRADFORD AND LEE 11
Sewer Control Valve	CH-52					EDDINGTON 2
Sewer Control Valve	SSO 88					HAMPSHIRE LANE AT MAYFIELD (18") 42
Sewer Control Valve	SSO 122					EAST OVERLOOK AT EDGEHILL 36
Sewer Control Valve	SSO 89					HAMPSHIRE LANE AT MAYFIELD (36") 34
Sewer Structure	SA16ADZB0					1536
Sewer Control Valve	SSO 91					HAMPSHIRE AT EUCLID HTS. BLVD. 20
Sewer Structure	SA16ADPH0					4446
Sewer Control Valve	SSO 120					CEDAR BTW. FAIRMOUNT/DEMINGTON 8
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230120-0001

Work Order Detail Report

1/24/2023

SSO INSPECTION 1-19-2023 1.02 INCHES OF RAIN

4:48 PM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

1/24/2023

SSO INSPECTION 1-19-2023 1.02 INCHES OF RAIN

4:48 PM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	1/24/2023/ 8:17 am	1/24/2023
Reset					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	1/20/2023/ 1:59 pm	1/20/2023
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	1/20/2023/ 1:48 pm	1/20/2023
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	1/20/2023/ 1:52 pm	1/20/2023
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	1/24/2023/ 8:22 am	1/24/2023
Can't reset still surcharging					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	1/24/2023/ 9:16 am	1/24/2023
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	1/24/2023/ 9:17 am	1/24/2023
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	1/24/2023/ 9:11 am	1/24/2023
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	1/24/2023/ 9:11 am	1/24/2023
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	1/24/2023/ 9:11 am	1/24/2023
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	1/20/2023/ 1:10 pm	1/20/2023
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	1/20/2023/ 1:18 pm	1/20/2023
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	1/20/2023/ 1:23 pm	1/20/2023
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	1/24/2023/ 9:24 am	1/24/2023
Can't reset need help block stuck					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	/ 1:36 pm	1/20/2023
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	1/20/2023/ 1:44 pm	1/20/2023
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	1/24/2023/ 8:13 am	1/24/2023
Reset					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	1/24/2023/ 8:03 am	1/24/2023
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	1/20/2023/ 1:27 pm	1/20/2023
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	1/20/2023/ 1:01 pm	1/20/2023
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	1/20/2023/ 1:06 pm	1/20/2023
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	1/24/2023/ 8:57 am	1/24/2023
Meter in hole					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	1/20/2023/10:13 am	1/20/2023
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	1/20/2023/10:23 am	1/20/2023

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230120-0001

Work Order Detail Report

1/24/2023

SSO INSPECTION 1-19-2023 1.02 INCHES OF RAIN

4:48 PM

25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	1/20/2023/10:25 am	1/20/2023
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	1/20/2023/10:29 am	1/20/2023
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Not Sound	1/24/2023/ 9:47 am	1/24/2023
Reset					
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPEF0	<input type="checkbox"/>	Sound	1/24/2023/ 9:43 am	1/24/2023
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	1/24/2023/ 9:33 am	1/24/2023
30	B-15 COVENTRY AND CEDAR SA16ADBHQ0	<input type="checkbox"/>	Sound	1/24/2023/ 9:52 am	1/24/2023
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	1/20/2023/12:31 pm	1/20/2023
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	1/24/2023/10:18 am	1/24/2023
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Not Sound	1/20/2023/12:58 pm	1/20/2023
Still surcharging reset					
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	1/24/2023/10:26 am	1/24/2023
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	1/24/2023/ 8:47 am	1/24/2023
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	1/24/2023/ 8:44 am	1/24/2023
Reset					
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	1/20/2023/12:41 pm	1/20/2023
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	1/20/2023/12:44 pm	1/20/2023
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Not Sound	1/20/2023/12:48 pm	
Reset					
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	1/20/2023/10:05 am	1/20/2023
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	1/20/2023/10:03 am	1/20/2023
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	1/20/2023/ 9:57 am	1/20/2023
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	1/20/2023/ 9:29 am	1/20/2023
44	C-51 AATHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	1/20/2023/ 9:35 am	1/20/2023
Still surcharging can't reset					
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	1/20/2023/ 9:43 am	1/20/2023

Work Order Detail Report

1/24/2023

SSO INSPECTION 1-19-2023 1.02 INCHES OF RAIN

4:48 PM

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC:	\$18.69	*Task Cost:	\$841.04
Supervisor:	UOM:	Each	# of Units:	45.00	*Unit Cost:	\$0.00
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	8.00	\$197.52		1/20/2023	1/23/2023
32032 Hooten, Daniel	Hours	4.00	\$103.52		1/20/2023	1/23/2023
28056 Palmisano, Anthony	Hours	4.00	\$92.40		1/20/2023	1/23/2023
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		1/20/2023	1/23/2023
5						
CHFLT55 INTERNATIONAL GAP VAC	Hours	4.00	\$340.40		1/20/2023	1/23/2023
2						
Task Comment: SSO INSPECTIONS 1.02" OF RAIN						

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	29.00	0.00
Repair Type:			Labor Hours	16.00	0.00
Subcontractor:			Labor Costs	\$393.44	\$0.00
Profit Center:			Material Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00
Unit of Measure:	Each		Equipment Costs	447.60	0.00
*Unit Cost:	\$0.00		Contractor Costs	0.00	0.00
WO Hours:	0.00		Misc. Costs	0.00	0.00
			Total Costs	\$841.04	\$0.00
			Use Task Info:	True	True

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:	Imported to Financials: <input type="checkbox"/>
		Payment Method:	

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>
Tracking			
Item	Description	By	Date
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aferrone	1/20/2023
Supervisor Notification	Email Queued Successfully!	aferrone	1/20/2023
Status Change	From New Work Order to Complete	aferrone	1/24/2023
			Time
			9:01 AM
			9:01 AM
			4:45 PM

Work Order Detail Report

1/24/2023


SSO INSPECTION 1-19-2023 1.02 INCHES OF RAIN

4:48 PM

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date:	
Dye Test Results:		
WO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Sled	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Repair:		
Construction Crew:		
WO User 39:	OUPS #:	
WO User 40:	WO User 48:	
WO User 41:		
WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	Quantity:	Paid: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>
WO Creator: aferrone	WO Creation Date: 1/20/2023	PM Trigger: Rec #: 13367

 **Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Wednesday, January 25, 2023
Accumulation in inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Wednesday, January 25, 2023

<u>Site Location</u>	<u>Peak Accumulation (inches)</u>				
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>
Beachwood	n/a	n/a	n/a	n/a	n/a
Brecksville	0.41	0.37	0.29	0.14	0.05
Brook Park	0.30	0.27	0.22	0.09	0.05
Cleveland Industrial Pkwy	0.34	0.31	0.25	0.11	0.06
Dille Ave PS	0.32	0.31	0.26	0.12	0.06
Division Ave PS	0.37	0.35	0.29	0.13	0.07
Easterly WWTP	0.33	0.31	0.27	0.13	0.06
Independence	0.41	0.37	0.32	0.15	0.06
James Rhodes HS	0.32	0.30	0.26	0.11	0.05
Jennings PS	0.41	0.38	0.31	0.14	0.07
Macedonia	0.35	0.30	0.20	0.11	0.05
Maple Heights	0.35	0.34	0.28	0.14	0.06
Mary Street PS	0.31	0.29	0.25	0.11	0.06
Mayfield Heights	0.35	0.33	0.27	0.12	0.05
Moreland Hills	0.38	0.35	0.24	0.11	0.05
North Olmsted	0.38	0.35	0.25	0.11	0.07
North Royalton	0.32	0.30	0.25	0.11	0.06
Oakwood	n/a	n/a	n/a	n/a	n/a
Olmsted Falls	0.38	0.34	0.28	0.12	0.07
Parma	0.35	0.34	0.28	0.13	0.06
Richfield	n/a	n/a	n/a	n/a	n/a
Shaker Heights	0.31	0.28	0.26	0.12	0.06
South Euclid	0.37	0.35	0.30	0.14	0.07
Southerly WWTC	0.36	0.34	0.29	0.12	0.06
Strongsville C WWTP	0.33	0.30	0.24	0.10	0.06
Strongsville Foltz	n/a	n/a	n/a	n/a	n/a
University Heights	0.32	0.31	0.28	0.12	0.06
Wade Park	0.34	0.33	0.28	0.14	0.06
Westerly WWTP	0.32	0.30	0.25	0.10	0.06
Westlake	0.46	0.41	0.31	0.15	0.08

Work Order Detail Report

2/3/2023

SSO INSPECTION 1-25-2023 0.32 INCHES OF RAIN

10:48 AM

WO Number:	230131-0001	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	2/3/2023 10:47 am	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather		
Assigned Crew:			
Supervisor:	Jackson, Jeff	Assigned By:	
Lead Worker:	Cardarella, Joe	Assigned Date:	
Priority:	High	Start Date:	1/25/2023 7:41 AM
Account #:		End Date:	1/25/2023 2:40 PM
Proj No - Acct:		Project ID:	Override Notifications
Project:		Project Name:	Problem <input type="checkbox"/>
Reason:			Overdue <input type="checkbox"/>
Received By:			Lead Worker <input type="checkbox"/>
Inspected By:			Task <input type="checkbox"/>
			Supervisor <input type="checkbox"/>
			Hard Lock WO <input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230131-0001

Work Order Detail Report

2/3/2023

SSO INSPECTION 1-25-2023 0.32 INCHES OF RAIN

10:48 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

2/3/2023

SSO INSPECTION 1-25-2023 0.32 INCHES OF RAIN

10:48 AM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

2/3/2023

SSO INSPECTION 1-25-2023 0.32 INCHES OF RAIN

10:48 AM

Work Order Assets							
Object Type	System ID 1	System ID 2	Description 1		Description 2		Completed
			Odometer	Hourmeter	Othermeter	PM Description	Asset ID
Sewer Control Valve	SSO 431					FAIRFAX AT NORTH PARK	26
Sewer Control Valve	SSO 114					NORTH PARK AND COVENTRY	16
Sewer Control Valve	SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH	35
Sewer Structure	SA16AAWB0						3094
Sewer Control Valve	SSO 112					FAIRMOUNT AT FAIRFAX	7
Sewer Control Valve	SSO 99					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6
Sewer Control Valve	SSO 432					3012 NORTH WOODLAND	14
Sewer Control Valve	DB-03						55
Sewer Control Valve	DB-01						56
Sewer Control Valve	DB-02						57
Sewer Control Valve	CH-04					FAIRMOUNT AT DARTMOOR	5
Sewer Control Valve	SSO 110					FAIRMOUNT AT WELLINGTON	44
Sewer Control Valve	SSO 87					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33
Sewer Control Valve	SSO 116					FAIRMOUNT AT MARLBORO	4
Sewer Control Valve	SSO 111					FAIRMOUNT AT ARLINGTON	46
Sewer Control Valve	SSO 113					FAIRMOUNT & COVENTRY (SCARBOROUGH)	37
Sewer Control Valve	SSO 124					FAIRMOUNT AND COVENTRY	47
Sewer Control Valve	CH-50					SCARBOROUGH AT LAMBERTON	53
Sewer Control Valve	SSO 129					BRADFORD AND LEE	11
Sewer Control Valve	CH-52					EDDINGTON	2
Sewer Control Valve	SSO 88					HAMPSHIRE LANE AT MAYFIELD (18")	42
Sewer Control Valve	SSO 122					EAST OVERLOOK AT EDGEHILL	36
Sewer Control Valve	SSO 89					HAMPSHIRE LANE AT MAYFIELD (36")	34
Sewer Structure	SA16ADZB0						1536
Sewer Control Valve	SSO 91					HAMPSHIRE AT EUCLID HTS. BLVD.	20
Sewer Structure	SA16ADPH0						4446
Sewer Control Valve	SSO 120					CEDAR BTW. FAIRMOUNT/DEMINGTON	8
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230131-0001

Work Order Detail Report

2/3/2023

SSO INSPECTION 1-25-2023 0.32 INCHES OF RAIN

10:48 AM

SSO 103	19
Sewer Control Valve	
SSO 104	3003 EUCLID HEIGHTS BLVD
Sewer Structure	15
SA16AGMG0	
Sewer Control Valve	3402
CH-30	South Taylor between Antisdale Ave and Superior F
Sewer Control Valve	52
DV-11	LEE RD. & SUPERIOR AVE.
Sewer Control Valve	9
SSO 108	EUCLID HEIGHTS BLVD AND LEE
Sewer Control Valve	22
SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND
Sewer Control Valve	43
SSO 95	1685 CUMBERLAND
Sewer Control Valve	18
SSO 105	CUMBERLAND/SOMERTON
Sewer Structure	30
SA16AQQD0	4987
Sewer Structure	3745
SA16AQQC0	
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	1809
SA16APEF0	

Work Order Detail Report

2/3/2023

SSO INSPECTION 1-25-2023 0.32 INCHES OF RAIN

10:48 AM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	1/31/2023/10:25 am	
Reset					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	1/31/2023/12:55 pm	1/31/2023
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	1/31/2023/12:39 pm	1/31/2023
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	1/31/2023/12:49 pm	1/31/2023
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	1/31/2023/10:21 am	1/31/2023
Reset					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	1/31/2023/12:59 pm	1/31/2023
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	1/31/2023/12:01 pm	1/31/2023
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	1/31/2023/ 1:13 pm	1/31/2023
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	1/31/2023/ 1:14 pm	1/31/2023
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	1/31/2023/ 1:15 pm	1/31/2023
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	1/31/2023/10:04 am	1/31/2023
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	1/31/2023/ 1:21 pm	1/31/2023
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	1/31/2023/ 1:23 pm	1/31/2023
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	2/1/2023/ 8:21 am	2/1/2023
Reset					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	2/1/2023/ 8:32 am	2/1/2023
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	1/31/2023/ 2:01 pm	1/31/2023
17	A-35 2393 COVENTRY SA16AAASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	1/31/2023/12:40 pm	1/31/2023
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	1/31/2023/12:33 pm	1/31/2023
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	1/31/2023/ 1:49 pm	1/31/2023
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	1/31/2023/10:02 am	1/31/2023
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	1/31/2023/10:03 am	1/31/2023
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	1/31/2023/ 9:54 am	1/31/2023
Meter in manhole					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	1/31/2023/ 9:25 am	1/31/2023
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	1/31/2023/ 9:26 am	1/31/2023
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	1/31/2023/ 9:26 am	1/31/2023

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230131-0001

Work Order Detail Report

2/3/2023

SSO INSPECTION 1-25-2023 0.32 INCHES OF RAIN

10:48 AM

26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	1/31/2023/ 9:29 am	1/31/2023
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Not Sound	1/31/2023/ 9:27 am	1/31/2023
Reset					
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	1/31/2023/ 9:25 pm	1/31/2023
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	1/31/2023/ 1:52 pm	1/31/2023
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	1/31/2023/ 1:58 pm	1/31/2023
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	1/31/2023/ 9:28 am	1/31/2023
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	1/31/2023/10:11 am	1/31/2023
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	1/31/2023/ 9:45 am	1/31/2023
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	1/31/2023/ 2:27 pm	1/31/2023
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	1/31/2023/ 9:41 am	1/31/2023
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	1/31/2023/ 9:41 am	1/31/2023
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	1/31/2023/ 9:25 am	1/31/2023
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	1/31/2023/ 9:30 am	1/31/2023
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Not Sound	1/31/2023/ 9:35 am	1/31/2023
Reset					
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>		1/31/2023/ 9:23 am	1/31/2023
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	1/31/2023/ 9:23 am	1/31/2023
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	1/31/2023/ 9:24 am	1/31/2023
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	1/31/2023/ 9:24 am	1/31/2023
44	C-51 AATHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	1/31/2023/ 9:24 am	1/31/2023
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	1/31/2023/ 9:24 am	1/31/2023

Tasks/Resources

SMCT36 Inspection

Crew:	Status:	*Cal'c UC: \$15.67	*Task Cost: \$705.00	Start Dt: 1/25/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 1/25/2023

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	12.00	\$296.28		1/25/2023	1/25/2023
39986 O'Brien, Dominick	Hours	12.00	\$247.92		1/25/2023	1/25/2023

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	12.00	\$160.80		1/25/2023	1/25/2023

5

Task Comment: SSO INSPECTIONS 0.32 INCHES

Work Order Detail Report

2/3/2023

SSO INSPECTION 1-25-2023 0.32 INCHES OF RAIN

10:48 AM

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	6.98	0.00
Repair Type:			Labor Hours	24.00	0.00
Subcontractor:			Labor Costs	\$544.20	\$0.00
Profit Center:			Material Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00
Unit of Measure:	Each		Equipment Costs	160.80	0.00
*Unit Cost:	\$0.00		Contractor Costs	0.00	0.00
WO Hours:	0.00		Misc. Costs	0.00	0.00
			Total Costs	\$705.00	\$0.00
			Use Task Info:	True	True

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Cell #:	
State:		Fax #:	
Zip:		E-mail:	
Billing Data			
Contact Name:		*Billing Amount:	<input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/>
		Payment Method:	<input type="checkbox"/>
Imported to Financials: <input type="checkbox"/>			

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

Tracking					
Item	Description	By	Date	Time	
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jackson	1/31/2023	7:34 AM	
Supervisor Notification	Email Queued Successfully!	jackson	1/31/2023	7:34 AM	
Status Change	From New Work Order to Complete	aferrone	2/3/2023	10:47 AM	

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 1/31/2023	8:00 AM
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	Measurement Line 2:	
History:		

Work Order Detail Report

2/3/2023

SSO INSPECTION 1-25-2023 0.32 INCHES OF RAIN

10:48 AM

Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sleeve		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 1/31/2023	PM Trigger:	Rec #: 13398