



Law Department

April 13, 2023

***Via E-Mail: [vezner.kris@epa.gov](mailto:vezner.kris@epa.gov) and [Berger.Jake@epa.gov](mailto:Berger.Jake@epa.gov)***

Kris P. Vezner, Esq.  
Associate Regional Counsel  
U.S. Environmental Protection Agency  
Region 5 (C-14J)  
77 West Jackson Blvd.  
Chicago, IL 60604

and

Jake Berger  
Physical Scientist  
Water Enforcement & Compliance Assurance Branch  
U.S. Environmental Protection Agency  
77 W. Jackson Blvd.  
Mail Code ECW-15J  
Chicago, IL 60604

Re: March 2023 Overflow Monitoring Reports  
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through March 31, 2023, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,

A handwritten signature in blue ink that reads "William R. Hanna".  
William R. Hanna  
Director of Law

Enclosures


cc: Thomas Benson, Esq., EPA Attorney  
James Vinch, Esq., EPA Attorney  
James Zimny, EPA Engineer  
U.S. EPA Region 5 Water Enforcement Branch  
Mark Klingenstein, Environmental Engineer  
Erm Gomes, Ohio EPA  
Allison Cycyk, Ohio EPA  
Casey Galligan, Ohio EPA  
David Brumbaugh, Ohio EPA  
Bill Fischbein, Ohio EPA  
Kahlil Seren, Mayor  
Collette Clinkscale, Director of Public Works  
Steve Barker, Public Relations  
Anthony Ferrone, Utilities Commissioner  
Kevin Vander Tuig, P.E. (Outside Engineer)  
Mathew St. Pierre, (Outside Engineer)  
Dan Porter (Outside Engineer)  
Cindy Biacofsky (Outside Engineer)  
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

  
**Northeast Ohio  
Regional Sewer District**

**Daily Precipitation Report**

**Friday, March 3, 2023**

Accumulation in inches



## Northeast Ohio Regional Sewer District

### Daily Precipitation Report

Friday, March 3, 2023

<b>Site Location</b>	<b>Peak Accumulation (inches)</b>				
	<b>24-Hour</b>	<b>6-Hour</b>	<b>3-Hour</b>	<b>1-Hour</b>	<b>15-Minute</b>
<b>Beachwood</b>	<b>1.08</b>	<b>0.81</b>	<b>0.55</b>	<b>0.24</b>	<b>0.10</b>
Brecksville	1.07	0.87	0.55	0.26	0.08
<b>Brook Park</b>	<b>1.11</b>	<b>0.96</b>	<b>0.72</b>	<b>0.33</b>	<b>0.17</b>
Cleveland Industrial Pkwy	1.26	1.05	0.76	0.34	0.18
Dille Ave PS	1.03	0.87	0.62	0.29	0.14
Division Ave PS	1.17	0.98	0.73	0.35	0.18
<b>Easterly WWTP</b>	<b>1.15</b>	<b>0.98</b>	<b>0.74</b>	<b>0.37</b>	<b>0.20</b>
Independence	1.02	0.82	0.57	0.24	0.10
<b>James Rhodes HS</b>	<b>1.23</b>	<b>1.04</b>	<b>0.72</b>	<b>0.33</b>	<b>0.16</b>
Jennings PS	1.13	0.93	0.67	0.30	0.14
Macedonia	1.06	0.78	0.50	0.22	0.09
Maple Heights	1.16	0.88	0.59	0.23	0.09
<b>Mary Street PS</b>	<b>1.06</b>	<b>0.87</b>	<b>0.63</b>	<b>0.29</b>	<b>0.15</b>
Mayfield Heights	1.14	0.89	0.59	0.24	0.09
Moreland Hills	1.16	0.91	0.63	0.24	0.11
North Olmsted	1.30	1.08	0.78	0.37	0.16
North Royalton	1.07	0.87	0.57	0.24	0.08
Oakwood	1.17	0.90	0.58	0.23	0.10
Olmsted Falls	1.17	1.01	0.74	0.32	0.11
Parma	1.32	1.11	0.76	0.29	0.12
Richfield	1.17	0.95	0.58	0.27	0.13
Shaker Heights	1.15	0.90	0.64	0.29	0.12
<b>South Euclid</b>	<b>1.22</b>	<b>0.99</b>	<b>0.66</b>	<b>0.30</b>	<b>0.12</b>
Southerly WWTC	0.97	0.80	0.56	0.24	0.10
Strongsville C WWTP	1.06	0.91	0.66	0.28	0.15
Strongsville Foltz	1.19	0.99	0.66	0.27	0.12
University Heights	1.17	0.95	0.62	0.28	0.12
Wade Park	1.11	0.93	0.69	0.31	0.15
<b>Westerly WWTP</b>	<b>1.09</b>	<b>0.91</b>	<b>0.69</b>	<b>0.33</b>	<b>0.16</b>
Westlake	1.23	1.02	0.71	0.29	0.11

## Work Order Detail Report

3/9/2023

SSO INSPECTION 3-3-2023 1.17 INCHES OF RAIN

4:09 PM

WO Number:	230309-0001	Category:	SSOs			
Status:	Complete	Problem:	Storm Response			
Status Date:	3/9/2023 4:08 pm	Main Task:	Inspection			
Asset:	SSO 431					
Location:	FAIRFAX AT NORTH PARK					
Cause:	Weather					
Assigned Crew:						
Supervisor:	Jackson, Jeff	Assigned By:				
Lead Worker:	Manco, Angelo	Assigned Date:				
Priority:	High	Start Date:	3/6/2023 7:05 AM			
Account #:						
Proj No - Acct:						
Project:						
Reason:						
Received By:						
Inspected By:						
<b>Request Comments for Work Order</b>						
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.						
Location						
Department:	Sewer Collection					
Division:	Sewer					
Sub-Division:						
Area:						
Sub-Area:						
Owner:						
Location:						
Classification:						
Maintenance Zone:	Alternate Zone:					
<b>Work Order Locations</b>						
<u>Address</u>	<u>Address 2</u>					
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>				
FAIRFAX AT NORTH PARK						
2,220,655.65435414	665,517.24643672	Doan Brook				
NORTH PARK AND COVENTRY						
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH				
FAIRMOUNT SOUTH OF SCARBOROUGH						
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH				
FAIRMOUNT AT FAIRFAX						
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH				
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)						
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH				
3012 NORTH WOODLAND						
2,222,845.06631389	664,689.08536339	Doan Brook				
2,226,440.21168265						
2,226,354.79813956	664,409.89202413					
2,226,389.92077273						
2,225,149.97508989	664,379.07548472	DOAN BROOK - MAIN BRANCH				
FAIRMOUNT AT DARTMOOR						
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH				



**Work Order Detail Report**

3/9/2023

SSO INSPECTION 3-3-2023 1.17 INCHES OF RAIN

4:09 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	



---

**Work Order Detail Report**

3/9/2023

SSO INSPECTION 3-3-2023 1.17 INCHES OF RAIN

4:09 PM

---

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------



## Work Order Detail Report

3/9/2023

SSO INSPECTION 3-3-2023 1.17 INCHES OF RAIN

4:09 PM

### Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>Asset ID</u>	<u>Completed</u>
			<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>
Sewer Control Valve					FAIRFAX AT NORTH PARK	
SSO 431					26	
Sewer Control Valve					NORTH PARK AND COVENTRY	
SSO 114					16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH	
SSO 121					35	
Sewer Structure					3094	
SA16AAWB0					FAIRMOUNT AT FAIRFAX	
Sewer Control Valve					7	
SSO 112					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
Sewer Control Valve					6	
SSO 99					3012 NORTH WOODLAND	
Sewer Control Valve					14	
SSO 432					55	
Sewer Control Valve					56	
DB-03					57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR	
DB-01					5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON	
DB-02					44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
CH-04					33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO	
SSO 110					4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON	
SSO 87					46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)	
SSO 116					37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY	
SSO 111					47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON	
SSO 113					53	
Sewer Control Valve					BRADFORD AND LEE	
SSO 124					11	
Sewer Control Valve					EDDINGTON	
CH-50					2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")	
SSO 88					42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL	
SSO 122					36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")	
SSO 89					34	
Sewer Structure					1536	
SA16ADZB0					HAMPSHIRE AT EUCLID HTS. BLVD.	
Sewer Control Valve					20	
SSO 91					4446	
Sewer Structure					CEDAR BTW. FAIRMOUNT/DEMINGTON	
SA16ADPH0					8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY	
SSO 120						
Sewer Control Valve						
SSO 94						

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230309-0001



## Work Order Detail Report

3/9/2023

SSO INSPECTION 3-3-2023 1.17 INCHES OF RAIN

4:09 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQCO	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809



**Work Order Detail Report**

3/9/2023

SSO INSPECTION 3-3-2023 1.17 INCHES OF RAIN

4:09 PM

Check List		<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0 over flowed and reset block	<input type="checkbox"/>	Not Sound	3/8/2023/ 8:05 am	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Not Sound	3/8/2023/ 8:15 am	
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0 block reset	<input type="checkbox"/>	Not Sound	3/8/2023/ 8:17 am	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	3/8/2023/ 8:18 am	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	3/8/2023/ 8:19 am	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Not Sound	3/8/2023/ 8:21 am	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	3/8/2023/ 8:23 am	
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	3/8/2023/ 8:26 am	
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	3/8/2023/ 8:29 am	
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	3/8/2023/ 8:32 am	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	3/8/2023/ 8:33 am	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	3/8/2023/ 8:35 am	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	3/8/2023/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	3/8/2023/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	3/8/2023/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	3/8/2023/	
17	A-35 2393 COVENTRY SA16AAASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	3/8/2023/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	3/8/2023/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	3/8/2023/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	3/8/2023/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	3/8/2023/	
22	A-9 BRADFORD AT LEE SA16AFL00 (INTERSECTION)	<input type="checkbox"/>	Sound	3/8/2023/	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	3/8/2023/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	3/8/2023/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	3/8/2023/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Not Sound	3/8/2023/	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230309-0001



## Work Order Detail Report

3/9/2023

SSO INSPECTION 3-3-2023 1.17 INCHES OF RAIN

4:09 PM

27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	3/8/2023/
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	3/8/2023/
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Not Sound	3/8/2023/
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	3/8/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	3/8/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Not Sound	3/8/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	3/8/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	3/8/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	3/8/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	3/8/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	3/8/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Not Sound	3/8/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	3/8/2023/
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	3/8/2023/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	3/8/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	3/8/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	3/8/2023/
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	3/8/2023/
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Not Sound	3/8/2023/

### Tasks/Resources

#### SWCT26 Inspection

Crew:	Status:	*Cal'c UC: \$22.08	*Task Cost: \$993.72	Start Dt: 3/6/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 3/7/2023

#### Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
13859 Moten, Robert	Hours	12.00	\$296.28		3/6/2023	3/7/2023
12459 Eathridge, David	Hours	12.00	\$310.56		3/6/2023	3/7/2023
29960 Jackson, Jeff	Hours	12.00	\$0.00		3/6/2023	3/7/2023
40404 Don Johnson		12.00	\$226.08		3/6/2023	3/7/2023

#### Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	12.00	\$160.80		3/6/2023	3/7/2023
CHFT-500 FORD F250 PICK UP TRUCK	Each	12.00	\$0.00		3/6/2023	3/7/2023

Task Comment: SSO INSPECTIONS1.17 INCHES OF RAIN



## Work Order Detail Report

3/9/2023

SSO INSPECTION 3-3-2023 1.17 INCHES OF RAIN

4:09 PM

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	12.00	0.00
Repair Type:			Labor Hours	48.00	0.00
Subcontractor:			Labor Costs	\$832.92	\$0.00
Profit Center:			Material Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00
Unit of Measure:	Each		Equipment Costs	160.80	0.00
*Unit Cost:	\$0.00		Contractor Costs	0.00	0.00
WO Hours:	0.00		Misc. Costs	0.00	0.00
			Total Costs	\$993.72	\$0.00
			Use Task Info:	True	True

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Cell #:	
State:		Fax #:	
Zip:		E-mail:	
Billing Data			
Contact Name:		*Billing Amount:	<input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/>
		Payment Method:	<input type="checkbox"/>
Imported to Financials: <input type="checkbox"/>			

Associated PMs		PM Code and Description		Closed	
		SSO-02	SSO INSPECTION	<input checked="" type="checkbox"/>	

Tracking		Closed			
Item	Description	By	Date	Time	
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	3/9/2023	3:15 PM	
Supervisor Notification	Email Queued Successfully!	jjackson	3/9/2023	3:15 PM	
Leadworker Notification	Email Queued Successfully!	jjackson	3/9/2023	3:15 PM	
Status Change	From New Work Order to Complete	aferrone	3/9/2023	4:08 PM	

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned,	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 3/8/2023	8:00 AM
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	Measurement Line 2:	
History:		



## Work Order Detail Report

SSO INSPECTION 3-3-2023 1.17 INCHES OF RAIN

3/9/2023


4:09 PM

Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Slic
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:
Curb Repair:	
Driveway- Sidewalk Re	
Construction Crew:	
WO User 39:	OUPS #:
WO User 40:	WO User 48:
WO User 41:	
WO User 52:	WO User 62:
WO User 53:	WO User 63:
WO User 54:	WO User 64:
WO User 55:	WO User 65:
WO User 56:	WO User 66:
WO User 57:	WO User 67:
WO User 58:	WO User 68:
WO User 59:	WO User 69:
WO User 60:	WO User 70:
WO User 61:	WO User 71:
WO User 72:	WO User 82:
WO User 73:	Quantity:
WO User 74:	WO User 84:
WO User 75:	WO User 85:
WO User 76:	WO User 86:
WO User 92 Date:	WO User 97 Date:
WO User 93 Date:	WO User 98 Date:
WO User 94 Date:	WO User 99 Date:
WO User 95 Date:	WO User 100 Date:
WO User 96 Date:	WO User 101 Date:
WO User 77:	WO User 87:
WO User 78:	WO User 88:
WO User 79:	WO User 89:
WO User 80:	WO User 90:
WO User 81:	WO User 91:
WO Creator: jjackson	WO Creation Date: 3/9/2023
	PM Trigger: Rec #: 13503



 **Northeast Ohio  
Regional Sewer District**

**Daily Precipitation Report**  
Thursday, March 23, 2023  
Accumulation in Inches



## Northeast Ohio Regional Sewer District

Daily Precipitation Report  
Thursday, March 23, 2023

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.74	0.36	0.25	0.15	0.08
Brecksville	0.94	0.57	0.32	0.20	0.09
Brook Park	0.63	0.42	0.28	0.17	0.06
Cleveland Industrial Pkwy	0.66	0.36	0.23	0.14	0.09
Dille Ave PS	0.56	0.29	0.23	0.12	0.06
Division Ave PS	0.54	0.26	0.22	0.14	0.08
Easterly WWTP	0.61	0.35	0.31	0.19	0.13
Independence	0.74	0.38	0.21	0.17	0.11
James Rhodes HS	0.66	0.32	0.25	0.19	0.14
Jennings PS	0.63	0.35	0.25	0.14	0.08
Macdonnia	1.04	0.60	0.36	0.23	0.11
Maple Heights	0.80	0.48	0.29	0.16	0.09
Mary Street PS	0.57	0.30	0.24	0.13	0.06
Mayfield Heights	0.65	0.32	0.26	0.15	0.09
Moreland Hills	0.98	0.55	0.34	0.19	0.12
North Olmsted	0.64	0.40	0.26	0.12	0.06
North Royalton	0.94	0.61	0.38	0.26	0.13
Oakwood	0.97	0.52	0.31	0.23	0.14
Olmsted Falls	0.96	0.50	0.31	0.21	0.13
Parma	0.78	0.46	0.30	0.19	0.08
Richfield	1.02	0.58	0.36	0.30	0.11
Shaker Heights	0.74	0.37	0.24	0.16	0.09
South Euclid	0.60	0.31	0.27	0.16	0.10
Southerly WWTC	0.68	0.34	0.24	0.19	0.13
Strongsville C WWTP	0.82	0.40	0.25	0.16	0.10
Strongsville Foltz	1.07	0.70	0.46	0.31	0.16
University Heights	0.76	0.36	0.29	0.19	0.10
Wade Park	0.62	0.32	0.28	0.20	0.11
Westerly WWTP	0.51	0.26	0.21	0.14	0.08
Westlake	0.63	0.37	0.31	0.12	0.07

## Work Order Detail Report

3/28/2023

SSO INSPECTIONS 3-23-2023 0.76 INCHES OF RAIN

11:10 AM

WO Number:	230327-0003	Category:	SSOs			
Status:	Complete	Problem:	Storm Response			
Status Date:	3/28/2023 11:08 am	Main Task:	Inspection			
Asset:	SSO 431					
Location:	FAIRFAX AT NORTH PARK					
Cause:	Weather					
Assigned Crew:						
Supervisor:	Jackson, Jeff	Assigned By:				
Lead Worker:	Manco, Angelo	Assigned Date:				
Priority:	High	Start Date:	3/27/2023 7:06 AM			
Account #:						
Proj No - Acct:						
Project:						
Reason:						
Received By:						
Inspected By:						
<b>Request Comments for Work Order</b>						
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.						
Location						
Department:	Sewer Collection	Comments for Crew				
Division:	Sewer	Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.				
Sub-Division:						
Area:						
Sub-Area:						
Owner:						
Location:						
Classification:						
Maintenance Zone:	Alternate Zone:					
<b>Work Order Locations</b>						
<u>Address</u>	<u>Address 2</u>					
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>				
FAIRFAX AT NORTH PARK						
2,220,655.65435414	665,517.24643672	Doan Brook				
NORTH PARK AND COVENTRY						
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH				
FAIRMOUNT SOUTH OF SCARBOROUGH						
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH				
FAIRMOUNT AT FAIRFAX						
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH				
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)						
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH				
3012 NORTH WOODLAND						
2,222,845.06631389	664,689.08536339	Doan Brook				
2,226,440.21168265						
2,226,354.79813956	664,409.89202413					
2,226,389.92077273						
FAIRMOUNT AT DARTMOOR	664,379.07548472					
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH				
FAIRMOUNT AT WELLINGTON						
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH				

**Work Order Detail Report**

3/28/2023

SSO INSPECTIONS 3-23-2023 0.76 INCHES OF RAIN

11:10 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

---

**Work Order Detail Report**

3/28/2023

SSO INSPECTIONS 3-23-2023 0.76 INCHES OF RAIN

11:10 AM

---

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

## Work Order Detail Report

3/28/2023

SSO INSPECTIONS 3-23-2023 0.76 INCHES OF RAIN

11:10 AM

### Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>Description 2</u>	<u>PM Description</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve							FAIRFAX AT NORTH PARK			
SSO 431									26	
Sewer Control Valve							NORTH PARK AND COVENTRY			
SSO 114									16	
Sewer Control Valve							FAIRMOUNT SOUTH OF SCARBOROUGH			
SSO 121									35	
Sewer Structure										
SA16AAWB0									3094	
Sewer Control Valve							FAIRMOUNT AT FAIRFAX			
SSO 112									7	
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
SSO 99									6	
Sewer Control Valve							3012 NORTH WOODLAND			
SSO 432									14	
Sewer Control Valve										
DB-03									55	
Sewer Control Valve										
DB-01										
Sewer Control Valve									56	
DB-02										
Sewer Control Valve							FAIRMOUNT AT DARTMOOR			
CH-04									5	
Sewer Control Valve							FAIRMOUNT AT WELLINGTON			
SSO 110									44	
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
SSO 87									33	
Sewer Control Valve							FAIRMOUNT AT MARLBORO			
SSO 116									4	
Sewer Control Valve							FAIRMOUNT AT ARLINGTON			
SSO 111									46	
Sewer Control Valve							FAIRMOUNT & COVENTRY (SCARBOROUGH)			
SSO 113									37	
Sewer Control Valve							FAIRMOUNT AND COVENTRY			
SSO 124									47	
Sewer Control Valve							SCARBOROUGH AT LAMBERTON			
CH-50									53	
Sewer Control Valve							BRADFORD AND LEE			
SSO 129									11	
Sewer Control Valve							EDDINGTON			
CH-52									2	
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (18")			
SSO 88									42	
Sewer Control Valve							EAST OVERLOOK AT EDGEHILL			
SSO 122									36	
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (36")			
SSO 89									34	
Sewer Structure										
SA16ADZB0										
Sewer Control Valve							1536			
SSO 91							HAMPSHIRE AT EUCLID HTS. BLVD.			
Sewer Structure									20	
SA16ADPH0										
Sewer Control Valve							4446			
SSO 120							CEDAR BTW. FAIRMOUNT/DEMINGTON			
Sewer Control Valve									8	
							2828 BERKSHIRE, EAST OF COVENTRY			

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230327-0003

## Work Order Detail Report

3/28/2023

SSO INSPECTIONS 3-23-2023 0.76 INCHES OF RAIN

11:10 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	3402
SA16AGMG0	
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	4987
SA16AQD0	
Sewer Structure	3745
SA16AQC0	
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

## Work Order Detail Report

3/28/2023

SSO INSPECTIONS 3-23-2023 0.76 INCHES OF RAIN

11:10 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	3/27/2023/	
	Reset block				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ / AM				
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Not Sound	3/27/2023/	
	Reset block. DJ / AM				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ / AM				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	3/27/2023/	
	Reset block. DJ / AM				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ / AM				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ / AM				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ / AM				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ / AM				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ / AM				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ //AM				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ/ AM				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ/AM				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	3/27/2023/	
	DJ / AM. Reset block				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	3/27/2023/	
	DJ/AM. Reset block				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ / AM				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ/AM				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	3/27/2023/	
	DJ/AM				

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230327-0003

## Work Order Detail Report

3/28/2023

SSO INSPECTIONS 3-23-2023 0.76 INCHES OF RAIN

11:10 AM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION) DJ/AM	<input type="checkbox"/> Sound	3/27/2023/
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE) DJ/AM	<input type="checkbox"/> Sound	3/27/2023/
21	A-58 E MONMOUTH AT EXETER (INTERSECTION) DJ/AM	<input type="checkbox"/> Sound	3/27/2023/
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION) Attached block and rope DJ/AM	<input type="checkbox"/> Sound	3/27/2023/
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0 Dominic	<input type="checkbox"/> Sound	3/27/2023/
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0 Dominic	<input type="checkbox"/> Sound	3/27/2023/
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEAO Dominic	<input type="checkbox"/> Sound	3/27/2023/
26	B-61 2600 HAMPSHIRE SA16ADZB0 Dominic	<input type="checkbox"/> Sound	3/27/2023/
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO Dominic	<input type="checkbox"/> Sound	3/27/2023/
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0 Dominic	<input type="checkbox"/> Sound	3/27/2023/
29	B-42 12537 CEDAR SA16ACZA0 AM/DJ	<input type="checkbox"/> Sound	3/27/2023/
30	B-15 COVENTRY AND CEDAR SA16ADBHO AM/DJ	<input type="checkbox"/> Sound	3/27/2023/
31	B-23 2828 BERKSHIRE SA16AETA0 DJ/AM	<input type="checkbox"/> Sound	3/27/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0 Dominic	<input type="checkbox"/> Sound	3/27/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0 Dominic	<input type="checkbox"/> Not Sound	3/27/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0 Reset block. Dominic	<input type="checkbox"/> Not Sound	3/27/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0 Reset block. Dominic	<input type="checkbox"/> Not Sound	3/27/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0 Reset block. Dominic	<input type="checkbox"/> Not Sound	3/27/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0 Reset block. Dominic	<input type="checkbox"/> Not Sound	3/27/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0 Reset block. Dominic	<input type="checkbox"/> Not Sound	3/27/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/> /	
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/> Sound	3/27/2023/

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230327-0003

## Work Order Detail Report

3/28/2023

SSO INSPECTIONS 3-23-2023 0.76 INCHES OF RAIN

11:10 AM

Dominic			
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound 3/27/2023/
Dominic			
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound 3/27/2023/
Dominic			
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound 3/27/2023/
Dominic			
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound 3/27/2023/
Dominic			
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound 3/27/2023/
AM /DJ			

### Tasks/Resources

#### SMCT36 Inspection

Crew:	Status:	*Cal'c UC: \$17.38	*Task Cost: \$782.24	Start Dt: 3/27/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 3/27/2023

### Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
19356 Manco, Angelo	Hours	8.00	\$217.84		3/27/2023	3/27/2023
40404 Don Johnson		8.00	\$150.72		3/27/2023	3/27/2023
39986 O'Brien, Dominick	Hours	8.00	\$165.28		3/27/2023	3/27/2023

### Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB 9	Hours	8.00	\$141.20		3/27/2023	3/27/2023
CHFLT55 FORD F250 PICK UP 0	Hours	8.00	\$107.20		3/27/2023	3/27/2023

Task Comment: SSO INSPECTIONS 0.67 INCES OF RAIN

Projected Complete:	Lock: <input type="checkbox"/>	*Actual	*Estimated	*Difference
Repair Type:		WO Duration	8.00	0.00
Subcontractor:		Labor Hours	24.00	0.00
Profit Center:		Labor Costs	\$533.84	\$0.00
Quantity:	0.00	Material Costs	0.00	0.00
Unit of Measure:	Each	Fluids Costs	0.00	0.00
*Unit Cost:	\$0.00	Equipment Costs	248.40	0.00
WO Hours:	0.00	Contractor Costs	0.00	0.00
		Misc. Costs	0.00	0.00
		Total Costs	\$782.24	\$0.00
		Use Task Info:	True	True

<b>Billed Party</b>		<b>Billing</b>	
Customer ID:	Customer Number:		
Customer Name:	Last Name:		
Address:			
City:	Phone:	Cell #:	
State:	Fax #:		
Zip:	E-mail:		
<b>Billing Data</b>			
Contact Name:	*Billing Amount:		
Invoice Number:	Date Bill Sent:		
Incoming Account #:	Payment Received:		
	Payment Method:		
	Billing Required: <input type="checkbox"/>		
	Billing Processed: <input type="checkbox"/>		
	Imported to Financials: <input type="checkbox"/>		

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230327-0003

## Work Order Detail Report

3/28/2023

SSO INSPECTIONS 3-23-2023 0.76 INCHES OF RAIN

11:10 AM

Associated PMs		PM Code and Description	Closed		
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>		
Item	Tracking	Description	By	Date	Time
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	jjackson	3/27/2023	12:13 PM
Supervisor Notification		Email Queued Successfully!	jjackson	3/27/2023	12:13 PM
Leadworker Notification		Email Queued Successfully!	jjackson	3/27/2023	12:14 PM
Status Change		From New Work Order to Complete	aferrone	3/28/2023	11:08 AM
Rate:		Opened At:		Televised:	<input type="checkbox"/>
Received By:		Pipe Footage Cleaned.		Power Rooter:	<input type="checkbox"/>
Work From:		Gallons Used:		Jet:	<input type="checkbox"/>
Pipe Size:		WO User 23:		Gap Vac:	<input type="checkbox"/>
Pipe Condition:		WO User 24:		Dye Test:	<input type="checkbox"/>
Could Not Open:		WO User 9:		Gap Root Cut:	<input type="checkbox"/>
Additional Repair:		User 10:		GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:		Appointment Date DNL		Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:		Appointment Date:	3/27/2023	8:00 AM	
Dye Test Results:		E Mail:			
WO User 51:		Measurement Line 2:			
Measurement:		Pipe Size:			
History:		PVC Tees, Angles, Sles			
Manhole Basin Repair:		WO User 44:			
Material Used:		WO User 45:			
Pipe Repair:		WO User 46:			
Street Repair:					
Grass Repair:					
Curb Repair:					
Driveway- Sidewalk Re					
Construction Crew:					
WO User 39:		OUPS #:			
WO User 40:		WO User 48:			
WO User 41:					
WO User 52:		WO User 62:			
WO User 53:		WO User 63:			
WO User 54:		WO User 64:			
WO User 55:		WO User 65:			
WO User 56:		WO User 66:			
WO User 57:		WO User 67:			
WO User 58:		WO User 68:			
WO User 59:		WO User 69:			
WO User 60:		WO User 70:			
WO User 61:		WO User 71:			
WO User 72:		WO User 82:		Televised:	<input type="checkbox"/>
WO User 73:		Quantity:		Paid:	<input type="checkbox"/>
WO User 74:		WO User 84:		WO User 104:	<input type="checkbox"/>
WO User 75:		WO User 85:		WO User 105:	<input type="checkbox"/>
WO User 76:		WO User 86:		WO User 106:	<input type="checkbox"/>
WO User 92 Date:		WO User 97 Date:			
WO User 93 Date:		WO User 98 Date:			
WO User 94 Date:		WO User 99 Date:			
WO User 95 Date:		WO User 100 Date:			
WO User 96 Date:		WO User 101 Date:			

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230327-0003

---

**Work Order Detail Report**

3/28/2023

SSO INSPECTIONS 3-23-2023 0.76 INCHES OF RAIN

11:10 AM

WO User 77:

WO User 87:

WO User 107:

WO User 78:

WO User 88:

WO User 108:

WO User 79:

WO User 89:

WO User 109:

WO User 80:

WO User 90:

WO User 110:

WO User 81:

WO User 91:

WO User 111:

WO Creator: jjackson

WO Creation Date: 3/27/2023

PM Trigger:

Rec #: 13551