

CITY OF  
**CLEVELAND  
HEIGHTS**   
LAW DEPARTMENT

October 13, 2023

*Via E-Mail: [vezner.kris@epa.gov](mailto:vezner.kris@epa.gov) and [Berger.Jake@epa.gov](mailto:Berger.Jake@epa.gov)*

Kris P. Vezner, Esq.  
Associate Regional Counsel  
U.S. Environmental Protection Agency  
Region 5 (C-14J)  
77 West Jackson Blvd.  
Chicago, IL 60604

and

Jake Berger  
Physical Scientist  
Water Enforcement & Compliance Assurance Branch  
U.S. Environmental Protection Agency  
77 W. Jackson Blvd.  
Mail Code ECW-15J  
Chicago, IL 60604

Re: September 2023 Overflow Monitoring Report  
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Report for an inspection performed for September 6, 2023, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,

  
William R. Hanna  
Director of Law


Enclosures

Overflow Monitoring Update

October 13, 2023

cc: Thomas Benson, Esq., EPA Attorney  
James Vinch, Esq., EPA Attorney  
James Zimny, EPA Engineer  
U.S. EPA Region 5 Water Enforcement Branch  
Mark Klingenstein, Environmental Engineer  
Erm Gomes, Ohio EPA  
Allison Cycyk, Ohio EPA  
Casey Galligan, Ohio EPA  
David Brumbaugh, Ohio EPA  
Bill Fischbein, Ohio EPA  
Kahlil Seren, Mayor  
Collette Clinkscale, Director of Public Works  
Steve Barker, Public Relations  
Anthony Ferrone, Utilities Commissioner  
Kevin Vander Tuig, P.E. (Outside Engineer)  
Mathew St. Pierre, (Outside Engineer)  
Dan Porter (Outside Engineer)  
Cindy Biacofsky (Outside Engineer)  
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northeast Ohio  
Regional Sewer District**



## Northeast Ohio Regional Sewer District

### Daily Precipitation Report

Wednesday, September 6, 2023

<u>Site Location</u>	<u>Precipitation (inches)</u>					
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>	<u>5-Minute</u>
Beachwood	0.04	0.04	0.04	0.04	0.03	0.02
Brecksville	0.00	0.00	0.00	0.00	0.00	0.00
Brook Park	0.06	0.06	0.06	0.05	0.02	0.01
Cleveland Industrial Pkwy	0.04	0.04	0.04	0.03	0.02	0.01
Dille Ave PS	0.16	0.16	0.16	0.16	0.10	0.08
Division Ave PS	0.16	0.16	0.16	0.14	0.09	0.09
Easterly WWTP	0.14	0.14	0.14	0.12	0.10	0.08
Independence	0.02	0.02	0.02	0.02	0.02	0.02
James Rhodes HS	0.26	0.26	0.26	0.25	0.15	0.14
Jennings PS	0.21	0.21	0.21	0.20	0.15	0.09
Macedonia	0.00	0.00	0.00	0.00	0.00	0.00
Maple Heights	0.00	0.00	0.00	0.00	0.00	0.00
Mary Street PS	0.14	0.14	0.14	0.12	0.08	0.07
Mayfield Heights	0.04	0.04	0.04	0.04	0.03	0.02
Moreland Hills	0.03	0.03	0.03	0.03	0.03	0.02
North Olmsted	0.12	0.12	0.12	0.11	0.10	0.08
North Royalton	0.12	0.12	0.12	0.12	0.12	0.09
Oakwood	0.02	0.02	0.02	0.02	0.02	0.02
Olmsted Falls	0.17	0.17	0.17	0.16	0.14	0.06
Parma	0.14	0.14	0.14	0.13	0.09	0.04
Richfield	0.00	0.00	0.00	0.00	0.00	0.00
Shaker Heights	0.10	0.10	0.10	0.10	0.08	0.07
South Euclid	0.32	0.32	0.32	0.32	0.23	0.17
Southerly WWTC	0.19	0.19	0.19	0.19	0.17	0.11
Strongsville C WWTP	0.08	0.08	0.08	0.07	0.04	0.03
Strongsville Foltz	0.10	0.10	0.10	0.08	0.05	0.05
University Heights	0.22	0.22	0.22	0.22	0.15	0.11
Wade Park	0.21	0.21	0.21	0.20	0.14	0.08
Westerly WWTP	0.16	0.16	0.16	0.15	0.13	0.12
Westlake	0.05	0.05	0.05	0.04	0.02	0.02

## Work Order Detail Report

9/8/2023

so overflow inspections 9-6-2023 0.22'

2:49 PM

WO Number:	230908-0001	Category:	SSOs	
Status:	Complete	Problem:	Storm Response	
Status Date:	9/8/2023 2:47 pm	Main Task:	Inspection	
Asset:	SSO 431			
Location:	FAIRFAX AT NORTH PARK			
Cause:	Weather	Assigned By:		
Assigned Crew:		Assigned Date:		
Supervisor:	Jackson, Jeff	Start Date:	9/8/2023 8:00 AM	Override
Lead Worker:	Cardarella, Joe	End Date:	9/8/2023 2:00 PM	Notifications
Priority:	High			Problem <input type="checkbox"/>
Account #:				Overdue <input type="checkbox"/>
Proj No - Acct:		Project ID:		Lead Worker <input type="checkbox"/>
Project:		Project Name:		Task <input type="checkbox"/>
Reason:				Supervisor <input type="checkbox"/>
Received By:				Hard Lock WO <input type="checkbox"/>
Inspected By:				

### Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

#### Location

Department: Sewer Collection  
Division: Sewer

Comments for Crew  
Inspect all (45) SSO's when rainfall is one quarter (1/4")  
inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

#### Work Order Locations

<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

## Work Order Detail Report

9/8/2023

2:49 PM

iso overflow inspections 9-6-2023 0.22'

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

---

**Work Order Detail Report**

9/8/2023

sso overflow inspections 9-6-2023 0.22'

2:49 PM

2,227,825.14395215 684,881.15948047

# Work Order Detail Report

9/8/2023

iso overflow inspections 9-6-2023 0.22'

2:49 PM

## Work Order Assets

Object Type	System ID 1	System ID 2	Description 1	Odometer	Hourmeter	Othermeter	Description 2	PM Description	Asset ID	Completed
Sewer Control Valve							FAIRFAX AT NORTH PARK			
SSO 431							26			
Sewer Control Valve							NORTH PARK AND COVENTRY			
SSO 114							16			
Sewer Control Valve							FAIRMOUNT SOUTH OF SCARBOROUGH			
SSO 121							35			
Sewer Structure										
SA16AAWB0							3094			
Sewer Control Valve							FAIRMOUNT AT FAIRFAX			
SSO 112							7			
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
SSO 99							6			
Sewer Control Valve							3012 NORTH WOODLAND			
SSO 432							14			
Sewer Control Valve										
DB-03							55			
Sewer Control Valve										
DB-01							56			
Sewer Control Valve										
DB-02							57			
Sewer Control Valve							FAIRMOUNT AT DARTMOOR			
CH-04							5			
Sewer Control Valve							FAIRMOUNT AT WELLINGTON			
SSO 110							44			
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
SSO 87							33			
Sewer Control Valve							FAIRMOUNT AT MARLBORO			
SSO 116							4			
Sewer Control Valve							FAIRMOUNT AT ARLINGTON			
SSO 111							46			
Sewer Control Valve							FAIRMOUNT & COVENTRY (SCARBOROUGH)			
SSO 113							37			
Sewer Control Valve							FAIRMOUNT AND COVENTRY			
SSO 124							47			
Sewer Control Valve							SCARBOROUGH AT LAMBERTON			
CH-50							53			
Sewer Control Valve							BRADFORD AND LEE			
SSO 129							11			
Sewer Control Valve							EDDINGTON			
CH-52							2			
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (18")			
SSO 88							42			
Sewer Control Valve							EAST OVERLOOK AT EDGEHILL			
SSO 122							36			
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (36")			
SSO 89							34			
Sewer Structure										
SA16ADZB0							1536			
Sewer Control Valve							HAMPSHIRE AT EUCLID HTS. BLVD.			
SSO 91							20			
Sewer Structure										
SA16ADPH0							4446			
Sewer Control Valve							CEDAR BTW. FAIRMOUNT/DEMINGTON			
SSO 120							8			
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY			
SSO 103							19			
Sewer Control Valve							3003 EUCLID HEIGHTS BLVD			
SSO 104							15			

## Work Order Detail Report

9/8/2023

2:49 PM

SSO overflow inspections 9-6-2023 0.22'

Sewer Structure		3402
SA16AGMG0		
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F	
CH-30	52	
Sewer Control Valve	LEE RD. & SUPERIOR AVE.	
DV-11	9	
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE	
SSO 108	22	
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND	
SSO 106	43	
Sewer Control Valve	1685 CUMBERLAND	
SSO 95	18	
Sewer Control Valve	CUMBERLAND/SOMERTON	
SSO 105	30	
Sewer Structure		4987
SA16AQD0		
Sewer Structure		3745
SA16AQQC0		
Sewer Control Valve	2225 NOBLE ROAD	
SSO 102	3	
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF	
SSO 107	38	
Sewer Control Valve	LANGTON AND AHERSTONE	
CH-51	54	
Sewer Structure		1809
SA16APEF0		

## Work Order Detail Report

9/8/2023

iso overflow inspections 9-6-2023 0.22'

2:49 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
	<u>Item</u>				
Reset					
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	9/8/2023/ 1:33 pm	9/8/2023
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	9/8/2023/ 1:34 pm	9/8/2023
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	9/8/2023/ 1:36 pm	9/8/2023
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	9/8/2023/ 1:36 pm	9/8/2023
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/8/2023/ 1:36 pm	9/8/2023
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	9/8/2023/ 1:37 pm	9/8/2023
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	9/8/2023/ 1:37 pm	9/8/2023
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	9/8/2023/ 1:37 pm	9/8/2023
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/8/2023/ 1:38 pm	9/8/2023
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	9/8/2023/ 1:38 pm	9/8/2023
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	9/8/2023/ 1:38 pm	9/8/2023
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/8/2023/ 1:38 pm	9/8/2023
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	9/8/2023/ 1:39 pm	9/8/2023
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/8/2023/ 1:39 pm	9/8/2023
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/8/2023/ 1:39 pm	9/8/2023
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	9/8/2023/ 1:40 pm	9/8/2023
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/8/2023/ 1:40 pm	9/8/2023
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/8/2023/ 1:40 pm	9/8/2023
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/8/2023/ 1:41 pm	9/8/2023
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	9/8/2023/ 1:41 pm	9/8/2023
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	9/8/2023/ 1:41 pm	9/8/2023
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/8/2023/ 1:34 pm	9/8/2023
Meter					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	9/8/2023/ 1:42 pm	9/8/2023
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	9/8/2023/ 1:42 pm	9/8/2023
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	9/8/2023/ 1:42 pm	9/8/2023
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	9/8/2023/ 1:42 pm	9/8/2023
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	9/8/2023/ 1:43 pm	9/8/2023

## Work Order Detail Report

9/8/2023

2:49 PM

sso overflow inspections 9-6-2023 0.22'

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	9/8/2023/ 1:43 pm	9/8/2023
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	9/8/2023/ 1:43 pm	9/8/2023
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	9/8/2023/ 1:44 pm	9/8/2023
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	9/8/2023/ 1:44 pm	9/8/2023
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	9/8/2023/ 1:44 pm	9/8/2023
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	9/8/2023/ 1:45 pm	9/8/2023
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	9/8/2023/ 1:45 pm	9/8/2023
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	9/8/2023/ 1:45 pm	9/8/2023
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	9/8/2023/ 1:46 pm	9/8/2023
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	9/8/2023/ 1:35 pm	
No access construction					
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	9/8/2023/ 1:46 pm	9/8/2023
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	9/8/2023/ 1:47 pm	9/8/2023
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	9/8/2023/ 1:47 pm	9/8/2023
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	9/8/2023/ 1:47 pm	9/8/2023
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	9/8/2023/ 1:47 pm	9/8/2023
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	9/8/2023/ 1:48 pm	9/8/2023
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	9/8/2023/ 1:48 pm	9/8/2023
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	9/8/2023/ 1:48 pm	9/8/2023

### Tasks/Resources

#### SWCT26 Inspection

Crew:

Supervisor:

Status:

UOM: Each

\*Cal'c UC: \$4.23

# of Units: 45.00

\*Task Cost: \$190.45

\*Unit Cost: \$0.00

Start Dt: 9/8/2023

End Dt: 9/8/2023

### Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	5.00	\$123.45		9/8/2023	9/8/2023
29960 Jackson, Jeff	Hours	5.00	\$0.00		9/8/2023	9/8/2023

### Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT93 FORD F250 4 X 4 PICK UP 1	Hours	5.00	\$67.00		9/8/2023	9/8/2023
CHFT-500 FORD F250 PICK UP TRUCK	Each	5.00	\$0.00		9/8/2023	9/8/2023

Task Comment: sso overflow inspections 9-6-2023 0.22'

Projected Complete:	Lock: <input type="checkbox"/>	Equipment Costs	*Actual	*Estimated	*Difference
			WO Duration	6.00	0.00
Repair Type:		Labor Hours	10.00	0.00	0.00
Subcontractor:		Labor Costs	\$123.45	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Contractor Costs	67.00	0.00	0.00
Unit of Measure:	Each	Misc. Costs	0.00	0.00	0.00
Unit Cost:	\$0.00	Total Costs	\$190.45	\$0.00	\$0.00
NO Hours:	0.00	Use Task Info:	True	True	

# Work Order Detail Report

9/8/2023

SSO overflow inspections 9-6-2023 0.22'

2:49 PM

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	<input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/>
		Payment Method:	<input type="checkbox"/>
Associated PMs		Imported to Financials: <input type="checkbox"/>	
Item	PM Code and Description		
Work Order Creation	SSO-02 SSO INSPECTION	Closed	<input checked="" type="checkbox"/>
Tracking			
Item	Description	By	Date
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	9/8/2023
Supervisor Notification	Email Queued Successfully!	jjackson	9/8/2023
Status Change	From New Work Order to Complete	jjackson	9/8/2023
Time			
Rate:		Opened At:	Televised: <input type="checkbox"/>
Received By:		Pipe Footage Cleaned:	Power Rooter: <input type="checkbox"/>
Work From:		Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:		WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:		WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:		WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:		User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:		Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:		Appointment Date: 9/8/2023	8:00 AM
Dye Test Results:			
NO User 51:		E Mail:	
Measurement:		Measurement Line 2:	
History:		Pipe Size:	
Manhole Basin Repair:		PVC Tees, Angles, Sles:	
Material Used:		WO User 44:	
Pipe Repair:		WO User 45:	
Street Repair:		WO User 46:	
Grass Repair:			
Curb Repair:			
Driveway- Sidewalk Re:			
Construction Crew:			
NO User 39:		OUPS #:	
NO User 40:		WO User 48:	
NO User 41:		WO User 62:	
NO User 52:		WO User 63:	
NO User 53:		WO User 64:	
NO User 54:		WO User 65:	
NO User 55:		WO User 66:	
NO User 56:		WO User 67:	
NO User 57:		WO User 68:	
NO User 58:		WO User 69:	
NO User 59:		WO User 70:	
NO User 60:		WO User 71:	
NO User 61:			

## Work Order Detail Report

9/8/2023

sso overflow inspections 9-6-2023 0.22'

2:49 PM

WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 9/8/2023	PM Trigger:	Rec #: 15045