

CITY OF
CLEVELAND
HEIGHTS
LAW DEPARTMENT

October 14, 2024

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604


Re: September 2024 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through September 30, 2024, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,



William R. Hanna
Director of Law


Enclosures

Overflow Monitoring Update
October 14, 2024

cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Sarah Fuller, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Friday, September 6, 2024
Accumulation in inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Friday, September 6, 2024

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.89	0.72	0.47	0.23	0.13
Brecksville	0.83	0.82	0.51	0.28	0.12
Brook Park	1.33	1.19	0.67	0.33	0.13
Cleveland Industrial Pkwy	1.33	1.02	0.66	0.33	0.18
Dille Ave PS	1.47	1.19	0.81	0.47	0.25
Division Ave PS	1.15	1.07	0.61	0.33	0.15
Easterly WWTP	1.40	1.32	1.09	0.66	0.31
Independence	1.18	1.12	0.78	0.41	0.20
James Rhodes HS	1.25	1.09	0.73	0.43	0.18
Jennings PS	n/a	n/a	n/a	n/a	n/a
Macedonia	0.67	0.58	0.36	0.21	0.11
Maple Heights	0.77	0.70	0.47	0.24	0.13
Mary Street PS	1.27	1.04	0.67	0.44	0.19
Mayfield Heights	0.86	0.71	0.44	0.26	0.11
Moreland Hills	0.89	0.83	0.55	0.28	0.15
North Olmsted	1.30	1.07	0.61	0.33	0.16
North Royalton	1.03	0.99	0.54	0.27	0.13
Oakwood	0.59	0.58	0.38	0.20	0.14
Olmsted Falls	1.04	0.89	0.55	0.30	0.13
Parma	1.29	1.21	0.76	0.36	0.19
Richfield	0.76	0.66	0.40	0.21	0.11
Shaker Heights	0.87	0.73	0.45	0.23	0.15
South Euclid	1.18	0.94	0.61	0.37	0.18
Southerly WWTC	1.23	1.10	0.79	0.48	0.27
Strongsville C WWTP	1.38	1.29	0.72	0.34	0.18
Strongsville Foltz	1.18	1.10	0.65	0.36	0.17
University Heights	1.12	0.91	0.60	0.38	0.23
Wade Park	1.04	0.88	0.53	0.24	0.15
Westerly WWTP	1.25	1.18	0.72	0.42	0.23
Westlake	1.58	1.24	0.71	0.41	0.18

WO Number: 240910-0001

Category: SSOs

Status: New Work Order

Problem: Storm Response

Status Date: 9/10/2024 7:16 am

Main Task: Inspection

Asset: SSO 431

Assigned By:

Location: FAIRFAX AT NORTH PARK

Assigned Date:

Cause: Weather

Start Date: 9/9/2024 8:00 AM

Assigned Crew:

End Date: 9/9/2024 1:00 PM

Supervisor: Jackson, Jeff

Override

Lead Worker: Cardarella, Joe

Notifications

Priority: High

Problem ☐

Account #:

Overdue ☐

Proj No - Acct:

Lead Worker ☐

Project:

Task ☐

Reason:

Supervisor ☐

Received By:

Hard Lock WO ☐

Inspected By:

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Comments for Crew

Sub-Division:

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address		General Location	
X Coord	Y Coord		
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339	Doan Brook	
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO			
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

9/11/2024

so overflow inspections 9-6-2024 1.12'

12:06 PM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

9/11/2024

so overflow inspections 9-6-2024 1.12'

12:06 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

9/11/2024

ssso overflow inspections 9-6-2024 1.12'

12:06 PM

Work Order Assets

<u>Object Type</u>		<u>Description 1</u>			<u>Description 2</u>		<u>Completed</u>
<u>System ID 1</u>	<u>System ID 2</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>	<u>Asset ID</u>	
Sewer Control Valve					FAIRFAX AT NORTH PARK	26	
SSO 431							
Sewer Control Valve					NORTH PARK AND COVENTRY	16	
SSO 114							
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH	35	
SSO 121							
Sewer Structure						3094	
SA16AAWB0							
Sewer Control Valve					FAIRMOUNT AT FAIRFAX	7	
SSO 112							
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6	
SSO 99							
Sewer Control Valve					3012 NORTH WOODLAND	14	
SSO 432							
Sewer Control Valve						55	
DB-03							
Sewer Control Valve						56	
DB-01							
Sewer Control Valve						57	
DB-02							
Sewer Control Valve					FAIRMOUNT AT DARTMOOR	5	
CH-04							
Sewer Control Valve					FAIRMOUNT AT WELLINGTON	44	
SSO 110							
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33	
SSO 87							
Sewer Control Valve					FAIRMOUNT AT MARLBORO	4	
SSO 116							
Sewer Control Valve					FAIRMOUNT AT ARLINGTON	46	
SSO 111							
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)	37	
SSO 113							
Sewer Control Valve					FAIRMOUNT AND COVENTRY	47	
SSO 124							
Sewer Control Valve					SCARBOROUGH AT LAMBERTON	53	
CH-50							
Sewer Control Valve					BRADFORD AND LEE	11	
SSO 129							
Sewer Control Valve					EDDINGTON	2	
CH-52							
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")	42	
SSO 88							
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL	36	
SSO 122							
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")	34	
SSO 89							
Sewer Structure						1536	
SA16ADZB0							
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.	20	
SSO 91							
Sewer Structure						4446	
SA16ADPH0							
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON	8	
SSO 120							
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY	19	
SSO 103							
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD	15	
SSO 104							

Work Order Detail Report

9/11/2024

ssso overflow inspections 9-6-2024 1.12'

12:06 PM

Sewer Structure		
SA16AGMG0		3402
Sewer Control Valve		South Taylor between Antisdale Ave and Superior F
CH-30		52
Sewer Control Valve		LEE RD. & SUPERIOR AVE.
DV-11		9
Sewer Control Valve		EUCLID HEIGHTS BLVD AND LEE
SSO 108		22
Sewer Control Valve		EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106		43
Sewer Control Valve		1685 CUMBERLAND
SSO 95		18
Sewer Control Valve		CUMBERLAND/SOMERTON
SSO 105		30
Sewer Structure		
SA16AQD0		4987
Sewer Structure		
SA16AQQC0		3745
Sewer Control Valve		2225 NOBLE ROAD
SSO 102		3
Sewer Control Valve		QUILLIAMS, N. OF RANDOLF
SSO 107		38
Sewer Control Valve		LANGTON AND ATHERSTONE
CH-51		54
Sewer Structure		
SA16APEF0		1809

Work Order Detail Report

9/11/2024

iso overflow inspections 9-6-2024 1.12'

12:06 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Not Sound	9/10/2024/ 1:08 pm	9/10/2024
Reset					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	9/10/2024/ 1:14 pm	9/10/2024
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	9/10/2024/ 1:14 pm	9/10/2024
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	9/10/2024/ 1:14 pm	9/10/2024
5	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	9/10/2024/ 1:15 pm	9/10/2024
6	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	9/10/2024/ 1:15 pm	9/10/2024
7	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	9/10/2024/ 1:15 pm	9/10/2024
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	9/10/2024/ 1:16 pm	9/10/2024
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	9/10/2024/ 1:16 pm	9/10/2024
10	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	9/10/2024/ 1:16 pm	9/10/2024
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	9/10/2024/ 1:17 pm	9/10/2024
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	9/10/2024/ 1:17 pm	9/10/2024
13	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Not Sound	9/10/2024/ 1:11 pm	9/10/2024
NR needs board					
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Not Sound	9/10/2024/ 1:13 pm	9/10/2024
Reset					
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	9/10/2024/ 1:17 pm	9/10/2024
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	9/10/2024/ 1:19 pm	9/10/2024
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	9/10/2024/ 1:19 pm	9/10/2024
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Not Sound	9/10/2024/ 1:18 pm	9/10/2024
NR needs rope and board					
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Not Sound	9/10/2024/ 1:19 pm	9/10/2024
NR no board					
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	9/10/2024/ 1:20 pm	9/10/2024
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	9/10/2024/ 1:20 pm	9/10/2024
22	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Not Sound	9/10/2024/ 1:21 pm	9/10/2024
Reset					
23	B-13-HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Not Sound	9/10/2024/ 1:21 pm	9/10/2024
Reset					
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Not Sound	9/10/2024/ 1:21 pm	9/10/2024
Reset					
25	B-42 12537 CEDAR SA16ACZA0	☐		/	

Work Order Detail Report

9/11/2024

sso overflow inspections 9-6-2024 1.12'

12:06 PM

26	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	9/10/2024/ 1:22 pm	9/10/2024
27	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	9/10/2024/ 1:22 pm	9/10/2024
28	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	9/10/2024/ 1:22 pm	9/10/2024
29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	9/10/2024/ 1:23 pm	9/10/2024
30	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	9/10/2024/ 1:23 pm	9/10/2024
31	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	9/10/2024/ 1:24 pm	9/10/2024
32	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	9/10/2024/ 1:24 pm	9/10/2024
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	9/10/2024/	9/10/2024
34	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	9/10/2024/ 1:25 pm	9/10/2024
35	C-55 3593 FENLEY SA16APEH0	☐	Sound	9/10/2024/ 1:25 pm	9/10/2024

Tasks/Resources

SMCT36 Inspection

Crew: Status: *Cal'c UC: \$5.51 *Task Cost: \$192.90 Start Dt: 9/9/2024
Supervisor: UOM: Each # of Units: 35.00 *Unit Cost: \$0.00 End Dt: 9/9/2024

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	5.00	\$125.90		9/9/2024	9/9/2024

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT93 FORD F250 4 X 4 PICK UP	Hours	5.00	\$67.00		9/9/2024	9/9/2024

1

Task Comment: sso overflow inspections 9-6-2024 1.12'

		*Actual	*Estimated	*Difference
Projected Complete:	Lock: ☐	WO Duration	5.00	0.00
Repair Type:		Labor Hours	5.00	0.00
Subcontractor:		Labor Costs	\$125.90	\$0.00
Profit Center:		Material Costs	0.00	0.00
		Fluids Costs	0.00	0.00
Quantity:	0.00	Equipment Costs	67.00	0.00
Unit of Measure:	Each	Contractor Costs	0.00	0.00
Unit Cost:	\$0.00	Misc. Costs	0.00	0.00
WO Hours:	0.00	Total Costs	\$192.90	\$0.00
Use Task Info:		True	True	

Billing

Billed Party

Customer ID: Customer Number:
Customer Name: Last Name:
Address: Phone: Cell #:
City: Fax #:
State: E-mail:
Zip:

Billing Data

Contact Name: *Billing Amount: Billing Required: ☐
Invoice Number: Date Bill Sent: Billing Processed: ☐
Incoming Account #: Payment Received: Imported to Financials: ☐
Payment Method:

Associated PMs

PM Code and Description
SSO-02 SSO INSPECTION

Closed



Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	9/10/2024	7:16 AM
Supervisor Notification	Email Queued Successfully!	jjackson	9/10/2024	7:16 AM

Rate:

Recieved By:

Work From:

Pipe Size:

Pipe Condition:

Could Not Open:

Additional Repair:

Dye Test Reason:

Test Performed Throug

Dye Test Results:

NO User 51:

Measurement:

History:

Manhole Basin Repair:

Material Used:

Pipe Repair:

Street Repair:

Grass Repair:

Curb Repair:

Driveway- Sidewalk Re

Construction Crew:

NO User 39:

NO User 40:

NO User 41:

NO User 52:

NO User 53:

NO User 54:

NO User 55:

NO User 56:

NO User 57:

NO User 58:

NO User 59:

NO User 60:

NO User 61:

NO User 72:

NO User 73:

NO User 74:

NO User 75:

NO User 76:

NO User 92 Date:

NO User 93 Date:

NO User 94 Date:

NO User 95 Date:

NO User 96 Date:

NO User 77:

NO User 78:

NO User 79:

NO User 80:

NO User 81:

Opened At:

Pipe Footage Cleaned .

Gallons Used:

WO User 23:

WO User 24:

WO User 9:

User 10:

Appointment Date DNL

Appointment Date:

E Mail:

Measurement Line 2:

Pipe Size:

PVC Tees, Angles, Slec

WO User 44:

WO User 45:

WO User 46:

OUPS #:

WO User 48:

WO User 62:

WO User 63:

WO User 64:

WO User 65:

WO User 66:

WO User 67:

WO User 68:

WO User 69:

WO User 70:

WO User 71:

WO User 82:

Quantity:

WO User 84:

WO User 85:

WO User 86:

WO User 97 Date:

WO User 98 Date:

WO User 99 Date:

WO User 100 Date:

WO User 101 Date:

WO User 87:

WO User 88:

WO User 89:

WO User 90:

WO User 91:

Televised:

Power Rooter:

Jet:

Gap Vac:

Dye Test:

Gap Root Cut:

GIS Correction?:

Test Tee Correction:

Televised:

Paid:

WO User 104:

WO User 105:

WO User 106:

WO User 107:

WO User 108:

WO User 109:

WO User 110:

WO User 111:

Created By:


WO Creation Date:

PM Trigger:

Rec #:

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Tuesday, September 24, 2024
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Tuesday, September 24, 2024

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.44	0.44	0.25	0.17	0.09	0.05
Brecksville	0.60	0.58	0.31	0.22	0.11	0.04
Brook Park	0.48	0.46	0.29	0.23	0.08	0.04
Cleveland Industrial Pkwy	0.48	0.48	0.30	0.23	0.08	0.03
Dille Ave PS	0.35	0.35	0.21	0.17	0.06	0.03
Division Ave PS	0.38	0.38	0.22	0.17	0.06	0.03
Easterly WWTP	0.22	0.22	0.13	0.11	0.06	0.02
Independence	0.49	0.48	0.29	0.20	0.09	0.04
James Rhodes HS	0.41	0.41	0.26	0.19	0.08	0.03
Jennings PS	n/a	n/a	n/a	n/a	n/a	n/a
Macedonia	0.55	0.54	0.30	0.22	0.12	0.05
Maple Heights	0.48	0.47	0.30	0.21	0.09	0.04
Mary Street PS	0.41	0.41	0.25	0.20	0.07	0.04
Mayfield Heights	0.38	0.38	0.24	0.17	0.05	0.02
Moreland Hills	0.50	0.49	0.26	0.20	0.08	0.04
North Olmsted	0.54	0.48	0.25	0.20	0.07	0.03
North Royalton	0.63	0.62	0.34	0.25	0.17	0.09
Oakwood	0.57	0.56	0.30	0.22	0.12	0.05
Olmsted Falls	0.48	0.42	0.27	0.21	0.07	0.03
Parma	0.50	0.49	0.32	0.23	0.08	0.03
Richfield	0.76	0.75	0.47	0.36	0.24	0.14
Shaker Heights	0.43	0.43	0.29	0.21	0.07	0.03
South Euclid	0.32	0.32	0.19	0.15	0.05	0.02
Southerly WWTC	0.43	0.43	0.28	0.20	0.08	0.03
Strongsville C WWTP	0.52	0.50	0.35	0.26	0.08	0.04
Strongsville Foltz	0.66	0.63	0.40	0.30	0.13	0.06
University Heights	0.42	0.42	0.28	0.20	0.07	0.03
Wade Park	0.34	0.34	0.21	0.15	0.06	0.02
Westerly WWTP	0.33	0.33	0.18	0.14	0.06	0.02
Westlake	0.43	0.38	0.24	0.21	0.07	0.03

Work Order Detail Report

9/26/2024

so overflow inspections 9-24-2024 0.42'

12:02 PM

WO Number: 240926-0001

Category: SSOs

Status: New Work Order

Problem: Storm Response

Status Date: 9/26/2024 7:05 am

Main Task: Inspection

Asset: SSO 431

Assigned By:

Location: FAIRFAX AT NORTH PARK

Assigned Date:

Cause: Weather

Start Date: 9/25/2024 8:00 AM

Assigned Crew:

End Date: 9/25/2024 2:00 PM

Supervisor: Jackson, Jeff

Override

Lead Worker: Cardarella, Joe

Notifications

Priority: High

Problem ☐

Account #:

Overdue ☐

Proj No - Acct:

Lead Worker ☐

Project:

Task ☐

Reason:

Supervisor ☐

Received By:

Hard Lock WO ☐

Inspected By:

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

Address

Address 2

X Coord

Y Coord

General Location

FAIRFAX AT NORTH PARK

2,220,655.65435414 665,517.24643672

Doan Brook

NORTH PARK AND COVENTRY

2,219,873.16674590 666,048.82312946

DOAN BROOK - MAIN BRANCH

FAIRMOUNT SOUTH OF SCARBOROUGH

2,220,364.86097248 666,446.72325230

DOAN BROOK - MAIN BRANCH

FAIRMOUNT AT FAIRFAX

2,220,920.81917815 666,080.57995571

DOAN BROOK - MAIN BRANCH

FAIRMOUNT AT NORTH WOODLAND (S. SIDE)

2,223,053.81655256 664,693.25202172

DOAN BROOK - MAIN BRANCH

3012 NORTH WOODLAND

2,222,845.06631389 664,689.08536339

Doan Brook

2,226,440.21168265 664,329.55524255

2,226,354.79813956 664,409.89202413

2,226,389.92077273 664,379.07548472

FAIRMOUNT AT DARTMOOR

2,225,149.97508989 664,453.31024438

DOAN BROOK - MAIN BRANCH

FAIRMOUNT AT WELLINGTON

2,223,969.26550905 664,532.08075613

DOAN BROOK - MAIN BRANCH

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)

2,223,111.44143730 664,794.46048072

DOAN BROOK - MAIN BRANCH

FAIRMOUNT AT MARLBORO

2,221,638.88762389 665,726.15513962

DOAN BROOK - MAIN BRANCH

A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 240926-0001

Work Order Detail Report

9/26/2024

iso overflow inspections 9-24-2024 0.42'

12:02 PM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

9/26/2024

iso overflow inspections 9-24-2024 0.42'

12:02 PM

2,227,825.14395215 684,881.15948047

Work Order Assets							
Object Type		Description 1			Description 2		
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19	
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD		
SSO 104						15	

Work Order Detail Report

9/26/2024

so overflow inspections 9-24-2024 0.42'

12:02 PM

Sewer Structure		
SA16AGMG0		3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F	
CH-30		52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.	
DV-11		9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE	
SSO 108		22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND	
SSO 106		43
Sewer Control Valve	1685 CUMBERLAND	
SSO 95		18
Sewer Control Valve	CUMBERLAND/SOMERTON	
SSO 105		30
Sewer Structure		
SA16AQQD0		4987
Sewer Structure		
SA16AQQC0		3745
Sewer Control Valve	2225 NOBLE ROAD	
SSO 102		3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF	
SSO 107		38
Sewer Control Valve	LANGTON AND ATHERSTONE	
CH-51		54
Sewer Structure		
SA16APEF0		1809

Work Order Detail Report

9/26/2024

iso overflow inspections 9-24-2024 0.42'

12:02 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	9/26/2024/ 9:53 am	9/26/2024
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	9/26/2024/ 9:53 am	9/26/2024
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Not Sound	9/26/2024/ 9:54 am	9/26/2024
Reset					
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	9/26/2024/ 9:54 am	9/26/2024
5	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	9/26/2024/ 9:55 am	9/26/2024
6	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	9/26/2024/ 9:55 am	9/26/2024
7	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	9/26/2024/ 9:55 am	9/26/2024
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	9/26/2024/ 9:56 am	9/26/2024
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	9/26/2024/ 9:56 am	9/26/2024
10	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Not Sound	9/26/2024/ 9:57 am	9/26/2024
Reset					
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	9/26/2024/ 9:57 am	9/26/2024
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	9/26/2024/ 9:58 am	9/26/2024
13	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Not Sound	9/26/2024/ 9:58 am	9/26/2024
NR					
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	9/26/2024/ 9:59 am	9/26/2024
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Not Sound	9/26/2024/ 9:59 am	9/26/2024
Reset					
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	9/26/2024/10:01 am	9/26/2024
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Not Sound	9/26/2024/10:00 am	9/26/2024
Reset needs jetting					
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	9/26/2024/10:01 am	9/26/2024
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Not Sound	9/26/2024/10:01 am	9/26/2024
NR					
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	9/26/2024/10:02 am	9/26/2024
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	9/26/2024/10:02 am	9/26/2024
22	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	9/26/2024/10:02 am	9/26/2024
23	B-13-HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	9/26/2024/10:03 am	9/26/2024
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	9/26/2024/10:03 am	9/26/2024
25	B-42 12537 CEDAR SA16ACZA0	☐	Sound	9/26/2024/10:04 am	9/26/2024
26	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	9/26/2024/10:04 am	9/26/2024
27	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	9/26/2024/10:04 am	9/26/2024

9/26/2024

12:02 PM

Tasks/Resources						
SMCT36 Inspection						
Crew:	Status:	*Cal'c UC: \$5.51		*Task Cost: \$192.90		Start Dt: 9/25/2024
Supervisor:	UOM: Each	# of Units: 35.00		*Unit Cost: \$0.00		End Dt: 9/25/2024
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	5.00	\$125.90		9/25/2024	9/25/2024
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	5.00	\$67.00		9/25/2024	9/25/2024
5						
Task Comment: sso overflow inspections 9-24-2024 0.42'						

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:			
City:		Phone:	Cell #:
State:		Fax #:	
Zip:		E-mail:	
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: ☐
Invoice Number:		Date Bill Sent:	Billing Processed: ☐
Incoming Account #:		Payment Received:	Imported to Financials: ☐
		Payment Method:	

PM Code and Description
SSO-02 SSO INSPECTION

Closed

A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 240926-0001

Work Order Detail Report

iso overflow inspections 9-24-2024 0.42'

9/26/2024

12:02 PM

Rate:

Recieved By:

Work From:

Pipe Size:

Pipe Condition:

Could Not Open:

Additional Repair:

Dye Test Reason:

Test Performed Throug

Dye Test Results:

NO User 51:

Measurement:

History:

Manhole Basin Repair:

Material Used:

Pipe Repair:

Street Repair:

Grass Repair:

Curb Repair:

Driveway- Sidewalk Re

Construction Crew:

NO User 39:

NO User 40:

NO User 41:

NO User 52:

NO User 53:

NO User 54:

NO User 55:

NO User 56:

NO User 57:

NO User 58:

NO User 59:

NO User 60:

NO User 61:

NO User 72:

NO User 73:

NO User 74:

NO User 75:

NO User 76:

NO User 92 Date:

NO User 93 Date:

NO User 94 Date:

NO User 95 Date:

NO User 96 Date:

NO User 77:

NO User 78:

NO User 79:

NO User 80:

NO User 81:

NO Creator:

Opened At:

Pipe Footage Cleaned

Gallons Used:

WO User 23:

WO User 24:

WO User 9:

User 10:

Appointment Date DNL

Appointment Date:

E Mail:

Measurement Line 2:

Pipe Size:

PVC Tees, Angles, Slec

WO User 44:

WO User 45:

WO User 46:

OUPS #:

WO User 48:

WO User 62:

WO User 63:

WO User 64:

WO User 65:

WO User 66:

WO User 67:

WO User 68:

WO User 69:

WO User 70:

WO User 71:

WO User 82:

Quantity:

WO User 84:

WO User 85:

WO User 86:

WO User 97 Date:

WO User 98 Date:

WO User 99 Date:

WO User 100 Date:

WO User 101 Date:

WO User 87:

WO User 88:

WO User 89:

WO User 90:

WO User 91:

WO Creation Date:

Televised:

Power Rooter:

Jet:

Gap Vac:

Dye Test:

Gap Root Cut:

GIS Correction?:

Test Tee Correction:

Televised:

Paid:

WO User 104:

WO User 105:

WO User 106:

WO User 107:

WO User 108:

WO User 109:

WO User 110:

WO User 111:

Rec #:

jjackson


9/26/2024

PM Trigger:

15835

**Northwest Ohio
Regional Sewer District**

Daily Precipitation Report
Sunday, September 29, 2024
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, September 29, 2024

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.31	0.15	0.10	0.05	0.02
Brecksville	0.42	0.21	0.14	0.06	0.04
Brook Park	0.26	0.13	0.09	0.04	0.02
Cleveland Industrial Pkwy	0.28	0.14	0.10	0.05	0.02
Dille Ave PS	0.26	0.15	0.09	0.05	0.02
Division Ave PS	0.29	0.16	0.11	0.06	0.04
Easterly WWTP	0.19	0.10	0.07	0.04	0.02
Independence	0.35	0.19	0.12	0.06	0.03
James Rhodes HS	0.27	0.13	0.09	0.05	0.02
Jennings PS	n/a	n/a	n/a	n/a	n/a
Macedonia	0.30	0.15	0.11	0.05	0.02
Maple Heights	0.28	0.13	0.09	0.05	0.02
Mary Street PS	0.27	0.15	0.10	0.05	0.02
Mayfield Heights	0.25	0.12	0.08	0.03	0.02
Moreland Hills	0.41	0.18	0.11	0.05	0.02
North Olmsted	0.31	0.14	0.11	0.05	0.02
North Royalton	0.33	0.14	0.11	0.05	0.02
Oakwood	0.31	0.17	0.11	0.05	0.02
Olmsted Falls	0.34	0.17	0.10	0.07	0.03
Parma	0.31	0.16	0.11	0.05	0.02
Richfield	0.49	0.27	0.18	0.08	0.04
Shaker Heights	0.25	0.12	0.09	0.04	0.02
South Euclid	0.29	0.15	0.09	0.04	0.02
Southerly WWTC	0.27	0.14	0.10	0.05	0.02
Strongsville C WWTP	0.33	0.15	0.10	0.05	0.02
Strongsville Foltz	0.39	0.19	0.13	0.06	0.03
University Heights	0.25	0.14	0.11	0.06	0.02
Wade Park	0.29	0.15	0.11	0.06	0.04
Westerly WWTP	0.25	0.14	0.09	0.05	0.03
Westlake	0.25	0.13	0.10	0.05	0.02

WO Number: 241001-0002

Category: SSOs

Status: New Work Order

Problem: Storm Response

Status Date: 10/1/2024 2:11 pm

Main Task: Inspection

Asset: SSO 431

Assigned By:

Location: FAIRFAX AT NORTH PARK

Assigned Date:

Cause: Weather

Start Date: 10/1/2024 8:00 AM

Assigned Crew:

End Date: 10/1/2024 2:00 PM

Supervisor: Jackson, Jeff

Override

Lead Worker: Cardarella, Joe

Notifications

Priority: High

Problem ☐

Account #:

Overdue ☐

Proj No - Acct:

Lead Worker ☐

Project:

Task ☐

Reason:

Supervisor ☐

Received By:

Hard Lock WO ☐

Inspected By:

Project ID:

Project Name:

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Comments for Crew

Sub-Division:

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address			
X Coord	Y Coord	General Location	
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339	Doan Brook	
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO			
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

10/2/2024

also overflow inspections 9-29-2024 0.25'

10:02 AM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

10/2/2024

so overflow inspections 9-29-2024 0.25'

10:02 AM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

10/2/2024

iso overflow inspections 9-29-2024 0.25'

10:02 AM

Work Order Assets

Object Type		Description 1			Description 2		Completed
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	
Sewer Control Valve					FAIRFAX AT NORTH PARK	26	
SSO 431							
Sewer Control Valve					NORTH PARK AND COVENTRY	16	
SSO 114							
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH	35	
SSO 121							
Sewer Structure						3094	
SA16AAWB0							
Sewer Control Valve					FAIRMOUNT AT FAIRFAX	7	
SSO 112							
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6	
SSO 99							
Sewer Control Valve					3012 NORTH WOODLAND	14	
SSO 432							
Sewer Control Valve						55	
DB-03							
Sewer Control Valve						56	
DB-01							
Sewer Control Valve						57	
DB-02							
Sewer Control Valve					FAIRMOUNT AT DARTMOOR	5	
CH-04							
Sewer Control Valve					FAIRMOUNT AT WELLINGTON	44	
SSO 110							
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33	
SSO 87							
Sewer Control Valve					FAIRMOUNT AT MARLBORO	4	
SSO 116							
Sewer Control Valve					FAIRMOUNT AT ARLINGTON	46	
SSO 111							
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)	37	
SSO 113							
Sewer Control Valve					FAIRMOUNT AND COVENTRY	47	
SSO 124							
Sewer Control Valve					SCARBOROUGH AT LAMBERTON	53	
CH-50							
Sewer Control Valve					BRADFORD AND LEE	11	
SSO 129							
Sewer Control Valve					EDDINGTON	2	
CH-52							
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")	42	
SSO 88							
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL	36	
SSO 122							
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")	34	
SSO 89							
Sewer Structure						1536	
SA16ADZB0							
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.	20	
SSO 91							
Sewer Structure						4446	
SA16ADPH0							
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON	8	
SSO 120							
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY	19	
SSO 103							
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD	15	
SSO 104							

Work Order Detail Report

10/2/2024

so overflow inspections 9-29-2024 0.25'

10:02 AM

Sewer Structure		
SA16AGMG0		3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F	
CH-30		52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.	
DV-11		9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE	
SSO 108		22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND	
SSO 106		43
Sewer Control Valve	1685 CUMBERLAND	
SSO 95		18
Sewer Control Valve	CUMBERLAND/SOMERTON	
SSO 105		30
Sewer Structure		
SA16AQQD0		4987
Sewer Structure		
SA16AQQC0		3745
Sewer Control Valve	2225 NOBLE ROAD	
SSO 102		3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF	
SSO 107		38
Sewer Control Valve	LANGTON AND ATHERSTONE	
CH-51		54
Sewer Structure		
SA16APEF0		1809

Work Order Detail Report

10/2/2024

iso overflow inspections 9-29-2024 0.25'

10:02 AM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	10/1/2024/ 2:54 pm	10/1/2024
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	10/1/2024/ 2:55 pm	10/1/2024
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	10/1/2024/ 2:55 pm	10/1/2024
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	10/1/2024/ 2:56 pm	10/1/2024
5	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	10/1/2024/ 2:56 pm	10/1/2024
6	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	10/1/2024/ 2:56 pm	10/1/2024
7	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	10/1/2024/ 2:57 pm	10/1/2024
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	10/1/2024/ 2:57 pm	10/1/2024
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	10/1/2024/ 2:57 pm	10/1/2024
10	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	10/1/2024/ 2:57 pm	10/1/2024
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	10/1/2024/ 2:58 pm	10/1/2024
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	10/1/2024/ 2:58 pm	10/1/2024
13	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	10/1/2024/ 2:55 pm	10/1/2024
Couldn't find					
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	10/1/2024/ 2:58 pm	10/1/2024
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	10/1/2024/ 2:59 pm	10/1/2024
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	10/1/2024/ 2:59 pm	10/1/2024
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	10/1/2024/ 2:59 pm	10/1/2024
18	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	☐	Sound	10/1/2024/ 3:00 pm	10/1/2024
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	10/1/2024/ 3:00 pm	10/1/2024
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	10/1/2024/ 3:00 pm	10/1/2024
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	10/1/2024/ 3:01 pm	10/1/2024
22	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	10/1/2024/ 3:01 pm	10/1/2024
23	B-13-HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Not Sound	10/1/2024/ 3:01 pm	10/1/2024
Reset					
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	10/1/2024/ 3:02 pm	10/1/2024
25	B-42 12537 CEDAR SA16ACZA0	☐	Sound	10/1/2024/ 3:03 pm	10/1/2024
26	B-15 COVENTRY AND CEDAR SA16ADBHO	☐	Sound	10/1/2024/ 3:03 pm	10/1/2024
27	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	10/1/2024/ 3:03 pm	10/1/2024
28	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	10/1/2024/ 3:03 pm	10/1/2024
Couldn't locate					

sso overflow inspections 9-29-2024 0.25'

29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	10/1/2024/ 3:05 pm	10/1/2024
Couldn't locate					
30	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	10/1/2024/ 3:05 pm	10/1/2024
31	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	10/1/2024/	10/1/2024
32	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	10/1/2024/ 3:07 pm	10/1/2024
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	10/1/2024/ 3:07 pm	10/1/2024
34	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	10/1/2024/ 3:07 pm	10/1/2024
Needsblock					
35	C-55 3593 FENLEY SA16APEH0	☐	Sound	10/1/2024/ 3:08 pm	10/1/2024

Tasks/Resources

SMCT36 Inspection

Crew:

Supervisor:

Employee

Status:

UOM: Each

*Cal'c UC: \$5.51

of Units: 35.00

*Task Cost: \$192.90

*Unit Cost: \$0.00

Start Dt: 10/1/2024

End Dt: 10/1/2024

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	5.00	\$125.90		10/1/2024	10/1/2024

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	5.00	\$67.00		10/1/2024	10/1/2024

Task Comment: sso overflow inspections 9-29-2024 0.25'

Projected Complete:

Repair Type:

Subcontractor:

Profit Center:

Lock: ☐

WO Duration

Labor Hours

Labor Costs

Material Costs

Fluids Costs

Equipment Costs

Contractor Costs

Misc. Costs

Total Costs

Use Task Info:

Quantity: 0.00

Unit of Measure: Each

Unit Cost: \$0.00

NO Hours: 0.00

Lock: ☐

6.00

5.00

\$125.90

0.00

0.00

67.00

0.00

0.00

\$192.90

True

*Actual

*Estimated

*Difference

0.00

0.00

\$0.00

0.00

0.00

0.00

0.00

0.00

\$0.00

True

Billing

Billed Party

Customer ID:

Customer Name:

Address:

City:

State:

Zip:

Customer Number:

Last Name:

Phone:

Fax #:

E-mail:

Cell #:

Billing Data

Contact Name:

Invoice Number:

Incoming Account #:

*Billing Amount:

Date Bill Sent:

Payment Received:

Payment Method:

Billing Required: ☐

Billing Processed: ☐

Imported to Financials: ☐

Associated PMs

PM Code and Description	Closed
SSO-02 SSO INSPECTION	☒

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	10/1/2024	2:11 PM
Supervisor Notification	Email Queued Successfully!	jjackson	10/1/2024	2:11 PM

Work Order Detail Report

10/2/2024

iso overflow inspections 9-29-2024 0.25'

10:02 AM

Rate:

Received By:

Work From:

Pipe Size:

Pipe Condition:

Could Not Open:

Additional Repair:

Dye Test Reason:

Test Performed Throug

Dye Test Results:

NO User 51:

Measurement:

History:

Manhole Basin Repair:

Material Used:

Pipe Repair:

Street Repair:

Grass Repair:

Curb Repair:

Driveway- Sidewalk Re

Construction Crew:

NO User 39:

NO User 40:

NO User 41:

NO User 52:

NO User 53:

NO User 54:

NO User 55:

NO User 56:

NO User 57:

NO User 58:

NO User 59:

NO User 60:

NO User 61:

NO User 72:

NO User 73:

NO User 74:

NO User 75:

NO User 76:

NO User 92 Date:

NO User 93 Date:

NO User 94 Date:

NO User 95 Date:

NO User 96 Date:

NO User 77:

NO User 78:

NO User 79:

NO User 80:

NO User 81:

NO Creator:

Opened At:

Pipe Footage Cleaned

Gallons Used:

WO User 23:

WO User 24:

WO User 9:

User 10:

Appointment Date DNL

Appointment Date:

E Mail:

Measurement Line 2:

Pipe Size:

PVC Tees, Angles, Slee

WO User 44:

WO User 45:

WO User 46:

OUPS #:

WO User 48:

WO User 62:

WO User 63:

WO User 64:

WO User 65:

WO User 66:

WO User 67:

WO User 68:

WO User 69:

WO User 70:

WO User 71:

WO User 82:

Quantity:

WO User 84:

WO User 85:

WO User 86:

WO User 97 Date:

WO User 98 Date:

WO User 99 Date:

WO User 100 Date:

WO User 101 Date:

WO User 87:

WO User 88:

WO User 89:

WO User 90:

WO User 91:

WO User 107:

WO User 108:

WO User 109:

WO User 110:

WO User 111:

WO Creation Date:

10/1/2024

PM Trigger:

Televised:

Power Rooter:

Jet:

Gap Vac:

Dye Test:

Gap Root Cut:

GIS Correction?:

Test Tee Correction:

Televised:

Paid:

WO User 104:

WO User 105:

WO User 106:

Rec #:

15844