



Then / Now Photo Comparison


Scanned Photos of Park Synagogue from the Western Reserve Historical Society Archive Compared to Present Day Photos to Identify Alternations over time for the Historic Preservation.

By David Craun, AIA, Cleveland Planning Advisors, LLC, Owner Representative Services

03 29 2024 DRAFT | XX XX XXXX UPDATE



Park Synagogue
Mendelsohn Restoration



Historic Photo c.1950



Present Day Photo


HISTORIC ALTERATIONS


- 1. Added Site Walls for Ramp
- 2. Bridge Addition*
- 3. Elevator Addition
- 4. Non-Period Window Replacement
- 5. Facade Lighting
- 6. AC Unit in Window
- 7. Thickened Fascia

*1968 Bridge and Kangesser Hall addition.
Note: landscape alternations not included.



Reference photos of ramp alternation.





Historic Photo c.1950

HISTORIC ALTERATIONS



- 1. ADA Ramp Over Stairs
- 2. Step Lighting
- 3. Ramp/Garden Wall
- 4. Stair Handrails
- 5. Thickened Fascia
- 6. Roof lighting
- 7. Double-Thick Fascia
- 8. Exposed Electrical

Note: landscape alternations not included.

Incomplete Elements In Historic Photo:

- Sacred Letters in Copula
- Sacred Words Above Entry
- Patterned Grills Over Glass

Reference drawings/photos of ADA ramp.



Present Day Photo



Present Day Photo



Park Synagogue
Mendelsohn Restoration

Exterior Temple Entry View
Then / Now Photo Comparison | 03 29 2024



Park Synagogue
Mendelsohn Restoration

Exterior Temple Entry View
Then / Now Photo Comparison | 03 29 2024



Historic Photo c.1955



Present Day Photo



HISTORIC ALTERATIONS


- 1. Ramp Over Stairs
- 2. Stair/Ramp Handrails
- 3. Knox Box for CHFD
- 4. Historic Building Marker
- 5. Double-Thick Fascia

Note: landscape alternations not included.



Reference photos of entry interior.





Historic Photo c.1955

HISTORIC ALTERATIONS

- 1. Site Lighting Poles
- 2. Stair Handrails
- 3. Ramp Over Entry Stairs
- 4. Enlarged Facade Vent
- 5. Roof lighting
- 6. Double-Thick Fascia
- 7. Enlarged Service Panel
- 8. Facade Lighting
- 9. Chase Under Roof


Note: landscape alternations not included.



Enlarged detail photos for reference.



Present Day Photo



Present Day Photo



Historic Photo c.1970



Present Day Photo




HISTORIC ALTERATIONS

- 1. Site Lighting Poles
- 2. Ramp Over Entry Stairs
- 3. Double-Thick Fascia
- 4. Facade Lighting
- 5. Chase Under Roof
- 6. Courtyard Storage Addition*


*2003 Storage addition removed large window and converted a public connection to courtyard into a janitorial/service entry.

Note: landscape alternations not included



Enlarged photos and drawing/photos of storage room addition for reference.





Historic Photo c.1955




Present Day Photo


HISTORIC ALTERATIONS

- 1. Paving Infill of Circular Lawn Area
- 2. Removal of Existing Trees*
- 3. Addition of Non-period Fixtures
- 4. Change in Concrete Pattern/Shape
- 5. Inconsistent Perimeter Plantings
- 6. Thickened Fascia

*According to Mendelsohn’s design drawings, existing trees were to remain at random locations in the courtyard. The two remaining trees appear to be original.



Reference drawing/photos of courtyard from c1955 to present.





Historic Photo c.1950



Present Day Photo

HISTORIC ALTERATIONS

- 1. Removal of Curtains
- 2. Non-Period Lighting Fixtures
- 3. Enlarged HVAC Diffusers
- 4. Repositioned Flush Doors
- 5. Removal of Projection Windows

Incomplete Elements In Historic Photo:

- Sliding partition wall for ballroom
- Wood cladding at corner behind curtain
- School wing under construction



Enlarged detail photos for reference.





Historic Photo c.1955



Present Day Photo

Park Synagogue
Mendelsohn Restoration


Interior Foyer Sitting Area
Then / Now Photo Comparison | 03 29 2024

HISTORIC ALTERATIONS

1. Added Floor Outlet
2. Enlarged Opening to Elevator Lobby*
3. Added Hood Over Wall Heater
4. Original Signage Moved from Entry
5. Removal of Curtains
6. Non-Period & Added Lighting Fixtures
7. Added HVAC Diffuser
8. Added Exposed Electrical
9. Added Security Camera

*1998 Renovation of former men's restroom to lobby for elevator addition.

Reference photos of lounge area with enlarged opening to elevator lobby.



Park Synagogue
Mendelsohn Restoration

Interior Foyer Sitting Area
Then / Now Photo Comparison | 03 29 2024



Historic Photo c.1955



Present Day Photo


HISTORIC ALTERATIONS

1. Original Signage Moved for Memorial
2. Removal of Curtains
3. Non-Period Lighting Fixtures
4. Enlarged HVAC Diffusers
5. Removal of Speaker [Organ Tone Box]
6. Enlarged Opening to Elevator Lobby

Note: the original ceramic tile artwork shown on the wall of the historic photo has been relocated to the lobby of the administration wing.



Enlarged detail photos for reference.





Historic Photo c.1955



Present Day Photo

Park Synagogue

Mendelsohn Restoration


Interior Ark Elevation

Then / Now Photo Comparison | 03 29 2024




HISTORIC ALTERATIONS

1. Expanded List of Names in Memoriam



Enlarged historic c1955 and present detail photos for reference.



Park Synagogue

Mendelsohn Restoration

Interior Ark Elevation

Then / Now Photo Comparison | 03 29 2024





Historic Photo c.1950




Present Day Photo

HISTORIC ALTERATIONS

- 1. Non-Period Replacement Windows
- 2. Former Door Closed In
- 3. Enlarged HVAC Diffusers
- 4. Added Return Air Vents
- 5. Added Non-Period Lighting Fixtures

Incomplete Elements In Historic Photo:

- Decorative Grille Over Ark Speaker
- Decorative Metal *Shin* on Ark Doors
- Decorative Metal Hands on Lectern
- Menorah Candelabras



Enlarged historic c1955 and present detail and approach photos for reference.






Historic Photo c.1950




Present Day Photo

HISTORIC ALTERATIONS

- 1. Added Window Shades
- 2. Removal of Privacy Curtains
- 3. Added Return Air Vents
- 4. Enlarged HVAC Diffusers
- 5. Added Non-Period Lighting Fixtures
- 6. Added Dedication Signage
- 7. Added Wall Switches/Controls



Reference photos included for chapel entries, corridor, and conference room.





Historic Photo c.1950




Present Day Photo

HISTORIC ALTERATIONS

- 1. Bridge Addition*
- 2. Added Site Walls for Ramp
- 3. Panic Hardware on Exit Doors
- 4. Ceiling Painted Lighter Color**
- 5. Non-Period Lighting Fixtures
- 6. Added Stair Handrail

*1968 Bridge and Kangesser Hall Addition.

**Ceiling color appears to have originally matched between exterior and interior.



Reference photos included of bridge interior.





Historic Photo c.1950



Present Day Photo


HISTORIC ALTERATIONS

- 1. Knox Box for CHFD
- 2. Bridge Addition*
- 3. Discolored Wood Panel
- 4. Added Handrail
- 5. Motion Detector & Security Camera
- 6. Non-Period Ceiling Signage Feature
- 7. Non-Period Lighting Fixtures
- 8. Window System Altered for Doors
- 9. Curtains of Office in Bridge
- 10. Elevator Addition**
- 11. Slip-Resistant Pads on Stairs
- 12. Handrail Replaced with ADA Lift

*1968 Bridge and Kangesser Hall Addition.

**1998 Elevator Addition

Reference photos/drawing of elevator addition between main and ground floors.





Historic Photo c.1955



Present Day Photo

HISTORIC ALTERATIONS

- 1. Replaced Wood Paneling
- 2. Wood Cove Lighting
- 3. Added Hood Over Wall Heater
- 4. Enlarged HVAC Diffusers
- 5. Non-Period Lighting Fixtures
- 6. Removed Curtains
- 7. Panic Door Hardware



Reference photos/drawings of former
“Mens Club Parlor” & “Sisterhood Parlor”.





Historic Photo c.1950



Present Day Photo

HISTORIC ALTERATIONS

- 1. Removed Millwork Doors
- 2. Non-Period Lighting Fixtures
- 3. Alarm Device with Exposed Conduit
- 4. Removed Drinking Fountain



Additional photos of coat check for reference.





Historic Photo c.1955



Present Day Photo

HISTORIC ALTERATIONS

- 1. Window Blinds Replaced Curtains
- 2. Added Storefront System
- 3. Added Dedication Plaque
- 4. Non-Period Lighting Fixture
- 5. Added *Shin* Decorative Grill
- 6. Added Mirror Glass at Display
- 7. Replaced Wood Paneling
- 8. Non-Period Exit Sign



Additional photos of administration entry and reception for reference.





Historic Photo c.1955



Present Day Photo

HISTORIC ALTERATIONS

- 1. Added HVAC Ceiling Return Air
- 2. Removed Privacy Curtains
- 3. Added HVAC Wall Diffuser
- 4. Removed Lighting Fixture Reflector
- 5. Removed Built-In Desk



Additional photos of the former Rabbi's office for reference.





Historic Photo c.1955

HISTORIC ALTERATIONS

1. Non-Period Lighting Fixtures
2. Casework Blocking Door
3. Added Radiators
4. Added Electrical Outlets
5. Removed Built-In Desk



Additional photos of Library for reference.



Present Day Photo



Park Synagogue

Mendelsohn Restoration

Interior Library View

Then / Now Photo Comparison | 03 29 2024

Park Synagogue

Mendelsohn Restoration

Interior Library View

Then / Now Photo Comparison | 03 29 2024




Historic Photo c.1955



Present Day Photo

HISTORIC ALTERATIONS

- 1. Enlarged HVAC Diffusers
- 2. Added ACT Ceiling in Lighting Coves
- 3. Removed Wall-Mounted Speakers



Additional photos of Glass Auditorium stage and drawing/photo of the lighting coves in the lobby and auditorium for reference.

