

CITY OF  
**CLEVELAND  
HEIGHTS**   
LAW DEPARTMENT

September 11, 2023

***Via E-Mail:*** [vezner.kris@epa.gov](mailto:vezner.kris@epa.gov) and [Berger.Jake@epa.gov](mailto:Berger.Jake@epa.gov)

Kris P. Vezner, Esq.  
Associate Regional Counsel  
U.S. Environmental Protection Agency  
Region 5 (C-14J)  
77 West Jackson Blvd.  
Chicago, IL 60604

and

Jake Berger  
Physical Scientist  
Water Enforcement & Compliance Assurance Branch  
U.S. Environmental Protection Agency  
77 W. Jackson Blvd.  
Mail Code ECW-15J  
Chicago, IL 60604

Re: August 2023 Overflow Monitoring Reports  
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through August 31, 2023, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.


Very truly yours,

  
William R. Hanna  
Director of Law

Enclosures

cc: Thomas Benson, Esq., EPA Attorney  
James Vinch, Esq., EPA Attorney  
James Zimny, EPA Engineer  
U.S. EPA Region 5 Water Enforcement Branch  
Mark Klingenstein, Environmental Engineer  
Erm Gomes, Ohio EPA  
Allison Cycyk, Ohio EPA  
Casey Galligan, Ohio EPA  
David Brumbaugh, Ohio EPA  
Bill Fischbein, Ohio EPA  
Kahlil Seren, Mayor  
Collette Clinkscale, Director of Public Works  
Steve Barker, Public Relations  
Anthony Ferrone, Utilities Commissioner  
Kevin Vander Tuig, P.E. (Outside Engineer)  
Mathew St. Pierre, (Outside Engineer)  
Dan Porter (Outside Engineer)  
Cindy Biacofsky (Outside Engineer)  
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northeast Ohio  
Regional Sewer District**



## Northeast Ohio Regional Sewer District

### Daily Precipitation Report

Monday, August 7, 2023

Point Accumulation (Inches)						
Site Location	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.57	0.47	0.27	0.23	0.10	0.05
Brecksville	0.88	0.78	0.69	0.60	0.29	0.14
Brook Park	1.30	1.25	1.01	0.95	0.48	0.24
Cleveland Industrial Pkwy	0.71	0.69	0.62	0.57	0.29	0.16
Dillie Ave PS	0.91	0.90	0.89	0.84	0.49	0.23
Division Ave PS	0.64	0.64	0.63	0.58	0.29	0.14
Easterly WWTP	0.84	0.84	0.84	0.79	0.50	0.19
Independence	0.50	0.39	0.31	0.20	0.12	0.08
James Rhodes HS	1.27	1.26	1.12	1.06	0.49	0.19
Jennings PS	1.05	1.03	0.94	0.88	0.44	0.19
Macedonia	0.49	0.46	0.43	0.36	0.20	0.10
Maple Heights	0.41	0.34	0.27	0.18	0.10	0.05
Mary Street PS	0.93	0.92	0.92	0.87	0.46	0.17
Mayfield Heights	0.47	0.41	0.39	0.28	0.15	0.11
Moreland Hills	0.55	0.49	0.36	0.20	0.15	0.08
North Olmsted	0.35	0.33	0.32	0.19	0.08	0.07
North Royalton	0.96	0.68	0.51	0.33	0.17	0.09
Oakwood	0.91	0.87	0.73	0.55	0.36	0.25
Olmsted Falls	0.83	0.80	0.52	0.48	0.21	0.10
Parma	1.16	1.14	1.07	1.00	0.54	0.26
Richfield	0.43	0.38	0.34	0.31	0.23	0.19
Shaker Heights	0.79	0.69	0.54	0.47	0.29	0.18
South Euclid	0.69	0.68	0.67	0.60	0.24	0.12
Southerly WWTC	1.14	1.00	0.85	0.73	0.34	0.16
Strongsville Foltz	1.52	1.46	1.37	1.33	0.53	0.24
Strongsville C WWTP	1.21	1.18	1.16	1.11	0.61	0.24
University Heights	0.90	0.83	0.77	0.67	0.43	0.29
Wade Park	0.98	0.97	0.97	0.91	0.49	0.20
Westerly WWTP	0.57	0.56	0.56	0.51	0.30	0.13
Westlake	0.48	0.46	0.46	0.26	0.16	0.08

## Work Order Detail Report

8/8/2023

sso inspections 8-8-2023 0.90'

2:32 PM

WO Number:	230808-0001	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	8/8/2023 2:31 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	8/8/2023 8:00 AM
Lead Worker:	Manco, Angelo	End Date:	8/8/2023 2:30 PM
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

### Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

#### Location

Department: Sewer Collection  
Division: Sewer

#### Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations				
Address	X Coord	Y Coord	Address 2	General Location
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook	
	2,226,440.21168265	664,329.55524255		
	2,226,354.79813956	664,409.89202413		
	2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON	2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO	2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

## Work Order Detail Report

8/8/2023

sso inspections 8-8-2023 0.90'

2:32 PM

FAIRMOUNT AT ARLINGTON  
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH  
FAIRMOUNT & COVENTRY (SCARBOROUGH)  
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH  
FAIRMOUNT AND COVENTRY  
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH  
SCARBOROUGH AT LAMBERTON  
2,221,598.28993607 666,996.61322863  
MONMOUTH, EAST OF DARTMOOR  
2,225,152.08663423 665,499.19660404 DOAN BROOK  
BRADFORD AND LEE  
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH  
EDDINGTON  
2,221,299.08384156 674,932.84604380  
HAMPSHIRE LANE AT MAYFIELD (18")  
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH  
EAST OVERLOOK AT EDGEHILL  
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH  
HAMPSHIRE LANE AT MAYFIELD (36")  
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH  
2600 HAMPSHIRE RD  
  
HAMPSHIRE AT EUCLID HTS. BLVD.  
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH  
CEDAR BTW. FAIRMOUNT/DEMINGTON  
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH  
2828 BERKSHIRE, EAST OF COVENTRY  
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH  
3003 EUCLID HEIGHTS BLVD  
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH  
South Taylor between Antisdale Ave and Superior Rd  
2,227,113.30810548 671,276.67684697  
LEE RD. & SUPERIOR AVE.  
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA  
EUCLID HEIGHTS BLVD AND LEE  
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH  
EUCLID HEIGHTS BLVD/CUMBERLAND  
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH  
1685 CUMBERLAND  
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH  
CUMBERLAND/SOMERTON  
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH  
2225 NOBLE RD  
  
2225 NOBLE ROAD  
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH  
QUILLIAMS, N. OF RANDOLF  
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH  
LANGTON AND AATHERSTONE  
2,228,126.76638040 684,188.23206055  
  
2,220,777.89623564 666,181.72575080  
  
2,218,501.67473823 671,997.54581206  
  
2,216,759.55453481 670,474.59347738  
  
2,224,536.21778722 668,887.44048372  
  
2,226,741.35609348 679,432.95121680  
  
2,226,591.76420106 679,420.92761880

---

**Work Order Detail Report**

sso inspections 8-8-2023 0.90'

8/8/2023

2:32 PM

2,227,825.14395215 684,881.15948047

## Work Order Detail Report

8/8/2023

sso inspections 8-8-2023 0.90'

2:32 PM

### Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>Asset ID</u>	<u>Completed</u>
			<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>
Sewer Control Valve					FAIRFAX AT NORTH PARK	
SSO 431					26	
Sewer Control Valve					NORTH PARK AND COVENTRY	
SSO 114					16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH	
SSO 121					35	
Sewer Structure					3094	
SA16AAWB0						
Sewer Control Valve					FAIRMOUNT AT FAIRFAX	
SSO 112					7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
SSO 99					6	
Sewer Control Valve					3012 NORTH WOODLAND	
SSO 432					14	
Sewer Control Valve						
DB-03					55	
Sewer Control Valve						
DB-01					56	
Sewer Control Valve						
DB-02					57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR	
CH-04					5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON	
SSO 110					44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
SSO 87					33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO	
SSO 116					4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON	
SSO 111					46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)	
SSO 113					37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY	
SSO 124					47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON	
CH-50					53	
Sewer Control Valve					BRADFORD AND LEE	
SSO 129					11	
Sewer Control Valve					EDDINGTON	
CH-52					2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")	
SSO 88					42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL	
SSO 122					36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")	
SSO 89					34	
Sewer Structure						
SA16ADZB0					1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.	
SSO 91					20	
Sewer Structure						
SA16ADPH0					4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON	
SSO 120					8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY	
SSO 103					19	
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD	
SSO 104					15	

## Work Order Detail Report

8/8/2023

2:32 PM

sso inspections 8-8-2023 0.90'

Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior F 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

**Work Order Detail Report**

8/8/2023

sso inspections 8-8-2023 0.90'

2:32 PM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Not Sound	/	
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Not Sound	/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	/	
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	/	
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	/	
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Not Sound	/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	/	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	/	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Not Sound	/	8/8/2023
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Not Sound	/	
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	/	
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	/	

## Work Order Detail Report

8/8/2023

2:32 PM

sso inspections 8-8-2023 0.90'

30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Not Sound	/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Not Sound	/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	/
38	C-25 CUMBERLAND AND SOMERTON SA16AISAO	<input type="checkbox"/>	Sound	/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	/
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOQU0	<input type="checkbox"/>	Not Sound	/
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	/
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	/
46		<input type="checkbox"/>	Sound	/

### Tasks/Resources

#### SMCT36 Inspection

Crew: **Status:** \*Cal'c UC: \$5.98 \*Task Cost: \$269.28 Start Dt: 8/8/2023  
Supervisor: **UOM:** Each # of Units: 45.00 \*Unit Cost: \$0.00 End Dt: 8/8/2023

### Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
19356 Manco, Angelo	Hours	6.00	\$163.38		8/8/2023	8/8/2023

### Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB 9	Hours	6.00	\$105.90		8/8/2023	8/8/2023

Task Comment: sso overflow inspections 8-8-2023 0.90'

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	6.50	0.00	0.00
Subcontractor:		Labor Costs	\$163.38	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	105.90	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$269.28	\$0.00	\$0.00
		Use Task Info:	True	True	

# Work Order Detail Report

8/8/2023

sso inspections 8-8-2023 0.90'

2:32 PM

<b>Billed Party</b>		<b>Billing</b>	
Customer ID: Customer Name: Address: City: State: Zip:		Customer Number: Last Name:  Phone: Fax #: E-mail:	
Contact Name: Invoice Number: Incoming Account #:		*Billing Amount: Date Bill Sent: Payment Received: Payment Method:	Cell #:  Billing Required: <input type="checkbox"/> Billing Processed: <input type="checkbox"/> Imported to Financials: <input type="checkbox"/>

<b>Associated PMs</b>		<b>PM Code and Description</b>	<b>Closed</b>
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

<b>Tracking</b>		<b>Description</b>	<b>By</b>	<b>Date</b>	<b>Time</b>
Item					
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	jjackson	8/8/2023	6:54 AM
Supervisor Notification		Email Queued Successfully!	jjackson	8/8/2023	6:54 AM
Leadworker Notification		Email Queued Successfully!	jjackson	8/8/2023	6:55 AM
Status Change		From New Work Order to Closed In Field	amanco	8/8/2023	1:57 PM
Status Change		From Closed In Field to Complete	jjackson	8/8/2023	2:31 PM

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 8/8/2023	8:00 AM
Dye Test Results:		

WO User 51:	E Mail:
Measurement:	Measurement Line 2:
History:	

Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Slect
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:
Curb Repair:	
Driveway- Sidewalk Re:	
Construction Crew:	
WO User 39:	
WO User 40:	OUPS #:
WO User 41:	WO User 48:

WO User 52:	WO User 62:
WO User 53:	WO User 63:
WO User 54:	WO User 64:
WO User 55:	WO User 65:
WO User 56:	WO User 66:
WO User 57:	WO User 67:
WO User 58:	WO User 68:
WO User 59:	WO User 69:
WO User 60:	WO User 70:
WO User 61:	WO User 71:

## Work Order Detail Report


8/8/2023

sso inspections 8-8-2023 0.90'

2:32 PM

WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 8/8/2023	PM Trigger:	Rec #: 13928

 **Northeast Ohio  
Regional Sewer District**



## Northeast Ohio Regional Sewer District

### Daily Precipitation Report

Saturday, August 12, 2023

Site Location	Peak Accumulation (Inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	1.08	1.01	0.79	0.69	0.50
Brecksville	0.45	0.25	0.25	0.17	0.09
Brook Park	0.31	0.26	0.26	0.17	0.12
Cleveland Industrial Pkwy	0.85	0.70	0.70	0.50	0.47
Dille Ave PS	0.84	0.79	0.74	0.57	0.37
Division Ave PS	1.31	1.19	1.05	0.92	0.67
Easterly WWTP	0.67	0.65	0.65	0.48	0.31
Independence	1.02	0.59	0.59	0.33	0.27
James Rhodes HS	0.81	0.70	0.70	0.48	0.44
Jennings PS	0.77	0.65	0.65	0.44	0.34
Macedonia	0.56	0.40	0.40	0.37	0.30
Maple Heights	1.20	0.83	0.83	0.64	0.45
Mary Street PS	1.03	0.97	0.89	0.65	0.44
Mayfield Heights	1.58	1.55	1.36	1.19	0.50
Moreland Hills	0.90	0.48	0.48	0.31	0.29
North Olmsted	0.59	0.56	0.55	0.29	0.25
North Royalton	0.64	0.40	0.40	0.29	0.26
Oakwood	0.70	0.49	0.49	0.28	0.24
Olmsted Falls	0.31	0.23	0.23	0.20	0.12
Parma	0.54	0.38	0.38	0.27	0.17
Richfield	0.63	0.46	0.46	0.35	0.29
Shaker Heights	0.53	0.50	0.49	0.35	0.18
South Euclid	1.09	1.05	0.79	0.58	0.33
Southerly WWTC	0.84	0.62	0.62	0.47	0.42
Strongsville CWWTP	0.40	0.26	0.26	0.24	0.13
Strongsville Foltz	0.52	0.36	0.35	0.21	0.18
University Heights	2.32	2.18	1.67	1.18	0.85
Wade Park	1.41	1.35	1.07	0.84	0.60
Westerville WWTP	1.05	0.94	0.90	0.82	0.58
Westlake	1.49	1.45	1.45	1.07	0.68

## Work Order Detail Report

8/16/2023

sso inspections 8-15-2023 - 2.32

9:06 AM

WO Number:	230815-0002	Category:	SSOs
Status:	New Work Order	Problem:	Storm Response
Status Date:	8/15/2023 7:18 am	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	8/15/2023 8:00 AM
Lead Worker:	Cardarella, Joe	End Date:	8/15/2023 2:30 PM
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

### Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

#### Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

#### Maintenance Zone:

#### Alternate Zone:

#### Work Order Locations

#### Address 2

<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>	<u>Address 2</u>
FAIRFAX AT NORTH PARK				
2,220,655.65435414	665,517.24643672		Doan Brook	
NORTH PARK AND COVENTRY				
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH				
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX				
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)				
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND				
2,222,845.06631389	664,689.08536339		Doan Brook	
2,226,440.21168265	664,329.55524255			
2,226,354.79813956	664,409.89202413			
2,226,389.92077273	664,379.07548472			
FAIRMOUNT AT DARTMOOR				
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON				
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)				
2,223,111.44143730	664,794.46048072		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO				
2,221,638.88762389	665,726.15513962		DOAN BROOK - MAIN BRANCH	

#### Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

**Work Order Detail Report**

8/16/2023

sso inspections 8-15-2023 - 2.32

9:06 AM

FAIRMOUNT AT ARLINGTON  
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH  
FAIRMOUNT & COVENTRY (SCARBOROUGH)  
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH  
FAIRMOUNT AND COVENTRY  
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH  
SCARBOROUGH AT LAMBERTON  
2,221,598.28993607 666,996.61322863  
MONMOUTH, EAST OF DARTMOOR  
2,225,152.08663423 665,499.19660404 DOAN BROOK  
BRADFORD AND LEE  
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH  
EDDINGTON  
2,221,299.08384156 674,932.84604380  
HAMPSHIRE LANE AT MAYFIELD (18")  
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH  
EAST OVERLOOK AT EDGEHILL  
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH  
HAMPSHIRE LANE AT MAYFIELD (36")  
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH  
2600 HAMPSHIRE RD  
  
HAMPSHIRE AT EUCLID HTS. BLVD.  
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH  
CEDAR BTW. FAIRMOUNT/DEMINGTON  
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH  
2828 BERKSHIRE, EAST OF COVENTRY  
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH  
3003 EUCLID HEIGHTS BLVD  
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH  
South Taylor between Antisdale Ave and Superior Rd  
2,227,113.30810548 671,276.67684697  
LEE RD. & SUPERIOR AVE.  
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA  
EUCLID HEIGHTS BLVD AND LEE  
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH  
EUCLID HEIGHTS BLVD/CUMBERLAND  
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH  
1685 CUMBERLAND  
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH  
CUMBERLAND/SOMERTON  
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH  
2225 NOBLE RD  
  
2225 NOBLE ROAD  
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH  
QUILLIAMS, N. OF RANDOLF  
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH  
LANGTON AND AATHERSTONE  
2,228,126.76638040 684,188.23206055  
  
2,220,777.89623564 666,181.72575080  
  
2,218,501.67473823 671,997.54581206  
  
2,216,759.55453481 670,474.59347738  
  
2,224,536.21778722 668,887.44048372  
  
2,226,741.35609348 679,432.95121680  
  
2,226,591.76420106 679,420.92761880

---

**Work Order Detail Report**

sso inspections 8-15-2023 - 2.32

8/16/2023

9:06 AM

---

2,227,825.14395215 684,881.15948047

## Work Order Detail Report

8/16/2023

sso inspections 8-15-2023 - 2.32

9:06 AM

### Work Order Assets

Object Type	System ID 1	System ID 2	Description 1	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve							FAIRFAX AT NORTH PARK		
SSO 431							26		
Sewer Control Valve							NORTH PARK AND COVENTRY		
SSO 114							16		
Sewer Control Valve							FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121							35		
Sewer Structure							3094		
SA16AAWB0							FAIRMOUNT AT FAIRFAX		
Sewer Control Valve							7		
SSO 112							FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
Sewer Control Valve							6		
SSO 99							3012 NORTH WOODLAND		
Sewer Control Valve							14		
SSO 432							55		
Sewer Control Valve							56		
DB-03							57		
Sewer Control Valve							FAIRMOUNT AT DARTMOOR		
DB-01							5		
Sewer Control Valve							FAIRMOUNT AT WELLINGTON		
DB-02							44		
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
CH-04							33		
Sewer Control Valve							FAIRMOUNT AT MARLBORO		
SSO 110							4		
Sewer Control Valve							FAIRMOUNT AT ARLINGTON		
SSO 87							46		
Sewer Control Valve							FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 116							37		
Sewer Control Valve							FAIRMOUNT AND COVENTRY		
SSO 111							47		
Sewer Control Valve							SCARBOROUGH AT LAMBERTON		
SSO 113							53		
Sewer Control Valve							BRADFORD AND LEE		
SSO 124							11		
Sewer Control Valve							EDDINGTON		
CH-50							2		
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 129							42		
Sewer Control Valve							EAST OVERLOOK AT EDGEHILL		
CH-52							36		
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 88							34		
Sewer Control Valve							1536		
SSO 122							SCARBOROUGH AT EUCLID HTS. BLVD.		
Sewer Control Valve							20		
SSO 89							4446		
Sewer Structure							CEDAR BTW. FAIRMOUNT/DEMINGTON		
SA16ADZB0							8		
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY		
SSO 91							19		
Sewer Structure							3003 EUCLID HEIGHTS BLVD		
SA16ADPH0							15		
Sewer Control Valve									
SSO 120									
Sewer Control Valve									
SSO 103									
Sewer Control Valve									
SSO 104									

## Work Order Detail Report

8/16/2023

sso inspections 8-15-2023 - 2.32

9:06 AM

Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQKD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

## Work Order Detail Report

8/16/2023

sso inspections 8-15-2023 - 2.32

9:06 AM

### Check List

	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	8/15/2023/12:06 pm	8/15/2023
<b>Reset</b>					
2	A-36-NORTH PARK AT COVENTRY SA16ACNBO (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	8/15/2023/12:06 pm	8/15/2023
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	8/15/2023/12:06 pm	8/15/2023
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	8/15/2023/12:07 pm	8/15/2023
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	8/15/2023/12:07 pm	8/15/2023
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	8/15/2023/12:08 pm	8/15/2023
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	8/15/2023/12:08 pm	8/15/2023
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	8/15/2023/12:09 pm	8/15/2023
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	8/15/2023/12:09 pm	8/15/2023
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	8/15/2023/12:09 pm	8/15/2023
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	8/15/2023/12:10 pm	8/15/2023
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/15/2023/12:11 pm	8/15/2023
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	8/15/2023/12:11 pm	8/15/2023
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/15/2023/12:12 pm	8/15/2023
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/15/2023/12:12 pm	8/15/2023
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	8/15/2023/12:13 pm	8/15/2023
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	8/15/2023/12:13 pm	8/15/2023
<b>Reset</b>					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	8/15/2023/12:14 pm	8/15/2023
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	8/15/2023/12:14 pm	8/15/2023
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	8/15/2023/12:15 pm	8/15/2023
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	8/15/2023/	8/15/2023
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	<input type="checkbox"/>	Sound	8/15/2023/12:16 pm	8/15/2023
<b>Monitor</b>					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Not Sound	8/15/2023/12:17 pm	8/15/2023
<b>Reset</b>					
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	8/15/2023/12:17 pm	8/15/2023
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEAO	<input type="checkbox"/>	Sound	8/15/2023/12:18 pm	8/15/2023
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Not Sound	8/15/2023/12:18 pm	8/15/2023
<b>Reset</b>					

## Work Order Detail Report

8/16/2023

sso inspections 8-15-2023 - 2.32

9:06 AM

27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Not Sound	8/15/2023/12:19 pm	8/15/2023
<b>Reset</b>					
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Not Sound	8/15/2023/12:19 pm	8/15/2023
<b>Reset</b>					
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Not Sound	8/15/2023/12:20 pm	8/15/2023
<b>Reset</b>					
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Not Sound	8/15/2023/12:20 pm	8/15/2023
<b>Reset</b>					
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	8/15/2023/12:21 pm	8/15/2023
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Not Sound	8/15/2023/12:22 pm	8/15/2023
<b>Reset</b>					
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	8/15/2023/12:22 pm	8/15/2023
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVFO	<input type="checkbox"/>	Not Sound	8/15/2023/ 2:45 pm	8/15/2023
<b>No block</b>					
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Not Sound	8/15/2023/ 2:45 pm	8/15/2023
<b>Construction zone can't do</b>					
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	8/15/2023/ 2:46 pm	8/15/2023
<b>Reset</b>					
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	8/15/2023/ 2:47 pm	8/15/2023
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Not Sound	8/15/2023/ 2:47 pm	8/15/2023
<b>Reset</b>					
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	8/15/2023/ 2:47 pm	8/15/2023
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	8/15/2023/ 2:48 pm	8/15/2023
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	8/15/2023/ 2:48 pm	8/15/2023
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	8/15/2023/ 2:48 pm	8/15/2023
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Not Sound	8/15/2023/ 2:49 pm	8/15/2023
<b>Reset</b>					
44	C-51 AATHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	8/15/2023/ 2:49 pm	8/15/2023
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	8/15/2023/ 2:51 pm	8/15/2023

### Tasks/Resources

#### SMCT36 Inspection

Crew:	Status:	*Cal'c UC: \$5.08	*Task Cost: \$228.54	Start Dt: 8/15/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 8/15/2023

### Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	6.00	\$148.14		8/15/2023	8/15/2023

### Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	6.00	\$80.40		8/15/2023	8/15/2023

5  
Task Comment: sso inspection 8-12-2023 - 2.32'

# Work Order Detail Report

8/16/2023

sso inspections 8-15-2023 - 2.32

9:06 AM

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	6.50	0.00
Repair Type:			Labor Hours	6.00	0.00
Subcontractor:			Labor Costs	\$148.14	\$0.00
Profit Center:			Material Costs	0.00	0.00
			Fluids Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Equipment Costs	80.40	0.00
Unit of Measure:	Each		Contractor Costs	0.00	0.00
*Unit Cost:	\$0.00		Misc. Costs	0.00	0.00
WO Hours:	0.00		Total Costs	\$228.54	\$0.00
			Use Task Info:	True	True

<b>Billed Party</b>		<b>Billing</b>	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Cell #:	
State:		Fax #:	
Zip:		E-mail:	
<b>Billing Data</b>			
Contact Name:		*Billing Amount:	<input type="checkbox"/> Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/> Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/> Imported to Financials: <input type="checkbox"/>
		Payment Method:	

<b>Associated PMs</b>		<b>PM Code and Description</b>	<b>Closed</b>
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

<b>Tracking</b>					
<b>Item</b>	<b>Description</b>	<b>By</b>	<b>Date</b>	<b>Time</b>	
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	8/15/2023	7:18 AM	
Supervisor Notification	Email Queued Successfully!	jjackson	8/15/2023	7:18 AM	

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 8/15/2023	8:00 AM

Dye Test Results:	E Mail:
WO User 51:	Measurement Line 2:
Measurement:	
History:	

Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Sled
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:
Curb Repair:	
Driveway- Sidewalk Re:	
Construction Crew:	
WO User 39:	
WO User 40:	OUPS #:
WO User 41:	WO User 48:

## Work Order Detail Report

8/16/2023

sso inspections 8-15-2023 - 2.32

9:06 AM

WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	Quantity:	Paid: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>


WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>

WO Creator: jjackson      WO Creation Date: 8/15/2023      PM Trigger:      Rec #: 14949

 **Northeast Ohio  
Regional Sewer District**

Daily/Precipitation Report

Tuesday August 16, 2023



## Northeast Ohio Regional Sewer District

### Daily Precipitation Report

Tuesday, August 15, 2023

Site Location	Peak Accumulation (Inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.43	0.34	0.34	0.23	0.22	0.12
Brecksville	0.35	0.27	0.27	0.26	0.24	0.12
Brook Park	0.16	0.16	0.15	0.08	0.07	0.05
Cleveland Industrial Pkwy	0.20	0.20	0.20	0.11	0.09	0.05
Dill Ave PS	0.23	0.23	0.23	0.13	0.13	0.07
Division Ave PS	0.55	0.30	0.30	0.23	0.23	0.19
Easterly WWTP	0.30	0.30	0.30	0.15	0.15	0.11
Independence	0.26	0.21	0.21	0.13	0.13	0.10
James Rhodes HS	0.25	0.25	0.25	0.15	0.14	0.09
Jennings PS	0.25	0.23	0.23	0.14	0.13	0.06
Macedonia	0.15	0.12	0.12	0.09	0.07	0.03
Maple Heights	0.28	0.20	0.20	0.12	0.12	0.07
Mary Street PS	0.18	0.18	0.18	0.09	0.09	0.07
Mayfield Heights	0.35	0.34	0.33	0.23	0.21	0.12
Moreland Hills	0.11	0.11	0.10	0.07	0.06	0.05
North Olmsted	0.13	0.13	0.12	0.11	0.08	0.04
North Royalton	0.35	0.27	0.27	0.15	0.14	0.09
Oakwood	0.10	0.08	0.08	0.04	0.04	0.03
Olmsted Falls	0.28	0.16	0.16	0.15	0.10	0.05
Parma	0.29	0.22	0.22	0.16	0.14	0.08
Richfield	0.22	0.16	0.16	0.14	0.09	0.03
Shaker Heights	0.47	0.45	0.45	0.25	0.25	0.18
South Euclid	0.46	0.36	0.36	0.23	0.21	0.12
Southerly WWTP	0.17	0.17	0.16	0.09	0.09	0.07
Strongsville C WWTP	0.40	0.22	0.19	0.14	0.11	0.08
Strongsville Foltz	0.46	0.29	0.21	0.16	0.08	0.04
University Heights	0.32	0.32	0.32	0.21	0.21	0.10
Wade Park	0.45	0.45	0.45	0.26	0.24	0.17
Westerly WWTP	0.34	0.25	0.25	0.15	0.11	0.07
Westlake	0.11	0.08	0.08	0.04	0.04	0.03

## Work Order Detail Report

8/18/2023

sso overflow inspections 08-15-2023 0.32'

1:31 PM

WO Number:	230818-0001	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	8/18/2023 1:26 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather		
Assigned Crew:			
Supervisor:	Jackson, Jeff	Assigned By:	
Lead Worker:	Cardarella, Joe	Assigned Date:	
Priority:	High	Start Date:	8/18/2023 7:30 AM
Account #:		End Date:	8/18/2023 2:30 PM
Proj No - Acct:		Project ID:	<u>Override</u>
Project:		Project Name:	<u>Notifications</u>
Reason:			Problem <input type="checkbox"/>
Received By:			Overdue <input type="checkbox"/>
Inspected By:			Lead Worker <input type="checkbox"/>
			Task <input type="checkbox"/>
			Supervisor <input type="checkbox"/>
			Hard Lock WO <input type="checkbox"/>

### Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

#### Location

Department: Sewer Collection  
Division: Sewer

Comments for Crew  
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

#### Work Order Locations

Address	X Coord	Y Coord	General Location	Address 2
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook	
	2,226,440.21168265	664,329.55524255		
	2,226,354.79813956	664,409.89202413		
	2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON	2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO	2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

**Work Order Detail Report**

8/18/2023

sso overflow inspections 08-15-2023 0.32'

1:31 PM

FAIRMOUNT AT ARLINGTON  
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH  
FAIRMOUNT & COVENTRY (SCARBOROUGH)  
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH  
FAIRMOUNT AND COVENTRY  
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH  
SCARBOROUGH AT LAMBERTON  
2,221,598.28993607 666,996.61322863  
MONMOUTH, EAST OF DARTMOOR  
2,225,152.08663423 665,499.19660404 DOAN BROOK  
BRADFORD AND LEE  
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH  
EDDINGTON  
2,221,299.08384156 674,932.84604380  
HAMPSHIRE LANE AT MAYFIELD (18")  
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH  
EAST OVERLOOK AT EDGEHILL  
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH  
HAMPSHIRE LANE AT MAYFIELD (36")  
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH  
2600 HAMPSHIRE RD  
  
HAMPSHIRE AT EUCLID HTS. BLVD.  
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH  
CEDAR BTW. FAIRMOUNT/DEMINGTON  
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH  
2828 BERKSHIRE, EAST OF COVENTRY  
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH  
3003 EUCLID HEIGHTS BLVD  
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH  
South Taylor between Antisdale Ave and Superior Rd  
2,227,113.30810548 671,276.67684697  
LEE RD. & SUPERIOR AVE.  
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA  
EUCLID HEIGHTS BLVD AND LEE  
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH  
EUCLID HEIGHTS BLVD/CUMBERLAND  
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH  
1685 CUMBERLAND  
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH  
CUMBERLAND/SOMERTON  
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH  
2225 NOBLE RD  
  
2225 NOBLE ROAD  
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH  
QUILLIAMS, N. OF RANDOLF  
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH  
LANGTON AND AATHERSTONE  
2,228,126.76638040 684,188.23206055  
  
2,220,777.89623564 666,181.72575080  
2,218,501.67473823 671,997.54581206  
2,216,759.55453481 670,474.59347738  
2,224,536.21778722 668,887.44048372  
2,226,741.35609348 679,432.95121680  
2,226,591.76420106 679,420.92761880

---

**Work Order Detail Report**

8/18/2023

sso overflow inspections 08-15-2023 0.32'

1:31 PM

---

2,227,825.14395215 684,881.15948047

## Work Order Detail Report

8/18/2023

sso overflow inspections 08-15-2023 0.32'

1:31 PM

### Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>PM Description</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve	SSO 431			FAIRFAX AT NORTH PARK			26
Sewer Control Valve	SSO 114			NORTH PARK AND COVENTRY			16
Sewer Control Valve	SSO 121			FAIRMOUNT SOUTH OF SCARBOROUGH			35
Sewer Structure	SA16AAWB0					3094	
Sewer Control Valve	SSO 112			FAIRMOUNT AT FAIRFAX		7	
Sewer Control Valve	SSO 99			FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		6	
Sewer Control Valve	SSO 432			3012 NORTH WOODLAND		14	
Sewer Control Valve	DB-03					55	
Sewer Control Valve	DB-01					56	
Sewer Control Valve	DB-02					57	
Sewer Control Valve	CH-04			FAIRMOUNT AT DARTMOOR		5	
Sewer Control Valve	SSO 110			FAIRMOUNT AT WELLINGTON		44	
Sewer Control Valve	SSO 87			FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		33	
Sewer Control Valve	SSO 116			FAIRMOUNT AT MARLBORO		4	
Sewer Control Valve	SSO 111			FAIRMOUNT AT ARLINGTON		46	
Sewer Control Valve	SSO 113			FAIRMOUNT & COVENTRY (SCARBOROUGH)		37	
Sewer Control Valve	SSO 124			FAIRMOUNT AND COVENTRY		47	
Sewer Control Valve	CH-50			SCARBOROUGH AT LAMBERTON		53	
Sewer Control Valve	SSO 129			BRADFORD AND LEE		11	
Sewer Control Valve	CH-52			EDDINGTON		2	
Sewer Control Valve	SSO 88			HAMPSHIRE LANE AT MAYFIELD (18")		42	
Sewer Control Valve	SSO 122			EAST OVERLOOK AT EDGEHILL		36	
Sewer Control Valve	SSO 89			HAMPSHIRE LANE AT MAYFIELD (36")		34	
Sewer Structure	SA16ADZB0					1536	
Sewer Control Valve	SSO 91			HAMPSHIRE AT EUCLID HTS. BLVD.		20	
Sewer Structure	SA16ADPH0					4446	
Sewer Control Valve	SSO 120			CEDAR BTW. FAIRMOUNT/DEMINGTON		8	
Sewer Control Valve	SSO 103			2828 BERKSHIRE, EAST OF COVENTRY		19	
Sewer Control Valve	SSO 104			3003 EUCLID HEIGHTS BLVD		15	

## Work Order Detail Report

8/18/2023

sso overflow inspections 08-15-2023 0.32'

1:31 PM

Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior F 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

## Work Order Detail Report

8/18/2023

sso overflow inspections 08-15-2023 0.32'

1:31 PM

### Check List

<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1 A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	8/18/2023/12:34 pm	8/18/2023
2 A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	8/18/2023/12:35 pm	8/18/2023
3 A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	8/18/2023/12:35 pm	8/18/2023
4 A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	8/18/2023/12:35 pm	8/18/2023
5 A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	8/18/2023/12:36 pm	8/18/2023
6 A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	8/18/2023/12:37 pm	8/18/2023
7 A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Not Sound	8/18/2023/12:37 pm	8/18/2023
Reset				
8 A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	8/18/2023/12:36 pm	8/18/2023
Reset				
9 A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	8/18/2023/12:39 pm	8/18/2023
10 A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Not Sound	8/18/2023/12:40 pm	8/18/2023
Still surcharging				
11 A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	8/18/2023/12:45 pm	8/18/2023
12 A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/18/2023/12:46 pm	8/18/2023
13 A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	8/18/2023/12:37 pm	8/18/2023
14 A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/18/2023/12:47 pm	8/18/2023
15 A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/18/2023/12:47 pm	8/18/2023
16 A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	8/18/2023/12:48 pm	8/18/2023
17 A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/18/2023/12:51 pm	8/18/2023
18 A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	8/18/2023/12:51 pm	8/18/2023
19 A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	8/18/2023/12:51 pm	8/18/2023
20 A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	8/18/2023/12:51 pm	8/18/2023
21 A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	8/18/2023/12:50 pm	8/18/2023
22 A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	<input type="checkbox"/>	Sound	8/18/2023/12:50 pm	8/18/2023
23 B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	8/18/2023/12:53 pm	8/18/2023
24 B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	8/18/2023/12:53 pm	
25 B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEAO	<input type="checkbox"/>	Sound	8/18/2023/12:54 pm	8/18/2023
26 B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	8/18/2023/12:55 pm	8/18/2023
27 HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	8/18/2023/12:54 pm	8/18/2023

## Work Order Detail Report

8/18/2023

1:31 PM

sso overflow inspections 08-15-2023 0.32'

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPFO	<input type="checkbox"/>	Sound	8/18/2023/12:55 pm	8/18/2023
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	8/18/2023/12:55 pm	8/18/2023
30	B-15 COVENTRY AND CEDAR SA16ADBHO	<input type="checkbox"/>	Sound	8/18/2023/12:56 pm	8/18/2023
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	8/18/2023/12:53 pm	8/18/2023
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	8/18/2023/12:52 pm	8/18/2023
33	B-56 LEE AND MEADOWBROOK SA16AGM0	<input type="checkbox"/>	Not Sound	8/18/2023/12:52 pm	8/18/2023
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVFO	<input type="checkbox"/>	Not Sound	8/18/2023/12:56 pm	8/18/2023
Block broken					
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Not Sound	8/18/2023/12:57 pm	8/18/2023
Can't do construction					
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	8/18/2023/12:58 pm	8/18/2023
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	8/18/2023/12:58 pm	8/18/2023
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	8/18/2023/12:58 pm	8/18/2023
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	8/18/2023/12:59 pm	8/18/2023
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	8/18/2023/12:58 pm	8/18/2023
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Not Sound	8/18/2023/12:57 pm	8/18/2023
Rope broke					
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	8/18/2023/12:59 pm	8/18/2023
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	8/18/2023/12:59 pm	8/18/2023
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	8/18/2023/12:59 pm	8/18/2023
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	8/18/2023/ 1:00 pm	8/18/2023

### Tasks/Resources

#### SMCT36 Inspection

Crew:	Status:	*Cal'c UC: \$5.08	*Task Cost: \$228.54	Start Dt: 8/18/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 8/18/2023

#### Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	6.00	\$148.14		8/18/2023	8/18/2023

#### Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	6.00	\$80.40		8/18/2023	8/18/2023

Task Comment: sso inspections 08-15-2023 0.32

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	6.00	0.00	0.00
Subcontractor:		Labor Costs	\$148.14	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	80.40	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$228.54	\$0.00	\$0.00
		Use Task Info:	True	True	

## Work Order Detail Report

8/18/2023

sso overflow inspections 08-15-2023 0.32'

1:31 PM

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:	Cell #:	
City:		Fax #:		
State:		E-mail:		
Billing Data				
Contact Name:		*Billing Amount:	Billing Required: <input type="checkbox"/>	
Invoice Number:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>	
Incoming Account #:		Payment Received:	Imported to Financials: <input type="checkbox"/>	
Associated PMs		Closed <input checked="" type="checkbox"/>		
Item	Tracking	PM Code and Description		
		SSO-02 SSO INSPECTION		
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jackson	8/18/2023	7:11 AM
Supervisor Notification	Email Queued Successfully!	jackson	8/18/2023	7:11 AM
Status Change	From New Work Order to Complete	jackson	8/18/2023	1:26 PM
Rate:	Opened At:	Televised: <input type="checkbox"/>		
Received By:	Pipe Footage Cleaned	Power Rooter: <input type="checkbox"/>		
Work From:	Gallons Used:	Jet: <input type="checkbox"/>		
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>		
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>		
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>		
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>		
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>		
Test Performed Through:	Appointment Date: 8/18/2023 8:00 AM			
Dye Test Results:				
WO User 51:	E Mail:			
Measurement:	Measurement Line 2:			
History:				
Manhole Basin Repair:	Pipe Size:			
Material Used:	PVC Tees, Angles, Sles			
Pipe Repair:	WO User 44:			
Street Repair:	WO User 45:			
Grass Repair:	WO User 46:			
Curb Repair:				
Driveway- Sidewalk Re				
Construction Crew:				
WO User 39:	OUPS #:			
WO User 40:	WO User 48:			
WO User 41:				
WO User 52:	WO User 62:			
WO User 53:	WO User 63:			
WO User 54:	WO User 64:			
WO User 55:	WO User 65:			
WO User 56:	WO User 66:			
WO User 57:	WO User 67:			
WO User 58:	WO User 68:			
WO User 59:	WO User 69:			
WO User 60:	WO User 70:			
WO User 61:	WO User 71:			

## Work Order Detail Report

8/18/2023

sso overflow inspections 08-15-2023 0.32'


1:31 PM

WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>

WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>

WO Creator: jjackson      WO Creation Date: 8/18/2023      PM Trigger:      Rec #: 14970

 Northeast Ohio  
Regional Sewer District



# Northeast Ohio Regional Sewer District

Daily Precipitation Report  
Friday, August 25, 2023

Site Location	Precipitation (Inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.28	0.28	0.28	0.18	0.09	0.05
Brecksville	0.37	0.37	0.37	0.29	0.22	0.10
Brook Park	0.29	0.29	0.29	0.20	0.17	0.08
Cleveland Industrial Pkwy	0.30	0.30	0.30	0.22	0.17	0.08
Dillie Ave PS	0.25	0.25	0.25	0.17	0.13	0.07
Division Ave PS	0.25	0.25	0.25	0.17	0.15	0.10
Easterly WWTP	0.31	0.31	0.31	0.18	0.11	0.09
Independence	0.28	0.28	0.28	0.19	0.12	0.06
James Rhodes HS	0.35	0.35	0.34	0.25	0.20	0.12
Jennings PS	0.30	0.30	0.29	0.20	0.16	0.11
Macedonia	0.32	0.32	0.32	0.24	0.15	0.07
Maple Heights	0.32	0.32	0.32	0.21	0.13	0.06
Mary Street PS	0.26	0.26	0.25	0.17	0.14	0.08
Mayfield Heights	n/a	n/a	n/a	n/a	n/a	n/a
Moreland Hills	0.29	0.29	0.29	0.18	0.08	0.07
North Olmsted	0.35	0.35	0.35	0.27	0.23	0.14
North Royalton	0.36	0.36	0.36	0.29	0.22	0.11
Oakwood	0.33	0.33	0.33	0.21	0.12	0.08
Olmsted Falls	0.43	0.43	0.43	0.34	0.30	0.13
Parma	0.33	0.33	0.33	0.24	0.19	0.10
Ritchfield	0.33	0.33	0.33	0.25	0.19	0.10
Shaker Heights	0.28	0.28	0.28	0.18	0.11	0.07
South Euclid	0.40	0.40	0.40	0.29	0.19	0.13
Southerly WWTC	0.30	0.30	0.30	0.21	0.16	0.11
Strongsville C WWTP	0.42	0.42	0.42	0.34	0.28	0.14
Strongsville Foltz	0.33	0.33	0.33	0.29	0.26	0.14
University Heights	0.28	0.27	0.27	0.18	0.07	0.04
Wade Park	0.30	0.30	0.30	0.20	0.12	0.08
Westerville WWTP	0.20	0.20	0.19	0.12	0.10	0.08
Westlake	0.22	0.22	0.21	0.14	0.12	0.07

## Work Order Detail Report

8/28/2023

sso overflow inspections 08-25-2023 0.28'

9:05 AM

WO Number:	230827-0001	Category:	SSOs			
Status:	Complete	Problem:	Storm Response			
Status Date:	8/28/2023 9:04 am	Main Task:	Inspection			
Asset:	SSO 431					
Location:	FAIRFAX AT NORTH PARK					
Cause:	Weather					
Assigned Crew:						
Supervisor:	Jackson, Jeff	Assigned By:				
Lead Worker:	Mc Coy, Sam	Assigned Date:				
Priority:	High	Start Date:	8/25/2023 8:00 AM			
Account #:						
Proj No - Acct:						
Project:						
Reason:						
Received By:						
Inspected By:						
<b>Request Comments for Work Order</b>						
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.						

Location	Comments for Crew	
Department:	Sewer Collection	
Division:	Sewer	
Sub-Division:		
Area:		
Sub-Area:		
Owner:		
Location:		
Classification:		
Maintenance Zone:	Alternate Zone:	
Work Order Locations		
Address	Address 2	
X Coord	Y Coord	General Location

Work Order Locations		
X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

## Work Order Detail Report

8/28/2023

sso overflow inspections 08-25-2023 0.28'

9:05 AM

FAIRMOUNT AT ARLINGTON  
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH  
FAIRMOUNT & COVENTRY (SCARBOROUGH)  
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH  
FAIRMOUNT AND COVENTRY  
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH  
SCARBOROUGH AT LAMBERTON  
2,221,598.28993607 666,996.61322863  
MONMOUTH, EAST OF DARTMOOR  
2,225,152.08663423 665,499.19660404 DOAN BROOK  
BRADFORD AND LEE  
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH  
EDDINGTON  
2,221,299.08384156 674,932.84604380  
HAMPSHIRE LANE AT MAYFIELD (18")  
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH  
EAST OVERLOOK AT EDGEHILL  
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH  
HAMPSHIRE LANE AT MAYFIELD (36")  
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH  
2600 HAMPSHIRE RD  
  
HAMPSHIRE AT EUCLID HTS. BLVD.  
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH  
CEDAR BTW. FAIRMOUNT/DEMINGTON  
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH  
2828 BERKSHIRE, EAST OF COVENTRY  
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH  
3003 EUCLID HEIGHTS BLVD  
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH  
South Taylor between Antisdale Ave and Superior Rd  
2,227,113.30810548 671,276.67684697  
LEE RD. & SUPERIOR AVE.  
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA  
EUCLID HEIGHTS BLVD AND LEE  
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH  
EUCLID HEIGHTS BLVD/CUMBERLAND  
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH  
1685 CUMBERLAND  
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH  
CUMBERLAND/SOMERTON  
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH  
2225 NOBLE RD  
  
2225 NOBLE ROAD  
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH  
QUILLIAMS, N. OF RANDOLF  
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH  
LANGTON AND AATHERSTONE  
2,228,126.76638040 684,188.23206055  
  
2,220,777.89623564 666,181.72575080  
  
2,218,501.67473823 671,997.54581206  
  
2,216,759.55453481 670,474.59347738  
  
2,224,536.21778722 668,887.44048372  
  
2,226,741.35609348 679,432.95121680  
  
2,226,591.76420106 679,420.92761880

---

**Work Order Detail Report**

8/28/2023

sso overflow inspections 08-25-2023 0.28'

9:05 AM

---

2,227,825.14395215 684,881.15948047

## Work Order Detail Report

8/28/2023

sso overflow inspections 08-25-2023 0.28'

9:05 AM

### Work Order Assets

Object Type	System ID 1	System ID 2	Description 1	Odometer	Hourmeter	Othermeter	PM Description	Description 2	Asset ID	Completed
Sewer Control Valve								FAIRFAX AT NORTH PARK		
SSO 431									26	
Sewer Control Valve								NORTH PARK AND COVENTRY		
SSO 114									16	
Sewer Control Valve								FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121									35	
Sewer Structure										
SA16AAWB0									3094	
Sewer Control Valve								FAIRMOUNT AT FAIRFAX		
SSO 112									7	
Sewer Control Valve								FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99									6	
Sewer Control Valve								3012 NORTH WOODLAND		
SSO 432									14	
Sewer Control Valve										
DB-03									55	
Sewer Control Valve										
DB-01									56	
Sewer Control Valve										
DB-02									57	
Sewer Control Valve								FAIRMOUNT AT DARTMOOR		
CH-04									5	
Sewer Control Valve								FAIRMOUNT AT WELLINGTON		
SSO 110									44	
Sewer Control Valve								FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87									33	
Sewer Control Valve								FAIRMOUNT AT MARLBORO		
SSO 116									4	
Sewer Control Valve								FAIRMOUNT AT ARLINGTON		
SSO 111									46	
Sewer Control Valve								FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113									37	
Sewer Control Valve								FAIRMOUNT AND COVENTRY		
SSO 124									47	
Sewer Control Valve								SCARBOROUGH AT LAMBERTON		
CH-50									53	
Sewer Control Valve								BRADFORD AND LEE		
SSO 129									11	
Sewer Control Valve								EDDINGTON		
CH-52									2	
Sewer Control Valve								HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88									42	
Sewer Control Valve								EAST OVERLOOK AT EDGEHILL		
SSO 122									36	
Sewer Control Valve								HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89									34	
Sewer Structure										
SA16ADZB0									1536	
Sewer Control Valve								HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91									20	
Sewer Structure										
SA16ADPH0									4446	
Sewer Control Valve								CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120									8	
Sewer Control Valve								2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103									19	
Sewer Control Valve								3003 EUCLID HEIGHTS BLVD		
SSO 104									15	

## Work Order Detail Report

8/28/2023

sso overflow inspections 08-25-2023 0.28'

9:05 AM

Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

**Work Order Detail Report**

8/28/2023

sso overflow inspections 08-25-2023 0.28'

9:05 AM

<b>Check List</b>		<b>Completed</b>	<b>Condition</b>	<b>Completion Date/Time</b>	<b>Est Completion Date</b>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	8/25/2023/ 8:20 am	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Not Sound	8/25/2023/ 8:15 am	
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	8/25/2023/ 8:27 am	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	8/25/2023/ 8:30 am	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	8/25/2023/ 8:34 am	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Not Sound	8/25/2023/ 8:38 am	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Not Sound	8/25/2023/ 8:42 am	
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	8/25/2023/ 8:45 am	
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	8/18/2023/ 8:47 am	
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Not Sound	8/25/2023/ 8:49 am	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	8/25/2023/ 8:51 am	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/25/2023/ 8:55 am	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Not Sound	8/25/2023/ 9:00 am	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	8/25/2023/ 9:04 am	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/25/2023/ 9:07 am	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Not Sound	8/25/2023/ 9:10 am	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	8/25/2023/ 9:12 am	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	8/25/2023/ 9:15 am	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	8/25/2023/ 9:17 am	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	8/25/2023/ 9:19 am	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	8/25/2023/ 9:21 am	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	8/25/2023/ 9:24 am	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Not Sound	8/25/2023/ 9:27 am	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	8/25/2023/ 9:29 am	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	8/25/2023/ 9:32 am	
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Not Sound	8/25/2023/ 9:37 am	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	8/18/2023/ 9:42 am	
Needs a block replacement					
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Not Sound	8/25/2023/ 9:48 am	

## Work Order Detail Report

8/28/2023

9:05 AM

sso overflow inspections 08-25-2023 0.28'

29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	8/25/2023/ 9:51 am
30	B-15 COVENTRY AND CEDAR SA16ADBHQ	<input type="checkbox"/>	Sound	8/25/2023/10:00 am
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	8/25/2023/10:04 am
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	8/25/2023/10:07 am
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	8/25/2023/10:10 am
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	8/25/2023/10:18 am
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	8/25/2023/10:22 am
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	8/18/2023/10:29 am
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	8/18/2023/10:38 am
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	8/25/2023/10:41 am
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	8/25/2023/10:44 am
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	8/25/2023/10:46 am
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	8/25/2023/10:50 am
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	8/25/2023/10:53 am
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Not Sound	8/18/2023/10:57 am
44	C-51 AATHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	8/25/2023/10:55 am
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Not Sound	8/25/2023/10:59 am

### Tasks/Resources

#### SWCT26 Inspection

Crew:	Status:	*Cal'c UC: \$3.49	*Task Cost: \$157.12	Start Dt: 8/25/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 8/25/2023

#### Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
40151 Mc Coy, Sam	Hours	4.00	\$103.52		8/25/2023	8/25/2023
29960 Jackson, Jeff	Hours	4.00	\$0.00		8/25/2023	8/25/2023

#### Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT93 FORD F250 4 X 4 PICK UP 1	Hours	4.00	\$53.60		8/25/2023	8/25/2023
CHFT-500 FORD F250 PICK UP TRUCK	Each	4.00	\$0.00		8/25/2023	8/25/2023

Task Comment: sso overflow inspection 08-25-2023 0.28'

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	6.50	0.00	0.00
Subcontractor:		Labor Costs	8.00	0.00	0.00
Profit Center:		Material Costs	\$103.52	\$0.00	\$0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	53.60	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$157.12	\$0.00	\$0.00
		Use Task Info:	True	True	

# Work Order Detail Report

8/28/2023

sso overflow inspections 08-25-2023 0.28'

9:05 AM

<b>Billed Party</b>		<b>Billing</b>	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
<b>Billing Data</b>			
Contact Name:		*Billing Amount:	<input type="checkbox"/> Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/> Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/> Imported to Financials: <input type="checkbox"/>
<b>Associated PMs</b>		<b>Closed</b> <input checked="" type="checkbox"/>	
		<b>PM Code and Description</b>	
		SSO-02 SSO INSPECTION	

<b>Tracking</b>		<b>Description</b>	<b>By</b>	<b>Date</b>	<b>Time</b>
Item		From Routine Work SSO-02 - SSO INSPECTION	jackson	8/27/2023	8:23 PM
Work Order Creation					
Supervisor Notification		Email Queued Successfully!	jackson	8/27/2023	8:23 PM
Status Change		From New Work Order to Complete	jackson	8/28/2023	9:04 AM

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 8/25/2023 8:00 AM	
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	Measurement Line 2:	
History:		
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Sled	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Re:		
Construction Crew:		
WO User 39:	OUPS #:	
WO User 40:	WO User 48:	
WO User 41:		

WO User 52:	WO User 62:
WO User 53:	WO User 63:
WO User 54:	WO User 64:
WO User 55:	WO User 65:
WO User 56:	WO User 66:
WO User 57:	WO User 67:
WO User 58:	WO User 68:
WO User 59:	WO User 69:
WO User 60:	WO User 70:
WO User 61:	WO User 71:

## Work Order Detail Report

8/28/2023

sso overflow inspections 08-25-2023 0.28'

9:05 AM

WO User 72:

WO User 82:

Televised:

WO User 73:

Quantity:

Paid:

WO User 74:

WO User 84:

WO User 104:

WO User 75:

WO User 85:

WO User 105:

WO User 76:

WO User 86:

WO User 106:

WO User 92 Date:

WO User 97 Date:

WO User 93 Date:

WO User 98 Date:

WO User 94 Date:

WO User 99 Date:

WO User 95 Date:

WO User 100 Date:

WO User 96 Date:

WO User 101 Date:

WO User 77:

WO User 87:

WO User 107:

WO User 78:

WO User 88:

WO User 108:

WO User 79:

WO User 89:

WO User 109:

WO User 80:

WO User 90:

WO User 110:

WO User 81:

WO User 91:

WO User 111:

WO Creator: jjackson

WO Creation Date:

8/27/2023

PM Trigger:

Rec #: 15008